

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
1	12062 Broadstreet Avenue			1926	Tudor Revival	n/a	C	Unknown	Unknown	The commercial building at 12062 Broadstreet Avenue is one story with a flat roof. The parapet is capped with cast stone coping and rectangular and pointed crenellation. The façade is clad in brick laid in a running bond pattern that has been painted blue, and is divided into four bays by pilasters topped by cast stone capitals. The storefronts have been infilled with brick and CMU and there are three contemporary metal entrance doors. Other facades are clad in brick laid in a common bond pattern painted blue.
2	12065 Broadstreet Avenue	Broadstreet Presbyterian Church	Broadstreet Presbyterian Church	1927	Tudor Revival	n/a	C	Unknown	Unknown	The church at 12065 Broadstreet Avenue is one story with a raised basement, composed of two wings in an irregular footprint recombining an L-shape faced with brown brick laid in a Flemish bond pattern. The original wing has a steeply pitched, slate shingle, side gabled roof, intersected by a front gabled wing with parapet on the south and a flat roof entrance vestibule on the north. There is a brick chimney located at the eave on the south façade, and another brick chimney centered on the peak of the front gable, below the gable is decorative stone detailing and a segmented arch window with stone surrounds. The entrance vestibule has a stepped parapet capped in cast stone, above a Tudor arched door with a quoined cast stone door surround, and buttresses capped in stone on the corners. The flat roofed wing addition adjoined to the south of the original building features corner buttresses capped in stone, a polychromatic rose window centered on the façade, and polychromatic tall narrow windows with stone sills along the north façade. The church is set back on the lot with a concrete sidewalk and landscaping, and a metal display sign centered on the lawn.
3	12080 Broadstreet Avenue			1928	Tudor Revival	n/a	C	Unknown	Unknown	The apartment building at 12080 Broadstreet Avenue is three stories tall with a raised basement and flat roof, with a mostly rectangular footprint that has a small projecting portion on the rear creating a slight L-shape. The parapeted roofline is decorated with front gables, crenellation, false miniature towers and slate roof tiles. The façade is clad in red and brown brick laid in a running bond pattern, with decorative brick and rusticated stonework, and slate roofing over projecting awnings. The south corner of the façade is canted. Windows, where present, are hung and vinyl, with brick sills. Tall, narrow windows sit within the canted portion of the south corner of the façade. A concrete path leads to a terrace accessed by concrete steps at the south façade.
4	12098 Broadstreet Avenue			1965	Commercial Style	n/a	C	Unknown	Unknown	The commercial building at 12098 Broadstreet Avenue is one story with a flat roof. The parapet is capped with cast stone on the primary façade and tile coping on the secondary facades. The façade is clad in red brick laid in a running bond pattern. There is a contemporary entrance door with a transom above towards the north corner of the building, next to a display window that has been boarded over. Below the display window is a brick kneewall capped in cast stone that surrounds a planting box. The lot is enclosed by a chain link security fence.
5	12121 Broadstreet Avenue	Winterhalter Elementary School	Hope Academy	1922	Jacobethan Revival	1/other	C	Malcolmson & Higginbotham; Wakely Kushner Associates	Max Bartholomew	The school building at 12121 Broadstreet Avenue is a complex consisting of a two-story original central block with side gabled roof containing classrooms built in 1922, with additional classroom wings with flat roofs on either side and a T-shaped addition to the rear built in 1924, adjoined by a one and two-story addition with an irregular plan and flat roof that was added in 1971. The front façade is eleven bays wide, with red-brown brick veneer laid in a common bond and limestone detailing including coping, beltcourses, quoins, sills, window and door surrounds. The seven central bays are separated by brick double buttresses and contain aluminum windows, with spandrels between the first and second story containing brick and multi-colored tile decoration. Windows on the first floor in the central bays have segmented arch tops. The endwalls facing Cortland to the north and a parking lot to the south are three bays wide, with recessed Tudor-arched entrances. The 1971 portion has an unadorned brick veneer façade with a recessed entrance and windows with limestone sills, lintels, and coping. A spacious lawn with mature trees enclosed by a chain link fence surrounds the Broadstreet façade, and there is a small parking lot with drive-through drop-off accessed by Cortland Street. At the northwest corner of the lot is an unoccupied outbuilding consisting of a front gabled central portion with two flat roofed wings on either side.
6	12130 Broadstreet Avenue		First Glory Missionary Baptist Church	1926	Modern Movement	n/a	C	Unknown	Unknown	The building at 12130 Broadstreet Avenue is one and a half story on top of a raised basement, with front gabled roof and swept-back eave that overhangs deeper near the peak. On top of the peak near the front of the building is a slender hexagonal spire painted white. The façade is clad in blonde brick veneer laid in a running bond pattern, and features polychromatic glazing with spandrel panels separated by full-height brick pilasters and geometric muntins at the first floor. The entrance is accessed by a concrete stoop with metal railing, leading to a brick and concrete porch with a ramp that wraps the north corner towards the parking lot. There is a metal display sign in front of the building.
7	12142 Broadstreet Avenue			1928	Tudor Revival	n/a	C	Unknown	Unknown	The house at 12142 Broadstreet Avenue is two-stories and topped with an asphalt shingle side gable roof intersected by a front gable. Shingled trim beneath the side gables gives the roof a faux-gambrel appearance. A brick chimney is located at the eave on the north façade of the house. The façade is clad in brown face brick laid in a running bond pattern, other facades are composed of red common brick laid in a running bond pattern. The entrance is decorated with arched brick surrounds and stone accents, set beneath a front gabled bay near the south corner of the facade, accessed by a concrete and brick stoop. West of the entrance are three hung vinyl windows, beneath two windows on the second floor. Two additional small hung windows on the second floor above the front gabled entrance bay. Windows have brick sills. Similar windows appear on other elevations. A sidewalk runs along the south of the house. There is no garage.
8	12146 Broadstreet Avenue						NC			The parcel is vacant.
9	12160 Broadstreet Avenue	possibly Land Court Apartments	12160 Broadstreet Avenue	1927	Spanish Revival	n/a	C	Unknown	Unknown	The apartment building at 12160 Broadstreet Avenue is three stories tall with a raised basement and flat roof, with a mostly rectangular footprint that has a small projecting portion on the rear creating a slight L-shape. The parapeted roofline is decorated with Mission-shaped parapets and false miniature bell towers. The façade is clad in light brown brick laid in a running bond pattern, with decorative brickwork including corbelling and arched arches over cast stone tiles. The southeast corner of the building has a projecting canted bay. The entrance is on the south façade set within a projecting vestibule beneath an awning, accessed by concrete terrace and steps at the south façade surrounded by a brick kneewall. Windows, where present, are boarded over but those visible are wood hung in three-over-one and two-over-one configurations, with cast stone sills.
10	12170 Broadstreet Avenue			1926	Tudor Revival	n/a	C	Unknown	Unknown	The apartment building at 12170 Broadstreet Avenue is three stories tall with a raised basement and flat roof, with a mostly rectangular footprint with small projections on the front and rear creating a slight H-shape. The parapeted roofline is clad in slate shingles on the façade and is hipped on the north end wall, while it terminates in a side gabled parapet on the south end wall, and is intersected by two front gables and a brick chimney. The façade is clad in red brick laid in a common bond pattern, with some parquet-patterned brickwork. The façade is wrapped by a cast stone beltcourse above the basement level. There is false half-timbering infilled with stucco beneath one of the front gables. The entrance is set beneath this front gable, slightly off-center on the façade, and is accessed by concrete sidewalk and covered by a contemporary awning. Windows, where present, are multi-paned wood hung and casement, with cast stone sills. A concrete sidewalk runs along the north side of the building where there are steps leading below grade to a basement entrance.
11	12182 Broadstreet Avenue			1949	Colonial Revival	n/a	C	Unknown	Unknown	The house at 12182 Broadstreet Avenue is two-stories and topped with a side gable asphalt shingle roof. A brick chimney is located at the eave near the center of the north façade. The exterior is clad in red brick veneer laid in a running bond pattern except for the overhanging second floor facade which is clad in white vinyl siding. The primary entrance is near the south corner of the facade and is accessed by a brick and concrete stoop. A vinyl clad canted one-story bay window is north of the entrance and two vinyl windows with shutters are on the second floor. Similar windows are arranged on other elevations, although other elevations have brick sills. There is a driveway running along the south of the house and no garage.
12	12190 Broadstreet Avenue			1949	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 12190 Broadstreet Avenue is two-stories and topped with a side gable asphalt shingle roof. A brick chimney is located at the eave near the center of the north facade. The exterior is clad in red brick veneer laid in a running bond pattern except for the overhanging second floor facade which is clad in white vinyl siding. The primary entrance is near the south corner of the facade and is accessed by a brick and concrete stoop. A picture window with two narrow hung sidelights and vinyl-clad window surround is north of the entrance and two vinyl windows with shutters are on the second floor. Similar windows are arranged on other elevations, although other elevations have brick sills. There is a driveway accessed off of Cortland Street at the rear of the house leading to a pyramidal roofed garage.
13	12300 Broadstreet Avenue			1960	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 12300 Broadstreet Avenue is two-stories and topped with a pyramidal asphalt shingle roof. A brick chimney is located at the eave near the center of the north facade. The exterior is clad in red brick veneer laid in a running bond pattern except for the overhanging second floor facade which is clad in white vinyl siding. The primary entrance is near the south corner of the facade and is accessed by a brick and concrete stoop. A divided light picture window and decorative shutters is north of the entrance and two vinyl windows with shutters are on the second floor. Similar windows are arranged on other elevations, although other elevations have cast stone sills. There is a driveway accessed off of Cortland Street at the rear of the house leading to a pyramidal roofed garage.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
14	12305 Broadstreet Avenue			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 12305 Broadstreet Avenue is two-and-a-half stories and topped with a side gable asphalt shingle roof intersected by overlapping front gables. A brick chimney is at the eave near the center of the south facade. The facade is clad in brown face brick laid in a running bond pattern on the first floor, and vinyl siding at the second floor. A one-story side gabled bay projects from the south facade above an enclosed glazed porch supported by brick piers. The primary entrance is near the north corner of the facade set within a front gabled projecting bay, accessed by a brick and concrete porch with metal railings. North of the porch, the front gable extends into a brick arch above a sidewalk leading along the north side of the house, where there is a one-story projecting bay supporting a small balcony with metal railing above. There is a gabled, vinyl clad addition on the rear of the house. Windows are wood hung with divided upper sashes and aluminum storms affixed to the exterior. Some windows have cast stone sills. A concrete driveway is accessed off of Cortland Street leading to a garage with a pyramidal roof at the rear.
15	12314 Broadstreet Avenue			1960	Modern Movement	n/a	C	Unknown	Unknown	The house at 12314 Broadstreet Avenue is two-stories and topped with a low-pitched front gable asphalt shingle roof. A brick chimney is located at the eave peak on the rear facade. The exterior is clad in red brick veneer on the first floor, laid in a running bond pattern with some decorative brickwork, and the second floor facade is clad in white vinyl siding. Between the first and second stories, a front-gabled awning with a wide overhang wraps the facade and creates a recessed entry porch at the north corner of the house. The entrance is accessed by a brick and concrete stoop. A large window is south of the entrance and two slider windows are on the second floor. Similar windows are arranged on other elevations. There is a driveway running along the south of the house and no garage.
16	12315 Broadstreet Avenue			1926	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 12315 Broadstreet Avenue is two stories and topped with a deck on hipped asphalt shingle roof intersected by a front gabled projecting bay on the front facade and a gabled dormer on the south facade. A tall brick chimney is at the eave near the center of the north facade. The facade is clad in brown face brick laid in a running bond pattern with accents of klinker brick, vinyl siding is present beneath the front gable and on the secondary facades at the second floor. A one-story hipped roof bay projects from the north facade. The primary entrance is near the south corner of the facade set within a front gabled projecting vestibule, accessed by a brick and concrete porch. The door is arched and surrounded with decorative brickwork. North of the porch are three hung windows covered by an aluminum awning, beneath a set of two windows within the front gable on the second story. Windows are wood hung with divided upper sashes and aluminum storms affixed to the exterior. Windows on the first floor have brick sills. A concrete driveway runs along the south of the house leading to a garage with a pyramidal roof at the rear.
17	12324 Broadstreet Avenue			1937	French Eclectic	1/garage	C	Unknown	Unknown	The house at 12324 Broadstreet Avenue is two-stories topped with a pyramidal asphalt shingle roof intersected by a two-story canted bay with a polygonal roof on the facade. A brick chimney is at the eave near the front of the north facade. The exterior is clad in brown brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is trimmed in stone, slightly off-center on the facade beneath a small leaded glass window at the second floor, and is accessed by a brick and concrete porch with brick kneewall. The bay is clad in stone veneer on the first floor and white vinyl siding on the second floor, and contains vinyl windows on the first and second floors with a projecting greenhouse window in the center bay. Other windows on the front facade have stone surrounds. Windows on other elevations have brick sills. A concrete driveway runs along the south side of the house to a front gable roof garage at the rear.
18	12325 Broadstreet Avenue			1928	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 12325 Broadstreet Avenue is two stories and topped with a pyramidal asphalt shingle roof intersected by two front gables on the front facade, a vinyl clad hipped dormer to the south, and a hipped dormer on the rear facade overhanging a rear balcony. A tall brick chimney is at the eave on the north facade. The facade is clad in red and light brown face brick laid in a running bond pattern with accents of decorative brickwork. The primary entrance is centered on the facade set within a front gabled projecting vestibule, accessed by a brick and concrete porch with metal railing covered by an aluminum awning. North of the porch are three hung windows also covered by the awning, beneath a set of two windows on the second story. South of the entrance are three narrow casement windows beneath a set of two hung windows on the second story. Windows have cast stone sills. A concrete driveway runs along the south of the house leading to a garage with a front gabled roof at the rear.
19	12332 Broadstreet Avenue			1930	French Eclectic	1/garage	C	Unknown	Unknown	The house at 12332 Broadstreet Avenue is two-and-a-half-stories and topped with a tall, steeply pitched hipped asphalt shingle roof intersected by hipped roof with hipped roof wall dormer on the facade, an engaged polygonal tower capped with a polygonal roof at the center of the facade, and continuous shed dormer on the rear. A dominant brick chimney is beside the tower near the south corner. The exterior is clad in blonde brick veneer laid in a Flemish bond pattern with accents of rusticated stone and decorative brickwork. The primary entrance is arched, trimmed in stone quoins, set within the tower beneath a small leaded glass window with Juliet balcony on the second floor, and is accessed a stone and concrete porch with a stone kneewall and a metal awning structure. Three tall, narrow windows are north of the entrance set beneath three similar windows on the second floor. Windows have brick sills. Similar windows are arranged on other elevations. A concrete driveway runs along the south side of the property leading to a pyramidal roof garage at the rear.
20	12335 Broadstreet Avenue			1940c.	Tudor Revival	n/a	C	Unknown	Unknown	The house at 12335 Broadstreet Avenue is two-stories and topped with a side gable asphalt shingle roof intersected by a front gabled wall dormer and a two story front gabled projecting bay off of the front facade. A brick chimney is located at the eave near the front of the north facade. The exterior is clad in brown brick veneer laid in a running bond pattern with false half-timbering on the second floor infilled with decorative brickwork. The primary entrance is off-center near the south corner of the facade, trimmed in stone quoins and label molding, and is accessed by a stone and concrete porch. South of the entrance is a multi-paned casement window with transom and sidelights, beneath a slightly smaller similar window on the second floor. Similar windows are arranged on other elevations and all windows have brick sills. There is a driveway running along the south of the house towards the rear of the house leading to a side entrance covered by a contemporary awning. There is no garage.
21	12342 Broadstreet Avenue			1936	French Eclectic	1/garage	C	Unknown	Unknown	The house at 12342 Broadstreet Avenue is two-stories and topped with a deck, flat-on-hipped asphalt shingle roof intersected by hipped roof projecting bays at the front and rear, with hipped roof wall dormers on the facade, an engaged polygonal tower capped with a polygonal roof at the center of the facade. A tall brick chimney is located at the eave on the north corner facade. The exterior is clad in red and brown brick veneer laid in a running bond pattern with accents of decorative brickwork, with some sections set proud at the corners to give a quoined appearance. The primary entrance set within the tower, accessed by a concrete stoop. North of the entrance is a canted bay window covered by a metal roof with flared eaves. Windows are multi-paned wood casement windows with transom and sidelights with brick sills. Similar windows are arranged on other elevations. A concrete driveway accessed from Sturtevant Street at the north side of the property leads to a pyramidal roof garage at the rear.
22	12345 Broadstreet Avenue			1942	Streamline Moderne	n/a	C	Unknown	Unknown	The house at 12345 Broadstreet Avenue is two-stories and topped with a pyramidal asphalt shingle roof. A brick chimneys is located at the eave on the south facade. The exterior is clad in blonde brick veneer laid in a running bond pattern with stone belt courses set proud to create horizontal bands across the facade. The primary entrance is centered on the facade and is accessed by a concrete stoop with a small wood cantilevered awning above. A second entrance is located off of Sturtevant Street, beneath a stepped glass block section of wall. To the west of this entrance is a rounded brick bay glazed with a large glass block window. Other windows are hung and covered by aluminum awnings. The concrete driveway is accessed off of Sturtevant Street leading to an attached garage with an enclosed sunroom above.
23	12500 Broadstreet Avenue			1928	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 12500 Broadstreet Avenue is two-stories and topped with a deck asphalt shingle roof, with hipped massing below the flat portion, intersected by a two story front gabled projecting bay and a front gabled wall dormer off of the front facade, a hipped dormer on the south and rear, and a shed dormer on the north. A brick chimney is located at the eave on the front facade where the two main bays intersect. The exterior is clad in brown brick veneer laid in a running bond pattern with accents of klinker brick and false half-timbering beneath the front gables on the second floor infilled with decorative brickwork. The primary entrance is centered on the facade, trimmed in stone, and is accessed by a brick and concrete porch and a wooden ramp. South of the entrance is a multi-paned casement window with transom and sidelights, beneath a slightly smaller similar window on the second floor. Similar windows are arranged on other elevations and some windows have rounded cast stone sills. Off of Sturtevant Street a concrete sidewalk leads between two brick piers to a rear stoop and there is a driveway leading to a hipped roof garage.
24	12503 Broadstreet Avenue			1924	Prairie	1/garage	C	Unknown	Unknown	The house at 12503 Broadstreet Avenue is two-stories and topped with a pyramidal asphalt shingle roof, intersected by hipped roof dormers with slider windows on all four facades. A brick chimney is near the eave on the south facade and another brick chimney is at the eave on the north facade near the rear of the house. The facade is clad in red face brick laid in a running bond pattern. The primary entrance is slightly off-center near the east corner of the facade beneath a wraparound hipped-roof porch supported by brick piers with a brick kneewall and accessed by concrete steps. There is a front gabled dormer above the steps and the door is flanked by sidelights. To the south of the entrance is a bay window. Windows are mostly hung, with some slider windows, and all have cast stone sills. A concrete driveway is accessed off of Sturtevant Avenue leading to a pyramidal roof garage at the rear of the house.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
25	12512 Broadstreet Avenue			1929	Tudor Revival	n/a	C	Unknown	Unknown	The house at 12512 Broadstreet Avenue is two-stories and topped with a side gable asphalt shingle roof intersected by a front gable and a shed roof wall dormer with two narrow hung windows on the front façade and multiple shed dormers on the rear. A brick chimney is located at the peak of the eave on the north façade. The exterior is clad in brown brick veneer laid in a Flemish bond pattern with false half-timbering on the second floor infilled with stucco and decorative brickwork. The primary entrance is centered on the façade within a front gabled vestibule, arched and trimmed in stone quoins next to a small arched window also trimmed in stone quoins, and is accessed by a stone and concrete porch. On either side of the entrance are a series of four tall, narrow multi-paned windows with cast stone sills, the set to the north appears to be wood while the set to the south appears to be vinyl. An oriel window with flared metal roof is beneath the front gable. Windows are arranged on other elevations appear to be wood hung with multi-light upper sashes, with a combination of wood and brick sills. There is a driveway running along the south of the house towards the rear of the house. There is no garage.
26	12515 Broadstreet Avenue			1931	French Eclectic	1/garage	C	Unknown	Brownwell Corporation	The house at 12515 Broadstreet Avenue is two-stories and topped with a side gable asphalt shingle roof with slightly flared eaves intersected by hipped roof addition on the rear. The house has paired end chimneys made of brick. The exterior is clad in brown brick veneer laid in a running bond pattern with accents of orange brick, and some sections set proud on the corners to create a quoined appearance. Vinyl siding is present beneath the gable ends at the attic level. The primary entrance is centered on the symmetrical façade with a wood door surround including pilasters and filled fanlight accessed by a semi-circular brick and concrete stoop. On either side of the entrance are eight-over-eight wood hung windows, set beneath six-over-six wood hung windows on the second floor. A small four-over-four wood hung window is directly above the entrance. All windows on the façade have brick sills and shutters painted white. The entrance and first floor windows have cast stone keystones and brick lintels above. Windows on other facades are multi-light and wood hung. There is a driveway running along the south of the house towards a pyramidal roof garage at the rear.
27	12524 Broadstreet Avenue			1928	French Eclectic	n/a	C	Unknown	Unknown	The house at 12524 Broadstreet Avenue is two-stories and topped with a hipped asphalt shingle roof intersected by two hipped roof two-story bays: one centered on the south façade, and one projecting off the southeast corner to the rear. There is a shed roof dormer clad in vinyl siding on the north side of the roof. The house has a large brick chimney at the eave on the north façade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of brown klinker brick. The primary entrance is recessed within the hipped roof bay on the south façade, with a wood door surround beneath a brick arch, and is accessed by a brick and concrete porch. North of the entrance, there are two slider windows and a bay window topped with a metal roof with flared eaves. The second floor windows are hung and have shutters painted red. All windows have brick sills. Similar windows appear on other elevations. There is a driveway running along the south of the house towards the rear. There is no garage.
28	12525 Broadstreet Avenue			1928	Tudor Revival	n/a	C	Robert W. Tempest	Unknown	The house at 12525 Broadstreet Avenue is two-stories and topped with a cross gable asphalt shingle roof with no overhang, the front gable is also a catslide that extends over a recessed porch and this portion is clad in vinyl. There are two shed roof dormers, also clad in vinyl siding, that meet at the intersection of the cross gables. The house has a large brick chimney at the eave on the north façade. The exterior is clad in brown brick veneer laid in a common bond pattern. At the north corner, the wall junction transitions into a brick garden wall extending north from the house. The primary entrance is recessed beneath the catslide on the south façade, which is supported by square wood posts and brackets atop of square brick piers. North of the entrance is a bay window set beneath a single hung window on the second floor. Windows have brick sills. Similar windows appear on other elevations. There is a driveway running along the south of the house towards the rear. There is no garage.
29	12532 Broadstreet Avenue			1927	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 12532 Broadstreet Avenue is two-stories with a deck, flat-on-hipped, shingle roof intersected by a catslide front gable and a shed roof dormer on the south. There is a large brick chimney at the eave centered on the north façade. The exterior is clad in brown brick veneer laid in a running bond pattern with some decorative brick and stonework. The primary entrance is recessed beneath a front gabled brick porch with a Tudor arched opening, concrete steps, and metal railing. North of the entrance is a set of three hung windows with a brick segmented arch lintel and rusticated stone accents, set beneath a set of two hung windows on the second floor and a small hung window beneath the peak of the front gable. Windows have cast stone sills. Similar windows appear on other elevations, along with glass block windows. There is a driveway running along the south of the house towards a pyramidal roof garage at the rear.
30	12533 Broadstreet Avenue			1924	Georgian Revival	1/garage	C	Unknown	Unknown	The house at 12533 Broadstreet Avenue is two-stories and topped with a side gable asphalt shingle roof intersected by three pedimented dormers containing arched hung windows and clad in vinyl siding, and a gabled dormer on the rear of the house. The cornice line is elaborated by dentils. A brick chimney is located at the eave at the peak of the side gable on the south façade. The exterior is clad in brown brick veneer laid in a running bond pattern. The primary entrance is centered on the symmetrical façade and accentuated by a semicircular portico with round columns, and the door is surrounded by sidelights and transom accessed by semi-circular concrete steps. On either side of the entrance are multi-light wood hung windows with splayed brick lintels arranged symmetrically, set beneath matching wood hung windows on the second floor where they have wood shutters painted white. Windows have cast stone sills painted white. The entrance and first floor windows have cast stone keystones and brick lintels above. Similar windows are arranged on other elevations. There is a driveway running along the north of the house towards a pyramidal roof garage at the rear.
31	12546 Broadstreet Avenue			1948	French Eclectic	1/garage	C	Unknown	Unknown	The house at 12546 Broadstreet Avenue is two-stories and topped with a pyramidal asphalt shingle roof. A tall brick chimney is located at the eave on the south façade near the front of the house. The exterior is clad in brown brick veneer laid in a running bond. The primary entrance is centered on the façade, within a cast stone surround with fluted pilasters, and accessed by a brick and concrete porch. South of the entrance is a canted bay window covered by a metal roof with flared eaves and clad with stone veneer. A picture window sits to the north of the entrance and has cast stone lintel, sill, and quoins. There are two slider windows on the second floor. Similar windows are arranged on other elevations. A concrete driveway accessed from Fullerton Street at the north side of the property leads to a pyramidal roof garage at the rear.
32	12547 Broadstreet Avenue			1963	Modern Movement	n/a	C	Nathan Johnson	Unknown	The house at 12547 Broadstreet Avenue is two-stories and topped with a gabled asphalt shingle roof with overhanging eaves and exposed beams. A brick chimney is located at the eave centered on the south façade. The exterior is clad in vertical blonde brick veneer laid in a running bond, interrupted by sections of large vertical glazing with wood spandrel panels painted brown. These full-height windows are fixed but some have a lower section containing a small slider window. The primary entrance is recessed on the north façade, beneath a cantilevered overhang with a single pole support, and accessed by a small concrete step. A concrete driveway runs along the south side of the property. There is no garage.
33	12604 Broadstreet Avenue			1927	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 12604 Broadstreet Avenue is two-stories and topped with a deck asphalt shingle roof with flared eaves intersected by a front gable with white vergeboard and a triangular dormer with two triangular multi-light windows on the front façade, and shed dormers centered on both the north and south portions of the roof. A tall brick chimney with stone accents is located at the eave on the south façade. The exterior is clad in brown and red brick veneer laid in a running bond pattern with decorative brickwork beneath the front gable and stone buttresses at the corners. The primary entrance is within a front gabled vestibule with white vergeboard and stone buttressed corners, with an arched door trimmed in stone quoins, and is accessed by a brick and concrete full width porch with metal railing. South of the entrance are three wood hung windows beneath two wood hung windows with divided upper sashes on the second floor. Windows on the street-facing facades have stone lintels and keystones. Windows on all facades have cast stone sills. There is a driveway accessed off of Fullerton Street to the south of the house leading to a hipped roof garage.
34	12626 Broadstreet Avenue			1929	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 12626 Broadstreet Avenue is two-stories and topped with a cross gable asphalt shingle roof intersected by overlapping front gables and a wall dormer on the front façade. A brick chimney is located at the eave centered on the south façade. The exterior is clad in a mix of dark and light brown brick veneer laid in a running bond pattern with decorative brickwork and false half-timbering infilled with stucco beneath the front gables. The primary entrance is within a front gabled vestibule clad in stone veneer, with a Tudor-arched door trimmed with a cast stone label mold, and is accessed by a brick and concrete porch with metal railing. South of the entrance is a canted bay window with multi-light wood casement windows and transoms above, and topped with a metal roof with flared eaves. The metal structure for an awning is present. North of the entrance is a wood casement window with divided lights and a splayed brick lintel with keystone. There are two small, multi-light wood hung windows on the second floor. Windows have brick sills. There is a concrete driveway running along the south of the house leading to a pyramidal roof garage at the rear.
35	12636 Broadstreet Avenue			1927	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 12636 Broadstreet Avenue is two-stories and topped with a cross hipped asphalt shingle roof intersected by a front gable and an eyebrow dormer on the front façade. A brick and stone chimney is located at the eave centered on the north façade. The exterior is clad in reddish brown brick veneer laid in a running bond pattern and false half-timbering infilled with stucco and wood clapboard siding beneath the front gabled bay. The primary entrance is within a vestibule topped with an asphalt shingle eyebrow roof with brick parapeted endwalls and stone coping. The segmental arch door is trimmed with a stucco surround between brick pilasters, and is accessed by a brick and concrete full width porch. South of the entrance is a brick and asphalt shingled porte cochere extending from the front corner. North of the entrance is a canted bay window with multi-light wood hung windows, beneath three hung windows with diamond patterned leaded glass. Similar windows appear on other elevations and have cast stone sills. An arched brick opening extends off the north corner of the façade. There is a concrete driveway running along the south of the house leading to a pyramidal roof garage at the rear.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
36	12650 Broadstreet Avenue			1927	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 12650 Broadstreet Avenue is two-stories and topped with a deck, flat on hipped asphalt shingle roof intersected by a front gable with flared eaves, shed roof dormers on the north and south, and a hipped roof overhang at the rear above a two-story porch. A brick chimney is located at the eave on the north façade near the front of the house. The exterior is clad in reddish brown brick veneer laid in a Dutch bond pattern. The primary entrance is within a front gabled vestibule with flared eaves, and the arched door is trimmed with brick surround and rusticated stone accents. The entrance is accessed by a brick and concrete porch. North of the entrance are three wood hung windows, beneath two hung windows on the second floor. Similar windows appear on other elevations and all have cast stone sills. There is a concrete driveway accessed off of Leslie Street to the north of the house leading to a pyramidal roof garage at the rear.
37	12655 Broadstreet Avenue	Russell Woods Park	Russell Woods Park				C			Russell Woods Park is roughly 4-acre green space with a pavilion, walking trail, mature trees and flower beds. Signage is located off of Broadstreet Avenue.
38	12703 Broadstreet Avenue			1926	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 12703 Broadstreet Avenue is two-stories and topped with a deck, flat on hipped asphalt shingle roof intersected by a front gable with flared eaves, shed roof dormers on the north and south, and a hipped roof overhang at the rear above a two-story porch. A large brick chimney is located at the eave on the south façade near the front of the house. The exterior is clad in light brown brick veneer laid in a running bond pattern with decorative brickwork. The primary entrance is within a steeply pitched front gabled vestibule, and the basket-handle-arched door is trimmed with brick surround and rusticated stone accents. The entrance is accessed by a brick and concrete porch with metal railing. On either side of the entrance are wood hung windows with divided lights and security bars, these have brick label mold lintels and brick sills. Other facades have wood hung windows with brick sills and lintels, some fixed windows have diamond pattern leaded glass. There is a concrete driveway accessed off of Leslie Street to the south of the house leading to a front gabled and hipped roof garage at the rear.
39	12715 Broadstreet Avenue			1926	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 12715 Broadstreet Avenue is two-stories and topped with a deck, flat on hipped asphalt shingle roof intersected by a front gable with flared eaves and white vergeboards, rounded roof dormers clad in wood shingles on the north and south, and a hipped roof overhang at the rear above a two-story enclosed porch. A large brick chimney with rusticated stone accents is located at the eave on the front of the house. The exterior is clad in brown brick veneer laid in a unique alternating stacked and header bond pattern with decorative brickwork. The primary entrance is centered on the facade within a front gabled vestibule with flared eaves and white vergeboard, and the arched door is recessed within an arched brick surround. The entrance is accessed by a concrete porch. South of the entrance is a segmental arched set of three windows, with brick lintel accented by rusticated stone. A single segmental arch window is to the north of the chimney. Two wood hung windows glaze the second floor with shutters painted white. Similar windows exist on other elevations. There is a concrete driveway to the south of the house leading to a pyramidal roof garage at the rear.
40	12716 Broadstreet Avenue			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 12716 Broadstreet Avenue is two-stories and topped with a deck, flat on dual-pitched hipped asphalt shingle roof with no overhang, intersected by two front gables, and shed roof dormers on the north and rear. A tall brick chimney is located at the eave on the south façade near the front of the house. The exterior is clad in brown brick veneer laid in a running bond pattern, with false half-timbering infilled with stucco beneath a projecting front gabled bay supported by brackets, and additional false half-timbering infilled brick on the other front gable. The primary entrance is within a canted vestibule clad in stone veneer, with a Tudor-arched door flanked by two narrow multi-light casement windows. The entrance is accessed by a brick and concrete porch with metal railing. South of the entrance is a vinyl picture window, set beneath a set of three vinyl hung windows on the second floor, both with cast stone sills. Three additional vinyl hung windows are above the entrance on the second floor. Similar windows exist on other elevations. There is a concrete driveway that runs along the north of the house leading to a pyramidal roof garage at the rear.
41	12725 Broadstreet Avenue			1926	Tudor Revival	n/a	C	Unknown	Unknown	The house at 12725 Broadstreet Avenue is two-stories and topped with a hipped asphalt shingle roof intersected by a front gable, and hipped roof dormer on the south. A tall brick chimney is located at the eave on the north façade near the front of the house. The exterior is clad in light and dark brown brick veneer laid in a running bond pattern, with a soldier course between the second floor and attic. The primary entrance is near the south corner, accessed by a brick and concrete porch beneath a front gabled overhang supported by a brick arch. North of the entrance is a set of three wood hung windows with metal security bars. The second floor has wood hung windows with awnings. There is a narrow arched fixed window at the attic level beneath the front gable. Similar windows exist on other elevations, and all windows have cast stone sills. There is a concrete driveway running along the south of the house. There is no garage.
42	12726 Broadstreet Avenue			1924	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 12726 Broadstreet Avenue is two-stories and topped with a deck, flat on hipped asphalt shingle roof intersected by a front gable, and hipped roof dormers on the front, north, and rear façades. A tall brick chimney is located at the eave on the south façade near the center of the house. The exterior is clad in reddish brown brick veneer laid in a running bond pattern, with false half-timbering with stucco infill beneath the front gable. The primary entrance is centered on the façade beneath a front gabled portico with a brick arch, accessed by a full width brick and concrete porch. North of the door is a small window with diamond patterned leaded glass, and a small multi-light window is beneath the peak on the front gabled portico. On either side of the entrance is a set of three wood hung multi-light windows that together form a segmental arch, topped with segmental arch brick lintels. The second floor has two sets of paired wood hung windows. There is a narrow arched fixed window at the attic level beneath the front gable. Similar windows exist on other elevations, and all windows have cast stone sills. There is a concrete driveway running along the south of the house. There is no garage.
43	12733 Broadstreet Avenue			1928	Tudor Revival	n/a	C	Unknown	Unknown	The house at 12733 Broadstreet Avenue is two-stories and topped with a side gable asphalt shingle roof intersected by a hipped roof on the front facade, and shed roof dormers on the rear. A brick chimney is near the center of the house. The exterior is clad in red and brown brick veneer laid in a running bond pattern, with false half-timbering with decorative brick infill. The primary entrance is near the south corner of the house beneath a hipped roof portico supported by brick piers, accessed by a brick and concrete porch. North of the entrance are two vinyl hung windows with brick lintels, set directly beneath vinyl hung windows on the second floor. Similar windows exist on other elevations, and all windows have brick sills. There is a concrete driveway running along the south of the house. There is no garage.
44	12736 Broadstreet Avenue			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 12736 Broadstreet Avenue is two-and-a-half stories and topped with a jerkinhead asphalt shingle roof intersected by a hipped roof dormer on the north facade, and gabled roof dormer on the south. A monumental brick chimney is located at the eave near the front of the house on the south facade. The exterior is clad in brown brick veneer laid in a running bond pattern, with false half-timbering with brick infill. The primary entrance is off-center beneath a shingled overhang with bracket support that extends over a canted bay window south of the entrance. The door is accessed by a small concrete porch. The bay window has multi-light casement windows, and similar windows glaze the second floor. Similar windows exist on other elevations. There is a concrete driveway running along the north of the house leading to a pyramidal roof garage.
45	12745 Broadstreet Avenue			1930	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 12745 Broadstreet Avenue is two stories and topped with a cross gable asphalt shingle roof with a catslide and two wall dormers on the front facade, intersected by a hipped roof dormer and shed roof dormer, both clad in wood shingles, on the rear. A brick chimney is located at the peak of the eave on the facade. The exterior is clad in brown brick veneer laid in a running bond pattern, with false half-timbering with brick infill beneath the front gable. The primary entrance is centered on the façade beneath the catslide, and the segmental arched door is trimmed in stone quoins and accessed by a small brick and concrete porch with metal railing. Windows on the front facade are six-over-six wood hung windows with aluminum storms, and have brick sills and lintels. Beneath the front gable, the window has shutters painted brown. Similar windows exist on other elevations. There is a canted one-story bay window clad in wood shingles at the rear of the house, supporting a balcony above, as well as a one-story enclosed porch. There is a concrete driveway accessed from Glendale Street north of the house leading to a hipped roof garage.
46	12746 Broadstreet Avenue			1937	Colonial Revival	n/a	C	Unknown	Miller-Storm Company	The house at 12746 Broadstreet Avenue is two-stories and topped with a side gable asphalt shingle roof intersected by a gabled one-story wing on the rear of the house. A brick chimney is located at the eave on the north façade. The exterior is clad in brown brick veneer laid in a running bond pattern, with some sections set proud at the corners to create a quoined appearance. The primary entrance is centered on the symmetrical façade, recessed within a wood surround with pilasters painted white, and fanlight above the door. The entrance is accessed by a small brick and concrete porch with metal railing. On either side of the entrance are multi-light hung windows, set beneath matching hung windows on the second floor, they have wood shutters painted dark blue. Similar windows are arranged on other elevations, and all windows have brick sills and some have aluminum storms. There is a driveway accessed from Glendale Street north of the house, but there is no garage.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
47	12804 Broadstreet Avenue			1935	French Eclectic	1/garage	C	Unknown	Benjamin Koloff	The house at 12804 Broadstreet Avenue is two-stories and topped with a deck, flat-on-hipped asphalt shingle roof intersected by a hipped roof projecting wing at the front, with many hipped roof wall dormers across the façades, and an engaged polygonal tower clad in stone veneer capped with a polygonal roof centered on the façade at the intersection of the two wings. A tall brick chimney is located at the eave on the south facade. The exterior is clad in red and brown brick veneer laid in a running bond pattern, with some sections set proud at the corners to give a quoined appearance. The primary entrance set within the tower, accessed by a brick and concrete porch with metal railing. On either side of the entrance are two narrow windows, and south of the entrance is a canted bay window covered by a metal roof with flared eaves. Windows are multi-paned wood casement windows with transom and sidelights with brick sills, matching the other windows on the first floor. On the second floor, windows are multi-light hung or slider windows with brick sills. Similar windows are arranged on other elevations. At the rear of the house is a one-story, hipped roof enclosed porch with brick kneewall and piers, and louver windows. A canopy structure provides a covered walkway from the house to the pyramidal roofed garage in the rear which is accessed by a concrete driveway off of Glendale Street to the south.
48	12805 Broadstreet Avenue			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 12805 Broadstreet Avenue is two-stories and topped with a deck, flat on hipped asphalt shingle roof intersected by a front gable, and hipped roof dormers on the south and rear façades. A tall brick chimney with stone accents is located at the eave on the south façade. The exterior is clad in brown brick veneer laid in a running bond pattern, with accents of klinker brick throughout. The primary entrance is located near the north corner of the façade beneath a front gabled portico with flared eaves, supported by brick piers and a brick arch accented by stone quoins, and is accessed by a full width brick and concrete porch with metal railing. South of the entrance is a set of three wood hung windows with divided upper sashes, with rusticated stone quoined surrounds. The second floor has a smaller paired set of hung windows with divided upper sashes and a paired set of narrow windows with leaded glass in diamond pattern, each of which have cast stone sills and brick lintels with stone accents. There is a narrow arched fixed window at the attic level beneath the front gable. Similar windows exist on other elevations, and all windows have cast stone sills. There is a concrete driveway accessed off of Glendale Street to the south of the house leading to a pyramidal roof garage.
49	12817 Broadstreet Avenue			1924	Tudor Revival	n/a	C	Unknown	Unknown	The house at 12817 Broadstreet Avenue is two-stories and topped with a hipped asphalt shingle roof intersected by a prominent front gable, and a hipped roof dormer on the rear. A tall brick chimney is located at the eave on the north façade near the front of the house. The exterior is clad in blonde brick veneer laid in a running bond pattern on the first floor and beneath the front gable, with the second floor clad in wood shingle siding. The primary entrance is located near the south corner of the façade beneath a front gabled vestibule and is accessed by a full width brick and concrete porch with metal railing. The arched door is accented by cast stone keystone and tabs. North of the entrance is a set of three hung windows with stone accents at the corners, brick lintel, and cast stone sill painted brown. The second floor has a smaller set of three hung windows with shutters painted brown, beneath a small attic window with matching shutters at the peak of the front gable. Similar windows exist on other elevations. There is a concrete driveway running along the south of the house. There is no garage.
50	12818 Broadstreet Avenue			1926	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 12818 Broadstreet Avenue is two-stories and topped with a side gable asphalt shingle roof intersected by two front gabled roof dormers, and a shed dormer at the rear. The side gables each have a decorative asphalt shingled trim that creates a gambrel roof appearance, which runs along the façade as a shingled awning between the first and second floor. Modillions accent the roofline and awning. A brick chimney is located at the eave on the north façade. The exterior is clad in brown brick veneer laid in a running bond pattern on the first floor, while the second floor is clad in wood shingle siding painted white. The primary entrance is centered on the symmetrical façade, emphasized by a triangular projection on the awning and a wood surround with pilasters and sidelights painted white. The entrance is accessed by a small brick and concrete porch with metal railing. On either side of the entrance is a bay window featuring wood hung windows with divided upper sashes, beneath similar windows on the second floor which have shutters painted tan. Similar windows are arranged on other elevations, and all windows have aluminum storms. A driveway runs along the south of the house to the rear where there is a pyramidal roof garage.
51	12824 Broadstreet Avenue			1934	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 12824 Broadstreet Avenue is two-stories and topped with a side gable asphalt shingle roof with slightly flared eaves and intersected by a hipped roof at the rear. A brick chimney is located at the eave on the south façade. The exterior is clad in reddish brown brick veneer laid in a running bond pattern. The primary entrance is centered on the symmetrical façade, trimmed by a broken pediment wood surround with pilasters. The entrance is accessed by a small brick and concrete porch with metal railing. On either side of the entrance is a wood hung six-over-six window with wood panel below and topped with brick lintels and cast stone keystones, beneath matching windows on the second floor. Windows on the façade have shutters painted white. Similar windows are arranged on other elevations, and all windows have cast stone sills. A driveway runs along the south of the house to the rear where there appears to be a garage.
52	12825 Broadstreet Avenue			1936	French Eclectic	1/garage	C	Unknown	Unknown	The house at 12825 Broadstreet Avenue is two-stories and topped with a hipped asphalt shingle roof with a hipped roof projecting bay both at the front and rear, and two hipped roof wall dormers. Additional hipped roof dormers face the north and south. A tall brick chimney is located at the eave on the north facade. The exterior is clad in brown brick veneer laid in a running bond pattern, with areas of stone veneer. The primary entrance is centered on the façade and accessed by a brick and concrete porch with metal railing. The arched door is accented by stone veneer, set beneath a wall dormer containing a leaded glass window with a diamond pattern on the second floor. North of the entrance is a canted bay window clad in stone veneer and cast stone window surrounds, beneath a wall dormer containing two windows on the second floor also with cast stone trim. Windows on the façade are six-over-six wood hung windows with brick sills. Similar windows are arranged on other elevations. A concrete sidewalk runs along the south of the house to the rear where there is a pyramidal roof garage.
53	12837 Broadstreet Avenue			1926	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 12837 Broadstreet Avenue is two-stories and topped with a hipped asphalt shingle roof intersected by overlapping front gables and gable roof dormers on the north and rear façades. A prominent brick chimney is located on the peak of the front gable. The exterior is clad in brown brick veneer laid in a running bond pattern, with accents of cast stone and some half-timbering infilled with stucco beneath the front gable. The primary entrance is located near the north corner of the façade, and is accessed by a brick and concrete porch with metal railing. Extending off the south façade is a rounded one-story bay supporting a balcony above. Windows are tall and narrow with cast stone sills across the façade. There is a stained glass circle window on the north corner of the house. There is a front gable roof garage with decorative brickwork accessed via the alley at the rear of the house, but there is no driveway.
54	12844 Broadstreet Avenue			1924	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 12844 Broadstreet Avenue is two-stories and topped with a side gable asphalt shingle roof intersected by a front gable, and a hipped roof at the rear with a shed dormer. A brick chimney is located near the eave on the north facade. The exterior is clad in blonde brick veneer laid in a running bond pattern. The primary entrance is located near the south corner, and is accessed by a brick and concrete porch with a wood and metal railing beneath a front gabled overhang supported by round wood posts. The door is arched, with cast stone keystone and tabs, and a matching brick arched opening extends off the south corner over a concrete sidewalk leading to the backyard. North of the entrance is a bay window with a central picture window flanked by two small hung windows, with an asphalt shingle roof. Extending off the north façade is a one-story brick and wood-clad projecting bay supporting a balcony with metal railing above. At the rear, a bay projects with large expanses of glass block window on the first floor and vinyl siding at the second floor level. Windows hung, fixed, or slider and have cast stone sills. There is a concrete driveway accessed off of Buena Vista Street to the north of the house leading to a pyramidal roof garage.
55	12845 Broadstreet Avenue			1924	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 12845 Broadstreet Avenue is two-stories and topped with a hipped asphalt shingle roof intersected by a shed roof dormer at the rear. A brick chimney is located near the northwest corner of the house. The exterior is clad in brown brick veneer laid in a running bond pattern. The primary entrance is centered on the symmetrical façade, beneath a portico with square wood columns. The entrance is accessed by a small porch. On either side of the entrance is a set of full height windows flanking a glazed door, covered by roll up awnings. On the second floor windows are hung with divided upper sashes and cast stone sills. Similar windows are arranged on other elevations. A driveway is accessed off of Buena Vista Street to the north of the house, leading to a pyramidal roof garage.
56	13100 Broadstreet Avenue			1923	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 13100 Broadstreet Avenue is two-stories and topped with a side gable asphalt shingle roof. The side gables each have a decorative asphalt shingled trim that creates a gambrel roof appearance, which continues along the façade as a shingled awning between the first and second floor. A brick chimney with decorative tile is located at the peak of the eave on the west facade. The exterior is clad in light brown brick veneer laid in a running bond pattern on the first floor and beneath the side gambrel, while the second floor is clad in vinyl siding. The primary entrance is centered on the south façade, orienting the house toward Buena Vista Street, and is emphasized by a pedimented projection on the awning supported by round wood columns, and the door is flanked by sidelights. The entrance is accessed by a small concrete porch. Windows on either side of the entrance are wood hung windows with cast stone sills, beneath similar windows on the second floor. Similar windows are arranged on other elevations, and all windows have aluminum storms. A second porch extends off the west façade, is made of brick and concrete, with a metal railing and beneath an aluminum awning. A driveway is accessed off of Buena Vista Street at the south of the house, leading to a pyramidal roof garage.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
57	13101 Broadstreet Avenue			1952	Modern Movement	1/garage	C	Unknown	Unknown	The house at 13301 Broadstreet Avenue is two-stories and topped with a pyramidal asphalt shingle roof. A brick chimney is at the eave on the north facade. The exterior is clad in red brick veneer laid in a running bond pattern. The primary entrance is near the south corner of the facade, recessed within a slightly projecting bay and is accessed by a brick and concrete porch with a metal railing and an asphalt shingle awning with an angled brick support. North of the entrance is a picture window with sidelights. Slider windows with white shutters are on the second floor. Windows have cast stone sills and aluminum storm windows. Similar windows are arranged on other elevations. An enclosed porch with hipped roof extends off the north facade. A concrete driveway is accessed off of Buena Vista Street to the south of the house leading to a pyramidal roof garage at the rear.
58	13114 Broadstreet Avenue			1936	French Eclectic	1/garage	C	Unknown	Unknown	The house at 13114 Broadstreet Avenue is two-stories and topped with a hipped asphalt shingle roof intersected by a front gabled wall dormer and a polygonal roof above an oriel window on the front facade. A brick chimney is located at the eave near the center of the north facade. The exterior is clad in brown and red brick veneer laid in a running bond pattern, with some sections set proud at the corners to create a quoined appearance. The primary entrance features a Tudor arched door with cast stone surround and is centered on the facade, accessed by a small brick and concrete porch. South of the entrance is wood casement window with transom and sidelights, with a quoined cast stone surround. North of the entrance is a canted bay with stone veneer cladding and wood casement windows with transoms above. Similar windows are arranged on the second floor and on other elevations, and windows have cast stone sills and some have aluminum storms. There is a driveway running along the south of the house to the rear where there is a hipped roof garage.
59	13115 Broadstreet Avenue			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 13115 Broadstreet Avenue is two-stories and topped with a side gabled asphalt shingle roof intersected by a front gable. A brick chimney is located at the eave on the south facade. The exterior is clad in light brown brick veneer laid in a running bond pattern. The primary entrance is located near the north corner of the facade, beneath a front gabled overhang with brick supports that form an arched opening with cast stone keystone and springers. The entrance is accessed by a brick and concrete porch with a brick kneewall. South of the entrance are three hung windows with security bars beneath an aluminum metal awning, and three matching windows on the second floor. Similar windows are arranged on other elevations and windows have cast stone sills. A driveway runs along the north of the house to the rear where there is a pyramidal roof garage.
60	13120 Broadstreet Avenue			1927	French Eclectic	1/garage	C	Unknown	Unknown	The house at 13120 Broadstreet Avenue is two-stories and topped with a hipped asphalt shingle roof intersected by a front gabled central bay and a hipped roof dormer at the rear. Modillions accentuate the eave below the roofline. A brick chimney is located at the eave near the center of the south facade. The exterior is clad in brown and red brick veneer laid in a running bond pattern. The primary entrance features a quoined cast stone surround, accessed by a full width brick and concrete porch. A narrow window with cast stone sill is directly north of the door, beneath two small hung windows on the second floor above a dentilled cast stone belt course. North of the entrance is a canted bay with stone coping and tiles, with a picture window in the center flanked by two narrow hung windows. South of the entrance is a large window in a similar configuration. Slider windows are present on the second floor. Similar windows are arranged on other elevations, and windows have cast stone sills. There is a driveway running along the south of the house to the rear where there is a hipped roof garage.
61	13125 Broadstreet Avenue			1926	Georgian Revival	1/garage	C	Unknown	Unknown	The house at 13125 Broadstreet Avenue is two-stories and topped with a cross gable asphalt shingle roof composed of a side gable intersected by a hipped roof at the rear, with three gabled roof dormers on the front and a gabled roof dormer at the rear. A brick chimney is located at the peak of the eave on the south facade of the house. The exterior is clad in brown and red brick veneer laid in a running bond pattern. The primary entrance is centered on the symmetrical facade, beneath a portico with round wood columns and pilasters, and the door is surrounded by sidelights and a fanlight. The entrance is accessed by a full width brick and concrete porch with a metal railing. On either side of the entrance are two hung windows with divided upper sashes with cast stone sills and blue shutters, set directly beneath matching windows on the second floor. Similar windows are arranged on other elevations. A driveway runs along the south of the house to the rear where there is a hipped roof garage.
62	13133 Broadstreet Avenue			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 13133 Broadstreet Avenue is two-stories and topped with a deck, flat on hipped asphalt shingle roof intersected by a front gable and arched roof dormers clad in wood shingles on the front and north facades, with shed roof dormers clad in wood shingles on the south and rear. A brick chimney is located in the center of the house. The exterior is clad in brown brick veneer laid in a running bond pattern, with some decorative brickwork. The primary entrance is located near the south corner of the facade beneath a front gabled entrance vestibule and is accessed by a brick and concrete porch with metal railing. The segmental arched door is accented by decorative brick and stone and a small multi-light window on either side, directly beneath a hung multi-light window on the second floor. North of the entrance is a ribbon of four hung multi-light windows beneath a bay window on the second floor with four narrow hung multi-windows. Similar windows appear on other elevations. Windows have brick sills and aluminum storms affixed to the exterior. A driveway runs along the south of the house to the rear where there is a hipped roof garage.
63	13134 Broadstreet Avenue			1951	Tudor Revival	n/a	C	Unknown	Unknown	The house at 13134 Broadstreet Avenue is two-stories topped with a pyramidal asphalt shingle roof intersected by a gabled wall dormer on the front facade. A brick chimney is at the eave near the front of the north facade. The exterior is clad in red brick veneer laid in a running bond pattern with some decorative brickwork beneath the wall dormer. The primary entrance is trimmed in stone, near the south corner of the facade, and is accessed by a brick and concrete porch. North of the entrance is a vinyl picture window flanked by slider windows with divided sashes and two hung vinyl windows with divided sashes are on the second floor. Windows have stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the south side of the house to the rear, but there is no garage.
64	13144 Broadstreet Avenue			1923	French Eclectic	1/garage	C	Unknown	Unknown	The house at 13144 Broadstreet Avenue is two-stories topped with a gable-on-hip asphalt shingle roof intersected by a hipped roof at the rear, with a shed roof dormer at the south and rear facades. Modillions are found along the eave. A brick chimney is at the eave near the front of the south facade. The exterior is clad in red brick veneer laid in a running bond pattern at the first floor and wood clapboard siding painted white on the second floor. The primary entrance is near the north corner of the facade, and is accessed by a brick and concrete porch with metal railing. The door is arched and covered by an asphalt shingle awning with flared eaves, directly beneath an arched window at the second floor. There is a bay window south of the entrance which has a matching flared eave awning beneath three hung windows with shutters on the second floor, and these are covered by fabric awnings. Windows are wood casement or hung with multi-light sashes, with stone sills painted white on the first floor. Similar windows are arranged on other elevations. A concrete driveway is accessed off of Tyler Street north of the house and leads to a pyramidal roof garage at the rear.
65	13145 Broadstreet Avenue			1952	Modern Movement	1/garage	C	Unknown	Unknown	The house at 13145 Broadstreet Avenue is two-stories topped with a pyramidal asphalt shingle roof. A brick chimney is at the eave near the front of the south facade. The exterior is clad in red brick veneer laid in a running bond pattern, with some areas of vinyl siding painted white. The primary entrance is near the north corner of the facade, and is accessed by a brick and concrete porch. South of the entrance is a vinyl picture window with a slightly projecting one-story bay, and two vinyl windows are on the second floor. Windows have stone sills. Similar windows are arranged on other elevations. A concrete driveway is accessed off of Tyler Street to the north of the house leading to a pyramidal roof garage at the rear.
66	13204 Broadstreet Avenue			1935	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 13204 Broadstreet Avenue is two-stories topped with a cross gable asphalt shingle roof composed of a side gable with a hipped roof at the rear. A brick chimney is at the eave centered on the south facade. The exterior is clad in red brick veneer laid in a running bond pattern. The primary entrance is near the north corner of the facade flanked in sidelights and covered by a cantilevered gabled awning, and is accessed by a small brick and concrete porch. South of the entrance are three six-over-six wood hung windows with black shutters and brick sills, beneath matching windows on the second floor. Similar windows are arranged on other elevations. On the south facade there is a bay window at the first floor. A concrete driveway is accessed off of Tyler Street to the south of the house leading to a pyramidal roof garage at the rear.
67	13205 Broadstreet Avenue			1928	Tudor Revival	1/garage	C	M. Martin	Unknown	The house at 13205 Broadstreet Avenue is two-stories topped with a cross gable asphalt shingle roof composed of multiple intersecting side and front gables with a hipped roof at the rear. A brick chimney is located near the center of the house. The exterior is clad in red, brown, and orange brick veneer laid in a running bond pattern with stone accents, and hexagonal shingles beneath some of the prominent gables. The primary entrance is near the center of the facade, and is accessed by a stone and concrete porch beneath a cross gabled awning supported by stone-clad piers. North of the entrance a stone buttress extends from the corner. Windows appear to be hung with aluminum storms and brick sills, though the facade is obstructed by vegetation. A two story balcony extends from the rear of the house, screened in on the first floor but open on the second. A concrete driveway is accessed off of Tyler Street to the south of the house leading to a garage at the rear.
68	13212 Broadstreet Avenue			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 13212 Broadstreet Avenue is two-stories topped with a pyramidal asphalt shingle roof intersected by a front gable and a gabled roof dormer at the rear. A brick chimney is located at the eave on the north facade of the house. The exterior is clad in red and brown brick veneer laid in a running bond pattern with stone accents. The primary entrance is near the south corner, beneath a front gabled awning supported by brick piers with an arched opening, and accessed by a stone and concrete porch. North of the entrance is a set of wood hung six-over-six windows, beneath three matching windows on the second floor. Similar windows are arranged on other elevations. A concrete ribbon driveway runs along the south of the house leading to a pyramidal roof garage at the rear.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
69	13213 Broadstreet Avenue			1962	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 13213 Broadstreet Avenue is a two story side gabled house clad in red brick on the first floor and wide white aluminum siding on the second floor, which overhangs slightly creating a Garrison Colonial type of style. The main entrance is near the south corner of the house and is accessed by a brick and concrete stoop, with white shutters on either side of the door. There is a sliding window north of the entrance, also with white shutters. There are two additional sliding windows on the second floor. A concrete driveway runs along the south of the house to the rear where there is a pyramidal roof garage.
70	13220 Broadstreet Avenue			1928	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 13220 Broadstreet Avenue is two-stories topped with a pyramidal asphalt shingle roof intersected by two front gables and a hipped roof dormer at the south. A tall brick chimney is located at the eave on the north facade of the house. The exterior is clad in reddish brown brick veneer laid in a running bond pattern with accents of decorative brickwork and stone. The primary entrance is centered on the facade, within a front gabled projecting vestibule and accessed by a brick and concrete porch. The facade is glazed with wood hung windows, some with divided upper sashes, and cast stone sills painted red. On the first floor, the entrance and windows are topped with splayed brick lintels, and windows on the second floor of the primary facade have scallop trimmed awnings. A concrete ribbon driveway runs along the south of the house leading to a pyramidal roof garage at the rear.
71	13232 Broadstreet Avenue			1961	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 13232 Broadstreet Avenue is a two story side gabled house clad in red brick. The main entrance is near the south corner of the house and is accessed by a brick and concrete stoop with metal railing, with white shutters on either side of the door. There is a sliding window north of the entrance, also with white shutters. There are three additional sliding windows on the second floor, with stone sills. A concrete driveway runs along the south of the house to the rear where there is a pyramidal roof garage.
72	13233 Broadstreet Avenue			1953	Ranch	n/a	C	Unknown	Unknown	The house at 13233 Broadstreet Avenue is a one story, hipped roof house clad in red brick laid in a running bond pattern and stone veneer. The main entrance is off center on the facade and is accessed by a low concrete stoop. North of the entrance is a large picture window with steel casement multi-pane sidelights, a smaller version of this configuration is south of the entrance. Both have stone sills. A concrete driveway runs along the south of the property to an attached garage.
73	13240 Broadstreet Avenue			1935	Georgian Revival	1/garage	C	Unknown	Unknown	The house at 13240 Broadstreet Avenue is two-stories topped with a side gable asphalt shingle roof with dentils along the cornice line. A brick chimney is at the eave near the front of the house on the south facade. The exterior is clad in red and brown brick veneer laid in a running bond pattern with a soldier course between the first and second floors and some sections set proud at the corners to create a quoined appearance. The primary entrance is near the north corner of the facade, trimmed with pilasters and flanked in sidelights with fanlight above, and covered by a cantilevered awning. The support columns and porch have been removed. South of the entrance are two wood hung windows with black shutters, brick lintels with keystones, and brick sills, beneath matching windows on the second floor. Similar windows are arranged on other elevations. A concrete driveway is accessed off of Waverly Street to the north of the house leading to the rear, but there is no garage.
74	13304 Broadstreet Avenue			1937	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 13304 Broadstreet Avenue is a two stories with a hipped roof intersected by two front gables. The house clad in red brick laid in a running bond pattern and stone quoins trim around the door. The main entrance is at the south corner of the facade and is accessed by a brick and concrete porch. Windows and door openings have been boarded over. North of the entrance is a projecting two story bay that is canted on the first floor. A concrete driveway is accessed to the south off of Waverly Street and leads to a garage at the rear.
75	13314 Broadstreet Avenue			1922	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 13314 Broadstreet Avenue is a two stories with a hipped roof intersected by a prominent front gable with wood shingle siding, and a hipped roof dormer clad in wood shingles on the south. The siding has been removed from the house which is under complete renovation. The main entrance is off-center towards the south corner of the facade and is accessed by a brick and concrete porch. The entrance is beneath an asphalt shingled awning with a front gabled portion with decorative brackets above the door. Windows appear to be a mix of vinyl and wood, with a large picture window just north of the entrance and other windows on the facade are hung. A concrete ribbon driveway runs along the south of the house.
76	13320 Broadstreet Avenue		not listed		Tudor Revival	1/garage	C	Unknown	Unknown	The house at 13314 Broadstreet Avenue is a two stories with a side gable roof intersected by a prominent front gable and a front gabled wall dormer above a door to a balcony above the entrance. The siding has been removed from the house which is under complete renovation. The main entrance is off-center towards the south corner of the facade and is accessed by a full width brick and concrete porch with wood railing. Windows present are vinyl and hung, however most window openings have been boarded over. A concrete driveway runs along the south of the house.
77	3727 Buena Vista Street			1964	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 3727 Buena Vista is two-stories and topped with a side gable asphalt shingle roof. The exterior is clad in red brick veneer laid in a running bond pattern. The primary entrance is set to the side of the primary facade, and is accessed by a concrete stoop porch and topped with an aluminum awning supported by metal posts. A vinyl sliding picture window is set beside the entrance and two vinyl windows are on the second floor. The area of the second floor above the awning over the porch is clad in white vinyl siding and the spandrel between the first floor picture window and the second floor window above it is also clad in white vinyl siding. Similar windows are arranged on other elevations. A concrete driveway runs along the side of the house leading to a front gabled garage.
78	3734 Buena Vista Street			1952	Tudor Revival		C	Unknown	Unknown	The duplex at 3734 Buena Vista is a two story Tudor Revival style house with a primary entrance set to the side of the primary facade. A large picture window flanked by hung windows is located beside the door with the same unit (picture window with hung units beside it) set above it on the second floor as well. The primary entrance is accessed by a brick stoop. A six light glass block window is set beside the primary entrance. The primary entrance is trim in stone. A six light glass block window is located above the door on the primary facade. There is a brick chimney on the side facade and a concrete driveway on the opposite side facade. Windows arranged on the secondary facades mirror each other on the first and second floors. There is no garage.
79	3735 Buena Vista Street			1960	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 3735 Buena Vista is two-stories and topped with a side gable asphalt shingle roof. The exterior is clad in red brick veneer laid in a running bond pattern on the first floor of the primary facade and on the secondary facades. The primary entrance is set to the side of the primary facade, and is accessed by a brick stoop porch and topped with an aluminum awning supported by metal posts. A vinyl picture window is set beside the entrance and three vinyl windows are on the second floor. The area of the second floor of the primary facades is clad in white vinyl siding. The first floor window on the primary facade has an aluminum awning with scalloped trim that matches the awning over the stoop. Similar windows are arranged on other elevations. A concrete driveway runs along the side of the house leading to a two car garage with a pyramidal roof.
80	3743 Buena Vista Street			1961	Colonial Revival		C	Unknown	Unknown	The house at 3743 Buena Vista is two-stories and topped with a side gable asphalt shingle roof. There is a brick chimney on the side facade. The exterior is clad in red brick veneer laid in a running bond pattern. The primary entrance is set to the side of the primary facade, and is accessed by a brick stoop porch and topped with a salmon pink aluminum awning supported by metal posts. A vinyl sliding picture window is set beside the entrance and two vinyl windows are on the second floor. The windows have stone sills. The first floor window on the primary facade has a salmon pink aluminum awning with scalloped trim that matches the awning over the stoop. Similar windows are arranged on other elevations. A concrete driveway runs along the side of the house and there is no garage.
81	3744 Buena Vista Street			1961	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 3744 Buena Vista is two-stories and topped with a side gable asphalt shingle roof. The exterior is clad in red brick veneer laid in a running bond pattern and the first floor of the facade is inset so as to create a Garrison Colonial type of facade. The primary entrance is set within the inset, to the side of the primary facade, and is accessed by a cast stone stoop porch. Above the inset first floor there are two metal panels with a diamond pattern that wrap under the inset to cover the soffit. A vinyl picture window is set beside the entrance and two vinyl windows are on the second floor. The windows on the primary facade have white vinyl shutters. Similar windows are arranged on other elevations. A concrete driveway runs along the side of the house leading to a two car garage with a front gabled roof. A globe style stick light is located on the front lawn.
82	3750 Buena Vista Street			1961	Colonial Revival		C	Unknown	Unknown	The house at 3750 Buena Vista is two-stories and topped with a side gable asphalt shingle roof. The exterior is clad in red brick veneer laid in a running bond pattern. The primary entrance is set to the side of the primary facade, and is accessed by a brick stoop porch and topped with an aluminum awning with scalloped trim, supported by metal posts--the awning covers the stoop porch and the majority of the first floor of the primary facade including the picture window which is set beside the entrance. There are three vinyl slider windows are on the second floor. The windows and the entrance door on the primary facade have black vinyl shutters. Similar windows are arranged on other elevations. A concrete driveway runs along the side of the house leading and there is no garage.
83	3751 Buena Vista Street			1930	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3751 Buena Vista is two-stories and topped with a side gable asphalt shingle roof intersected by a front gable with a half-hipped roof at the rear. A brick chimney is near the center of the house on the primary facade and the chimney piece juts above the side gabled roof on the primary facade. The house is clad in red and orange brick with accents of cast stone and decorative brickwork. The primary entrance juts out from the plane of the house and is set to the side of the primary facade--it has a flat roof which creates a porch above. The porch above is accessed by a door and is covered with a scalloped trim aluminum awning. There is a scalloped trim aluminum awning also found at the first floor, covering the large window set next to the primary entrance. A casement window is located on the second floor in the front facing gable. Both the first floor and second floor casement windows have stone and brick trimwork and are fitted with aluminum storms. Similar windows are arranged on other elevations. A concrete driveway runs along the side of the house. There is a side gabled two car garage behind the house.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
84	3760 Buena Vista Street			1940	Tudor Revival	1/garage	C	Unknown	Samuel Aiken	The house at 3760 Buena Vista Street is two-stories and topped with a hipped asphalt shingle roof intersected by a front gabled pediment that covers a porch on the second floor and the entrance below, on the first floor. A brick chimney is set on the secondary facade. The exterior is clad in brown brick veneer laid in a running bond pattern with accents of cast stone and decorative brickwork. The primary entrance has a classically styled brick surround with fluted, engaged columns and the entrance is set to the side of the primary facade. On either side of the main entrance door is a small stained glass window with a stone surround. Above the entrance there is an open balcony porch with arched openings which covers the second floor porch balcony and is topped with a front facing gable roof. The upper porch balcony has a metal railing. A two story bay window is set next to the main entrance and contains steel casement windows at the first and second floor. Windows and openings have cast stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the west side of the property ending at a two car garage. A black lightpost with a globe style fixture is near the center of the front lawn.
85	3761 Buena Vista Street			1930	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3761 Buena Vista is two-stories and topped with a side gabled roof intersected by a parapet wall that rises slightly above the gabled roof eave on the primary facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of cast stone. The primary entrance is set in a slightly projecting room off the front facade which creates a porch above. The porch above is covered in an aluminum awning. There is also a stoop porch on the first floor with a small aluminum awning covering a portion of the porch. A single-story bay containing steel casement windows is set beside the main entrance and a steel casement window is set above it on the second floor. An aluminum awning covers the second floor window. Windows and openings have cast stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the side of the property. There is a pyramidal roofed two car garage behind the house.
86	3766 Buena Vista Street			1962	Ranch	1/garage	C	Unknown	Unknown	The house at 3766 Buena Vista is a Ranch style split level house with a front gabled roof which is clad in asphalt shingles. The house has a primary entrance door offset on the facade which is covered with a projecting two story pediment supported by thin white vinyl columns. The is a black iron railing on the porch. Two vinyl sliding windows are set at grade (first floor) and on the second floor on the primary facade. Vinyl sliding windows are also found on the secondary facades. A black lightpost with globe style fixture is found in the front yard. The concrete driveway leads to a two car front gabled garage set behind the house.
87	3767 Buena Vista Street			1937	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3767 Buena Vista is a two story hipped roof house with a front facing gable attached to the main hip roof. The house is primarily clad in dark red brick with stone trim. The primary facade features a one story stone clad entrance vestibule with an open porch above. The door is a Gothic arched unit with a stone surround. The porch above has a green fabric awning with decorative cast iron supports with a cast iron railing. There is a two story bay window on the primary facade, set next to the primary entrance. This bay features leaded glass windows with aluminum storms at both the first and second floor. The first floor porch spans the whole facade and has a green cast iron railing and a green fabric awning over the west side of the porch. The awning has decorative cast iron finals at the end of each support post. There is a two car garage set behind the house with a hipped roof.
88	3774 Buena Vista Street			1940	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3774 Buena Vista is a two story hipped roof house with a half-hexagonal roof attached to the main hip roof which covers a two story bay window on the primary facade. The house is primarily clad in dark red brick with stone trim. The primary facade features a one story brick and stone clad entrance vestibule with an open porch above. The door is a Gothic arched unit with a stone surround. The porch above has a green fabric awning with decorative cast iron supports with a cast iron railing. There is a two story bay window on the primary facade, set next to the primary entrance. This bay features leaded glass windows with aluminum storms at both the first and second floor. The first floor porch spans the whole facade and has a green cast iron railing and a green fabric awning over the west side of the porch. The awning has decorative cast iron finals at the end of each support post. There is a two car garage set behind the house with a hipped roof. There is a black lightpost with glob style fixture in the front yard.
89	3777 Buena Vista Street			1963	Contemporary		C	Unknown	Unknown	The house at 3777 Buena Vista is a two story house with a side gabled roof that is covered in asphalt shingles. The house is clad in blonde brick, multi-colored stone, and vertical wood siding. The primary facade is offset on the front facade and is covered with a flat roof one story porch that covers the small concrete and brick porch. The porch roof is supported by white cast iron posts with an elaborate leaf design. The door has a matching cast iron security door also with a leaf design. There is one large sliding window set beside the main door on the first floor and two smaller sliding windows on the second floor. A spandrel panel of vertical wood siding spans from the second floor window above the entrance door down to the entrance door and another spandrel panel of vertical wood spans from the first floor window to the second floor window above. An accent of colored stone runs from the eave to grade at the mid point of the primary facade. A black lightpost with no globe is located in the center of the front lawn. There is a concrete driveway behind the house.
90	3782 Buena Vista Street			1938	Tudor Revival		C	Unknown	Unknown	The house at 3782 Buena Vista is a two story hipped roof duplex with a half-hexagonal roof attached to the main hip roof which covers a two story bay window on the primary facade and a small front facing dormer gable that covers a second floor door onto an upper balcony. The house is primarily clad in dark red brick with stone trim. The primary facade features a one story brick clad entrance vestibule with an open balcony porch above. The door is centered in the projecting vestibule and has a stone surround. The porch above has a cast iron railing set between two low brick pillars that extend up from the vestibule wall below and wrap the corners of the balcony to form the balcony knee wall. There is a two story bay window on the primary facade, set next to the primary entrance. This bay features steel casement windows with aluminum storms at both the first and second floor. The first floor porch spans the whole facade and has a cast iron railing around it. There is no garage.
91	3783 Buena Vista Street			1938	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3783 Buena Vista Street is two-stories and topped with a hipped asphalt shingle roof intersected by a front gabled pediment that covers a porch on the second floor and the entrance below, on the first floor. There is a two story bay window on the primary facade and a half-hexagonal roof that intersects the hipped roof as well. A brick chimney is set on the secondary facade. The exterior is clad in brown brick veneer laid in a running bond pattern with accents of cast stone and decorative brickwork. The primary entrance has an arch headed door with a stone surround. On either side of the main entrance door is a small stained glass window with a stone surround. The stone is painted white. Above the entrance there is an open balcony porch with arched openings which covers the second floor porch balcony and is topped with a front facing gable roof. The upper porch is screened in and the upper porch balcony has a metal railing. A two story bay window is set next to the main entrance and contains leaded glass casement windows at the first and second floor. Windows and openings have cast stone sills. Steel casement windows are arranged on other elevations. A concrete driveway runs along the west side of the property ending at a two car garage. The porch has the cast iron frame for an awning but there is no awning installed. The cast iron framework has decorative finals.
92	3790 Buena Vista Street			1961	Contemporary	1/garage	C	Unknown	Unknown	The house at 3790 Buena Vista is two-stories and topped with a side gable asphalt shingle roof. The exterior is clad in red brick veneer laid in a running bond pattern and the first floor of the facade is inset so as to create a Garrison Colonial type of facade. The primary entrance is set within the inset, to the side of the primary facade, and is accessed by a cast stone stoop porch. Above the inset first floor there is a metal fascia panels that wraps under the inset to cover the soffit. A vinyl window is set beside the entrance and two vinyl windows are on the second floor—one slightly larger than the other. The windows on the primary facade have black vinyl shutters. Similar windows are arranged on other elevations. A concrete driveway runs along the side of the house leading to a two car garage with a pyramidal roof.
93	3791 Buena Vista Street			1937	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3791 Buena Vista Street is two-stories and topped with a hipped asphalt shingle roof intersected by a half-hexagonal tower that covers a porch on the second floor and the entrance below, on the first floor. There is a one story bay window on the primary facade and above it, on the second floor, there is an eyebrow dormer that intersects the hipped roof as well. A brick chimney is set on the secondary facade. The exterior is clad in brown brick veneer laid in a running bond pattern with accents of cast stone and decorative brickwork. The primary entrance is set in the half-hexagonal tower and it has an arch headed door with a stone surround. On either side of the main entrance door is a small stained glass window with a stone surround. Above the entrance there is an open balcony porch with an arched opening above the main door while the two other openings on the upper balcony porch have flat headed openings. The upper porch is screened in and each of the openings on the upper porch balcony has a metal railing. A one story bay window is set next to the main entrance and contains leaded glass casement windows and there is another leaded glass casement window above it on the second floor. Windows and openings have cast stone sills and there is copious stone trim on the primary facade. Steel casement windows are arranged on other elevations. A concrete driveway runs along the west side of the property ending at a two car garage. The porch has the cast iron frame for an awning but there is no awning installed. The cast iron framework has decorative finals.
94	3799 Buena Vista Street			1937	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3799 Buena Vista is a two story side gabled and hipped roof house with two front facing gables attached to the main, side gabled roof. One front facing gable is placed over the second floor balcony door and one is placed beside it and that gable is elongated on one end. The house is primarily clad in red brick with stone trim. The primary facade features a one story stone and brick clad entrance vestibule with an open porch above. The door is a Gothic arched unit with a stone surround. The porch above has a cast iron frame for a fabric awning with decorative cast iron supports with a cast iron railing—there is no fabric awning installed. There is a one story bay window on the primary facade, set next to the primary entrance. This bay features leaded glass windows and there is a leaded glass casement window above it on the second floor, set under a front gabled wall dormer. The first floor porch spans the whole facade and has a cream colored cast iron railing and a frame for a fabric awning that is not currently installed. The awning has decorative cast iron supports and the awning frame and porch railing are painted cream. There is a two car garage set behind the house with a hipped roof.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
95	3800 Buena Vista Street			1939	Tudor Revival		C	Unknown	Unknown	The house at 3800 Buena Vista Street is two-stories and topped with a hipped asphalt shingle roof intersected by a half-hexagonal tower that covers a porch on the second floor and the entrance below, on the first floor. There is a two story bay window on the primary facade topped with a half-hexagonal roof that intersects the main hipped roof. A brick chimney is set on the secondary facade. The exterior is clad in brown and red brick veneer laid in a running bond pattern with accents of cast stone. The primary entrance is set in the half-hexagonal tower and it has a primary entrance door trimmed in stone. On either side of the main entrance door is a small stained glass window with a stone sill. Above the entrance there is an open balcony porch with three openings, trimmed in stone. The upper porch is screened in and each of the openings on the upper porch balcony has a metal railing. The two story bay window is set next to the main entrance and contains leaded glass casement windows on the first and the second floor. Windows and openings have cast stone sills and there is copious stone trim on the primary facade. Steel casement windows are arranged on other elevations. A concrete driveway runs along the side of the property.
96	3805 Buena Vista Street			1940	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3805 Buena Vista Street is two-stories and topped with a hipped asphalt shingle roof intersected by a half-hexagonal tower that covers a porch on the second floor and the entrance below, on the first floor. There is a one story bay window on the primary facade and above it, on the second floor, there is an eyebrow dormer that intersects the hipped roof as well. A brick chimney is set on the secondary facade. The exterior is clad in brown brick veneer laid in a running bond pattern with accents of cast stone. The primary entrance is set in the half-hexagonal tower and it has a main door trimmed with a stone surround. On either side of the main entrance door is a small glass block window with a stone sill. Above the entrance there is an open balcony porch with three arched openings—one on each side of the half-hexagonal tower. Each opening on the upper porch balcony has a metal railing. A one story bay window is set next to the main entrance and contains steel casement windows and there is another steel casement window above it on the second floor. The first floor bay is clad in stone and stone trim. Windows and openings have cast stone sills and there is copious stone trim on the primary facade. Steel casement windows are arranged on other elevations. A concrete driveway runs along the side of the property ending at a two car garage. The porch has the cast iron frame for an awning but there is no awning installed.
97	3806 Buena Vista Street			1939	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3806 Buena Vista is a two story hipped roof duplex with a half-hexagonal roof attached to the main hip roof which covers a two story bay window on the primary facade and a small front facing dormer gable that covers a second floor door onto an upper balcony. The house is primarily clad in dark red brick with stone trim. The primary facade features a one story brick clad entrance vestibule with an open balcony porch above. The door is centered in the projecting vestibule and has a stone surround. The porch above has a cast iron railing set between two low brick pillars that extend up from the vestibule wall below and wrap the corners of the balcony to form the balcony knee wall. There is a two story bay window on the primary facade, set next to the primary entrance. This bay features steel casement windows with leaded glass panes and aluminum storms at both the first and second floor. The first floor porch spans the whole facade and has a cast iron railing around it. There is an aluminum awning with scalloped trim over the first floor porch and the upper balcony porch. There is a front gabled two car garage behind the house.
98	3813 Buena Vista Street			1937	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3813 Buena Vista Street is two-stories and topped with a hipped asphalt shingle roof intersected by a half-hexagonal tower. The main entrance is located in the half-hexagonal tower. There is a one story bay window on the primary facade topped with a wrought iron railing at the top. A brick chimney is set on the secondary facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of cast stone and decorative brickwork. The primary entrance is set in the half-hexagonal tower and it has a primary entrance door trimmed in stone. On either side of the main entrance door is a small glass block window with a stone surround and sill. Above the entrance there are three vinyl windows, one on each side of the half-hex tower, trimmed in stone. The one story bay window is set next to the main entrance and contains steel casement windows with leaded glass transoms on the first and the second floor. Windows and openings have cast stone sills and the first floor bay is clad in stone. Steel casement windows are arranged on other elevations. A concrete driveway runs along the side of the property leading to a two car garage.
99	3814 Buena Vista Street			1938	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3814 Buena Vista is two-stories and topped with a hipped asphalt shingle roof intersected by a front gable on the primary facade and a half-hipped roof at the rear. A brick chimney is set on the side facade. The house is clad in red and brown brick with accents of cast stone and decorative brickwork. The primary entrance juts out from the plane of the house and is set to the side of the primary facade—it has a flat roof which creates a porch above. The porch above is accessed by a door and the porch above is covered with a scalloped trim aluminum awning. The primary entrance is trimmed in stone and there is one small leaded glass window on each side of the door. There is a one story porch on the primary facade. There is a scalloped trim aluminum awning also found at the first floor, covering a large, one story bay window set next to the primary entrance. A casement window is located on the second floor in the front facing gable. The second floor casement window has stone and brick trimwork. Similar windows are arranged on other elevations. A concrete driveway runs along the side of the house. There is a hipped roof, two car garage behind the house.
100	3823 Buena Vista Street			1937	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3823 Buena Vista Street is two-stories and topped with a hipped asphalt shingle roof intersected by a half-hexagonal tower that covers a porch on the second floor and the entrance below, on the first floor. There is a set of three hung windows on the primary facade, set next to the door and another three hung windows above it on the second floor of the primary facade. Above the second floor window there is a slightly extended half-hipped dormer that intersects the main hipped roof as well. A brick chimney is set on the secondary facade. The exterior is clad in brown brick veneer laid in a running bond pattern with accents of cast stone. The primary entrance is set in the half-hexagonal tower and it has a main door trimmed with a stone surround. On either side of the main entrance door is a small leaded glass window with a stone sill. Above the entrance there is an open balcony porch with three arched openings—one on each side of the half-hexagonal tower. Each opening on the upper porch balcony has a metal railing. Windows and openings have cast stone sills. Steel casement windows are arranged on other elevations. A concrete driveway runs along the side of the property ending at a two car garage. The porch has the cast iron frame for an awning but there is no awning installed.
101	3824 Buena Vista Street			1938	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3824 Buena Vista is a two story hipped roof house with a half-hexagonal roof attached to the main hip roof which covers a two story bay window on the primary facade and a small front facing dormer gable that covers a second floor door onto an upper balcony. The house is primarily clad in dark red brick with stone trim. The primary facade features a one story brick clad entrance vestibule with an open balcony porch above. The door is centered in the projecting vestibule and has a stone surround. The porch above has a cast iron railing and is covered by a green aluminum awning with metal posts. There is a two story bay window on the primary facade, set next to the primary entrance. This bay features steel casement windows with leaded glass transoms. There is a one story porch that spans the width of the facade that has an aluminum railing. The first floor porch spans the whole facade and has a cast iron railing around it. There is a two car garage with a front gabled roof located behind the house.
102	3830 Buena Vista Street			1939	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3830 Buena Vista is a two story hipped roof house with a half-hexagonal roof attached to the main hip roof which covers a two story bay window on the primary facade and a small front facing dormer gable that covers a second floor door onto an upper balcony. The house is primarily clad in dark red brick with stone trim. The primary facade features a one story brick clad entrance vestibule with an open balcony porch above. The door is centered in the projecting vestibule and has a stone surround. The porch above has a cast iron railing set between two low brick pillars that extend up from the vestibule wall below and wrap the corners of the balcony to form the balcony knee wall. There is a two story bay window on the primary facade, set next to the primary entrance. This bay features leaded glass windows with aluminum storms at both the first and second floor. The first floor porch spans the whole facade and has a cast iron railing around it. There is a two car garage behind the house.
103	3831 Buena Vista Street			1960	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 3831 Buena Vista is a two story side gabled house clad in red brick and wide white aluminum siding. The first floor is clad in brick while the second floor is clad in siding. The two secondary facades are clad in brick. The main entrance door is offset on the primary facade and is covered with a scalloped trim aluminum awning. There is a sliding window set beside the main door and it is also covered with a scalloped trim aluminum awning. There are three small windows evenly spaced on the second floor and these units have simulated diamond lite panes. There is a low stoop porch. The aluminum awning over the door is supported by wrought iron columns. The second floor slightly overhangs the first floor creating a Garrison Colonial type of style.
104	3840 Buena Vista Street			1940	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3840 Buena Vista Street is two-stories and topped with a hipped asphalt shingle roof intersected by a front gabled pediment that covers a porch on the second floor and the entrance below, on the first floor. A brick chimney is set on the secondary facade. The exterior is clad in brown brick veneer laid in a running bond pattern with accents of cast stone and decorative brickwork. The primary entrance is set to the side of the primary facade and is trimmed in stone. The protruding entrance and upper balcony bay has stone quoins along the edge. On either side of the main entrance door is a small leaded glass window with a stone surround. Above the entrance there is an open balcony porch with arched openings which covers the second floor porch balcony and is topped with a front facing gable roof. The upper porch balcony has a metal railing. A two story bay window is set next to the main entrance and contains steel casement windows at the first and second floor. The bay window is clad in stone. There is a full width porch on the primary facade a portion of which is covered with an aluminum awning. Windows and openings have cast stone sills. Similar windows are arranged on other elevations. The house sits on a corner and there is a two car garage behind the house. A lightpost with no globe is set near the center of the front lawn.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
105	3841 Buena Vista Street			1940	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3841 Buena Vista Street is two-stories and topped with a hipped asphalt shingle roof intersected by a half-hexagonal tower. The main entrance is located in the half-hexagonal tower. A brick chimney is set prominently on the primary facade and is flanked with steel casement windows on both the first and second floor. The exterior of the house is clad in red brick veneer laid in a running bond pattern with accents of cast stone and decorative brickwork. The primary entrance is set in the half-hexagonal tower and it has a primary entrance door trimmed in stone. On one side of the main entrance door is a small leaded glass window with a stone sill. Above the entrance there are three black vinyl windows, one on each side of the half-hex tower. Windows and openings have cast stone sills and the first floor windows have large stone headers/hoods. Steel casement windows are arranged on other elevations. The house is set on a corner and there is a garage behind the house. A lightpost is centered on the front lawn and it has a globe light fixture.
106	4002 Buena Vista Street			1941	Tudor Revival		C	Unknown	Unknown	The house at 4002 Buena Vista is a two story hipped roof house with a crenelated two story bay window attached to the main hip roof--the crenelated bay covers a two story bay window on the primary facade and there is a small front facing dormer gable that covers a second floor door onto an upper balcony. The house is primarily clad in dark red brick with stone trim. The primary facade features a one story brick clad entrance vestibule with an open balcony porch above. The door is arch headed and centered in the projecting vestibule and has a stone surround. The porch above has a cast iron railing set between two low brick pillars that extend up from the vestibule wall below and wrap the corners of the balcony to form the balcony knee wall. There is a two story bay window on the primary facade, set next to the primary entrance. This bay features leaded glass windows with aluminum storms at both the first and second floor. The first floor porch spans the whole facade and is covered with a red aluminum awning. There is no garage.
107	4003 Buena Vista Street			1937	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4003 Buena Vista is a two story house with a side gabled roof at the front and a half hipped roof at the back. The front facade also features a prominent front gable that intersects the main side gabled roof. The entrance is centered on a projecting vestibule bay with a knee wall above for the upper porch. The upper porch has been enclosed with vinyl sliding windows. The first floor of the projecting vestibule bay is clad in stone and stone trim is prominent on the primary facade. The prominent front gable has a first floor bay window and a second floor set of three hung windows nestled under the large front gable. The porch spans the full width of the house and is not covered and has a decorative wrought iron railing painted white. The house sits on a corner and there is a two car garage behind the house.
108	4012 Buena Vista Street			1942	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4012 Buena Vista Street is two-stories and topped with a hipped asphalt shingle roof intersected by a front gabled pediment that covers a porch on the second floor and the entrance below, on the first floor. A brick chimney is set on the secondary facade. The exterior is clad in brown brick veneer laid in a running bond pattern with accents of cast stone and decorative brickwork. The primary entrance has an arch headed Gothic style door with stone surround and the entrance is set to the side of the primary facade. On either side of the main entrance door is a small stained glass window with a stone surround. Above the entrance there is an open balcony porch with arched openings which covers the second floor porch balcony and is topped with a front facing gable roof. The upper porch balcony has a metal railing. A two story bay window is set next to the main entrance and contains steel casement windows at the first and second floor. Windows and openings have cast stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the west side of the property ending at a two car garage. A black lightpost with no globe is near the center of the front lawn.
109	4015 Buena Vista Street			1952	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4015 Buena Vista Street is a two story house with a hipped roof covered in asphalt shingles. The house has a shallow two story bay window on the primary facade that intersects the main hipped roof with a half-hexagonal roof. There is a small pediment above the upper balcony entrance door on the primary facade as well. The main entrance vestibule projects from the facade and creates a small upper balcony which has a brick knee wall around it. The two story bay has stone trim around the windows and the upper and lower large center window is a fixed unit while the two side units, on both the upper and lower level, are steel casements. The door is centered on the projecting vestibule bay and it has a classical stone surround and a glass block window on each side. There is a brick chimney on the side facade and a concrete driveway leads to a two car garage behind the house.
110	4020 Buena Vista Street			1940	Modern Movement	1/garage	C	Unknown	Unknown	The house at 4020 Buena Vista Street is a two story house with a hipped roof covered in asphalt shingles. The house has a shallow two story bay window on the primary facade that intersects the main hipped roof with a half-hexagonal roof. There is a rounded, projecting entrance vestibule that projects from the facade and creates a small upper balcony which has a rounded brick knee wall around it. The two story bay has stone trim around the windows and the upper and lower large center window is a fixed unit while the two side units, on both the upper and lower level, are vinyl hung units. The door is centered on the projecting vestibule bay and it has a classical stone surround and a glass block window on each side. The upper balcony above the main entrance is covered with an aluminum awning. There is a brick chimney on the side facade and a concrete driveway leads to a two car garage behind the house. The rounded elements give a Modern Movement (Moderne) stylistic feel to a transitional house with some Tudor Revival elements.
111	4023 Buena Vista Street			1940	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4023 Buena Vista is a two story hipped roof house with a half-hexagonal conical roof attached to the main hip roof which covers a two story bay window on the primary facade and a small front facing dormer gable that covers a second floor door onto an upper balcony. The house is primarily clad in dark red brick with stone trim. The primary facade features a one story brick clad entrance vestibule with an open balcony porch above. The open balcony porch door on the second floor is topped with a stepped crenelated parapet. The primary door on the first floor is centered in the projecting vestibule and has a stone surround with classical fluted, engaged columns. The porch above has a cast iron railing set between two low brick pillars that extend up from the vestibule wall below and wrap the corners of the balcony to form the balcony knee wall. There is a two story bay window on the primary facade, set next to the primary entrance. This bay features a fixed center pane on each floor with a vinyl hung unit on either side on both the upper and lower floor. The first floor porch spans the whole facade and has a cast iron railing around it and a frame for a fabric awning (with decorative finials) but no awning is installed. There is a two car garage behind the house.
112	4028 Buena Vista Street			1947	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 4028 Buena Vista is a two story, red brick clad house with a hipped roof that is covered in asphalt shingles. The primary facade has a two story, slightly projecting, squared bay. There is one fixed window flanked by a hung window at both the first and second floor of the projecting bay. The entrance is offset on the primary facade and is trimmed in stone. Set beside the main entrance is a paired set of hung, six over six units. Above the entrance, at the second floor is a set of two vinyl storm windows enclosing a small upper porch. There is another set of paired, six over six windows directly above the units on the first floor. A small pent roof covers the main entrance at the first floor. A black lightpost with a lantern style fixture is centered on the front lawn. There is a garage behind the house.
113	4031 Buena Vista Street			1940	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4031 Buena Vista Street is two-stories and topped with a hipped asphalt shingle roof intersected by a half-hexagonal tower that covers a porch on the second floor and the entrance below, on the first floor. There is a crenelated two story bay window attached to the main hip roof--the crenelated bay covers a two story bay window on the primary facade. A brick chimney is set on the secondary facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of cast stone and decorative brickwork. The primary entrance is set in the half-hexagonal tower and it has an arch headed door with a stone surround. On either side of the main entrance door is a small stained glass window with a stone surround. Above the entrance there is an open balcony porch with an arched opening above the main door while the two other openings on the upper balcony porch have flat headed openings. The upper porch has a metal railing in the arch opening while the other two openings have brick knee walls. The two story bay window is set next to the main entrance and contains steel casement windows at the first and second levels. Windows and openings have cast stone sills and stone trim on the primary facade. Steel casement windows are arranged on other elevations. A concrete driveway runs along the west side of the property ending at a two car garage. The porch has the cast iron frame for an awning but there is no awning installed. The cast iron framework has decorative finials.
114	4039 Buena Vista Street			1955	Modern Movement		C	Unknown	Unknown	The house at 4039 Buena Vista Street is a two story house with a hipped roof covered in asphalt shingles. The house has a shallow two story bay window on the primary facade that intersects the main hipped roof with a half-hexagonal roof. There is a slightly projecting entrance vestibule that projects from the facade covered by a half-hipped pent roof with a fairly deep eave overhang. The two story bay has stone trim around the windows and the upper and lower large center window is a fixed unit while the two side units, on both the upper and lower level, are steel casement units. The door is centered on the projecting vestibule bay and the projecting bay is clad in pink and beige limestone. The door has an elaborate wrought iron security gate. Above the main door is a small sliding vinyl unit. There is a brick chimney on the back facade and a concrete driveway on the side of the house. The limestone cladding, wrought iron details, and fixed windows give a Modern Movement (Moderne) stylistic feel to a transitional house that has some Tudor Revival elements.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
115	4040 Buena Vista Street			1946	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4040 Buena Vista is a two story hipped roof house with a shallow, half-hexagonal roof attached to the main hip roof which covers a two story bay window on the primary facade. The house is primarily clad in red brick with stone trim. The primary facade features a one story brick clad entrance vestibule with an open balcony porch above. The open balcony porch is covered with an aluminum awning. The primary door on the first floor is centered in the projecting vestibule and has a stone surround with a small glass block window on either side. The porch above has a cast iron railing set between two low brick pillars that extend up from the vestibule wall below and wrap the corners of the balcony to form the balcony knee wall. There is a two story bay window on the primary facade, set next to the primary entrance, clad in stone. This bay features steel casement windows on the upper floor--the lower floor is obscured by screening. The first floor porch spans the whole facade and has a cast iron railing around it and there is an aluminum awning over part of the part and screening has been hung from the awning.
116	4044 Buena Vista Street			1948	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4044 Buena Vista is a two story hipped roof house with a half-hexagonal conical roof attached to the main hip roof which covers a two story bay window on the primary facade and a small front facing dormer gable that covers a second floor door onto an upper balcony. The house is primarily clad in dark red and brown brick with stone trim. The primary facade features a one story brick clad entrance vestibule with an open balcony porch above. The primary door on the first floor is centered in the projecting vestibule and has a stone surround. The porch above has a cast iron railing set between two low brick pillars that extend up from the vestibule wall below and wrap the corners of the balcony to form the balcony knee wall. There is a two story bay window on the primary facade, set next to the primary entrance. This bay features a steel casement windows on the upper and lower floors. There is an aluminum awning that covers the entire first floor porch which spans the whole facade and has a cast iron railing around it. There is a two car garage behind the house.
117	4045 Buena Vista Street			1940	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4045 Buena Vista Street is two-stories and topped with a hipped asphalt shingle roof intersected by a front gabled pediment that covers a porch on the second floor and the entrance below, on the first floor. A brick chimney is set on the secondary facade. The exterior is clad in brown brick veneer laid in a running bond pattern with accents of cast stone and decorative brickwork. The primary entrance is centered on the projecting vestibule bay with a centered door with a stone surround. On either side of the main entrance door is a small stained glass window with a stone sill. Above the entrance there is an open balcony porch with arched openings which covers the second floor porch balcony and is topped with a front facing gable roof. The upper porch balcony has a metal railing. A two story bay window is set next to the main entrance and contains steel casement windows at the first and second floor. The two story bay is clad in stone. Windows and openings have cast stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the west side of the property ending at a two car garage. A black lightpost with a lantern style fixture is near the center of the front lawn.
118	4052 Buena Vista Street			1960	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 4052 Buena Vista Street is two-stories and topped with a side gable asphalt shingle roof. There is a brick chimney on the side facade. There is a small front gabled pediment on the primary facade above the larger of the second floor windows. The exterior is clad in reddish orange brick veneer laid in a running bond pattern. The primary entrance is set to the side of the primary facade, and is accessed by a brick stoop porch and topped with a flat, red aluminum awning supported by metal posts. A vinyl fixed picture window is set beside the entrance and two vinyl windows are on the second floor--one larger than the other. The windows have stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the side of the house and there is a two car garage behind the house. There is a black lightpost with a globe fixture set in the center of the front lawn.
119	4060 Buena Vista Street			1946	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4060 Buena Vista is a two story hipped roof house with a shallow, half-hexagonal roof attached to the main hip roof which covers a two story bay window on the primary facade. The house is primarily clad in red brick with stone trim. The primary facade features a one story brick clad entrance vestibule with an open balcony porch above. The open balcony porch is covered with an aluminum awning. The primary door on the first floor is centered in the projecting vestibule and has a stone surround with a small glass block window on either side. The porch above has a cast iron railing set between two low brick pillars that extend up from the vestibule wall below and wrap the corners of the balcony to form the balcony knee wall. There is a two story bay window on the primary facade, set next to the primary entrance, clad in stone. This bay features steel casement windows on the upper floor--the lower floor windows are vinyl with one unit fixed and the flanking units hung. The first floor porch spans the whole facade and has a cast iron railing around it. There is a two car garage behind the house.
120	4063 Buena Vista Street			1953	Modern Movement	1/garage	C	Unknown	Unknown	The house at 4063 is a two story building with a hipped roof covered in asphalt shingles. The house is comprised of two bays--the western bay has the main entrance under a one story porch. The porch is partial width and has a wooden railing. The roof of the porch is flat. Above the porch, on the second floor is a glass block window. On the other bay there is a three lite vinyl slider window on the first and second floor. Similar windows are arranged on other facades. A concrete drive on the side of the house leads to a two car garage.
121	4070 Buena Vista Street			1961	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 4070 Buena Vista Street is a two story house with a side gabled roof clad in red brick. The roof is clad in asphalt shingles. The primary entrance is offset on the facade, set beside a sliding window. The primary entrance has a pressed metal surround, vaguely classical in style. Above the entrance door is a small sliding window while another, slightly larger, sliding window is located above the first floor window. A small front gabled pediment is located over the larger sliding window. There is a brick chimney on the secondary facade. The house has stone sills. The porch is a small stoop with no cover. There is a black lightpost in the front lawn with a lantern style fixture. There is a two car garage behind the house with a pyramidal roof.
122	4071 Buena Vista Street			1953		1/garage	C	Unknown	Unknown	The house at 4071 Buena Vista is a two story house with a hipped roof clad in asphalt shingles. The house is clad in red brick laid in a running bond pattern with accents of cast stone. There is a two story shallow bay window on the primary facade clad with brick and stone veneer, with steel casement windows with stone trim. The entrance is centered on a projecting vestibule bay with an enclosed porch on the second floor which is glazed with vinyl windows. The cast stone and stone veneer entry porch is covered by an aluminum awning, and there is stone trim around the door. On either side of the door is a glass block window. The porch has a decorative wrought iron railing. Windows on other elevations are steel casement. A concrete driveway runs along the west of the property to the rear. There appears to be no garage.
123	4076 Buena Vista Street			1961	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 4076 Buena Vista is two-stories and topped with a side gable asphalt shingle roof. There is a brick chimney on the side facade. The exterior is clad in red brick veneer laid in a running bond pattern. The primary entrance is set to the side of the primary facade, and is accessed by a brick stoop porch and topped with a white aluminum awning with scalloped trim, supported by metal posts. A vinyl sliding picture window is set beside the entrance and three vinyl windows are on the second floor. The windows have stone sills. The first floor window on the primary facade has an aluminum awning with scalloped trim that matches the awning over the stoop. Similar windows are arranged on other elevations. A concrete driveway runs along the side of the house and there is a two car garage behind the house.
124	4077 Buena Vista Street			1952	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4077 Buena Vista is a two story house with a hipped roof clad in asphalt shingles. The house is clad in dark red brick. There is a one story shallow bay window on the primary facade the center window in the bay is fixed with the two flanking windows are steel casements. The windows have stone trim. The entrance is centered on a projecting vestibule bay with a knee wall above for the upper porch. The upper porch has been enclosed with vinyl sliding windows. The first floor of the projecting vestibule bay is clad in brick with stone trim around the door. The porch is partial width and is covered with an aluminum awning, supported by metal posts. The porch has a decorative wrought iron railing. There is a two car garage behind the house.
125	4084 Buena Vista Street			1947	Tudor Revival		C	Unknown	Unknown	The house at 4084 Buena Vista is a two story house with a side gabled roof in front and a half-hipped roof in back, clad in asphalt shingles. The house is clad in dark red brick. There is a one story shallow bay window on the primary facade and the center window in the bay is fixed while the two flanking windows are steel or wood casements. The windows have stone trim and the bay window is clad in stone. The entrance is centered on a projecting vestibule bay with a knee wall above for the upper porch. The upper porch is open and a projecting, front gabled pediment is supported by brick columns springing from the knee wall. The first floor of the projecting vestibule bay is clad in brick with stone trim around the door. The porch stoop is partial width and has a decorative wrought iron railing. There is no garage.
126	4085 Buena Vista Street			1949	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4085 Buena Vista is a two story house with a hipped roof clad in asphalt shingles. The house is clad in dark red brick. There is a two story shallow bay window on the primary facade with steel casements on the first and second floor. The windows have stone trim. The entrance is centered on a projecting vestibule bay with a knee wall above for the upper porch. The upper porch has been enclosed with vinyl sliding windows. The first floor of the projecting vestibule bay is clad in brick with stone trim around the door. The porch is full width and is covered with an aluminum awning, supported by metal posts. The porch has a decorative wrought iron railing. There is a two car garage behind the house.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
127	4094 Buena Vista Street			1961	Colonial Revival		C	Unknown	Unknown	The house at 4094 Buena Vista is a two story side gabled house clad in red brick and vertical white wood siding. The first floor is clad in brick while the second floor is clad in siding. The two secondary facades are clad in brick. The main entrance door is offset on the primary facade and there is a sliding window set beside the main door. Around the window on the first floor there is pink colored limestone cladding set upon a knee wall of brick. There are two small windows evenly spaced on the second floor and these units have white vinyl sliding windows. There is a low concrete stoop porch. The second floor of the house slightly over hangs the first floor creating a Garrison Colonial type of style. A two car garage is attached to the back of the house and accessed on the side street as this house is on a corner lot.
128	4099 Buena Vista Street			1949	Modern Movement	1/garage	C	Unknown	Unknown	This duplex at 4099 Buena Vista is clad in red brick and two stories tall. The roof is hipped and clad in asphalt shingles. The duplex is arranged into four bays with the inner two bay being recessed. The two units are divided on the facade with a fluted glass panel that runs from the eave to the porch. The porch spans the inner, recessed area of the facade and is covered by the overhanging roof above. The doors are inset into this recessed and set on the sides of the two outer projecting bays. Above each door is a shallow balcony with a solid, angled wood wall as a railing. There are sliding white vinyl units set on the inset on each facade and sliding door units above, behind the solid wood railing. There is a two car garage behind the building, accessed from the side street.
129	4200 Buena Vista Street			1925	Prairie	1/garage	C	Unknown	Unknown	The duplex at 4200 Buena Vista Street is two-stories and topped with a hipped asphalt shingle roof intersected by a hipped roof dormer clad in asphalt shingles centered above the facade. A brick chimney is located at the eave on the east facade near the center of the house. The facade is clad in red face brick laid in a running bond pattern. The primary entrance to each flat is centered on the facade beneath a second floor balcony supported by brick piers and square wood posts. The entrance is accessed by a brick and concrete porch with a brick kneewall. On either side of the entrance is a two-story canted bay, glazed with three vinyl hung windows, set beneath matching windows on the second floor. On the east facade, there is another canted bay and similar windows across the facade, with glass block windows at the basement. Windows have cast stone sills. A concrete driveway is accessed off of Petoskey Avenue leading to a gabled garage at the rear.
130	4203 Buena Vista Street			1928	Spanish Eclectic	n/a	C	Unknown	Unknown	The apartment building at 4203 Buena Vista Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof intersected by a rear wing that has a combination of gabled roof and flat roof with parapet. A brick chimney topped with a bell tower is located the east facade near the center of the house. The facades are clad in brown face brick laid in a running bond pattern with accents of klinker brick. The primary entrance to each flat is centered on the facade beneath a brick arched portico with spiral cast stone columns and brick piers. The entrance is accessed by a brick and concrete porch with a metal railing. Three entrances to units are accessed along the east facade, with a combination of arched and flat top doors, each with a brick and concrete porch and either a metal or wood railing. Windows are steel casement across the facade, the larger sets with fixed transom and sidelights. On the east facade, one casement window has an arched fanlight and wrought iron Juliet balcony at the second floor. Windows have brick sills and rusticated stone lintels. There is no driveway or garage.
131	4210 Buena Vista Street			1924	Tudor Revival	1/garage	C	Unknown	Unknown	The duplex at 4210 Buena Vista Street is two-and-a-half stories and topped with a cross gable asphalt shingle roof composed of a steeply pitched side gabled jerkinhead roof intersected by a front jerkinhead, with a hipped roof and a hipped roof dormer centered on the rear. A brick chimney is located at the eave on the west facade near the front of the house. The facade is clad in blonde face brick laid in a running bond pattern, with other facades clad in red brick laid in a running bond pattern. False half-timbering is present beneath the side jerkinhead roof at the attic level. The primary entrance to each flat is near the east corner of the facade beneath a second floor balcony, covered by a metal awning, with a painted wood railing supported by brick piers and arches. The entrance is accessed by a brick and concrete porch with a brick kneewall and painted wood railing. West of the entrance, the porch has been enclosed with brick beneath a metal awning. Windows are hung and appear to be a mix of wood and aluminum, and have cast stone sills. A concrete driveway runs along the east of the house to the rear where there is a gabled garage.
132	4211 Buena Vista Street			1924	Prairie	1/garage	C	Unknown	Unknown	The duplex at 4211 Buena Vista Street is two-stories and topped with a hipped asphalt shingle roof intersected by a hipped roof dormer centered above the facade with three vertically divided wood windows, and another hipped roof dormer on the east facade. A brick chimney is located at the eave on the west facade and another is near the center of the house. The facade is clad in brown face brick, and other facades clad in red brick, all laid in a running bond pattern with some decorative brickwork on the primary facade. The primary entrance to each flat is near the east corner the facade beneath a second floor balcony with metal railing, topped with a metal awning, and supported by brick piers. The entrance is accessed by a brick and concrete porch with a brick kneewall. West of the entrance are three wood hung windows with vertically divided upper sashes and brick lintels with keystones, set beneath matching windows on the second floor. Similar windows exist on other elevations. Windows have cast stone sills. A concrete driveway runs along the east of the house leading to a pyramidal roof garage at the rear.
133	4218 Buena Vista Street			1924	Prairie	1/garage	C	Unknown	Unknown	The duplex at 4218 Buena Vista Street is two-stories and topped with a hipped asphalt shingle roof intersected by a hipped roof dormer centered above the facade, and another hipped roof dormer on the east facade. A brick chimney is located at the eave on the west facade near the front of the house and another is near the center. The facade is clad in blonde face brick, and other facades clad in red brick, all laid in a running bond pattern. The primary entrance to each flat is near the east corner the facade beneath a second floor balcony with metal railing, topped with a metal awning, and supported by brick piers. The entrance is accessed through an arched opening on a brick and concrete full width porch, which is covered by an aluminum metal awning. West of the entrance are three wood hung windows topped with arched fanlights, set wood hung windows with leaded glass detailing on the second floor. Similar windows exist on other elevations. Windows have cast stone sills painted white. A concrete driveway runs along the east of the house leading to a pyramidal roof garage at the rear.
134	4219 Buena Vista Street			1924	Prairie	n/a	C	Unknown	Unknown	The duplex at 4219 Buena Vista Street is two-stories and topped with a hipped asphalt shingle roof intersected by a hipped roof dormer clad in asphalt shingles centered above the facade. A tall brick chimney is located at the eave on the west facade near the front of the house and another is near the center. The facade is clad in brown face brick, and other facades clad in red brick, all laid in a running bond pattern. The primary entrance to each flat is near the east corner the facade accessed by a brick and concrete stoop with metal railing, and door is trimmed in a wood surround painted white. Directly above the door is a leaded glass window on the second floor. West of the entrance are three leaded glass windows, beneath a matching set on the second floor. At the west corner is a two-story porch supported by brick piers with brick knee wall. Windows have cast stone sills painted white. A concrete driveway runs along the east of the house leading to a pyramidal roof garage at the rear.
135	4224 Buena Vista Street			1925	Prairie	n/a	C	Unknown	Unknown	The duplex at 4224 Buena Vista Street is two-stories and topped with a hipped asphalt shingle roof intersected by a front gable roof dormer clad in vinyl siding centered above the facade, and a hipped roof dormer facing east. A brick chimney is located near the center of the house. The facade is clad in tan face brick, and other facades clad in red brick, all laid in a running bond pattern. The primary entrance to each flat is near the east corner the facade accessed by a CMU full width porch with metal railing. West of the entrance are is a set of four casement windows with brick splayed lintel with keystone, beneath a casement window the second floor. Windows have cast stone sills painted white, and similar windows are found on elevations. A concrete driveway runs along the east of the house. A black lightpost with a globe light fixture is in the front lawn. There is no garage.
136	4225 Buena Vista Street			1924	Prairie	1/garage	C	Unknown	Unknown	The duplex at 4225 Buena Vista Street is two-stories and topped with a hipped asphalt shingle roof intersected by a front gable roof dormer clad in wood shingle siding centered above the facade. A brick chimney is located at the eave on the east facade, and another is near the center of the house. The facade is clad in blonde face brick laid in a running bond pattern with accents of decorative brickwork and cast stone painted gray, and other facades clad in red brick laid in a running bond pattern. The primary entrance to each flat is near the west corner the facade beneath a second floor balcony with metal railing, where the structure of a former metal awning is present, and supported by brick piers accessed by a brick and concrete porch with brick kneewall. West of the entrance are a set of four wood hung windows with divided upper sashes and cast stone lintel, beneath matching windows on the second floor. Windows have cast stone sills painted gray, and similar windows are found on elevations. A concrete driveway runs along the east of the house to the rear where there is a garage.
137	4231 Buena Vista Street			1927	Tudor Revival	1/garage	C	Unknown	Unknown	The duplex at 4231 Buena Vista Street is two-stories and topped with a side gable asphalt shingle roof intersected by a front gabled bay projecting from the east of the facade. Continuous shed dormers at the front and rear encompass the second floor of the house. A brick chimney is located at the eave on the west facade. The facade is clad in brown face brick laid in a running bond pattern, and false half-timbering infilled with stucco on the second floor. The primary entrance to each flat is near the east corner the facade beneath a second floor balcony beneath the front gable, and is accessed by a brick and concrete porch with metal railing. West of the entrance are a set of four wood casement windows with leaded glass in a diamond pattern, beneath matching windows on the second floor. Windows have brick sills, and windows on elevations appear to be a mix of casement and hung. A concrete driveway runs along the east of the house to the rear where there is a garage with a front gable roof.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
138	4232 Buena Vista Street			1922	Colonial Revival	n/a	C	Unknown	Unknown	The house at 4232 Buena Vista Street is two-stories and topped with a gambrel asphalt shingle roof. Continuous shed dormers clad in wood shingles at the front and rear encompass the second floor of the house. A brick chimney is located at the rear. The facade is clad in red brick laid in a running bond pattern, and wood shingle siding on the second floor. The primary entrance is near the east corner the facade beneath an arched portico with brick piers and asphalt shingle roof, and is accessed by a brick and concrete porch with metal railing. West of the entrance is a set of four wood hung windows with divided upper sashes. Two wood hung windows with divided upper sashes and wood shutters are on the second floor. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear where there is no garage.
139	4238 Buena Vista Street			1926	Prairie	1/garage	C	Unknown	Unknown	The duplex at 4238 Buena Vista Street is two-stories and topped with a hipped asphalt shingle roof, with a hipped roof dormer centered above the facade and another towards the east. A tall brick chimney is located at the eave on the west facade near the front of the house and another is centered towards the rear. The facade is clad in light brown brick laid in a running bond pattern with some decorative brickwork. The primary entrance is near the east corner the facade beneath an enclosed second-floor balcony topped with a shed roof and supported by brick piers. The door is accessed through an arched opening on a brick and concrete porch with brick kneewall. West of the entrance are three wood hung windows with leaded glass detailing, with brick infilled arches and keystones above, set beneath three matching windows on the second floor. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear where there is no garage.
140	4239 Buena Vista Street			1926	Tudor Revival	1/garage	C	Unknown	Unknown	The duplex at 4239 Buena Vista Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, with two front gables and a shed roof dormer towards the east. A brick chimney is located near the center of the house. The facade is clad in dark brown brick laid in a running bond pattern with some accents of cast stone and a brick buttress extending from the west corner. The primary entrance is near the east corner the facade beneath an second-floor balcony with an arched opening and supported by brick piers. The door is accessed by a brick and concrete porch with brick kneewall and metal railing. West of the entrance is a large slider window covered by an aluminum awning, set beneath a matching window on the second floor. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear where there is a pyramidal roof garage.
141	4245 Buena Vista Street			1924	Prairie	n/a	C	Unknown	Unknown	The duplex at 4245 Buena Vista Street is two-stories and topped with a hipped asphalt shingle roof, with a hipped roof dormer with three multi-light wood casement windows centered above the facade and another towards the rear. A brick chimney is located near the center of the house. The facade is clad in blonde brick, with red brick on the secondary facades, all laid in a running bond pattern. The primary entrance is near the west corner the facade beneath a second-floor balcony with metal railing supported by brick piers. The door has a leaded glass sidelight and is accessed by a brick and concrete porch with brick kneewall. East of the entrance are three wood casement windows with transoms and leaded glass detailing, set beneath three matching windows on the second floor. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear where there is no garage.
142	4246 Buena Vista Street			1925	Prairie	n/a	C	Unknown	Unknown	The duplex at 4246 Buena Vista Street is two-stories and topped with a hipped asphalt shingle roof, with a hipped roof dormer with three wood casement windows centered above the facade and a shed roof dormer towards the east. A tall brick chimney is located at the eave on the west facade near the front of the house, and another is located near the center. The facade is clad in light brown brick, with red brick on the secondary facades, all laid in a running bond pattern. The primary entrance is near the east corner the facade beneath an aluminum metal awning accessed by a brick and concrete full width porch with metal railing. The door has a stone veneer surround. West of the entrance is an aluminum slider window, set within the original opening that has been partially bricked in, set beneath a matching window on the second floor also with areas of brick infill. Windows have cast stone sills painted white. Similar windows exist on other elevations, and some appear to be hung. A concrete driveway runs along the east of the house to the rear where there is no garage.
143	4252 Buena Vista Street			1925	Prairie	1/garage	C	Unknown	Unknown	The duplex at 4252 Buena Vista Street is two-stories and topped with a hipped asphalt shingle roof, with a hipped roof dormer with three wood casement windows centered above the facade and another towards the east. A tall brick chimney is located at the eave on the west facade near the front of the house, and another is located near the center. The facade is clad in light brown brick, with red brick on the secondary facades, all laid in a running bond pattern. The primary entrance to each unit is near the east corner the facade beneath a second-floor balcony with metal railing and supported by brick piers, and is accessed by a brick and concrete porch. West of the entrance are three wood hung windows with leaded glass detailing, topped with infilled arches that have decorative tiles and keystones above. On the second floor set are three matching windows. Windows have cast stone sills painted white. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear where there is a pyramidal roof garage.
144	4253 Buena Vista Street			1924	Prairie	1/garage	C	Unknown	Unknown	The duplex at 4253 Buena Vista Street is two-stories and topped with a hipped asphalt shingle roof, with a hipped roof dormer with three wood casement windows centered above the facade and another centered on the rear. A brick chimney is located near the center of the house. The facade is clad in brown brick, with red brick on the secondary facades, all laid in a running bond pattern. The primary entrance to each unit is near the west corner the facade beneath a second-floor balcony with wood railing and supported by brick piers, and is accessed by a brick and concrete porch with brick kneewall. East of the entrance are three hung windows, set beneath three matching windows on the second floor. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear where there is a garage. A black lightpost with a globe light fixture is in the front lawn.
145	4258 Buena Vista Street			1924	Prairie	n/a	C	Unknown	Unknown	The duplex at 4258 Buena Vista Street is two-stories and topped with a hipped asphalt shingle roof, with a hipped roof dormer with three wood hung windows centered above the facade. A tall brick chimney is located at the eave on the west facade near the front of the house, and another is located near the center. The facade is clad in red and brown brick, with red brick on the secondary facades, all laid in a running bond pattern. The primary entrance to each unit is near the east corner the facade beneath a second-floor balcony with metal railing and supported by brick piers, and is accessed by a brick and concrete porch with brick kneewall. West of the entrance are three hung windows, covered by an aluminum metal awning, and set beneath three matching windows on the second floor. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear where there is no garage.
146	4261 Buena Vista Street			1925	Tudor Revival	n/a	C	Unknown	Unknown	The duplex at 4261 Buena Vista Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by a prominent front gable and a hipped roof dormer facing east. A brick chimney is located at the eave on the west facade and another is located near the center at the rear of the house. The facade is clad in brown brick, with red brick on the secondary facades, all laid in a running bond pattern. Stone accents are found across the facade and false half-timbering with stucco infill is beneath the front gable. The primary entrance to each unit is near the east corner the facade beneath a second-floor balcony with metal railing and metal awning, supported by paired wood square posts, and is accessed by a CMU porch. West of the entrance are three hung windows with metal security bars, set beneath a set of four hung windows on the second floor. Windows have cast stone sills painted black. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear where there is no garage. A black lightpost with a globe light fixture is in the front lawn.
147	4266 Buena Vista Street			1925	Prairie	n/a	C	Unknown	Unknown	The duplex at 4266 Buena Vista Street is two-stories and topped with a hipped asphalt shingle roof, with a hipped roof dormer with three wood casement windows with a diamond pattern centered above the facade. A tall brick chimney is located at the eave on the west facade near the front of the house, and another is located near the center. The facade is clad in brown brick, with red brick on the secondary facades, all laid in a running bond pattern. The primary entrance to each unit is near the east corner the facade beneath a second-floor balcony with wood railing and supported by brick piers, and is accessed by a brick and concrete porch with brick kneewall. West of the entrance are three wood hung windows with divided upper sashes, topped with infilled arches that have decorative tiles and keystones above. On the second floor are three matching windows. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear, and there is no garage.
148	4267 Buena Vista Street			1924	Prairie	n/a	C	Unknown	Unknown	The duplex at 4267 Buena Vista Street is two-stories and topped with a hipped asphalt shingle roof, intersected by a hipped roof dormer with two wood casement windows centered on the facade, with decorative exposed rafter tails along the eave. A brick chimney is located near the center of the house. The facade is clad in light brown brick, with red brick on the secondary facades, all laid in a running bond pattern. The primary entrance to each unit is near the east corner the facade beneath a second-floor balcony with wood railing and metal awning, supported by brick piers, and is accessed by a brick and concrete porch with brick kneewall. West of the entrance are three wood hung windows covered by an aluminum metal awning, set beneath a set three wood hung windows with divided upper sashes on the second floor. Windows have cast stone sills painted brown. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear where there is no garage. A black lightpost with a globe light fixture is in the front lawn.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
149	4274 Buena Vista Street			1926	Tudor Revival	1/garage	C	Unknown	Unknown	The duplex at 4274 Buena Vista Street is two-stories and topped with a cross gable asphalt shingle roof, composed of a side gable front portion and hipped roof toward the rear, intersected by two front gables. A brick chimney is located at the eave on the west façade and another is near the center of the house. The facade is clad in brick painted red, with brick on the secondary facades painted white, all laid in a running bond pattern. The primary entrance to each unit is near the east corner the facade beneath a two-story porch with brick arches and supported by brick piers, and is accessed by a brick and concrete full width porch with brick kneewall. West of the entrance are three wood casement windows with transoms covered by an aluminum metal awning, set beneath a set three matching windows on the second floor. Windows have cast stone sills painted white. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear where there is a garage with a pyramidal roof. A black lightpost with a globe light fixture is in the front lawn.
150	4277 Buena Vista Street			1925	Prairie	n/a	C	Unknown	Unknown	The duplex at 4277 Buena Vista Street is two-stories and topped with a hipped asphalt shingle roof, intersected by a hipped roof dormer with three wood casement windows centered on the façade, with decorative brackets along the eave. Another hipped roof dormer faces east. A tall brick chimney is located at the eave on the west façade and another is located near the center of the house. The facade is clad in light brown brick, with red common brick on the secondary facades, all laid in a running bond pattern. The primary entrance to each unit is near the east corner the facade beneath a second-floor balcony with wood railing supported by brick piers, and is accessed by a brick and concrete porch with brick kneewall. West of the entrance are three wood hung windows with leaded glass detailing covered by a roll-up awning, set beneath three wood hung windows on the second floor. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear. There is no garage.
151	4280 Buena Vista Street			1924	Prairie	n/a	C	Unknown	Unknown	The duplex at 4280 Buena Vista Street is two-stories and topped with a hipped asphalt shingle roof, intersected by a hipped roof dormer with two wood casement windows centered on the façade, and shed roof dormer on the rear. A tall brick chimney is located at the eave on the east façade and another is located near the center of the house. The facade is clad in light brown brick with decorative brickwork and cast stone accents, and red common brick on the secondary facades, all laid in a running bond pattern. The primary entrance to each unit is near the west corner the facade beneath a second-floor balcony that has been enclosed with metal paneled siding and slider windows, which is supported by brick piers. The entrance is accessed by a brick and concrete porch with brick kneewall. East of the entrance are three wood hung windows with vertically divided upper sashes underneath a metal awning, set beneath three matching wood hung windows on the second floor. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear. There is no garage.
152	4281 Buena Vista Street			1925	Prairie	n/a	C	Unknown	Unknown	The duplex at 4281 Buena Vista Street is two-stories and topped with a hipped asphalt shingle roof, intersected by a hipped roof dormer with three small wood hung windows centered above the façade, and another hipped roof dormer facing east, with decorative brackets along the eave. A tall brick chimney is located at the eave on the west façade and another is located near the center of the house. The facade is clad in light brown brick with decorative brickwork and cast stone accents, and red common brick on the secondary facades, all laid in a running bond pattern. The primary entrance to each unit is near the east corner the facade beneath a second-floor balcony with a wood railing, which is supported by brick piers and a brick arch. The entrance is accessed by a brick and concrete porch with brick kneewall. East of the entrance are three vinyl hung windows, set beneath three matching hung windows on the second floor. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear. There appears to be no garage.
153	4288 Buena Vista Street			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The duplex at 4288 Buena Vista Street is two-stories and topped with a cross gable asphalt shingle roof, composed of a side gable front portion and hipped roof toward the rear, intersected by two front gables. A brick chimney is located at the eave on the west façade and another is near the center of the house. The facade is clad in tan face brick laid in a running bond pattern with decorative brickwork and contrasting brick accents. The primary entrance to each unit is near the east corner the facade beneath a two-story porch with brick arched openings supported by brick piers, and is accessed by a brick and concrete full width porch. West of the entrance door are four hung windows topped with an arched and splayed brick lintel, beneath a set of three hung windows on the second floor. Windows have brick sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear where there appears to be a garage.
154	4289 Buena Vista Street			1924	Prairie	n/a	C	Unknown	Unknown	The duplex at 4289 Buena Vista Street is two-stories and topped with a hipped asphalt shingle roof, intersected by a hipped roof dormer with a slider window centered above the façade, and another hipped roof dormer facing east, with decorative brackets along the eave. A tall brick chimney is located at the eave on the west façade and another is located near the center of the house. The facade is clad in blonde brick with some decorative brickwork and cast stone accents, and red common brick on the secondary facades, all laid in a running bond pattern. The primary entrance to each unit is near the east corner of the facade beneath a gabled overhang with knee brackets. The entrance is accessed by a brick and concrete porch with brick kneewall. West of the entrance is a two-story porch supported by brick piers with a metal railing on the second floor. Two large fixed windows are on either side of the porch doors on both floors. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear. There is no garage.
155	4294 Buena Vista Street			1923	Colonial Revival	n/a	C	Unknown	Unknown	The house at 4294 Buena Vista Street is a two story side gabled house clad in white vinyl siding. The second floor overhangs slightly creating a Garrison Colonial type of style. A brick chimney is located at the eave on the west façade. The main entrance is near the east corner of the house and is accessed by a concrete stoop, with a decorative door surround with pilasters either side of the door. There is a set of three hung windows west entrance, and three hung windows on the second floor. There are two additional sliding windows on the second floor. A concrete driveway runs along the south of the house to the rear. There is no garage.
156	4295 Buena Vista Street			1926	Tudor Revival	1/garage	C	Unknown	Unknown	The duplex at 4295 Buena Vista Street is two-stories and topped with a cross gable asphalt shingle roof, composed of a side gable jerkinhead front portion and hipped roof toward the rear, intersected by a prominent front gable. A brick chimney is located at the eave on the west façade. The facade is clad in brown face brick and secondary facades composed of red common brick, both laid in a running bond pattern, with wood shingle siding beneath the side gable at the attic level. The primary entrance to each unit is near the east corner of the facade beneath a second floor balcony with metal railing supported by brick piers, and is accessed by a brick and concrete porch. West of the entrance door are four wood casement windows, beneath a set of three hung windows on the second floor. Two small hung windows with divided upper sashes are at the attic level beneath the front gable. Windows have brick sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear where there is a garage.
157	4302 Buena Vista Street			1923	Colonial Revival	n/a	C	Unknown	Unknown	The house at 4302 Buena Vista Street is two-stories and topped with a gambrel asphalt shingle roof. Continuous shed dormers clad in wood shingles at the front and rear encompass the second floor of the house. A brick chimney is located at the eave on the west façade. The facade is clad in wood clapboard siding, and wood shingle siding on the second floor. The primary entrance is near the east corner the facade beneath a portico with paired square wood posts and decorative brackets beneath a flat roof, and is accessed by a brick and concrete porch with metal railing. West of the entrance is a set of four wood hung windows with divided upper sashes. Two pairs of two wood hung windows with divided upper sashes are on the second floor. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear. There appears to be no garage.
158	4309 Buena Vista Street			1927	Tudor Revival	n/a	C	Unknown	Unknown	The duplex at 4309 Buena Vista Street is two-stories and topped with a side gable asphalt shingle roof, intersected by a front gable and a jerkinhead above a projecting entrance vestibule. A brick chimney is located at the eave on the east façade. The facade is clad in brown face brick laid in a running bond pattern, with false half-timbering on the second floor with stucco infill. The primary entrance to each unit is near the west corner of the façade, accessed by a brick and concrete full width porch. West of the entrance is a large fixed window flanked by hung windows, set beneath three hung windows on the second floor. Windows on the first floor have cast stone sills, and all have aluminum storms affixed to the exterior. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear where there is no garage.
159	4310 Buena Vista Street			1925	Tudor Revival	n/a	C	Unknown	Unknown	The duplex at 4310 Buena Vista Street is two-stories and topped with a cross gable asphalt shingle roof, composed of a side gable front portion and hipped roof toward the rear, intersected by two overlapping front gables. A brick chimney is located near the eave on the west façade and another is near the center of the house. The facade is clad in reddish brown face brick and secondary facades composed of red common brick, both laid in a running bond pattern, with false half-timbering infilled with stucco beneath the front and side gables at the attic level. The primary entrance to each unit is near the east corner of the facade beneath a second floor balcony with metal railing supported by brick piers, and is accessed by a brick and concrete porch. Aluminum metal awnings cover the porches at the first and second floors. Windows are obscured from view by vegetation but appear to be mainly hung with aluminum storms affixed to the exterior. Two small hung windows with divided upper sashes are at the attic level beneath the front gable. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the west of the house to the rear where there is no garage.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
160	4316 Buena Vista Street			1925	Prairie	n/a	C	Unknown	Unknown	The duplex at 4316 Buena Vista Street is two-stories and topped with a hipped asphalt shingle roof, intersected by a hipped roof dormer with three small multi-light windows centered above the façade, and another hipped roof dormer facing east. Two brick chimneys are located at the eave on the west façade. The facade is clad in red and brown brick with some decorative brickwork and cast stone accents, and red common brick on the secondary facades, all laid in a running bond pattern. The primary entrance to each unit is near the east corner of the facade beneath a second floor balcony with a metal railing, supported by brick piers with an arched opening, and is accessed by a brick and concrete porch. West of the entrance is a two-story rounded bay, containing four wood windows with leaded glass in a grid pattern on the upper sashes on each floor. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear. There is no garage.
161	4317 Buena Vista Street			1924	Prairie	n/a	C	Unknown	Unknown	The duplex at 4317 Buena Vista Street is two-stories and topped with a hipped roof, presently covered with a large tarp or membrane, intersected by a hipped roof dormer with two small fixed windows centered above the façade. A brick chimney is located at the eave on the west façade and another is near the center of the house. The facade is clad in light brown brick with some decorative brickwork, and red common brick on the secondary facades laid in a running bond pattern. The primary entrance to each unit is near the east corner of the facade beneath a second floor balcony with a metal railing, supported by brick piers, and is accessed by a brick and concrete full width porch. The balcony and porch are each covered with an aluminum metal awning. West of the entrance is a large slider window, beneath a matching slider window on the second floor. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear. There is no garage.
162	4324 Buena Vista Street			1927	Tudor Revival	n/a	C	Unknown	Unknown	The duplex at 4324 Buena Vista Street is two-stories and topped with a cross gable asphalt shingle roof, composed of a side gable jerkinhead front portion and hipped roof toward the rear, intersected by a prominent front gable, and a shed roof dormer on the east. A brick chimney is located near the eave on the west façade and another is near the center of the house. The facade is clad in reddish brown face brick and secondary facades composed of red common brick, both laid in a running bond pattern, with wood shingle siding beneath the side gables at the attic level. The primary entrance to each unit is near the east corner of the facade beneath a second floor balcony with metal railing supported by brick piers, and is accessed by a brick and concrete full width porch. The door has rounded corners. West of the entrance are three steel casement windows, beneath three wood hung windows with divided upper sashes on the second floor. Two small hung windows with divided upper sashes are at the attic level beneath the front gable. Windows have brick lintels and sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear where there is no garage.
163	4325 Buena Vista Street			1926	Prairie	n/a	C	Unknown	Unknown	The duplex at 4325 Buena Vista Street is two-stories and topped with a hipped asphalt shingle roof, intersected by a hipped roof dormer on the east façade, and another hipped roof dormer facing the rear. A brick chimney is located at the eave on the west façade, and another near the center of the house. The facade is clad in red and brown brick with some decorative brickwork and cast stone accents, and red common brick on the secondary facades, all laid in a running bond pattern. The primary entrance to each unit is near the east corner of the facade beneath a second-floor balcony with a metal railing supported by brick piers, and is accessed by a brick and concrete porch with a brick kneewall. West of the entrance is a two-story rounded bay, containing four vinyl windows on each floor. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear. There is no garage.
164	4330 Buena Vista Street			1926	Prairie	1/garage	C	Unknown	Unknown	The duplex at 4330 Buena Vista Street is two-stories and topped with a hipped asphalt shingle roof, intersected by a hipped roof dormer centered on the façade, and a shed roof dormer facing east. A brick chimney is located at the eave on the west façade, and another near the center of the house. The facade is clad in blonde brick, and red common brick on the secondary facades, all laid in a running bond pattern. The primary entrance to each unit is near the east corner of the facade beneath a second-floor balcony supported by brick piers, and is accessed by a brick and concrete porch. The balcony and porch both have metal railings and are covered by aluminum metal awnings. West of the entrance is a set of windows obstructed from view by vegetation, beneath three hung windows on the second floor. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear where there is a garage.
165	4331 Buena Vista Street			1926	Tudor Revival	1/garage	C	Unknown	Unknown	The duplex at 4324 Buena Vista Street is two-stories and topped with a cross gable asphalt shingle roof, composed of a side gable front portion and hipped roof toward the rear, intersected by a prominent jerkinhead front gable, and a gabled roof dormer on the west. A brick chimney is located near the eave on the east façade and another is near the center of the house. The facade is clad in reddish brown face brick and secondary facades composed of red common brick, both laid in a running bond pattern, with wood shingle siding beneath the side gables at the attic level. The primary entrance to each unit is near the east corner of the facade beneath a two-story full width porch with metal railing supported by brick piers. West of the entrance are three wood hung windows with leaded glass detailing on the upper sashes, beneath three matching windows on the second floor and at the attic level. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear where there is a pyramidal roof garage.
166	4336 Buena Vista Street			1924	Prairie	1/garage	C	Unknown	Unknown	The duplex at 4336 Buena Vista Street is two-stories and topped with a hipped asphalt shingle roof, intersected by a shed roof dormer on the rear. A brick chimney is located at the eave on the west façade, and another near the center of the house. The facade is clad in blonde brick with some decorative brickwork including inverted zigurat motifs, and common brick on the secondary facades that has been painted beige. The primary entrance to each unit is near the east corner of the facade in a slightly projecting vestibule beneath a metal awning, and is accessed by a full width brick and concrete porch with a metal railing. West of the entrance are three steel casement windows recessed into brick arches with keystones above and aluminum storm windows affixed to the exterior, beneath three steel casement windows also with storms on the second floor. Windows have cast stone sills. Two small arched window openings are above the entrance. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear where there is a garage.
167	4337 Buena Vista Street			1927	Tudor Revival	n/a	C	Unknown	Unknown	The duplex at 4337 Buena Vista Street is two-stories and topped with a cross gable asphalt shingle roof, composed of a side gable that meets a front gable toward the rear, intersected by two prominent overlapping front gables. A brick chimney is located near the eave on the east façade and another is near the center of the house. The facade is clad in reddish brown face brick and secondary facades composed of red common brick, both laid in a running bond pattern, with false half-timbering beneath the front gable and wood shingle siding beneath the side gables at the attic level. The primary entrance to each unit is near the east corner of the facade beneath a second floor balcony with metal awning and railing, supported by arched brick piers. The entrance is accessed by a concrete and brick full width porch with metal railing. West of the entrance are three vinyl hung windows with divided sashes with cast stone arched surrounds, beneath two hung windows on the second floor. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear. There is no garage.
168	4344 Buena Vista Street			1924	Colonial Revival	n/a	C	Unknown	Unknown	The house at 4344 Buena Vista Street is two-stories and topped with a gambrel asphalt shingle roof. Continuous shed dormers clad in wood shingles at the front and rear encompass the second floor of the house. A brick chimney is located at the eave on the west facade. The facade is clad with wood clapboard siding, and wood shingle siding on the second floor. The primary entrance is near the east corner of the facade beneath a pedimented portico with tapered square wood posts, and is accessed by a brick and concrete porch. West of the entrance is a set of three wood hung windows with divided upper sashes. Two pairs of two wood hung windows with divided upper sashes are on the second floor. Similar windows exist on other elevations, and all are affixed with aluminum storms on the exterior. A concrete driveway runs along the east of the house to the rear. There is no garage.
169	4345 Buena Vista Street			1924	Prairie	1/garage	C	Unknown	Unknown	The duplex at 4345 Buena Vista Street is two-stories and topped with a hipped asphalt shingle roof with a hipped roof dormer centered above the façade containing two leaded glass windows. A brick chimney is located near the eave on the east façade and another is near the center of the house. The facade is clad in light brown face brick and secondary facades composed of red common brick, both laid in a running bond pattern. The primary entrance to each unit is near the east corner of the facade beneath a second floor balcony with metal awning and railing, supported by brick piers. The entrance is accessed by a concrete and brick full width porch with brick kneewall. West of the entrance are three wood hung windows with leaded glass detailing on the upper sashes, beneath three matching windows on the second floor. Windows have cast stone sills painted white. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to a garage at the rear.
170	4350 Buena Vista Street			1925	Prairie	1/garage	C	Unknown	Unknown	The duplex at 4350 Buena Vista Street is two-stories and topped with a hipped asphalt shingle roof with a shed roof dormer centered above the façade containing two glass block windows, shed dormers on the east and rear, and decorative brackets along the eave. A brick chimney is located near the eave on the west façade and another is near the center of the house. The facade is clad in light brown face brick and secondary facades composed of red common brick, both laid in a running bond pattern. The primary entrance to each unit is near the east corner beneath a flared, asphalt shingled awning with decorative brackets. The entrance is accessed by a concrete and brick porch with wood railing. West of the entrance are three wood hung windows with divided upper sashes, beneath three matching windows on the second floor. Windows have cast stone sills painted white and aluminum storms affixed to the exterior. Similar windows exist on other elevations. At the west corner is a two-story porch with brick piers, covered by an aluminum metal awning. A concrete driveway runs along the east of the house to the rear. There is no garage.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
171	4353 Buena Vista Street			1926	Prairie	1/garage	C	Unknown	Unknown	The duplex at 4353 Buena Vista Street is two-stories and topped with a hipped asphalt shingle roof with a hipped roof dormer centered above the façade and a shed roof dormer on the east. A brick chimney is located near the eave on the west façade and another is near the center of the house. The facade is clad in brown face brick and secondary facades composed of red common brick, both laid in a running bond pattern. The primary entrance to each unit is near the east corner of the facade beneath a second floor balcony with metal railing, supported by brick piers. The entrance is accessed by a concrete and brick full width porch. West of the entrance are three wood hung windows with arches infilled with cast stone, beneath three windows with leaded glass detailing in a diamond pattern on the upper sashes on the second floor. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to a garage at the rear.
172	4359 Buena Vista Street			1925	Prairie	n/a	C	Unknown	Unknown	The duplex at 4359 Buena Vista Street is two-stories and topped with a hipped asphalt shingle roof with decorative brackets along the eave and a gabled roof dormer centered above the façade containing two small hung windows. A brick chimney is located near the eave on the west façade and another is near the center of the house. The facade is clad in blonde face brick and secondary facades composed of red common brick, both laid in a running bond pattern. The primary entrance to each unit is near the east corner of the facade beneath a second floor balcony with wood railing, supported by brick piers. The entrance is accessed by a concrete and brick full width porch with brick kneewall. West of the entrance are three six-over-six hung windows with Tudor arches infilled with cast stone, beneath three matching windows on the second floor. Windows have cast stone sills painted white. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear. There is no garage.
173	4364 Buena Vista Street			1925	Prairie	n/a	C	Unknown	Unknown	The duplex at 4364 Buena Vista Street is two-stories and topped with a hipped asphalt shingle roof with a hipped roof dormer centered above the façade containing two small windows. A brick chimney is located near the eave on the west façade and another is near the center of the house. The facade is clad in brown face brick and secondary facades composed of red common brick, both laid in a running bond pattern. The primary entrance to each unit is near the east corner beneath a second floor balcony with a metal awning and support by brick piers. The entrance is accessed by a full width concrete and brick porch with brick knee wall covered by an aluminum metal awning. West of the entrance are three wood hung windows with divided upper sashes, beneath three matching windows on the second floor. Windows have cast stone sills painted white. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear. There is no garage.
174	4367 Buena Vista Street			1925	Prairie	n/a	C	Unknown	Unknown	The duplex at 4367 Buena Vista Street is two-stories and topped with a hipped asphalt shingle roof, intersected by a shed roof dormer on the east. A brick chimney is located at the eave on the west façade, and another near the center of the house. The facade is clad in blonde brick with some decorative brickwork including inverted zigurat motifs, and red common brick on the secondary facades. The primary entrance to each unit is near the east corner of the facade within a slightly projecting vestibule, and is accessed by a full width brick and concrete porch with a metal railing. West of the entrance is are three vinyl windows with divided upper sashes recessed into brick arches with keystones above and aluminum storm windows affixed to the exterior, beneath three vinyl windows also with divided upper sashes and storms on the second floor. Windows have cast stone sills. Two small arched window openings are above the entrance. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear. There is no garage.
175	4372 Buena Vista Street			1925	Prairie	1/garage	C	Unknown	Unknown	The duplex at 4372 Buena Vista Street is two-stories and topped with a hipped asphalt shingle roof with a hipped roof dormer centered above the façade containing four small wood windows. A brick chimney is located near the eave on the west façade and another is near the center of the house. The facade is clad in brown face brick laid in a running bond pattern with a soldier course running between the first and second floor. The primary entrance to each unit is centered on the façade beneath a second floor balcony with a metal awning and supported by metal wrought iron posts. The entrance is accessed by a concrete and brick porch covered by an aluminum metal awning to the east. On either side of the entrance are three hung vinyl windows with divided upper sashes topped with brick arches and keystones, beneath two pairs of similar windows on the second floor. Windows have cast stone sills painted white. Similar windows exist on other elevations. An alley runs along the west of the house to the rear where there is a garage.
176	4375 Buena Vista Street			1925			NC			Recently demolished.
177	4734 Buena Vista Street			1925	Tudor Revival		C	Unknown	Unknown	The duplex at 4734 Buena Vista is a two and a half story building with a jerkinhead side gable and a half hipped roof at the back. The primary façade has a projecting porch over the primary entry with arched openings on the first floor with pillars and knee wall above to create a porch/balcony for the upper floor. The upper balcony porch is covered with an aluminum awning. There is a full width porch on the first floor that is brick and concrete with steps to the front lawn and steps off the side of the porch as well. There are three arch headed windows on the primary facade next to the front door at the first floor level. At the second floor level, above the arched windows, are four hung windows set together. At the attic level there are two windows, set together in a prominent front facing dormer wall gable. The side facade has a dominate brick chimney and white vinyl hung windows.
178	4735 Buena Vista Street			1926	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 4735 Buena Vista is two-stories and topped with a hipped asphalt shingle roof intersected by a front gable on the primary facade. A brick chimney is set on the side facade. The house is clad in red brick with accents of cast stone (primarily sills). The primary entrance juts out from the plane of the house and is set to the side of the primary facade—it has a flat roof which creates a porch above. The porch above is accessed by a door and is covered with a scalloped trim aluminum awning. The primary entrance is arch-headed with lantern sconces on each side of the door. There is a full width one story porch on the primary facade, partially covered by an aluminum awning set next to the primary entrance. Hung windows are located on the second floor in the front facing gable, also covered with an aluminum awning. The windows have stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the side of the house. There is a hipped roof, two car garage behind the house.
179	4741 Buena Vista Street			1925	Tudor Revival		C	Unknown	Unknown	The house at 4741 Buena Vista is a two story house with a side gabled roof at the front, intersected by a half-hipped roof at the back. There is a brick chimney on the side facade. The front façade has a two story projecting porch with openings on each side that are capped with stone sills. Doors from the house provide access to the porch at the first and second level. The first floor of the porch has no stair and the projecting porch tower is capped with a pyramidal roof, connected to the primary facade. The main entrance is offset on the facade and has an arch headed door with a radiating brick surround with stone accents. The main entrance is accessed by a low brick stoop with side knee walls. A fixed vinyl window is set beside the door and there is another fixed vinyl unit above it on the second floor. Above the door on the second level is a single hung vinyl window. There is a concrete driveway beside the house.
180	4742 Buena Vista Street			1925	Tudor Revival		C	Unknown	Unknown	The house at 4742 Buena Vista is two-stories and topped with a side gabled asphalt shingle roof intersected by a front gable on the primary facade while the back part of the house is covered in a half-hipped roof. A brick chimney is set on the side facade. The house is clad in brown brick with accents of cast stone (primarily sills). The primary entrance porch juts out from the plane of the house and is set to the side of the primary facade—it has a flat roof surrounded by a pent with shingles which creates a porch above. The porch above is accessed by a door at the second floor and is covered with a scalloped trim aluminum awning. The primary entrance is set with the protruding entrance porch and there are arches on all three sides of the porch. The entrance door arch-headed. There is a full width one story porch on the primary facade, partially covered by an aluminum awning set next to the primary entrance. Vinyl replacement windows are located on the second floor in the front facing gable and at the first floor. A shingled pent roof is found between the first and second floor windows on the primary facade. The windows have stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the side of the house. There is no garage.
181	4749 Buena Vista Street			1924	Colonial Revival		C	Unknown	Unknown	The house at 4749 Buena Vista is a two and a half story duplex with a hipped roof that is clad in asphalt shingles. The house is clad in red brick. The attic level has a hipped dormer centered on the primary façade with a three light window. At the first floor there are two entrance doors into the duplex located beneath a brick, one story porch. The roof above the porch is flat creating a balcony for the upper unit. The porch is supported by brick columns that extends up past the floor of the upper porch to create piers. Iron railings span between the brick piers to enclose the upper porch balcony. At the first floor there is a nearly full width porch, extending beyond the covered area where the primary entrance doors are located. This portion of the porch is covered by an aluminum awning with metal scrollwork columns. A three part vinyl sliding window is located on the first and second floors. There is no garage.
182	4750 Buena Vista Street			1927	Tudor Revival		C	Unknown	Unknown	The house at 4750 Buena Vista is two-stories and topped with a hipped asphalt shingle roof intersected by a front gable on the primary facade. The house is clad in red and brown brick with accents of cast stone (primarily sills). The primary entrance porch has been removed but ghost lines remain. The main entrance is a replacement fiberglass door set to the side of the primary facade. Three hung windows are set beside the main entrance door and, above each window, there is decorative brickwork in an arch shape. Three hung windows are also on the second floor, nestled into the front facing gable. The second floor door that provided access to the no-longer-extant porch is boarded over. The full width porch is made of CMU with a metal handicap access ramp on one side and CMU stairs on the other. The windows have stone sills. A concrete driveway runs along the side of the house. There is no garage.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
183	4757 Buena Vista Street			1925	Colonial Revival		C	Unknown	Unknown	The house at 4757 Buena Vista is a two story, brown brick clad house with a hipped roof that is covered in asphalt shingles. There is a half hipped dormer at the attic level on the primary facade. The primary facade has a two story, slightly projecting, squared bay with a half hipped roof that intersects the main roof. There are three hung windows at both the first and second floor of the projecting bay on the primary facade and these units are wood with leaded glass upper lights. The two entrances are offset on the primary facade and set beneath a porch which has a brick column and knee wall. The porch has a flat roof which creates a balcony porch above. There is an access door on the second floor that leads to the balcony porch and the balcony has an iron railing. There is no garage.
184	4765 Buena Vista Street			1929	Tudor Revival		C	Unknown	Unknown	The house at 4765 Buena Vista is a two story house with a side gabled roof at the front and half hipped roof at the back, clad in asphalt shingles. There is a prominent front facing gable that intersects the side gabled main roof. The front facing gable has an elongated eave that ends approximately 5' above grade. The main entrance is nestled within another, shorter front facing gable and the door is arch headed. Beside the door on each side is a small glass block window. At the first floor there is a vinyl sliding unit set beside the main door with a row of glass block directly above and below the vinyl unit. On the second floor there is a steel casement window nestled in the main front facing gable. There is a full width brick porch that is uncovered and it has a low metal railing. There is no garage.
185	3731 Cortland Street			1937	French Eclectic	n/a	C	Unknown	Unknown	The house at 3731 Cortland Street is two-stories and topped with a deck (hipped topped with flat) asphalt shingle roof intersected by a small gable above the facade. A large brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer and cast stone. The primary entrance is trimmed in cast stone near the east corner of the facade and is accessed by a brick and concrete porch with a metal railing. A bay containing steel windows is west of the entrance and two steel windows are arranged on the second floor. Windows have brick sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property. There is no garage.
186	3734 Cortland Street			1935	French Eclectic	n/a	C	Unknown	Unknown	The house at 3734 Cortland Street is two-stories and topped with a hipped asphalt shingle roof intersected by a small gable above the facade and a hipped roof two-story bay. A large brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer. The primary entrance is trimmed in cast stone near the east corner of the facade within the two-story bay and is accessed by a concrete porch. A curving bay containing steel windows is west of the entrance and a series of three vinyl windows are arranged on the second floor and a vinyl window is above the entrance. Windows have brick sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property. There is no garage.
187	3742 Cortland Street			1927	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3742 Cortland Street is two-stories and topped with a deck (hipped topped with flat) asphalt shingle roof intersected by a large gable above the facade and shed and hipped roof dormers. A large brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer and klinker bricks. The primary entrance is trimmed in stone veneer and brick near the east corner of the facade within a gabled vestibule, and is accessed by a brick and concrete porch with a low metal railing. A series of four windows are west of the entrance and a series of three windows are arranged above on the second floor. Two smaller windows are in the gable end and above the entrance. Windows have brick sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property. A pyramidal roof garage is at the rear of the property.
188	3749 Cortland Street			1926	Tudor Revival	n/a	C	Unknown	Unknown	The house at 3749 Cortland Street is two-stories and topped with a deck (hipped topped with flat) asphalt shingle roof intersected by a large jerkinhead above the facade and a hipped dormer above the east facade. A large brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of decorative brickwork and the second floor is clad in vinyl siding. The primary entrance is trimmed in stone veneer and brick near the east corner of the facade within a jerkinhead vestibule, and is accessed by a full-width brick and concrete porch with a brick kneewall. A series of four wood windows are west of the entrance and a series of three wood windows with an aluminum awning are arranged above on the second floor. Three smaller windows are in the gable end and above the entrance. Windows have brick sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property. There is no garage.
189	3750 Cortland Street			1933	French Eclectic	1/garage	C	Unknown	Unknown	The house at 3750 Cortland Street is two-stories and topped with a hipped asphalt shingle roof intersected by a small gable above the facade and a polygonal two-story bay. A stone kneewall extends from the west corner of the facade. A large brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer and decorative brickwork. The primary entrance is trimmed in cast stone near the east corner of the facade within the two-story bay and is accessed by a brick and concrete porch with a low metal railing. A steel window is west of the entrance and a steel window is arranged above on the second floor and has a metal railing beneath it. Windows have brick and stone sills, some are fitted with storms, and segmental and ogee arched openings are in the bay. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property. A pyramidal roof garage is at the rear of the property.
190	3757 Cortland Street			1923	Tudor Revival	n/a	C	Unknown	Unknown	The house at 3757 Cortland Street is two-stories and topped with a deck (hipped topped with flat) asphalt shingle roof intersected by a large catslide gable on the facade and a rectangular parapeted two-story bay. A large brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer and klinker brick. The primary entrance is trimmed in cast stone near the center of the facade within the two-story bay and is accessed by a brick and concrete porch with a low metal railing. A series of wood windows beneath segmental arches are on either side of the entrance, beneath paired wood windows on the second floor. Small arched windows are adjacent to the entrance, in the bay, and in the gable end. Windows have brick sills and are fitted with storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property. There is no garage. A white metal lightpost with a lantern-style fixture is in the front lawn.
191	3760 Cortland Street			1938	French Eclectic	1/garage	C	Unknown	Unknown	The house at 3760 Cortland Street is two-stories and topped with a pyramidal asphalt shingle roof intersected by hipped roofs above the facade. A large brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of cast stone. The primary entrance is trimmed in cast stone near the east corner of the facade and is accessed by a brick and concrete porch with a low metal railing. A one-story bay containing steel windows is west of the entrance beneath a pair of steel windows on the second floor. A steel leaded glass window is above the entrance and a smaller one is adjacent to the entrance. Windows have stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property. A hipped roof garage is at the rear of the property.
192	3765 Cortland Street			1926	Tudor Revival	n/a	C	Unknown	Unknown	The house at 3765 Cortland Street is two-stories and topped with a hipped asphalt shingle roof intersected by two large front gables above the facade and a hipped roof dormer above the east facade. A large brick chimney is at the eave near the front of the west facade. The exterior of the first floor is clad in blonde brick veneer laid in a running bond pattern with the second floor clad in wood shingles, stucco, and wood false half-timbering. The primary entrance is arched and trimmed in brick near the east corner of the facade, set within a vestibule with a catslide roof, and is accessed by a brick and concrete porch. Two pairs of wood windows are west of the entrance, and three windows are arranged on the second floor. Windows have stone and wood sills and are fitted with storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property. There is no garage.
193	3768 Cortland Street			1925c.	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3768 Cortland Street is two-stories and topped with a side gable asphalt shingle roof intersected by a large front gable on the facade and a shed roof wall roof dormer on the west facade. A large brick chimney is at the eave near the front of the east facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer and decorative brickwork. The primary entrance is arched and trimmed in brick near the center of the facade, set within the front gable, and is accessed by a brick and concrete porch. A series of four wood leaded glass windows are east of the entrance, and three of the same windows are arranged on the second floor. Windows have brick sills and are fitted with storms. Similar windows are arranged elsewhere on the facade and other elevations. A concrete driveway runs along the east side of the property. A hipped roof garage is at the rear of the property.
194	3774 Cortland Street			1927	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3774 Cortland Street is two-stories and topped with a deck (hipped topped with flat) asphalt shingle roof intersected by a large front gable and a recessed gable roof dormer on the facade and a shed roof dormer on the west facade. A large brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer and decorative brickwork. The primary entrance is arched and trimmed in brick with stone accents near the center of the facade, set within the jerkinhead vestibule, and is accessed by a brick and concrete porch with a brick kneewall. A partial bay west of the entrance contains vinyl windows and a pair of vinyl windows are east of the entrance. A vinyl window is centered above the bay on the second floor and another is in the dormer, and a small leaded glass window is in the apex of the front gable. Windows have brick sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property. A pyramidal roof garage is at the rear of the property.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
195	3775 Cortland Street			1926	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3775 Cortland Street is two-stories and topped with a hipped asphalt shingle roof intersected by a large gable above the facade and a hipped dormer above the east facade. A large brick chimney is at the eave near the front of the west facade. The first floor of the exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer and the second floor is clad in vinyl siding and wood shingles. The primary entrance is near the east corner of the facade within a catslide vestibule, and is accessed by a full-width brick and concrete porch with a low metal railing and an aluminum awning. Windows on the facade are obscure by foliage, but a pair of wood windows with an awning are visible on the second floor. Similar windows are arranged on other elevations and are fitted with storms. A concrete driveway runs along the east side of the property beneath a shed roof carport. A side gable roof garage is at the rear of the property. A black metal lightpost without a fixture is in the front lawn.
196	3781 Cortland Street			1927	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3781 Cortland Street is two-stories and topped with a side gable asphalt shingle roof intersected by a large gable above the facade and a deck (hipped topped with flat) roof at the rear. A large brick chimney is at the eave near the center of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer and the second floor facade is clad in stucco, wood false half-timbering, and wood siding. The primary entrance is near the east corner of the facade within a curved jerkinhead vestibule, and is accessed by a brick and concrete porch with a metal railing and an aluminum awning. A series of three wood leaded glass windows are west of the entrance beneath a pair of the same windows above on the second floor. Windows have wood or brick sills and are fitted with storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property. A hipped roof garage is at the rear of the property.
197	3784 Cortland Street			1933	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3784 Cortland Street is two-stories and topped with a hipped asphalt shingle roof intersected by a large gable on the facade and a polygonal roof two-story bay. A stone buttress extends outward from the west corner of the facade. A large brick chimney is at the eave near the front of the west facade. The exterior is clad in red and brown brick veneer laid in a running bond pattern with accents of stone veneer decorative brickwork. The primary entrance is near the east corner of the facade within the bay, and is accessed by a brick and concrete porch with a metal railing. A steel window set beneath a segmental arch is west of the entrance and two leaded glass windows are east of the entrance, with similar windows repeated above on the second floor. Windows have stone or brick sills, are fitted with storms, and some have metal railings below. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property. A pyramidal roof garage is at the rear of the property.
198	3790 Cortland Street			1927	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3790 Cortland Street is two-stories and topped with a deck (hipped topped with flat) asphalt shingle roof intersected by a large front gable and a hipped roof dormer on the facade and a hipped roof dormer on the east facade. A brick and stone buttress extends outward from the west corner of the facade. A large brick chimney is at the eave near the front of the west facade. The exterior is clad in purplish brick veneer laid in a running bond pattern with accents of stone veneer, klinker bricks, and decorative brickwork. The primary entrance is arched and trimmed in brick with stone accents, is near the center of the facade within a gabled vestibule, and is accessed by a brick and concrete porch with a low metal railing. A partial bay west of the entrance contains a series of four wood windows, a vinyl window is above on the second floor, a wood window is in the dormer, and a small arched window is in the gable end. Windows have brick sills and some are fitted with storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property. A front gable roof garage is at the rear of the property.
199	3791 Cortland Street			1926	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3791 Cortland Street is two-and-a-half stories and topped with a side gable asphalt shingle roof intersected by a large front gable and a shed roof dormer on the facade. A large brick chimney is near the center of the house. The exterior is clad in red and brown brick veneer laid in a running bond pattern with accents of decorative brickwork and the second floor is clad in vinyl siding. There are two entrances both of which are accessed by a brick and concrete porch with a metal railing and a brick kneewall. Four narrow steel windows are arranged on the first floor facade and multiple vinyl windows are on the second floor and in the dormer. Windows have brick or vinyl sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property. A front gable roof garage is at the rear of the property.
200	3799 Cortland Street			1927	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3799 Cortland Street is two-stories and topped with a deck (hipped topped with flat) asphalt shingle roof intersected by a large front gable and a jerkinhead roof dormer on the facade and a shed and gable roof dormers above other facades. A brick buttress extends outward from the west corner of the facade. A large brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of cast stone and decorative brickwork. The primary entrance is arched and trimmed in brick with stone near the center of the facade, set within the gabled vestibule, and is accessed by a brick and concrete porch with a brick kneewall and a metal awning structure. A partial bay west of the entrance contains a vinyl window and a vinyl window is east of the entrance. A series of three and a pair of wood windows are on the second floor, and a small window is in the gable end. Windows have stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property. A side gable roof garage is at the rear of the property.
201	3800 Cortland Street			1929	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3800 Cortland Street is two-stories and topped with a side gable asphalt shingle roof intersected by a large front gable on the facade. A brick and stone buttress extends outward from the west corner of the facade. A large brick chimney is at the eave near the front of the west facade. The exterior is clad in orange brick veneer laid in a Dutch bond pattern with accents of stone veneer and decorative brickwork. The primary entrance is arched and trimmed in brick and stone near the center of the facade, set within a gabled vestibule, and is accessed by a brick and concrete porch with a low metal railing. A series of four leaded glass windows are west of the entrance and a pair are east of the entrance. A pair and series of three of the same windows are arranged on the second floor. Windows have stone sills and are fitted with storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property. A hipped roof garage is at the rear of the property. A brown metal lightpost with a globe light fixture is in the front lawn.
202	3806 Cortland Street			1927	Italian Renaissance	1/garage	C	Unknown	Unknown	The house at 3806 Cortland Street is two-stories and topped with a hipped asphalt shingle roof intersected by a hipped roof on the facade and a hipped roof dormer above the east facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in orange Roman brick veneer laid in a running bond pattern. The primary entrance is near the center of the facade and is accessed by a brick and concrete porch with low metal railings, sheltered by an arched loggia with a balcony above. A series of three leaded glass windows are west of the entrance and a pair are east of the entrance. Two pairs of the same windows are arranged on the second floor. Windows have stone sills and are fitted with storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property. A hipped roof garage is at the rear of the property.
203	3807 Cortland Street			1930	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3807 Cortland Street is two-stories and topped with a hipped asphalt shingle roof intersected by a large front gable on the facade and a hipped roof dormer above the east facade. A brick and stone buttress extends outward from the west corner of the facade. A large brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer and decorative brickwork. The primary entrance is arched and trimmed in brick and stone near the east corner of the facade, set within a gabled vestibule, and is accessed by a brick and concrete porch with a low metal railing and a metal awning structure. A single-story bay with steel windows is west of the entrance and two steel windows are on the second floor facade. Windows have stone sills and some are fitted with storms. Similar windows are arranged on other elevations. An infilled concrete ribbon driveway runs along the east side of the property. A hipped roof garage is at the rear of the property. A black metal lightpost with a globe light fixture is in the front lawn.
204	3815 Cortland Street			1927	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3815 Cortland Street is two-stories and topped with a gable-on-hip asphalt shingle roof intersected on the facade by a large front gable and a gabled roof dormer. A brick buttress extends outward from the west corner of the facade. A large brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of decorative brickwork and klinker bricks. The primary entrance is arched and trimmed in brick near the center of the facade, set within a jerkinhead vestibule, and is accessed by a brick and concrete porch with a low metal railing. A partial bay west of the entrance contains a series of four leaded glass windows and a pair of leaded glass windows are east of the entrance. The same windows in a pair and a series of three are on the second floor facade and dormer. Windows have brick sills and some are fitted with storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property. A side gable roof garage is at the rear of the property. A black metal lightpost with a globe light fixture is in the front lawn.
205	3816 Cortland Street			1935	French Eclectic	1/garage	C	Unknown	Unknown	The house at 3816 Cortland Street is two-stories and topped with a hipped asphalt shingle roof intersected by hipped and gable roofs above the facade. A large brick chimney is located at the eave near the front of the west facade. The exterior is clad in orange brick veneer laid in a running bond pattern with accents of stone veneer and cast stone. The primary entrance is arched, trimmed in stone, and near the center of the facade. A brick, stone, and concrete porch surrounded by a brick kneewall accesses the entrance. A single-story bay with a flat roof is west of entrance and contains steel casement windows and a steel casement window is east of the entrance. Two steel windows and an arched steel window with leaded glass are on the second floor facade. Windows have cast stone sills. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. A pyramidal roof garage is at the rear of the property. A black lightpost with a globe light fixture is located near the center of the front lawn.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
206	3823 Cortland Street			1927	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3823 Cortland Street is two-stories and topped with a side jerkinhead asphalt shingle roof intersected by a large gable and a recessed shed roof dormer on the facade. A large brick chimney is located at the eave near the center of the west facade. The exterior is clad in brown brick veneer laid in a running bond pattern with accents of stone veneer. The primary entrance is near the east corner of the facade beneath an extension of the roof eave with arched openings supported by brick piers. A brick kneewall surrounds the porch. A vinyl window with an aluminum awning is west of the entrance and two vinyl hung windows are on the second floor and in the dormer. A small window is in the gable end. Windows have brick sills. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. A side gable roof garage is at the rear of the property. A black lightpost without a light fixture is located near the center of the front lawn.
207	3824 Cortland Street			1929	Tudor Revival	n/a	C	Unknown	Unknown	The house at 3824 Cortland Street is two-stories and topped with a side gable asphalt shingle roof intersected by two large front gables on the facade. A large brick chimney is at the eave near the front of the west facade. The exterior is clad in orange brick veneer laid in a running bond pattern with accents of stone veneer and decorative brickwork. The primary entrance is near the east corner of the facade beneath a catslide vestibule, the east eave of which extends over the driveway. The entrance is arched and trimmed with brick and stone, framed on either side with leaded glass windows, set beneath a decorative blind arch and balcony, and accessed by a partially demolished brick and concrete porch with a low metal railing and metal framing for an awning. A series of steel casement windows are west of the entrance a series of the same windows are on the second floor. Windows have brick sills. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. There is no garage.
208	3831 Cortland Street			1927	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3831 Cortland Street is two-stories and topped with a deck (hipped topped with flat) asphalt shingle roof intersected by a large gable above the facade and hipped roof dormers. A large brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer. The primary entrance is trimmed in stone veneer and brick near the east corner of the facade within a gabled vestibule, and is accessed by a brick and concrete porch with a low metal railing and an aluminum awning. A series of four leaded glass windows are west of the entrance and a series of three of the same windows are arranged above on the second floor. Two smaller windows are in the gable end and above the entrance. Windows have brick sills and are fitted with storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property. A side gable roof garage is at the rear of the property.
209	3832 Cortland Street			1929	French Eclectic	n/a	C	Unknown	Edward J. Mason	The house at 3832 Cortland Street is two-stories and topped with a side gable asphalt shingle roof. A brick buttress extends outward from the west corner of the facade. A large brick chimney is at the eave near the front of the west facade. The exterior is clad in purplish brick veneer laid in a running bond pattern with accents of stone veneer and klinker bricks. The primary entrance is near the east corner of the facade within an engaged polygonal turret topped with a polygonal roof, accessing a brick-clad full-width terrace with a short metal railing. Leaded glass windows are arranged on the turret and a series of steel windows are west of the entrance beneath a cantled oriel window with awnings on the second floor facade. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. There appears to be no garage.
210	3840 Cortland Street			1933	French Eclectic	1/garage	C	Unknown	Unknown	The house at 3840 Cortland Street is two-stories and topped with a hipped asphalt shingle roof intersected by hipped wall dormers above the facade, and a hipped and shed roof dormer above other facades. A brick and stone kneewall extends outward from the west corner of the facade. A large brick chimney is at the eave near the front of the west facade. The exterior is clad in orange brick veneer laid in a running bond pattern with accents of stone veneer and cast stone that has been painted white. The primary entrance is trimmed in stone near the center of the facade and is accessed by a brick and concrete porch with a low metal railing. Three glass block windows are west of the entrance, a vinyl window is east of the entrance, and two vinyl windows are on the second floor facade. Windows have brick and stone sills. Similar windows are arranged on other elevations. The driveway is concrete and runs along the rear of the property. A hipped roof garage is at the rear of the property.
211	3841 Cortland Street			1939	French Eclectic	1/garage	C	Unknown	Unknown	The house at 3841 Cortland Street is two-stories and topped with a hipped asphalt shingle roof intersected by a polygonal roof above the facade. A large brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone that has been painted white, and decorative brickwork. The primary entrance is trimmed in stone near the east corner of the facade and is accessed by a brick and concrete porch with a low metal railing. A two-story bay is west of the entrance and contains vinyl windows on the first and second floors. A vinyl window is above the entrance. Windows have stone sills. Similar windows are arranged on other elevations. The driveway is concrete and runs along the rear of the property. A hipped roof garage is at the rear of the property.
212	4000 Cortland Street			1940	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 4000 Cortland Street is two-stories and topped with a side gable asphalt shingle roof intersected by a front gable on the facade. A large brick chimney is at the eave near the front of the east facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of brick quoins. The primary entrance has a white broken pediment surround, is near the center of the facade, and is accessed by a brick and concrete porch. Three multi-light wood windows are arranged on the first floor and four are on the second floor. An oculus window is in the gable end. Windows have brick sills and most have white metal shutters. Similar windows are arranged on other elevations. The driveway is concrete and runs along the rear of the property. A front gable roof garage is at the rear of the property. A black lightpost without a light fixture is located near the center of the front lawn.
213	4003 Cortland Street			1935	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4003 Cortland Street is two-stories and topped with a hipped asphalt shingle roof intersected by two gables above the facade. A large brick chimney is at the eave near the front of the east facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of cast stone that has been painted white and decorative brickwork. The primary entrance is trimmed in stone near the west corner of the facade and is accessed by a brick and concrete porch with a low metal railing. A one-story bay is west of the entrance and contains steel windows and two steel windows are on the second floor beneath the gable ends. Windows have stone sills. Similar windows are arranged on other elevations. The driveway is concrete and runs along the rear of the property. A pyramidal roof garage is at the rear of the property.
214	4011 Cortland Street			1928	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4011 Cortland Street is two-stories and topped with a deck (hipped topped with flat) asphalt shingle roof intersected by a large front gable and a gable roof dormer on the facade and shed and hipped roof dormers above other facades. A brick buttress extends outward from the west corner of the facade. A large brick chimney is at the eave near the front of the west facade. The exterior is clad in brown brick veneer laid in a running bond pattern with accents of decorative brickwork. The primary entrance is arched and trimmed in brick with stone accents near the center of the facade, set within a jerkinhead vestibule, and is accessed by a brick and concrete porch with a brick kneewall. A partial bay west of the entrance contains leaded glass windows and a pair of leaded glass windows are east of the entrance. A series of three and a pair of wood windows are on the second floor facade. Windows have brick sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property. There is no garage.
215	4014 Cortland Street			1935	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4014 Cortland Street is two-stories and topped with a hipped asphalt shingle roof intersected by a gable and a hipped wall dormer above the facade. A brick kneewall extends outward from the west corner of the facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of cast stone that has been painted white and decorative brickwork. The primary entrance is trimmed in stone near the east corner of the facade and is accessed by a brick and concrete porch with a low metal railing. A one-story bay is west of the entrance and contains vinyl windows and two glass block windows are on the second floor beneath the dormers. Windows have stone sills. Similar windows are arranged on other elevations. The driveway is concrete and runs along the rear of the property. A pyramidal roof garage is at the rear of the property. A black lightpost with a globe light fixture is located near the center of the front lawn.
216	4020 Cortland Street			1935	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4020 Cortland Street is two-stories and topped with a hipped asphalt shingle roof intersected by a gable and a hipped-with-gable wall dormer above the facade. A brick kneewall extends outward from the west corner of the facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of cast stone, decorative brickwork, and wood false half-limbering. The primary entrance is trimmed in stone near the east corner of the facade and is accessed by a brick and concrete porch with a metal railing. A one-story bay is west of the entrance and contains vinyl windows and two vinyl windows are on the second floor beneath the dormers. Windows have stone sills. Similar windows are arranged on other elevations. The driveway is concrete and runs along the rear of the property. A pyramidal roof garage is at the rear of the property.
217	4021 Cortland Street			1928	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4021 Cortland Street is two-stories and topped with a side gable asphalt shingle roof intersected by a large gable above the facade. A large brick chimney is at the eave near the center of the west facade. The exterior is clad in brown brick veneer laid in a running bond pattern with accents of decorative brickwork. The primary entrance is near the east corner of the facade within a curved jerkinhead vestibule, and is accessed by a stone and concrete porch with a metal railing. A series of four vinyl windows are west of the entrance beneath a series of three of the same windows above on the second floor. A small arched window with a metal railing is in the gable end. Windows have brick sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property. There is no garage. A black lightpost with a globe light fixture is located near the center of the front lawn.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
218	4029 Cortland Street			1928	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4029 Cortland Street is two-stories and topped with a deck (hipped topped with flat) asphalt shingle roof intersected by a large front gable above the facade and a hipped dormer above the east facade. A large brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of decorative brickwork and the second floor is clad in aluminum siding. The primary entrance is trimmed in brick near the east corner of the facade within a gabled vestibule, and is accessed by a full-width brick and concrete porch with a low metal railing and a metal awning structure. A series of four wood windows are west of the entrance in a one-story bay and a series of three wood windows with a fabric awning are arranged above on the second floor. Two windows with a fabric awning are above the entrance. Windows have brick sills and are fitted with storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property. A pyramidal roof garage is at the rear of the property. A black lightpost without a light fixture is near the center of the front lawn.
219	4030 Cortland Street			1935	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4030 Cortland Street is two-stories and topped with a hipped asphalt shingle roof intersected by a gable and a hipped-with-gable roof dormers above the facade. A brick kneewall extends outward from the west corner of the facade. A brick chimney is at the eave on the rear facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of cast stone and decorative brickwork. The primary entrance is trimmed in stone near the east corner of the facade and is accessed by a brick and concrete porch with a metal railing and an aluminum awning. A one-story bay is west of the entrance and contains vinyl windows and a vinyl window and a leaded glass steel window are on the second floor beneath the dormers. Windows have stone sills. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. A pyramidal roof garage is at the rear of the property. A black lightpost without a light fixture is near the center of the front lawn.
220	4036 Cortland Street			1935	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4036 Cortland Street is two-stories and topped with a hipped asphalt shingle roof intersected by a gable and a hipped dormer above the facade. A stone kneewall extends outward from the west corner of the facade. A brick chimney is at the eave on the rear facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is trimmed in stone near the east corner of the facade and is accessed by a brick and concrete porch with a metal railing and an aluminum awning. A one-story bay is west of the entrance and contains steel windows and steel windows are on the second floor beneath the dormers. Windows have stone sills, are fitted with storms, and some have aluminum awnings. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. A pyramidal roof garage is at the rear of the property. A black lightpost with a globe light fixture is near the center of the front lawn.
221	4037 Cortland Street			1932	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4037 Cortland Street is two-stories and topped with a hipped asphalt shingle roof intersected by multiple hipped roofs and a crenellated irregularly shaped tower on the facade. A stone kneewall extends outward from the west corner of the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in brown brick veneer laid in a running bond pattern with accents of stone veneer and decorative brickwork. The primary entrance is trimmed in stone veneer within the crenellated tower near the east corner of the facade and is accessed by a concrete porch with a low metal railing. Steel and leaded glass windows are west of the entrance and leaded glass and a vinyl window are on the second floor facade. Windows have brick sills. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. A pyramidal roof garage is at the rear of the property. A black lightpost with a lantern-style light fixture is near the center of the front lawn.
222	4044 Cortland Street			1935	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4044 Cortland Street is two-stories and topped with a pyramidal asphalt shingle roof intersected by a gable with a curved soffit and a hipped roof on the facade. A stone and brick kneewall extends outward from the west corner of the facade. A brick chimney is at the eave on the rear facade. The exterior is clad in brown brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is trimmed in stone near the east corner of the facade and is accessed by a brick and concrete porch with a low metal railing. A one-story bay is west of the entrance and contains vinyl windows and steel windows are on the second floor. Windows have stone sills and are fitted with storms. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. A front gable roof garage is at the rear of the property. A black lightpost with a globe light fixture is near the center of the front lawn.
223	4045 Cortland Street			1935	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4045 Cortland Street is two-stories and topped with a pyramidal asphalt shingle roof intersected by two gables on the facade. A brick chimney is at the eave on the rear facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of cast stone, decorative brickwork, and false half-timbering. The primary entrance is trimmed in stone near the east corner of the facade and is accessed by a brick and concrete porch with a low metal railing and a metal awning structure. A one-story bay is west of the entrance and contains steel windows and steel windows are on the second floor. Windows have stone sills and are fitted with storms. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. A pyramidal roof garage is at the rear of the property. A black lightpost with a globe light fixture is near the center of the front lawn.
224	4052 Cortland Street			1935	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4052 Cortland Street is two-stories and topped with a hipped asphalt shingle roof intersected by a curved wall dormer and a hipped roof on the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer and decorative brickwork. The primary entrance is trimmed in stone near the east corner of the facade and is accessed by a brick and concrete porch with a low metal railing. A one-story curved bay is west of the entrance and contains steel windows and steel windows are on the second floor. Windows have brick sills. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. A hipped roof garage is at the rear of the property. A black lightpost with a globe light fixture is near the center of the front lawn.
225	4053 Cortland Street			1927	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4053 Cortland Street is two-and-a-half stories and topped with a side gable asphalt shingle roof intersected by a jerkinhead dormer on the facade. A brick chimney is at the eave near the center of the east facade. The first floor exterior is clad in red brick veneer laid in a running bond pattern and the second floor is clad in vinyl siding. The primary entrance is arched, trimmed in brick, sheltered by a metal awning, and set within a jerkinhead vestibule at the center of the facade. It is accessed by a brick and concrete porch with a low metal railing and an aluminum awning. Steel windows are on either side of the entrance, two steel windows are on the second floor, and one steel window is in the dormer. Windows have brick or vinyl sills. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. A front jerkinhead roof garage is at the rear of the property. A black lightpost with a globe light fixture is near the center of the front lawn.
226	4060 Cortland Street			1935	French Eclectic	n/a	C	Unknown	Unknown	The house at 4060 Cortland Street is two-stories and topped with a hipped asphalt shingle roof intersected by a gable wall dormer and a hipped roof on the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer and decorative brickwork. The primary entrance is trimmed in stone near the east corner of the facade and is accessed by a brick and concrete porch with a low metal railing. A one-story bay is west of the entrance and contains vinyl windows and wood or vinyl windows are on the second floor. Windows have brick sills and those on the second floor have aluminum awnings. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. There is no garage.
227	4061 Cortland Street			1931	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4061 Cortland Street is two-stories and topped with a hipped asphalt shingle roof intersected by multiple hipped roofs and a polygonal roof on the facade. A brick and stone kneewall extends outward from the west corner of the facade. A brick chimney is near the eave near the center of the east facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer and decorative brickwork. The primary entrance is trimmed in stone veneer within a polygonal tower near the east corner of the facade and is accessed by a concrete porch with a wood railing. Three wood leaded glass windows are west of the entrance and two of the same type of windows are on the second floor. Windows have brick sills. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. A garage with a pyramidal roof intersected by a shed roof is at the rear of the property.
228	4068 Cortland Street			1935	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4068 Cortland Street is two-stories and topped with a hipped asphalt shingle roof intersected by two gabled wall dormers on the facade. A brick chimney is near the center of the house. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer and decorative brickwork. The primary entrance is near the east corner of the facade set within a gable roof portico with brick and stone arches. A brick and concrete porch with a low metal railing and a metal awning structure is west of the entrance and is accessed by a metal ramp. A steel window is west of the entrance and two steel windows are on the second floor beneath the dormers. Windows have brick sills and are fitted with storms. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. A pyramidal roof garage is at the rear of the property. A black lightpost with a globe light fixture is near the center of the front lawn.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
229	4069 Cortland Street			1927	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4069 Cortland Street is two-stories and topped with a side gable asphalt shingle roof intersected by a large front gable above the facade. A large brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of decorative brickwork and the second floor is clad in aluminum siding. The primary entrance is arched and trimmed in brick near the east corner of the facade within a gabled vestibule, and is accessed by a full-width brick and concrete porch with a low metal railing and an aluminum awning. Four wood leaded glass windows are west of the entrance and four wood leaded glass windows with an aluminum awning are on the second floor. Windows have brick sills and are fitted with storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property. A side gable roof garage is at the rear of the property. A black lightpost with a globe light fixture is near the center of the front lawn.
230	4076 Cortland Street			1935	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4076 Cortland Street is two-stories and topped with a pyramidal asphalt shingle roof intersected by a gable wall dormer and a hipped roof with a gable wall dormer on the facade. A stone kneewall extends outward from the west corner of the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is trimmed in fluted stone near the east corner of the facade and is accessed by a brick and concrete porch with a low metal railing, an aluminum awning, and a wood ramp. A steel window is west of the entrance and steel windows are on the second floor. Windows have stone sills and are fitted with storms, and some have aluminum awnings. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. A pyramidal roof garage is at the rear of the property. A black lightpost with a globe light fixture is near the center of the front lawn.
231	4077 Cortland Street			1932	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4077 Cortland Street is two-stories and topped with a hipped asphalt shingle roof intersected by a large front gable above the facade. A brick chimney is near the center of the house and a decorative chimney is near the center of the facade. The exterior is clad in brown brick veneer laid in a running bond pattern with accents stone veneer, cast stone, decorative brickwork, and wood false half-timbering. The primary entrance is arched and trimmed in cast stone near the east corner of the facade within a cantilevered vestibule, and is accessed by a full-width brick, stone, and concrete porch with a low metal railing and fabric and aluminum awnings. Steel windows are west of the entrance and vinyl windows are on the second floor. Windows have brick sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property. A side gable roof garage is at the rear of the property. A black lightpost with a globe light fixture is near the center of the front lawn.
232	4082 Cortland Street			1935	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4082 Cortland Street is two-stories and topped with a hipped asphalt shingle roof intersected by hipped wall dormers on the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, decorative brickwork, and wood false half-timbering. The primary entrance is trimmed in fluted stone near the east corner of the facade and is accessed by a brick and concrete porch with a low metal railing and a fabric awning. A bay with steel windows is west of the entrance and steel windows are on the second floor. Windows have brick sills and are fitted with storms. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. A hipped roof garage is at the rear of the property. A black lightpost with a globe light fixture is near the center of the front lawn.
233	4085 Cortland Street			1935	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4085 Cortland Street is two-stories and topped with a pyramidal asphalt shingle roof intersected by two gable wall dormers on the facade. A brick chimney is at the eave on the rear facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of cast stone and decorative brickwork. The primary entrance is trimmed in stone near the east corner of the facade and is accessed by a brick and concrete porch with a low metal railing. A bay with steel windows is west of the entrance and steel windows are on the second floor. Windows have stone sills. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. A hipped roof garage is at the rear of the property. A black lightpost with a lantern-style light fixture is near the center of the front lawn.
234	4090 Cortland Street			1939	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4090 Cortland Street is one-and-a-half-stories and topped with a side gable asphalt shingle roof intersected by two front gables on the facade. A large brick chimney is at the eave near the front of the west facade. The exterior clad in red brick veneer laid in a running bond pattern with accents of cast stone and decorative brickwork. The primary entrance is trimmed in stone near the west corner of the facade within a gabled vestibule topped and is accessed by a brick and concrete porch with a wood railing. Vinyl windows are west of the entrance. Windows have brick sills. Similar windows are arranged on other elevations. A concrete driveway runs along the rear of the property. A hipped roof garage is at the rear of the property.
235	4093 Cortland Street			1939	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4093 Cortland Street is one-and-a-half-stories and topped with a side gable asphalt shingle roof intersected a front gable at the center of the facade. A large brick chimney is at the eave near the front of the east facade. The exterior clad in red brick veneer laid in a running bond pattern with accents of cast stone and decorative brickwork. The primary entrance is trimmed in stone near the center of the facade within a gabled vestibule and is accessed by a brick and concrete porch with a low metal railing. Vinyl windows are on either side of the entrance. Windows have brick sills. Similar windows are arranged on other elevations. A concrete driveway runs along the rear of the property. A front gable roof garage is at the rear of the property.
236	4200 Cortland Street			1926	Prairie	1/garage	C	Unknown	Unknown	The apartment building at 4200 Cortland Street is two-stories and topped with a hipped asphalt shingle roof with a rounded roof dormers above the east and south façades and a hipped roof dormer facing west. Three brick chimneys are located along the center line, near the front, middle, and rear of the house. The facade is clad in brown face brick laid in a running bond pattern with accents of cast stone painted white. There are three primary entrances to each unit, one on the south façade and two on the east façade, each accessed by a concrete and brick porch covered by a flat roof awning supported by brick piers. The building is glazed with hung vinyl windows in sets of two, three, or single windows. Windows have cast stone sills painted white. Similar windows exist on other elevations. A short concrete driveway is accessed off of Petoskey Street to the east leading to a hipped roof garage.
237	4203 Cortland Street			1928	Tudor Revival	n/a	C	Unknown	Unknown	The apartment building at 4203 Cortland Street is two stories tall with a raised basement and flat roof, with an asphalt shingled hipped parapet roofline with front gabled and jerkinhead projections. A chimney and mechanical penthouse are on the roof. The façade is clad in red brick laid in a running bond pattern, with some decorative brickwork, corbelling, and accents of klinker brick and rusticated stone. There is some false half-timbering infilled with stucco at the second floor and attic level. The entrance is recessed within a front gabled vestibule which is clad in brick with an arched opening. West of the entrance is a two-story balcony supported by brick piers. Windows are a mix of vinyl and wood hung with brick sills.
238	4208 Cortland Street			1925	Prairie	n/a	C	Unknown	Unknown	The duplex at 4208 Cortland Street is two-stories and topped with a hipped asphalt shingle roof with a hipped roof dormer clad in wood siding centered above the façade containing three small wood windows. A brick chimney is located near the center of the house. The facade is clad in brown face brick, and secondary facades are clad in common red brick, laid in a running bond pattern. The primary entrance to each unit is near the east corner of the façade beneath a second floor balcony with a metal railing and supported by brick piers. The entrance is accessed by a concrete and brick porch. West of the entrance are three hung wood windows with divided upper sashes topped with infilled brick arches, beneath matching windows on the second floor. Windows have cast stone sills painted pale yellow. Similar windows exist on other elevations. An alley runs along the east of the house to the rear. There is no garage.
239	4213 Cortland Street			1926	Tudor Revival	n/a	C	Unknown	Unknown	The duplex at 4213 Cortland Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof intersected by a front gable, a shed dormer on the east, and a hipped roof over a two-story porch at the rear. A brick chimney is located near the center of the house. The facade is clad in brown face brick, and secondary facades are clad in common red brick, laid in a running bond pattern. There is false half-timbering beneath the front gable. The primary entrance to each unit is near the east corner of the façade beneath a second floor balcony with a wood railing and supported by brick piers. The entrance is accessed by a concrete and CMU porch. West of the entrance are three window openings that have been boarded over, beneath matching openings on the second floor. Windows have cast stone sills. Similar windows exist on other elevations. An alley runs along the east of the house to the rear. There is no garage.
240	4218 Cortland Street			1926	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4218 Cortland Street is two-stories and topped with a front gable asphalt shingle roof, with an overlapping front gable slightly projecting from the front of house, and intersected by a side gable and two gabled roof dormers. A brick chimney is located near the eave on the east façade. The facade is clad in blonde face brick laid in a running bond pattern. The primary entrance is near the east corner of the facade and is accessed by a brick and concrete full width porch that has partially collapsed. The door is accented by an arched brick surround, and the ghost line of a steeply pitched awning that has been removed is above the door. West of the entrance are three hung windows with brick arched surrounds infilled with hast stone, beneath a set of three smaller windows on the second floor. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear where there is a garage with a front gable roof.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
241	4221 Cortland Street			1926	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4221 Cortland Street is two-stories and topped with a hipped asphalt shingle roof, with a prominent front gable, and intersected by a gabled roof dormer at the rear. A brick chimney is located near the eave on the east façade. The facade is clad in brown face brick laid in a running bond pattern with some stone accents. The primary entrance is near the west corner of the facade and is accessed by a brick and concrete full width porch. The door is accented by an arched brick surround with keystone, set within a slightly projecting front gabled entrance vestibule. East of the entrance are three wood hung windows, the whole set covered by a brick arched lintel, and the second floor is glazed with three wood hung windows with divided upper sashes. Windows have cast stone sills painted white. Similar windows exist on other elevations. A concrete driveway runs along the west of the house to the rear. There is no garage.
242	4224 Cortland Street			1927	Tudor Revival	n/a	C	Unknown	Unknown	The duplex at 4224 Cortland Street is two-stories and topped with a cross gable asphalt shingle roof, composed of a side gable that meets a front gable toward the rear, intersected by two prominent overlapping front gables. A brick chimney is located near the eave on the west façade and another is near the center of the house. The facade is clad in brown face brick laid in a running bond pattern, with areas that have been clad with wide metal siding. The primary entrance to each unit is near the east corner of the facade beneath a second-floor balcony with a wood railing, supported by brick piers. The door is arched and accessed by a concrete and brick porch. West of the entrance is a two story canted bay, glazed on both floors with steel casement windows with transoms above. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear. There is no garage.
243	4227 Cortland Street			1927	Tudor Revival	n/a	C	Unknown	Dean L. Cullum	The house at 4227 Cortland Street is two-stories and topped with a side gable asphalt shingle roof, which meets a front gable projecting slightly from the facade. A brick chimney is located on the front of the house. The facade is clad in brown face brick laid in a running bond pattern, with accents of stone and the second floor clad in wide metal siding. The primary entrance is near the east corner, with an arched door accessed by a concrete and brick porch. West of the entrance is a vinyl slider window, directly beneath a matching window on the second floor. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear. There is no garage.
244	4230 Cortland Street			1928	Tudor Revival	1/garage	C	Unknown	Unknown	The duplex at 4230 Cortland Street is two-stories and topped with a side gable asphalt shingle roof, which meets a prominent front gable overlapping with a jerkinhead projecting slightly from the facade. A brick chimney is located at the eave on the west façade of the house. The facade is clad in brown face brick laid in a running bond pattern, and the second floor clad in vinyl siding. The primary entrance is near the east corner, accessed by a concrete and brick full width porch with metal awning and railing. The door is covered with an aluminum awning, and flanked by small multi-light windows with brick arched lintels. West of the entrance are three multi-light wood hung windows, beneath three matching windows on the second floor, both with aluminum storms affixed to the exterior. Similar windows exist on other elevations and some have cast stone sills. A concrete driveway runs along the east of the house to the rear where there is a garage. A black lightpost with globe light fixture is in the front lawn.
245	4235 Cortland Street			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4235 Cortland Street is two-stories and topped with a side gable asphalt shingle roof, which meets a prominent centered front gable, and intersected by a hipped roof dormer at the rear. A brick chimney is located at the eave on the west façade of the house. The facade is clad in brown face brick laid in a running bond pattern, and the second floor clad in stucco. The primary entrance is near the east corner, accessed by a concrete and brick full width porch with metal railing. The door is arched with cast stone springers and set within a slightly projecting front gabled vestibule. West of the entrance is a window opening that has been boarded over, beneath three vinyl hung windows on the second floor. Similar windows exist on other elevations and have cast stone sills. A concrete driveway runs along the east of the house to the rear where there is a garage with front gabled roof.
246	4238 Cortland Street			1926	Tudor Revival	n/a	C	Unknown	Unknown	The duplex at 4238 Cortland Street is two-stories and topped with a cross gable asphalt shingle roof, composed of a side gable that meets a hipped roof toward the rear, intersected by a prominent front gable beside an arched wall dormer, and a shed roof dormer on the east. A brick chimney is located near the eave on the west façade and another is near the center of the house. The facade is clad in red face brick laid in a running bond pattern. The primary entrance to each unit is near the east corner of the facade beneath a second-floor balcony with a wood railing, supported by brick piers. The door is accessed by a concrete and brick full width porch with brick kneewall. West of the entrance are three vinyl windows within arched brick openings, beneath a ribbon of four vinyl windows on the second floor. A small arched wood window is within the front gable at the attic level. Similar windows exist on other elevations and have cast stone sills. A concrete driveway runs along the east of the house to the rear. There is no garage.
247	4246 Cortland Street			1925	Tudor Revival	n/a	C	Unknown	Unknown	The duplex at 4246 Cortland Street is two-stories and topped with a hipped asphalt shingle roof, intersected by a prominent front gable centered on the facade. A brick chimney is located near the eave on the west façade. The facade is clad in blonde face brick laid in a running bond pattern on the first floor, and wood shingles on the second floor, with false half-timbering on the attic level beneath the front gable and dentiled trim below. The primary entrance to each unit is near the east corner of the facade beneath a shingled cantilevered awning with flared eaves. The door is accessed by a concrete and brick full width porch. West of the entrance are three vinyl windows, with three matching windows on the second floor. A small fixed window is within the front gable at the attic level. Similar windows exist on other elevations and have cast stone sills on the first floor. A concrete ribbon driveway runs along the east of the house to the rear. There is no garage.
248	4249 Cortland Street			1925	Tudor Revival	1/garage	C	Unknown	Dean L. Cullum	The house at 4249 Cortland Street is two-stories and topped with a side gable asphalt shingle roof, which intersects with a prominent front gable. A brick chimney is located at the eave on the west façade of the house. The facade is clad in brown face brick laid in a running bond pattern, and the second floor clad in vinyl siding. The primary entrance is near the east corner, accessed by a concrete and brick stoop and a wood ramp, and covered by a front gabled portico supported by brick piers. West of the entrance are three hung windows covered by an aluminum metal awning, directly beneath three matching windows on the second floor. Similar windows exist on other elevations and have cast stone sills on the first floor. A concrete driveway runs along the east of the house to the rear where there is a garage with side gabled roof.
249	4252 Cortland Street			1927	Tudor Revival	n/a	C	Unknown	Unknown	The duplex at 4252 Cortland Street is two-stories and topped with a cross gable asphalt shingle roof, composed of a side gable that meets a hipped roof towards the rear, intersected by two prominent front gables. A brick chimney is located on the front façade. The facade is clad in red face brick laid in a running bond pattern with decorative brickwork and stone accents. The primary entrance to each unit is near the east corner of the facade beneath a two-story front gabled porch supported by brick piers with an arched opening. The door is accessed by a concrete and brick full width porch. West of the entrance are two narrow full height fixed windows on either side of the chimney, with two narrow slider wood windows on the second floor. Similar windows exist on other elevations and have cast stone sills. A concrete driveway runs along the east of the house to the rear. There is no garage.
250	4255 Cortland Street			1927	Tudor Revival	n/a	C	Unknown	Dean L. Cullum	The house at 4255 Cortland Street is two-stories and topped with a side gable asphalt shingle roof, which meets a front gable projecting slightly from the facade. A brick chimney is located on the front of the house. The facade is clad in brown face brick laid in a running bond pattern, with accents of stone and the second floor clad in vinyl siding. The primary entrance is near the east corner, with an arched door accessed by a concrete and brick porch. West of the entrance are two vinyl hung windows, set within a larger opening that has been partially infilled with vinyl siding, and two matching windows are on the second floor above. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear. There is no garage.
251	4260 Cortland Street			1925	Prairie	n/a	C	Unknown	Unknown	The duplex at 4260 Cortland Street is two-stories and topped with a hipped asphalt shingle roof with a hipped roof dormer clad in wood siding centered above the façade containing two wood windows. A brick chimney is located at the eave on the east façade and another is near the center of the house. The facade is clad in tan face brick, and secondary facades are clad in common red brick, laid in a running bond pattern. The primary entrance to each unit is near the west corner of the façade beneath a second floor balcony with a metal awning and railing, supported by brick piers. The entrance is accessed by a concrete and brick porch. East of the entrance are three hung windows beneath an aluminum metal awning, beneath matching windows on the second floor which are each covered with an awning. Windows have brick sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear. There appears to be no garage.
252	4267 Cortland Street			1925	Prairie	1/garage	C	Unknown	Unknown	The duplex at 4267 Cortland Street is two-stories and topped with a hipped asphalt shingle roof with a hipped roof dormer clad in wood shingle siding centered above the façade containing two wood windows, and shed roof dormer facing east. A brick chimney is located near the center of the house. The facades are clad in blonde face brick laid in a running bond pattern, with some decorative brickwork. The primary entrance to each unit is near the west corner of the façade, brick piers are present but a second floor balcony has been removed. The entrance is accessed by a concrete and brick porch. East of the entrance are three wood hung windows with divided upper sashes surrounded by infilled brick arches, beneath matching windows on the second floor. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear where there is a garage.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
253	4268 Cortland Street			1948	Colonial Revival	n/a	C	Unknown	Unknown	The duplex at 4268 Cortland Street is two-stories and topped with a hipped asphalt shingle roof. A brick chimney is located near the center towards the rear of the house. The facades are clad in red and brown face brick laid in a running bond pattern, with a two-story canted bay clad in vinyl on the first floor and wide metal siding on the second floor. The primary entrance to each unit is near the east corner of the façade, accessed by a small concrete and brick porch. West of the entrance, the canted bay is glazed with hung windows, some are wood with vertically divided upper sashes and aluminum storms and screens are on the second floor windows. Similar windows exist on other elevations, and have brick sills. A concrete driveway runs along the east of the house to the rear where there is no garage.
254	4271 Cortland Street			1923	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4271 Cortland Street is two-stories and topped with a front gable asphalt shingle roof. A brick chimney is located at the eave on the west façade of the house. The facade is clad in brown face brick laid in a running bond pattern, and the second floor clad in wood shingle siding. The primary entrance is near the east corner, accessed by a concrete and CMU porch, and the arched door is covered by an aluminum awning. West of the entrance are two hung windows covered by an aluminum metal awning, beneath two similar windows on the second floor. Similar windows exist on other elevations and have cast stone sills. A concrete driveway runs along the east of the house to the rear where there appears to be no garage.
255	4274 Cortland Street			1924	Prairie	1/garage	C	Unknown	Unknown	The duplex at 4274 Cortland Street is two-stories and topped with a hipped asphalt shingle roof with a rounded roof dormer clad in wood shingle siding centered above the façade, and hipped roof dormers facing east and at the rear. A brick chimney is located at the eave on the west façade and another is near the center of the house. The facade is clad in brown face brick, with secondary facades clad in red common brick, both laid in a running bond pattern, with some decorative brickwork and stone accents. The primary entrance to each unit is near the east corner of the façade, beneath a second floor balcony with metal railing supported by brick piers and covered by an aluminum awning. The entrance is accessed by a full width concrete and brick porch with metal railing and covered by an aluminum awning. West of the entrance are three wood hung windows with divided upper sashes, beneath matching windows on the second floor. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear where there is a garage.
256	4277 Cortland Street			1924	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4277 Cortland Street is two-stories and topped with a cross gable asphalt shingle roof, composed of a side gable that meets a front gable roof toward the rear, intersected by two prominent front gables. A brick chimney is located near the eave on the west façade. The facade is clad in blonde face brick laid in a running bond pattern. The primary entrance to each unit is near the east corner of the facade beneath a steeply pitched front gabled portico, supported by paired square wood posts. The door is trimmed in cast stone quoins painted white and is accessed by a concrete and brick porch. West of the entrance is a large slider window, beneath two hung vinyl windows on the second floor. Similar windows exist on other elevations and have cast stone sills on the first floor. A concrete driveway runs along the east of the house to the rear. There is no garage.
257	4280 Cortland Street			1925c.	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4280 Cortland Street is two-stories and topped with a hipped asphalt shingle roof, intersected by multiple overlapping front gables. A brick chimney is located near the eave on the west façade. The facade is clad in tan face brick laid in a running bond pattern, and wood shingle siding the second floor. The primary entrance to each unit is near the east corner of the facade beneath an aluminum awning. The door is arched and is accessed by a concrete and brick porch with metal railing. West of the entrance are two pairs of hung windows with divided upper sashes, each pair beneath an infilled brick arched lintel with keystones, beneath two hung matching windows on the second floor. Similar windows exist on other elevations and have cast stone sills. A concrete driveway runs along the east of the house to the rear where there is a garage.
258	4283 Cortland Street			1927	Tudor Revival	n/a	C	Unknown	Miller-Storm Company	The house at 4283 Cortland Street is two-stories and topped with a side gable asphalt shingle roof, intersected by an overlapping front gable. A stone chimney is located on the front façade. The facade is clad in stone veneer and brick veneer on the secondary facades, with vinyl siding on the second floor. The primary entrance to each unit is near the west corner of the facade. The door is arched and is accessed by a concrete and stone porch with metal railing. East of the entrance is a set of steel casement windows with brick sills, beneath windows on the second floor that are obscured from view behind vegetation. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear where there is no garage.
259	4288 Cortland Street			1925c.	Tudor Revival	1/garage	C	Unknown	Unknown	The duplex at 4288 Cortland Street is two-stories and topped with a cross gable asphalt shingle roof, composed of a side gable that meets a hipped roof toward the rear, intersected by two front gables. A brick chimney is located at the eave on the west façade and another is near the center of the house. The facade is clad in reddish brown brick veneer, with wide metal siding beneath the front gable on the second floor. The primary entrance to each unit is near the east corner of the façade, beneath a second floor balcony with metal railing supported by grouped square wood posts and covered by an aluminum awning. The door is accessed by a concrete and brick porch with the steps removed. West of the entrance is an enclosed porch beneath an aluminum awning, beneath three hung windows on the second floor. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear where there is a garage.
260	4291 Cortland Street			1926	Colonial Revival	n/a	C	Unknown	Unknown	The house at 4291 Cortland Street is two-stories and topped with a gambrel asphalt shingle roof. A shed wall dormer at the front of the house creates a recessed balcony, and a continuous shed dormer is at the rear. A brick chimney is located at the eave on the west facade. The facade is clad with brown brick veneer laid in a running bond pattern, and wood shingle siding on the second floor. The primary entrance is near the east corner the facade beneath a low pitched gabled portico with brick piers and arched openings, and is accessed by a brick and concrete porch with metal railing. West of the entrance is a set of steel casement windows. Similar windows exist on other elevations, and have cast stone sills. There is no garage.
261	4294 Cortland Street			1927	Tudor Revival	n/a	C	Unknown	Unknown	The duplex at 4294 Cortland Street is two-stories and topped with a front gable asphalt shingle roof, intersected by a side gable and an overlapping front gable above the entrance vestibule. A brick chimney is located on the front façade. The facade is clad in brown brick veneer laid in a running bond pattern, with some decorative brickwork and baby buttresses protruding from the corners, with vinyl siding on the second floor beneath the side gable. The primary entrance to each unit is near the east corner of the facade. The door is arched and is accessed by a concrete and brick and concrete porch. West of the entrance is a set of steel casement windows with sidelights and transoms, beneath matching windows on the second floor, both with brick sills. Similar windows exist on other elevations. A concrete ribbon driveway runs along the east of the house to the rear where there is no garage.
262	4300 Cortland Street			1925	Prairie	n/a	C	Unknown	Unknown	The duplex at 4300 Cortland Street is two-stories and topped with a hipped asphalt shingle roof with a hipped roof dormer clad in shingle siding centered above the façade, and a hipped roof dormer facing east. A brick chimney is located near the center of the house. The facade is clad in tan face brick, with secondary facades clad in red common brick, both laid in a running bond pattern, with some decorative brickwork. The primary entrance to each unit is near the east corner of the façade, beneath a two-story, hipped roof balcony supported by brick piers and a brick arch. The entrance is accessed by a full width concrete and brick porch with brick kneewall. West of the entrance are three wood hung windows within arched openings, beneath three wood hung windows on the second floor. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear where there is no garage.
263	4303 Cortland Street			1926	Prairie	1/garage	C	Unknown	Unknown	The duplex at 4303 Cortland Street is two-stories and topped with a hipped asphalt shingle roof with a hipped roof dormer clad in shingle siding centered above the façade. A brick chimney is located near the center of the house. The facade is clad in red face brick laid in a running bond pattern, with some decorative brickwork. The primary entrance to each unit is near the east corner of the façade, beneath a second floor balcony supported by brick piers, which has been enclosed beneath a metal awning and glazed metal panels. The entrance is accessed by a concrete and brick porch with brick kneewall. West of the entrance are three wood hung windows with leaded glass detailing, beneath matching windows on the second floor. Windows have aluminum storms affixed to the exterior and cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear where there is a pyramidal roof garage.
264	4310 Cortland Street			1929	Tudor Revival	n/a	C	Unknown	Unknown	The duplex at 4310 Cortland Street is two-stories and topped with a cross gable asphalt shingle roof, composed of a side gable that meets a hipped roof toward the rear, intersected by two overlapping front gables. A brick chimney is located at the eave on the west facade of the house. The facade is clad in orange and brown face brick laid in a running bond pattern, with some decorative brickwork and a baby buttress protruding from the west corner. The primary entrance to each unit is near the east corner of the façade, recessed within a brick arch and framed on either side and above by small fixed windows with leaded glass in a diamond pattern. The entrance is accessed by a concrete and brick porch with a metal railing. West of the entrance a steel casement window has been mostly boarded over, beneath a matching casement window with sidelights and transom on the second floor. Windows have brick sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear where there is no garage.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
265	4311 Cortland Street			1926	Tudor Revival	n/a	C	Unknown	Unknown	The duplex at 4311 Cortland Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof with a hipped roof dormer intersecting by a front gable and a shed roof dormer to the east. A brick chimney is located at the eave on the east facade of the house. The facade is clad in red face brick laid in a running bond pattern. The primary entrance to each unit is near the west corner of the façade, beneath a second floor balcony supported by paired square wood posts, which has been enclosed beneath a metal awning and metal panels and two hung windows. The entrance is accessed by a concrete and brick porch with metal railing. West of the entrance are three vinyl hung windows, beneath a ribbon of four windows on the second floor supported by decorative brackets. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear where there is no garage.
266	4316 Cortland Street			1925c.	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4316 Cortland Street is two-stories and topped with a side gable asphalt shingle roof intersected by front gables at the front and rear, and a jerkinhead above the entrance vestibule. A brick chimney is located at the eave on the west facade of the house. The facade is clad in red face brick laid in a running bond pattern on the first floor, and vinyl siding on the second floor. The primary entrance is near the east corner of the façade, accessed by a concrete and brick porch with metal railing. West of the entrance are three hung windows covered by an aluminum metal awning, beneath matching windows on the second floor. Similar windows exist on other elevations. A concrete driveway runs along the west of the house to the rear where there is a garage. A black lightpost is in the front lawn.
267	4319 Cortland Street			1926	Tudor Revival	1/garage	C	Unknown	Unknown	The duplex at 4319 Cortland Street is two-stories and topped with a cross gable asphalt shingle roof, composed of a side gable that meets a hipped roof toward the rear, intersected by an overlapping front gable. A brick chimney is located near the center of the house. The facade is clad in blonde face brick, and secondary facades clad in red common brick, both laid in a running bond pattern. There is wood shingle siding beneath the side gable at the attic level. The primary entrance to each unit is near the west corner of the façade, beneath a second floor balcony with metal railing supported by brick piers. The entrance is accessed by a concrete and brick porch with a metal railing. West of the entrance there are three wood hung windows with divided upper sashes topped with brick infilled arches, beneath three matching hung windows on the second floor. A small arched window at the attic level beneath the front gable. Windows have brick sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear where there is a pyramidal roof garage.
268	4320 Cortland Street			1927	Tudor Revival	n/a	C	Unknown	Miller-Storm Company	The duplex at 4320 Cortland Street is two-stories and topped with a side gable asphalt shingle roof intersected by front gables at the front and rear. A brick chimney is located at the eave on the west facade of the house and another is near the center of the house. The facade is clad in brown face brick laid in a running bond pattern on the first floor, and vinyl siding on the second floor. The primary entrance is near the east corner of the façade, beneath an asphalt shingled eyebrow dormer, and is accessed by a concrete and brick porch with metal railing. West of the entrance are two hung windows covered by an aluminum metal awning, beneath four hung windows with divided lights on the second floor also covered with an aluminum awning. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear where there is no garage.
269	4325 Cortland Street			1928	Tudor Revival	n/a	C	Unknown	Unknown	The duplex at 4325 Cortland Street is two-stories and topped with a side gable asphalt shingle roof intersected by a front gable and jerkinhead above the entrance vestibule. A brick chimney is located at the eave on the west facade of the house. The facade is clad in brown face brick laid in a running bond pattern, with some areas of false half-timbering on the second floor. The primary entrance is near the east corner of the façade, beneath a second-story recessed balcony with metal railing, and is accessed by a concrete and brick porch with metal railing which is covered by an aluminum metal awning. West of the entrance are three wood hung windows, beneath three windows on the second floor. Similar windows exist on other elevations, and have aluminum storm windows affixed to the exterior. A concrete driveway runs along the east of the house to the rear where there is no garage.
270	4328 Cortland Street			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The duplex at 4328 Cortland Street is two-stories and topped with a cross gable asphalt shingle roof, composed of a side gable that meets a hipped roof toward the rear, intersected by a front gable and front gabled roof dormer. A brick chimney is located at the eave on the west facade and another is near the center of the house. The facade is clad in red face brick, laid in a running bond pattern. There is vinyl siding beneath the front and side gables at the attic level. The primary entrance to each unit is near the east corner of the façade, beneath a second floor balcony with metal railing supported by brick piers. The entrance is accessed by a concrete and brick porch with a metal railing. West of the entrance there are three wood hung windows with divided upper sashes topped with brick lintels, beneath three similar windows on the second floor. Windows have brick sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear where there is no garage.
271	4333 Cortland Street			1925	Tudor Revival	n/a	C	Unknown	Unknown	The duplex at 4333 Cortland Street is two-stories and topped with a cross gable asphalt shingle roof, composed of a side gable that meets a hipped roof toward the rear, intersected by a front gable and front gabled roof dormer. A brick chimney is located near the center of the house. The facade is clad in tan face brick, with red common brick on the secondary facades, both laid in a running bond pattern. There is vinyl siding beneath the front and side gables at the attic level. The primary entrance to each unit is near the east corner of the façade, beneath a second floor balcony with metal railing awning that is supported by square wood posts. The entrance is accessed by a concrete and brick porch with a metal railing. West of the entrance there is a large slider window topped with brick lintel, beneath a matching window on the second floor. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear where there is no garage.
272	4336 Cortland Street			1926	Prairie	n/a	C	Unknown	Unknown	The duplex at 4336 Cortland Street is two-stories and topped with a hipped asphalt shingle roof with a hipped roof dormer clad in vinyl siding centered above the façade. A brick chimney is located at the eave on the west façade and another is near the center of the house. The facade is clad in red face brick laid in a running bond pattern, with some decorative brickwork. The primary entrance to each unit is near the east corner of the façade, beneath a second floor balcony supported by brick piers. The entrance is accessed by a concrete and brick porch with a metal railing and brick kneewall. West of the entrance are three wood hung windows with divided upper sashes topped with brick infilled arches, beneath matching windows on the second floor. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear where there is no garage.
273	4342 Cortland Street			1926	Tudor Revival	1/garage	C	Unknown	Unknown	The duplex at 4342 Cortland Street is two-stories and topped with a cross gable asphalt shingle roof, composed of a side gable that meets a hipped roof toward the rear, intersected by a front gable and an arched wall dormer. A brick chimney is located at the eave on the west façade and another near the center of the house. The facade is clad in brown face brick, with red common brick on the secondary facades, both laid in a running bond pattern, with some decorative brickwork. There is wood shingle siding beneath the side gables at the attic level. The primary entrance to each unit is near the east corner of the façade, beneath a second floor balcony with brick kneewall that is supported by brick piers and a brick arch. The entrance is accessed by a concrete and brick porch with a brick kneewall. West of the entrance there are three wood hung windows with leaded glass detailing on the upper sashes topped with brick arches infilled with stucco and tiles, beneath three wood hung windows with leaded glass detailing on the upper sashes on the second floor. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear where there is a garage.
274	4350 Cortland Street			1954	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4350 Cortland Street is one-and-a-half-stories and topped with a side gable asphalt shingle roof intersected by overlapping front gables. A brick chimney is at the eave near the rear of the west facade. The exterior is clad in yellow brick veneer laid in a running bond pattern with accents of cast stone at the entrance vestibule, which is at the east corner of the facade and is accessed by a brick and concrete porch with a low metal railing. A bay window is clad with vertical wood panel west of the entrance. The house is clad in wide metal siding beneath the front and side gables. Glass block windows are on either side of the entrance. Similar windows are arranged on other elevations. A concrete driveway runs along the east of the property to the rear where there is a front gable roof garage.
275	4502 Cortland Street			1926	Prairie	1/garage	C	Unknown	Unknown	The duplex at 4502 Cortland Street is two-stories and topped with a hipped asphalt shingle roof with a hipped roof dormer clad in shingle siding centered above the façade. A brick chimney is located at the eave on the west façade and another is near the center of the house. The facade is clad in brown face brick laid in a running bond pattern, with some decorative brickwork and cast stone accents, while the secondary facades are clad in red common brick. The primary entrance to each unit is near the east corner of the façade, beneath a second floor balcony with a metal awning and supported by brick piers. The entrance is accessed by a concrete and brick porch with a brick kneewall. West of the entrance are three wood hung windows topped with brick infilled arches, beneath three wood hung windows with divided upper sashes on the second floor. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear where there is a front gable roof garage.
276	4503 Cortland Street			1926	Tudor Revival	1/garage	C	Unknown	Unknown	The duplex at 4503 Cortland Street is two-stories with a gable-on-hip and jerkinhead asphalt shingle roof intersected by a hipped roof wing at the rear, creating an L-shaped footprint. A brick chimney is located at the peak on the front portion and another is towards the rear of the building. The facade is clad in blonde face brick laid in a running bond pattern, with false half-timbering at the wall dormers on the front façade. The primary entrance is near the west corner of the façade beneath a pergola, and is accessed by a concrete and CMU porch. The building has a mix of wood and vinyl hung windows, with divided sashes and cast stone sills. A concrete driveway is accessed off of Martindale Street to the south.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
277	4510 Cortland Street			1926	Tudor Revival	n/a	C	Unknown	Unknown	The duplex at 4510 Cortland Street is two-stories and topped with a cross gable asphalt shingle roof, composed of a side gable that meets a hipped roof toward the rear, intersected by a front gable. A brick chimney is located at the eave on the east façade and another near the center of the house. The facade is clad in light brown face brick, with red common brick on the secondary façades, both laid in a running bond pattern. There is wood shingle siding beneath the side gables at the attic level. The primary entrance to each unit is near the west corner of the façade, beneath a second floor balcony that is supported by brick piers. The entrance is accessed by a concrete and brick porch with a metal railing. West of the entrance there are three wood hung windows with divided upper sashes topped with brick arches infilled with stucco, beneath three matching windows on the second floor that are covered by an aluminum awning. Windows have brick sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear. There is no garage.
278	4511 Cortland Street			1925	Prairie	1/garage	C	Unknown	Unknown	The house at 4511 Cortland Street is two-stories and topped with a pyramidal asphalt shingle roof, with a hipped roof dormer facing east. A brick chimney is located at the eave on the west façade. The facade is clad in light brown face brick laid in a running bond pattern. The primary entrance is near the east corner of the façade, within a projecting vestibule clad in stone veneer. The entrance is covered by an aluminum metal awning and is accessed by a concrete porch with a metal railing. West of the entrance there are three hung windows topped with brick arches infilled with cast stone, beneath three matching windows on the second floor. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear where there is a front gable roof garage.
279	4516 Cortland Street			1926	Tudor Revival	n/a	C	Unknown	Miller-Storm Company	The house at 4516 Cortland Street is two-stories and topped with a side gable asphalt shingle roof intersected by a front gable overlapping with a jerkinhead above the entrance vestibule. A brick chimney is at the eave of the west facade. The exterior is clad in red and brown brick veneer laid in a running bond pattern on the first floor, with the second floor is clad in false half-timbering infilled with stucco. The entrance is arched and is accessed by a brick and concrete full width porch. Four vinyl hung windows are west of the entrance, beneath three vinyl hung windows on the second floor. Similar windows are arranged on other elevations, and have brick sills on the first floor. An alley runs along the west of the property. There is no garage.
280	4734 Cortland Street			1928	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4734 Cortland Street is two-stories and topped with a side gable asphalt shingle roof intersected by a front gable catslide above the entrance vestibule. A brick chimney is at the eave of the east facade. The exterior is clad in brown brick veneer laid in a running bond pattern on the first floor, with the second floor is clad in vinyl siding. The entrance is arched and is accessed by a brick and concrete full width porch with stairs facing the front and another set facing the alley to the east. A fixed window flanked by two small hung windows are west of the entrance, beneath a similar set of windows on the second floor. Similar windows are arranged on other elevations, and have cast stone sills on the first floor. An alley runs along the east of the property. There is no garage.
281	4740 Cortland Street			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The duplex at 4740 Cortland Street is two-stories and topped with a hipped asphalt shingle roof intersected by a hipped roof bay projecting from the front, and a steeply pitched front gable above the entrance. A brick chimney is near the center of the house. The exterior is clad in brown brick veneer laid in a running bond pattern on the first floor, with the second floor clad in wood shingle siding. The entrance is accessed by a concrete stoop. A fixed window is west of the entrance, beneath a matching window on the second floor. Similar windows arranged on other elevations, and have cast stone sills on the first floor. A concrete alley runs along the east of the property to the rear where there is a pyramidal roof garage.
282	4750 Cortland Street			1922	Prairie	n/a	C	Unknown	Unknown	The duplex at 4750 Cortland Street is two-stories and topped with a hipped asphalt shingle roof intersected by a hipped roof dormers above the front, west, and rear façades. A brick chimney is at the eave on the east façade of the house. The exterior is clad in brown brick veneer laid in a running bond pattern. The entrance is accessed by a brick and concrete stoop. A two-story canted bay is east of the entrance, with vinyl slider windows in the center and vinyl hung windows covered by aluminum awnings on either side. Similar windows are arranged on other elevations, and have cast stone sills on the first floor. A concrete alley runs along the east of the property to the rear. There is no garage.
283	4754 Cortland Street			1929	Tudor Revival	n/a	C	Unknown	Unknown	The duplex at 4754 Cortland Street is two-stories and topped with a cross gable asphalt shingle roof, composed of a side gable that meets a hipped roof toward the rear, intersected by overlapping front gables. A brick chimney is located on the front of the house. The facade is clad in red face brick laid in a running bond pattern with accents of cast stone, and false half-timbering at one of the front gables. The primary entrance to each unit is near the east corner of the façade within a projecting vestibule, topped with a cast stone lintel and flanked by two small window openings that have been boarded over, and is accessed by a concrete and brick porch. West of the entrance a window opening has been boarded over, beneath a steel casement window on a recessed balcony at the second floor. Another window on the second floor has leaded glass detailing in a diamond pattern. Windows have brick sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear. There is no garage.
284	4762 Cortland Street			1938	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 4762 Cortland Street is two-stories and topped with a side gable asphalt shingle roof. A brick chimney is located at the eave on the west facade. The facade is clad with brown brick veneer laid in a running bond pattern. The primary entrance is near the east corner the facade beneath an aluminum metal awning, and is accessed by a low brick and concrete porch. West of the entrance are two hung vinyl windows with vinyl siding below, beneath matching windows on the second floor, each with black shutters and cast stone sills. A driveway runs along the east of the property to the rear where there is a garage.
285	4768 Cortland Street			1926	Prairie	1/garage	C	Unknown	Unknown	The duplex at 4768 Cortland Street is two-stories and topped with a hipped asphalt shingle roof intersected by a front gabled roof dormer with three small windows with leaded glass detailing centered above the front facade. A brick chimney is near the center of the house. The exterior is clad in brown brick veneer laid in a running bond pattern. The entrance is accessed by a brick and concrete stoop beneath a second floor balcony with metal railing and awning, which is supported by brick piers. West of the entrance are three vinyl hung windows covered by an aluminum metal awning, beneath matching windows on the second floor. Similar windows are arranged on other elevations, and have cast stone sills. A driveway runs along the east of the property to the rear where there is a pyramidal roof garage.
286	4774 Cortland Street			1926	Prairie	n/a	C	Unknown	Unknown	The duplex at 4774 Cortland Street is two-stories and topped with a hipped asphalt shingle roof intersected by a front gabled roof dormer clad in wood shingles with three small windows centered above the front facade. A brick chimney is near the center of the house. The exterior is clad in blonde brick veneer, with red common brick at the secondary façades, both laid in a running bond pattern. The entrance is accessed by a brick and concrete porch beneath a second floor balcony with metal railing and awning, which is supported by brick piers. West of the entrance are three vinyl hung windows covered by an aluminum metal awning, beneath matching windows on the second floor. Similar windows are arranged on other elevations, and have cast stone sills. A driveway runs along the east of the property to the rear where there is no garage.
287	4782 Cortland Street			1926	Prairie	n/a	C	Unknown	Unknown	The duplex at 4782 Cortland Street is two-stories and topped with a hipped asphalt shingle roof intersected by a hipped roof dormer with three small windows centered above the front facade. A brick chimney is near the center of the house. The exterior is clad in orange brick veneer, with red common brick at the secondary façades, both laid in a running bond pattern with some decorative brickwork. The entrance is accessed by a brick and concrete porch beneath a second floor balcony with metal railing, which is supported by brick piers. West of the entrance are three vinyl hung windows topped with brick infilled arches, beneath matching windows on the second floor. Similar windows are arranged on other elevations, and have cast stone sills. A driveway runs along the east of the property to the rear where there is no garage.
288	4790 Cortland Street			1926	Prairie	n/a	C	Unknown	Unknown	The duplex at 4790 Cortland Street is two-stories and topped with a hipped asphalt shingle roof intersected by a front gabled roof dormer with three small leaded glass windows centered above the front facade. A brick chimney is near the center of the house. The exterior is clad in brown brick veneer, with red common brick at the secondary façades, both laid in a running bond pattern. The entrance is accessed by a brick and concrete porch beneath a second floor balcony covered by an aluminum awning, which is supported by brick piers. West of the entrance are three wood hung windows with leaded glass detailing on the upper sashes covered by an aluminum awning, beneath matching windows on the second floor. Similar windows are arranged on other elevations, and have cast stone sills. A driveway runs along the east of the property to the rear where there is no garage.
289	4798 Cortland Street			1926	Prairie	n/a	C	Unknown	Unknown	The duplex at 4798 Cortland Street is two-stories and topped with a hipped asphalt shingle roof intersected by a hipped roof dormer with three small leaded glass windows centered above the front facade. A brick chimney is near the center of the house. The exterior is clad in dark and light brown brick veneer, with red common brick at the secondary façades, both laid in a running bond pattern. The entrance is accessed by a brick and concrete porch beneath a second floor balcony with a metal railing and aluminum awning, which is supported by brick piers. West of the entrance are three wood hung windows with leaded glass detailing on the upper sashes covered by an aluminum awning, beneath matching windows on the second floor. Similar windows are arranged on other elevations, and have cast stone sills. A driveway runs along the east of the property to the rear where there is no garage.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
290	4804 Cortland Street			1926	Tudor Revival	n/a	C	Unknown	Unknown	The duplex at 4804 Cortland Street is two-stories and topped with a hipped asphalt shingle roof, intersected by a front gable. A brick chimney is located near the center of the house. The facade is clad in brown face brick laid in a running bond pattern with wood shingle siding beneath the front gable. The primary entrance to each unit is near the east corner of the facade and is accessed by a brick and concrete porch beneath a second floor balcony with a wood railing and aluminum awning, which is supported by brick piers. West of the entrance are three wood hung windows with leaded glass detailing on the upper sashes covered by an aluminum awning, beneath matching windows on the second floor. Similar windows are arranged on other elevations, and have cast stone sills. A driveway runs along the east of the property to the rear where there is no garage.
291	4810 Cortland Street			1926	Tudor Revival	n/a	C	Unknown	Unknown	The duplex at 4810 Cortland Street is two-stories and topped with a hipped asphalt shingle roof, intersected by overlapping front gables. A brick chimney is located near the center of the house. The facade is clad in brown face brick laid in a running bond pattern, with some decorative brickwork. The primary entrance to each unit is near the east corner of the facade and is accessed by a brick and concrete porch beneath a second floor balcony with a metal railing, which is supported by brick piers. West of the entrance are three vinyl hung windows beneath a brick segmental arch with keystone, beneath matching windows on the second floor. Similar windows are arranged on other elevations, and have cast stone sills. A driveway runs along the east of the property to the rear where there is no garage.
292	4815 Cortland Street			1926	Tudor Revival	n/a	C	Unknown	Unknown	The duplex at 4815 Cortland Street is two-stories and topped with a cross gable asphalt shingle roof, composed of a side gable that meets a hipped roof toward the rear, intersected by overlapping front gables, and a hipped roof dormer towards the east. A brick chimney is located at the eave on the west facade and another is near the center of the house. The facade is clad blonde face brick laid in a running bond pattern with accents of cast stone, with vinyl siding at the side gables and one of the front gables, and secondary facades finished in red common brick. The primary entrance to each unit is near the east corner of the facade within a projecting vestibule, beneath a second floor balcony with a metal railing, which is supported by brick piers. The entrance is accessed by a concrete and brick porch. West of the entrance are three vinyl hung windows topped with brick arches infilled with cast stone, beneath a vinyl slider window at the second floor. A window at the attic level has leaded glass detailing in a diamond pattern. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear. There is no garage.
293	4816 Cortland Street			1926	Prairie	1/garage	C	Unknown	Unknown	The duplex at 4816 Cortland Street is two-stories and topped with a hipped asphalt shingle roof, intersected by a hipped roof dormer centered above the facade containing three small leaded glass windows. A brick chimney is located near the center of the house. The facade is clad in light and dark brown face brick with red common brick at the secondary facades, both laid in a running bond pattern. The primary entrance to each unit is near the east corner of the facade and is accessed by a brick and concrete porch beneath a second floor balcony with a metal railing and aluminum awning, which is supported by brick piers. West of the entrance are three hung windows with aluminum storms covered by an aluminum awning, beneath matching windows on the second floor. Similar windows are arranged on other elevations, and have cast stone sills. A driveway runs along the east of the property to the rear where there is a garage with a pyramidal roof.
294	4819 Cortland Street			1926	Tudor Revival	1/garage	C	Unknown	Unknown	The duplex at 4819 Cortland Street is two-stories and topped with a cross gable asphalt shingle roof, composed of a side gable that meets a hipped roof toward the rear, intersected by two front gables. A brick chimney is located at the eave on the west facade and another is near the center of the house. The facade is clad in brown face brick laid in a running bond pattern, with wood shingle siding beneath the front and side gables and one of the front gables, and secondary facades finished in red common brick. The primary entrance to each unit is near the east corner of the facade and is accessed by a brick and concrete porch with a metal railing, beneath a second floor balcony with a metal railing and aluminum awning, which is supported by brick piers. West of the entrance are four narrow wood casement windows with diamond leaded glass detailing, beneath matching windows at the second floor which are covered by an aluminum awning. Windows at the attic level have leaded glass detailing in a diamond pattern. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear where there is a front gable roof garage.
295	4824 Cortland Street			1926	Prairie	1/garage	C	Unknown	Unknown	The duplex at 4824 Cortland Street is two-stories and topped with a hipped asphalt shingle roof, intersected by a front gabled roof dormer centered above the facade. A brick chimney is located near the center of the house. The facade is clad in red face brick with red common brick at the secondary facades, both laid in a running bond pattern. The primary entrance to each unit is near the east corner of the facade and is accessed by a brick and concrete porch that has partially collapsed, beneath a second floor balcony with a metal railing, which is supported by brick piers. West of the entrance are three wood hung windows with leaded glass detailing, beneath matching windows on the second floor. Similar windows are arranged on other elevations, and have cast stone sills. A driveway runs along the east of the property to the rear where there is a garage.
296	4827 Cortland Street			1927	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4827 Cortland Street is two-stories and topped with a cross gable asphalt shingle roof, composed of a front gabled jerkinhead that meets a side gabled jerkinhead roof towards the middle, intersected by a small front gable above the entrance. A brick chimney is located near the center of the house. The facade is clad in brown face brick laid in a running bond pattern, with false half-timbering on the second floor. The primary entrance to each unit is near the east corner of the facade accessed by a concrete and brick porch with brick kneewall. West of the entrance are three wood hung windows with divided upper sashes, beneath matching windows at the second floor. Windows have cast stone sills on the first floor, and similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear. There is no garage.
297	4832 Cortland Street			1927	Prairie	1/garage	C	Unknown	Unknown	The duplex at 4832 Cortland Street is two-stories and topped with a hipped asphalt shingle roof, intersected by a jerkinhead roof dormer containing three small leaded glass windows centered above the facade. A brick chimney is located near the center of the house. The facade is clad in light and dark brown face brick with red common brick at the secondary facades, both laid in a running bond pattern. The primary entrance to each unit is near the east corner of the facade and is accessed by a brick and concrete porch that has partially collapsed, beneath a second floor balcony with a metal railing, which is supported by brick piers and arches below. West of the entrance are three doors opening to the porch, glazed full height with leaded glass detailing and with cast stone, broken pedimented surrounds. On the second floor is a ribbon of four wood casement windows with a decorative cast stone sill. Similar windows are arranged on other elevations, and have cast stone sills. A driveway runs along the east of the property to the rear where there is a pyramidal roof garage.
298	4835 Cortland Street			1927	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4835 Cortland Street is two-stories and topped with a side gable asphalt shingle roof intersected by a front gable catside above the entrance vestibule. A brick chimney is at the eave of the west facade. The exterior is clad in brown brick veneer laid in a running bond pattern on the first floor and within the front gable, with the second floor is clad in metal siding. The attic level has wood shingle siding exposed beneath the metal siding. The entrance is arched and is accessed by a brick and concrete full width porch. A steel casement window with sidelights and transom is west of the entrance, beneath a similar set of windows on the second floor. Similar windows are arranged on other elevations, and have cast stone sills on the first floor. A concrete driveway runs along the east of the property to the rear where there is a front gable roof garage.
299	4838 Cortland Street			1926	Tudor Revival	n/a	C	Unknown	Unknown	The duplex at 4838 Cortland Street is two-stories and topped with a hipped asphalt shingle roof, intersected by overlapping front gables. A brick chimney is located near the center of the house. The facade is clad in brown face brick laid in a running bond pattern, with some decorative brickwork and vinyl siding beneath the front gable. The primary entrance to each unit is near the east corner of the facade and is accessed by a brick and concrete porch beneath a second floor balcony with a metal railing, which is supported by brick piers. West of the entrance are three vinyl hung windows, beneath matching windows on the second floor. Similar windows are arranged on other elevations, and windows have cast stone sills. A driveway runs along the east of the property to the rear where there is no garage.
300	4841 Cortland Street			1926	Prairie	1/garage	C	Unknown	Unknown	The duplex at 4841 Cortland Street is two-stories and topped with a hipped asphalt shingle roof, intersected by a hipped roof dormer centered above the facade containing two small windows. A brick chimney is located near the center of the house. The facade is clad in light brown face brick with red common brick at the secondary facades, both laid in a running bond pattern. The primary entrance to each unit is near the east corner of the facade and is accessed by a brick and concrete porch beneath a second floor balcony with a metal railing, which is supported by brick piers. West of the entrance are three hung windows with aluminum storms topped by brick arches infilled with cast stone painted white, beneath three wood casement windows on the second floor with aluminum storms affixed to the exterior. Similar windows are arranged on other elevations, and have cast stone sills. A driveway runs along the east of the property to the rear where there is a garage with a front gabled roof.
301	4844 Cortland Street			1925c.	Tudor Revival	n/a	C	Unknown	Unknown	The duplex at 4844 Cortland Street is two-stories and topped with a hipped asphalt shingle roof, intersected by a front gable. A brick chimney is located near the center of the house. The facade is clad in brown face brick laid in a running bond pattern, with some decorative brickwork, and red common brick at the secondary facades. The primary entrance to each unit is near the east corner of the facade and is accessed by a brick and concrete porch with a metal railing, beneath a second floor balcony with a metal railing, which is supported by brick piers. West of the entrance are three vinyl hung windows topped with a brick segmental arch, beneath matching windows on the second floor. Similar windows are arranged on other elevations, and windows have cast stone sills. A driveway runs along the east of the property to the rear where there is no garage.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
302	4851 Cortland Street			1925	Colonial Revival	n/a	C	Unknown	Unknown	The house at 4851 Cortland Street is two-stories and topped with a gambrel asphalt shingle roof. A brick chimney is located at the eave on the west facade. The facade is clad with brown brick veneer laid in a running bond pattern, and vinyl siding on the second floor. The primary entrance is near the east corner the facade beneath a cantilevered gabled overhang with decorative brackets, and is accessed by a brick and concrete porch with metal railing. West of the entrance is a set of wood hung windows with divided upper sashes and aluminum storms, beneath matching windows on the second floor. Similar windows exist on other elevations, and have cast stone sills on the first floor. There is no garage.
303	4852 Cortland Street			1926	Tudor Revival	n/a	C	Unknown	Unknown	The duplex at 4852 Cortland Street is two-stories and topped with a hipped asphalt shingle roof, intersected by a front gable centered above the façade containing a small hung window at the attic. A brick chimney is located near the center of the house. The facade is clad in red and brown face brick with red common brick at the secondary facades, both laid in a running bond pattern. The primary entrance to each unit is near the west corner of the façade and is accessed by a brick and concrete porch beneath a second floor balcony with a wood railing, which is supported by brick piers. West of the entrance are three hung windows topped by brick infilled arches, beneath three hung windows on the second floor. Similar windows are arranged on other elevations, and have cast stone sills. A driveway runs along the east of the property to the rear where there is no garage.
304	4857 Cortland Street			1925	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4857 Cortland Street is two-stories and topped with a hipped asphalt shingle roof, intersected by a front gable centered above the façade containing a small window at the attic. A brick chimney is located at the eave on the west facade of the house. The facade is clad in brown face brick laid in a running bond pattern on the first floor, and vinyl siding on the second floor. The primary entrance to each unit is near the east corner of the façade and is accessed by a brick and concrete porch beneath a hipped roof portico, which is supported by square wood posts. West of the entrance are four wood hung windows with divided upper sashes, beneath three matching windows on the second floor. Similar windows are arranged on other elevations, and have cast stone sills on the first floor. A driveway runs along the east of the property to the rear where there is no garage.
305	4860 Cortland Street			1925	Craftsman	1/garage	C	Unknown	Unknown	The house at 4860 Cortland Street is one-and-a-half-stories and topped with a side gable asphalt shingle roof intersected by a front gabled dormer clad in asphalt shingle siding above the façade and another facing the rear. A tall brick chimney is at the eave near the front of the east facade. The exterior clad in red brick veneer laid in a running bond pattern with accents of cast stone and decorative brickwork. The primary entrance is near the west corner of the facade beneath a gabled portico with tapered brick columns and is accessed by a brick and concrete porch. Vinyl windows are west of the entrance. Windows have cast stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along to the rear of the property where there is a pyramidal roof garage.
306	4866 Cortland Street			1925	Prairie	1/garage	C	Unknown	Unknown	The duplex at 4866 Cortland Street is two-stories and topped with a hipped asphalt shingle roof, intersected by a hipped roof dormer centered above the façade containing three small windows and another hipped roof dormer facing east. A brick chimney is located near the center of the house. The facade is clad in red and brown face brick with red common brick at the secondary facades, both laid in a running bond pattern. The primary entrance to each unit is near the east corner of the façade and is accessed by a brick and concrete full width porch beneath a second floor balcony with a wood railing, which is supported by brick piers and covered in an aluminum awning. West of the entrance are three wood hung windows with vertically divided upper sashes each topped with a brick infilled arch, beneath three matching windows on the second floor. Similar windows are arranged on other elevations, and have cast stone sills. A driveway runs along the east of the property to the rear where there is a garage with a pyramidal roof.
307	4871 Cortland Street			1925	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4871 Cortland Street is two-stories and topped with a hipped asphalt shingle roof, intersected by overlapping front gables and a hipped roof dormer facing east. A brick chimney is located at the eave on the west facade of the house. The facade is clad in brown face brick laid in a running bond pattern on the first floor, and wide metal siding on the second floor. The primary entrance to each unit is near the east corner of the façade and is accessed by a brick and concrete full width porch beneath a gabled roof portico, which is supported by brick piers. West of the entrance are three vinyl hung windows, beneath two vinyl hung windows on the second floor. Similar windows are arranged on other elevations, and have cast stone sills on the first floor. A driveway runs along the east of the property to the rear where there is no garage.
308	4874 Cortland Street			1925	Prairie	n/a	C	Unknown	Unknown	The house at 4874 Cortland Street is two-stories and topped with a hipped asphalt shingle roof, intersected by a hipped roof dormer centered above the façade containing two small windows and a shed roof dormer facing east. A brick chimney is located at the eave on the west facade of the house. The facade is clad in blonde face brick laid in a running bond pattern at the first floor and wide metal siding on the second floor. The primary entrance to each unit is near the east corner of the façade and is accessed by a brick and concrete beneath a hipped roof portico, which is supported by brick piers. West of the entrance are four wood hung windows with vertically divided upper sashes, with two pairs of matching windows on the second floor. Similar windows are arranged on other elevations, and have cast stone sills on the first floor. A driveway runs along the east of the property to the rear. There is no garage. There is a blight lightpost with a globe fixture on the front lawn.
309	4879 Cortland Street			1927	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4879 Cortland Street is two-stories and topped with a hipped asphalt shingle roof, intersected by overlapping front gables and a shed roof dormer facing east. A brick chimney is located at the eave on the west facade of the house. The facade is clad in brown face brick laid in a running bond pattern on the first floor and beneath the front gable, and wood shingle siding on the rest of the second floor. The primary entrance to each unit is near the east corner of the façade within a projecting front gabled vestibule and is accessed by a brick and concrete full width porch. West of the entrance are three hung windows that have been boarded over, beneath three narrow wood hung windows with aluminum storms on the second floor. Similar windows are arranged on other elevations, and have cast stone sills on the first floor. A driveway runs along the east of the property to the rear where there is a porte cochere structure.
310	4880 Cortland Street			1925	Prairie	1/garage	C	Unknown	Unknown	The duplex at 4880 Cortland Street is two-stories and topped with a hipped asphalt shingle roof, intersected by a hipped roof portico and a hipped roof dormer centered above the rear façade. A brick chimney is located near the center of the house. The facade is clad in blonde face brick with red common brick at the secondary facades, both laid in a running bond pattern. The primary entrance to each unit is near the west corner of the façade beneath a two-story porch supported by brick piers, with metal railings, and is accessed by a brick and concrete porch. East of the entrance are three wood hung windows with vertically divided upper sashes and aluminum storms, beneath matching windows on the second floor. Similar windows are arranged on other elevations, and have cast stone sills. A driveway runs along the east of the property to the rear where there appears to be a garage.
311	4887 Cortland Street			1924	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4887 Cortland Street is two-stories and topped with a front gabled asphalt shingle roof. A brick chimney is located at the eave on the west facade of the house. The facade is clad in brown face brick laid in a running bond pattern on the first floor, and wide metal siding on the second floor. The primary entrance to each unit is near the east corner of the façade beneath a projecting front gabled portico supported by brick piers, and is accessed by a wood full width porch. West of the entrance is a vinyl slider window, and two slider windows are on the second floor. Other elevations have hung windows. A driveway runs along the east of the property to the rear where there is a garage.
312	4888 Cortland Street			1925	Craftsman	1/garage	C	Unknown	Unknown	The house at 4888 Cortland Street is one-and-a-half-stories and topped with a side gable asphalt shingle roof intersected by a front gabled jerkinhead dormer clad in asphalt shingle siding above the façade and a gabled roof dormer facing the rear. A tall brick chimney is at the eave near the front of the east facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of cast stone and decorative brickwork, with wood shingle siding beneath the side gable. The primary entrance is near the west corner of the facade beneath a jerkinhead gabled portico with tapered wood posts on top of brick columns, and is accessed by a brick and concrete porch. A vinyl slider window is east of the entrance, beneath three hung vinyl windows on the second floor, both of which are covered with an aluminum awning. Windows have cast stone sills on the first floor. Similar windows are arranged on other elevations. A concrete driveway runs along to the rear of the property where there is a front gable roof garage.
313	4893 Cortland Street			1927	Tudor Revival	n/a	C	Unknown	Unknown	The duplex at 4893 Cortland Street is two-stories and topped with a cross gable asphalt shingle roof, composed of a front gabled that meets a hipped roof towards the rear, intersected by overlapping front gables. A brick chimney is located at the eave on the west facade of the house. The facade is clad in brown face brick laid in a running bond pattern, with some decorative brickwork. The primary entrance to each unit is near the east corner of the façade beneath a second floor balcony with a metal railing, supported by brick piers, and accessed by a concrete and brick porch. West of the entrance is a window opening that has been boarded over topped with brick infilled arches, beneath a ribbon of four narrow windows at the second floor. Windows have cast stone sills, and similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear. There is no garage.
314	4894 Cortland Street			1925	Prairie	1/garage	C	Unknown	Unknown	The duplex at 4894 Cortland Street is two-stories and topped with a hipped asphalt shingle roof, intersected by a hipped roof portico, and a hipped roof dormer centered above the rear façade. A brick chimney is located near the center of the house. The facade is clad in blonde face brick with red common brick at the secondary facades, both laid in a running bond pattern. The primary entrance to each unit is near the west corner of the façade beneath a two-story porch supported by brick piers, with wood railings, and is accessed by a brick and concrete porch. East of the entrance are three vinyl hung windows topped with brick arches infilled with cast stone, beneath matching windows on the second floor. Similar windows are arranged on other elevations, and all have cast stone sills. A driveway runs along the east of the property to the rear where there is a pyramidal roof garage. A white lightpost is in the front lawn.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
315	4900 Cortland Street			1925	Prairie	1/garage	C	Unknown	Unknown	The duplex at 4900 Cortland Street is two-stories and topped with a hipped asphalt shingle roof, intersected by a hipped roof portico, and a hipped roof dormer facing east. A brick chimney is located at the eave on the west façade and another is near the center of the house. The facade is clad in brown face brick with red common brick at the secondary facades, both laid in a running bond pattern. The primary entrance to each unit is near the east corner of the façade beneath a two-story porch supported by brick piers, with wood railings, and is accessed by a brick and concrete porch. West of the entrance are three vinyl hung windows beneath a wood awning with square wood posts. Three matching windows are on the second floor. Similar windows are arranged on other elevations, and all have cast stone sills. A driveway runs along the east of the property to the rear where there is a pyramidal roof garage.
316	4901 Cortland Street			1928	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4901 Cortland Street is two-stories and topped with a side gable asphalt shingle roof intersected by a front gable catside above the entrance vestibule. A brick chimney is at the eave of the west facade. The exterior is clad in brown brick veneer laid in a running bond pattern on the first floor and within the front gable, with the second floor is clad in vinyl siding. The entrance is arched and is accessed by a brick and concrete full width porch. A vinyl picture window is west of the entrance, beneath a vinyl slider window on the second floor. Similar windows are arranged on other elevations, and have cast stone sills on the first floor. A concrete driveway runs along the east of the property to the rear where there appears to be a garage.
317	4907 Cortland Street			1925	Craftsman	1/garage	C	Unknown	Unknown	The house at 4907 Cortland Street is two-stories and topped with a side gable asphalt shingle roof intersected by a front gable. A brick chimney is near the rear of the house. The exterior is clad in light brown brick veneer laid in a running bond pattern on the first floor and the second floor is clad in wood shingle siding. The entrance is accessed beneath distinctive full width front gabled porch supported by brick piers with a brick kneewall. Three wood hung windows with vertically divided upper sashes are west of the entrance, and similar windows are on the second floor with aluminum storms. Similar windows are arranged on other elevations, and have cast stone sills on the first floor. A concrete driveway runs along the east of the property to the rear where there is a front gabled roof garage.
318	4908 Cortland Street			1925	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4908 Cortland Street is one-and-a-half-stories and topped with a front gable asphalt shingle roof intersected by a side gable. A brick chimney is at the eave of the east facade. The exterior is clad in brown brick veneer laid in a running bond pattern on the first floor, with vinyl siding beneath the gables. The entrance is accessed by a brick and concrete full width porch, and is covered by a cantilevered, gabled overhang with decorative brackets. A vinyl slider window is east of the entrance, beneath two vinyl hung windows on the second floor. Similar windows are arranged on other elevations, and have cast stone sills on the first floor. An alley runs along the east of the property. There is no garage.
319	4915 Cortland Street			1924	Prairie	1/garage	C	Unknown	Unknown	The house at 4915 Cortland Street is two-stories and topped with a hipped asphalt shingle roof intersected by a hipped roof dormer centered above the façade and another facing east. A brick chimney is at the eave on the west facade. The exterior is clad in brown brick veneer laid in a running bond pattern on the first floor and the second floor is clad in wide metal siding. The entrance is accessed beneath full width, hipped roof porch supported by brick piers with a brick kneewall. A large slider window is west of the entrance, and two pairs of hung vinyl windows beneath aluminum awnings are on the second floor. Similar windows are arranged on other elevations, and have cast stone sills on the first floor. A concrete driveway runs along the east of the property to the rear where there is a front gabled roof garage.
320	4921 Cortland Street			1925c.	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4921 Cortland Street is two-stories and topped with a side gable asphalt shingle roof intersected by a front gable that overlaps with a projecting front gable above the entrance vestibule. A brick chimney is at the eave of the west facade. The exterior is clad in brown brick veneer laid in a running bond pattern on the first floor and within the front gable, with the second floor is clad in asbestos siding. The entrance is accessed by a brick and concrete porch with a metal railing. Three vinyl hung windows are west of the entrance, beneath a vinyl slider window on the second floor. Similar windows are arranged on other elevations, and have cast stone sills on the first floor. A concrete driveway is accessed from the alley west of the property leading to the rear where there is no garage.
321	3701 Davison Street			1952		n/a	NC	Unknown	Unknown	The commercial building at 3701 Davison Street is a gas station with a flat roof surrounded on three sides with a high parapet, contemporary vinyl cladding, and two unattached canopies above the pumps. The entirety of the property is paved in concrete. The property is Non-contributing due to lack of integrity.
322	3959 Davison Street	Zussman Park	Zussman Park			n/a	C			Zussman Park features a playground, exercise equipment, two pavilions, and a basketball court.
323	4059 Davison Street			1950		n/a	NC	Unknown	Unknown	The commercial building at 4059 Davison Street is three stories with a flat roof, clad in brick, with CMU block infilling the window openings on the front facade. A non-historic canopy with metal roof supported by concrete columns covers a roll up service bay door on the east façade. A large paved parking lot sits east of the building. The property is Non-contributing due to lack of integrity.
324	4095 Davison Street			2000		n/a	NC	Unknown	Unknown	The commercial building at 4095 Davison Street is a one-story building with a hipped asphalt shingle roof, brick veneer, and hipped car ports off the east and west facades. The property is enclosed by a metal security fence. The building is not historic.
325	4225 Davison Street			1940	Tudor Revival	n/a	C	Unknown	Unknown	The commercial building at 4225 Davison Street is a two-stories building with a side jerkinhead asphalt shingle roof, intersected by vinyl-clad full-width shed dormers on the front and rear, intersected by a front gable which overlaps a front gabled vestibule above the entrance. The building is clad in brick veneer comprised of red, brown, and blonde face bricks laid in a running bond pattern, with stones interspersed throughout the façade. The building is glazed by vinyl hung windows. The property is enclosed by a metal security fence.
326	4325 Davison Street			1973		n/a	NC	Unknown	Unknown	The building at 4325 Davison Street is a one-story building with a side gabled asphalt shingle roof, a shed roof wing to the east, and another wing to the west with a side gable roof. The building is clad in light brown brick veneer, with some areas clad in vinyl siding, and the west façade composed of CMU block. The building's entrance is located on the east façade and is accessed from the adjoining parking lot. The property is Non-contributing due to lack of integrity.
327	4363 Davison Street					n/a	NC	Unknown	Unknown	The property at 4363 Davison is a vacant lot.
328	12305 Dexter Avenue	Mogen Abraham Congregation, Yeshivah Beth Yehudah	12305 Dexter Avenue	1954	Streamline Moderne	n/a	C	Kohner & Payne	Unknown	The building at 12305 Dexter Avenue is a one-story with a flat roof and an L-shaped footprint. The building has an asymmetrical, two-part façade clad in buff colored brick-faced cinder block with two raised stone belt courses on the smaller section, while the larger section has curved corners and two sets of three tall vertical openings infilled with CMU, with a stone sill running along the façade above a masonry foundation. The primary entrance is between the two sections beneath a cantilevered overhang and accessed by a concrete ramp.
329	12312 Dexter Avenue			1940		n/a	NC	Unknown	Unknown	The building at 12312 Dexter Ave is a gas station with a flat roof, clad in brick and stone veneer and one large unattached canopy structure with brick support columns above the pumps. The property is Non-contributing due to lack of integrity.
330	12512 Dexter Avenue			1948	Art Deco	n/a	C	Unknown	Unknown	The building at 12512 Dexter Avenue is two-stories with a flat roof with parapet and clay coping tiles. The façade is three bays wide, with a set of three narrow window openings per bay on the second story. The first floor appears to have two display storefront entrances, which have been boarded over. At the second floor, an Art Deco inspired cladding has been installed over the original brick façade.
331	12521 Dexter Avenue	Young Israel of Detroit	Grace Temple Church of God in Christ	1948	Modern Movement	n/a	C	Louis G. Redstone; Roderick E. Warren	Unknown	The church at 12521 Dexter Avenue is one story comprised of a mostly flat, unadorned façade clad in blonde brick veneer. The main entrance off of Dexter Avenue is recessed to the south of a prominent central canted bay. To the south of the entrance are four large aluminum fixed windows. The northern-most block of the building features a gable-on-hip roof, clad in vertical wood siding at the gable end where there is a large stained glass window in a geometric pattern. The rest of the façade has narrow glass block windows.
332	12526 Dexter Avenue			1941	Prairie	n/a	C	Unknown	Unknown	The building at 12526 Dexter Avenue is one story with a flat roof. The parapet is capped with cast stone crenelations. The façade is two bays wide with an entrance recessed in the south bay. The display windows have been bricked in and the façade altered with contemporary cladding materials.
333	12546 Dexter Avenue			1928	Italian Renaissance	n/a	C	Unknown	Unknown	The building at 12546 Dexter Avenue is two-stories with a flat roof. The parapet is capped with cast stone. The façade is five bays wide along Dexter Avenue and eight bays deep along Fullerton Avenue, divided horizontally with cast stone belt courses above the first and second floor as well as a cast stone cornice below the parapet. The façade is clad with light brown faced brick laid in a Flemish bond pattern with sections set proud to create a pilaster-like effect between bays. Storefronts along Dexter Avenue have been infilled with CMU, boarded over, or clad in modern stone veneer. Centered on the Fullerton Avenue façade is an entrance with decorative door surround featuring pilasters, ornate frieze, dentiled cornice topped with a metal Juliet balcony railing, set beneath an arched opening on the second story. Windows on the building are boarded over or infilled with CMU block.
334	12603 Dexter Avenue			1947	Modern Movement	n/a	C	Louis G. Redstone	Unknown	The building at 12603 Dexter Avenue is one story with a flat roof and a large cantilevered overhang spanning the width of the façade. At the south corner a large metal signage structure projects from the parapet, supported by an angular support brace below. Former window openings have been infilled with brick and CMU.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
335	12626 Dexter Avenue			1948	Modern Movement	n/a	C	Unknown	Unknown	The building at 12626 Dexter Avenue is two-stories with a front gabled asphalt shingle roof. The façade is clad in brick veneer, interrupted by three vertical window openings spanning both stories, with vertical wood siding below the gable. The entrance is located at the south corner and is accessed by a brick and concrete stoop.
336	12632 Dexter Avenue			1945	Streamline Moderne	n/a	C	Unknown	Unknown	The building at 12632 Dexter Avenue is one story with a hipped asphalt shingle roof surrounded by a flat roof with parapet around the perimeter. The façade features rounded corners with large glass block windows and is clad in brick veneer with dentils along the parapet. The entrance is recessed at the south corner and is accessed by a brick and concrete stoop.
337	12647 Dexter Avenue			1940	Commercial Style	n/a	C	Unknown	Unknown	The building at 12647 Dexter Avenue is one story with a flat roof surrounded by a flat roof. The street-facing façades are clad in painted brick with other elevations clad in painted CMU block. The entrance faces Dexter Avenue, with a glass block window to the south.
338	12707 Dexter Avenue			1996	Postmodern	n/a	NC	Unknown	Unknown	The building at 12707 Dexter Avenue is not historic.
339	12710 Dexter Avenue			1940	Prairie	n/a	C	Unknown	Unknown	The building at 12710 Dexter Avenue is two-stories with a hipped asphalt shingle roof. A large brick chimney intersects the eave at the south façade. The façade is finished in blonde face brick with cast stone belt course between the first and second story. The entrance vestibule is enclosed with glass block at the corner of a projecting two story bay off the front facade.
340	12740 Dexter Avenue			1966	Modern Movement	n/a	NC	Unknown	Unknown	The building at 12740 Dexter Ave is a car wash comprised of a central one-story building, clad in brick and CMU, with three full-height drive-through bays on either side, all under a single flat roof. The drive-through bays consist of CMU and brick partition walls, open on the front and rear, beneath the shared roof. A mural adorns the north facade facing Glendale Avenue. The property is Non-contributing due to lack of integrity.
341	12837 Dexter Avenue			1955	Streamline Moderne	n/a	C	Louis G. Redstone	Unknown	The church at 12837 Dexter Avenue is one story, flat roof building that is clad in blonde brick laid in a running bond on the prominent curved brick portion of the façade which features a cast stone signage band with carved lettering. The entrance is located beneath a two-story recessed entryway with a large multi-paned window above four paneled doors. South of the entrance, the façade brick is laid in common bond and there are two slider windows covered with metal security bars. A brick chimney is near the center of the building.
342	12840 Dexter Avenue			1976		n/a	NC	Unknown	Unknown	The building at 12840 Dexter Avenue is a one-story, flat roof building clad in stone veneer, brick veneer, and metal siding. The entrance is recessed. There is a drive-through canopy to the rear. The property is Non-contributing due to lack of integrity.
343	13100 Dexter Avenue			1940	Art Deco	n/a	C	Unknown	Unknown	The building at 13100 Dexter Avenue is a one-story, flat roof building with parapet clad in CMU and a rusticated veneer with a grid pattern painted orange. A metal clad signage band runs along the façade at the parapet, which is stepped to elaborate a focal point above the entrance. North of the entrance are two service bays with garage service doors.
344	13107 Dexter Avenue			1948	Streamline Moderne	n/a	C	Unknown	Unknown	The building at 13107 Dexter Avenue is a one-story, flat roof building with a façade clad in brick veneer and CMU that is rounded at the southeast corner. There are non-descript entry doors facing Dexter Avenue and Buena Vista Street, and a service bay garage door on Buena Vista.
345	13113 Dexter Avenue			1946	Commercial Style	n/a	C	Unknown	Unknown	The building at 13113 Dexter Avenue is a narrow one-story, flat roof building with a façade clad in cast stone veneer and CMU that has been painted yellow. The entrance is recessed, with a large window opening to the north. A large metal support structure from former signage sits atop the roof.
346	13118 Dexter Avenue			1948	Commercial Style	n/a	NC	Unknown	Unknown	The building at 13118 Dexter Avenue is a one-story, flat roof building with a façade clad in contemporary materials. The entrance is recessed within a wide entryway. The property is Non-contributing due to lack of integrity.
347	13139 Dexter Avenue			1928	Spanish Revival	n/a	C	possibly Weidmaier and Gay	Edward J. Mason	The mixed-use building at 13139 Dexter Avenue (3711 Tyler Street) is four stories and has a U-shape plan, with 29 apartment units and four commercial storefronts on the ground floor. The building features orange-red face brick, corbeled rounded blind arches and lancet arches, projecting bays, Mission style gables and decorative tile and stone. The storefronts have recessed entrances along Dexter Avenue and two have been boarded over, the other two are behind a security gate and roll-up metal security door. The primary entrance to the apartment units is accessed off of Tyler Street, the door is boarded over but sidelights and fanlight are visible, and the entrance is trimmed in stone with a concrete banner inscribed with the building's name, "El Morada."
348	13140 Dexter Avenue			1933	Modern Movement	n/a	C	Unknown	Unknown	The building at 13140 Dexter Avenue is a one-story, flat roof building with a façade clad in brick veneer that has been painted. The entrance is located slightly north of center between two service bays with garage doors.
349	13200 Dexter Avenue					n/a	NC	Unknown	Unknown	The vacant lot at 13200 Dexter is currently occupied by a pop-up retail development built out of shipping containers with storefront entrances.
350	13201 Dexter Avenue			1946	Modern Movement	n/a	C	Unknown	Unknown	The building at 13201 Dexter Avenue is a one-story, flat roof building with a façade clad in painted vitrolite tiles and a glazed aluminum storefront system featuring a set of downward angled windows. Other elevations are clad with light brown brick veneer laid in common bond pattern. Above the entrance, on the roof sits a metal support structure and marquee signage.
351	13205 Dexter Avenue			1947	Commercial Style	n/a	NC	Unknown	Unknown	The building at 13205 Dexter Avenue is a one-story, flat roof building with a contemporary glazed aluminum storefront system with recessed entrance and what appears to be painted vitrolite above. Most of the upper façade is covered by a full-width contemporary signage awning. The property is Non-contributing due to lack of integrity.
352	13217 Dexter Avenue			1947	Commercial Style	n/a	NC	Unknown	Unknown	The building at 13217 Dexter Avenue is a one-story, flat roof building with a highly recessed entrance. The façade is clad in stucco and is mostly blind with a corner window on the north bay. The property is Non-contributing due to lack of integrity.
353	13219 Dexter Avenue			1946	Prairie	n/a	C	Unknown	Unknown	The building at 13219 Dexter Avenue is a one-story, flat roof building clad in blonde brick veneer. The façade is split into three bays each housing a storefront with cast stone vertical divisions between bays. The storefronts consist of a highly recessed entrance door with transom above, centered between glazed display windows. The northern-most bay has been boarded over.
354	13224 Dexter Avenue					n/a	NC	Unknown	Unknown	The vacant lot at 13224 Dexter Avenue is currently landscaped and being used as a public amenity adjacent to the pop-up retail in the neighboring lot at 13200 Dexter Avenue.
355	13237 Dexter Avenue			1949	Streamline Moderne	n/a	C	Unknown	Unknown	The building at 13237 Dexter Avenue is a one-story, flat roof building with a curved corner entrance. The facade is clad in what appears to be painted vitrolite, and is clad in brick towards the alley along Waverly Street which has also been painted. There are large fixed windows on either side of the corner entrance. An entire bay along Dexter Avenue has been infilled with brick. There is a large metal support structure with signage near the corner facing Dexter Avenue.
356	13244 Dexter Avenue			1928	Streamline Moderne	n/a	NC	Unknown	Unknown	The building at 13244 Dexter Avenue is a one-story, flat roof building with a façade clad in stucco over brick veneer with a horizontal grooved band near the roofline, the entire façade has been painted. There is a large service bay entrance toward the rear of the building. Window openings have been infilled with CMU or boarded over. The property is Non-contributing due to lack of integrity.
357	13300 Dexter Avenue			1969	Prairie	n/a	NC	Unknown	Unknown	The building at 12312 Dexter Avenue is a gas station a low-pitched front gable roof with wide eaves and ornamental rafter tails, clad in brick veneer, and one large unattached canopy structure above the pumps. The property is Non-contributing due to lack of integrity.
358	13301 Dexter Avenue			1955	Streamline Moderne	n/a	NC	Unknown	Unknown	The building at 13301 Dexter Avenue is two-stories with a flat roof. The façade is three bays wide along Dexter Avenue and six bays deep along Waverly Street, with a series of one-story buildings adjoining the rear. The Dexter Avenue façade is clad what appears to be painted Vitrolite installed over brick veneer, the other elevations are clad in brick laid in a common bond pattern that has been painted. The entrance is at the southeast corner below a contemporary awning that spans the length of the storefront, with large fixed windows covered in decal advertising on either side of the entrance. A large marquee sign extends above the corner entrance. All window openings on the second floor have been infilled with brick or CMU. The property is Non-contributing due to lack of integrity.
359	3736 Fullerton Street			1936	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3736 Fullerton Street is two-stories and topped with a hipped, asphalt shingle roof. A tall brick chimney is located at the eave near the center of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of cast stone, stone veneer, decorative brickwork, and false half-timbering. The primary entrance is located near the east corner of the facade and is accessed by a brick veneer-clad concrete porch with a brick kneewall. A shed roof supported by square posts shelters the porch. A large bay with vinyl windows and painted cast stone trim is west of the entrance and located beneath a squared bay. Vinyl windows with aluminum awnings are on the second floor of the facade beneath small gables. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. A hipped roof garage is at the rear of the property. A black lightpost is located near the center of the front lawn.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
360	3737 Fullerton Street			1946	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3737 Fullerton Street is two-stories and topped with a side gable, asphalt shingle roof intersected by a large, asymmetrical front gable. A large brick chimney is located at the eave near the center of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of cast stone and stone veneer. The primary entrance is trimmed with cast stone and located near the center of the facade within the front gable, and is accessed by a concrete stoop with a black metal handrail. A large bay with stone veneer and an asphalt shingle roof with vinyl windows is east of the entrance. Vinyl windows are arranged elsewhere on the first and second floors of the facade. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house and a wood shed roof carport is appended to the east facade. A hipped roof garage is at the rear of the property.
361	3744 Fullerton Street			1960	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 3744 Fullerton Street is two-stories and topped with a side gable, asphalt shingle roof intersected by a small gable. A brick chimney is located at the eave near the center of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern except for the overhanging second floor facade which is clad in white aluminum siding. The primary entrance surrounded by white trim is near the east corner of the facade and is accessed by a brick veneer-clad concrete stoop. A vinyl slider window with black shutters and a cast stone sill is east of the entrance, and two vinyl slider windows with black shutters are arranged on the second floor facade. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. A hipped roof garage is at the rear of the property. A black metal lamppost with a globe light fixture is near the driveway in the front lawn.
362	3749 Fullerton Street			1930	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3749 Fullerton Street is two-stories and topped with a side gable, asphalt shingle roof. A large brick chimney is prominently placed near the center of the facade. The exterior is clad in red brick veneer laid in a running bond pattern with copious accents of klinker brick in addition to stone veneer and stucco. The primary entrance is arched, accentuated with a starburst stone pattern, and is located in a steeply pitched front gable at the east corner of the facade. The entrance is accessed by a brick-clad full-width terrace with a short metal railing. A series of leaded glass casement windows are arranged west of the entrance and an aluminum window and steel casement window are arranged on the second floor. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house.
363	3750 Fullerton Street			1937	French Eclectic	1/garage	C	Unknown	Unknown	The house at 3750 Fullerton Street is two-stories and topped with a hipped asphalt shingle roof. A large brick chimney is at the eave near the center of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer and cast stone. A stone half-wall extends from the west corner of the facade. The primary entrance is trimmed in cast stone and set within a rectangular projection near the east corner of the facade. A concrete porch surrounded by a brick kneewall and sheltered by an aluminum awning supported by metal posts accesses the entrance. A stone veneer bay topped with an asphalt shingle roof is west of entrance and contains steel windows and cast stone trim. Steel casement and leaded glass windows are arranged on the second floor facade, each set beneath a small gable with bargeboard. Each window has a cast stone sill and is fitted with aluminum storms. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. A pyramidal roof garage is at the rear of the property.
364	3757 Fullerton Street			1930	French Eclectic	1/garage	C	Unknown	Unknown	The house at 3757 Fullerton Street is two-stories and topped with a pyramidal asphalt shingle roof. A large brick chimney is at the eave near the center of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer and cast stone. The primary entrance is near the east corner of the facade and is trimmed in cast stone and brick, beneath a stone belt course and the structure for an awning that has been removed. The entrance is accessed by a brick and concrete stoop. A one story canted bay topped with an asphalt shingle roof is west of entrance and contains steel casement windows and cast stone trim. Vinyl windows are arranged on the second floor facade, each set beneath a wall dormer. Each window has a cast stone sill. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. A pyramidal roof garage is at the rear of the property.
365	3760 Fullerton Street			1960	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 3760 Fullerton Street is two-stories and topped with a side gable, asphalt shingle roof intersected by a small gable. A brick chimney is located at the eave near the center of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern except for the overhanging second floor facade which is clad in light green vinyl siding. The primary entrance surrounded by white trim is near the east corner of the facade and is accessed by a brick veneer-clad concrete stoop with a metal handrail. A vinyl slider window with green shutters and a cast stone sill is east of the entrance, and two vinyl slider windows with green shutters are arranged on the second floor facade. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. A hipped roof garage is at the rear of the property.
366	3765 Fullerton Street			1930	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3765 Fullerton Street is two-stories and topped with a side gable asphalt shingle roof. A large brick chimney is at the eave near the center of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer and klinker bricks. The primary entrance is near the east corner of the facade within an engaged polygonal turret topped with a polygonal roof, accessing a brick-clad full-width terrace with a short metal railing. Leaded glass windows are arranged on the turret and a series of casement windows are west of the entrance beneath a canted oriel window on the second floor facade. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. A front gable roof garage is at the rear of the property. A black metal lamppost with a globe light fixture is near the center of the front lawn.
367	3766 Fullerton Street			1952	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 3766 Fullerton Street is two-stories and topped with a side gable, asphalt shingle roof. A large brick chimney is located at the eave near the center of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern. The primary entrance is near the east corner of the facade and is accessed by a brick veneer-clad concrete porch topped with an aluminum awning supported by white metal posts. A large wood picture window with a brick sill is east of the entrance, and two wood hung windows with white shutters are arranged on the second floor facade. Aluminum awnings shelter each window. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. A hipped roof garage is at the rear of the property.
368	3774 Fullerton Street			1936	French Eclectic	1/garage	C	Unknown	Unknown	The house at 3774 Fullerton Street is two-stories and topped with a hipped asphalt shingle roof. A large brick chimney is at the eave near the center of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer and cast stone. A stone half-wall extends from the west corner of the facade. The primary entrance is trimmed in cast stone and is accessed by a concrete porch surrounded by a brick kneewall. A brick veneer bay with a sloped metal roof is west of entrance and contains steel casement windows and cast stone trim. Steel casement windows are arranged on the second floor facade, each set beneath a small gable. Each window has a cast stone or brick sill. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. A pyramidal roof garage is at the rear of the property.
369	3775 Fullerton Street			1937	French Eclectic	1/garage	C	Unknown	Unknown	The house at 3775 Fullerton Street is two-stories and topped with a hipped asphalt shingle roof. A large brick chimney is at the eave near the center of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer and cast stone. A stone half-wall extends from the west corner of the facade. The primary entrance is trimmed in cast stone and set within a rectangular projection near the east corner of the facade. A brick-clad porch surrounded by a black metal railing beneath a black metal awning structure accesses the entrance. A brick veneer bay topped with an asphalt shingle roof is west of entrance and contains steel casement windows and cast stone trim. Vinyl windows are arranged on the second floor facade, one of which is set beneath a small gable and the other is set beneath a hipped roof. Each window has a cast stone sill and the first floor windows are fitted with aluminum storms. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. A pyramidal roof garage is at the rear of the property.
370	3783 Fullerton Street			1935c.	French Eclectic	n/a	C	Unknown	Unknown	The house at 3783 Fullerton Street is two-stories and topped with a pyramidal asphalt shingle roof. A large brick chimney is at the eave near the center of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer and cast stone. A stone half-wall extends from the west corner of the facade. The primary entrance is trimmed in cast stone and set within a rectangular projection near the east corner of the facade. A brick-clad porch surrounded by a white metal railing beneath an aluminum awning supported by white metal posts accesses the entrance. A brick veneer bay with a sloped metal roof is west of entrance and contains steel casement windows and cast stone trim. Steel casement and steel leaded glass windows are arranged on the second floor facade, one of which is set beneath a small gable and the other is set beneath a hipped roof. Each window has a cast stone sill. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
371	3784 Fullerton Street			1940	French Eclectic	1/garage	C	Unknown	Unknown	The house at 3784 Fullerton Street is two-stories and topped with a hipped, asphalt shingle roof. A tall brick chimney is located at the eave near the center of the east facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of vinyl siding in a false half-timbering pattern and decorative brickwork. A decorative brick half-wall slopes outward from the east corner of the facade. The primary entrance is located near the west corner of the facade and is accessed by a brick-clad concrete porch beneath an aluminum awning supported by black metal posts. A large bay clad in and topped with vinyl siding with steel casement windows is east of the entrance and set within a squared, gable roof projection. Steel casement windows are on the second floor of the facade, with one window set beneath a small gable. Each window has a cast stone sill and is fitted with aluminum storms. Similar windows are arranged on other elevations. The driveway is concrete and runs along the west side of the house. A pyramidal roof garage is at the rear of the property. A black lightpost with a globe light fixture is located near the center of the front lawn.
372	3790 Fullerton Street			1936	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3790 Fullerton Street is two-stories and topped with a hipped, asphalt shingle roof pierced by a pair of steeply pitched gables above the facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer and cast stone. The primary entrance is located near the west corner of the facade and is accessed by a brick-clad concrete porch surrounded by a brick kneewall. A large bay with a stone veneer-clad base topped with a metal roof with boarded over windows is east of the entrance. Steel casement windows are on the second floor of the facade within each gable. Each window has a cast stone sill and is fitted with aluminum storms. Similar windows are arranged on other elevations. The driveway is concrete and runs along the west side of the house. A pyramidal roof garage is at the rear of the property.
373	3791 Fullerton Street			1935c.	French Eclectic	1/garage	C	Unknown	Unknown	The house at 3791 Fullerton Street is two-stories and topped with a hipped, asphalt shingle roof. A tall brick chimney is located at the eave near the north corner of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern, the upper half of the two-story bay is clad in vinyl siding, and there are accents of stone veneer and cast stone which have been painted white. The primary entrance is located near the west corner of the facade and is accessed by a brick-clad concrete porch surrounded by a black metal railing beneath an aluminum awning supported by black metal posts. A two-story bay with a series of vinyl hung windows is east of the entrance and a single vinyl hung window is west of the entrance. Vinyl hung windows are arranged on the second floor of the facade. Most windows have a cast stone sill that has been painted white. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. A hipped roof garage is at the rear of the property. A black lightpost with a globe light fixture is located near the center of the front lawn.
374	3800 Fullerton Street			1937	French Eclectic	n/a	C	Unknown	Unknown	The house at 3800 Fullerton Street is two-stories and topped with a pyramidal asphalt shingle roof. A large brick chimney is at the eave near the center of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, blonde brick, and cast stone. A partially demolished stone half-wall extends from the west corner of the facade. The primary entrance is trimmed in rusticated stone and set within a rectangular projection near the east corner of the facade. A large brick-clad porch surrounded by a black metal railing accesses the entrance. A bay clad in brick and stone veneer topped with an asphalt roof is west of entrance and contains steel casement leaded glass windows. Steel casement leaded glass windows are arranged on the second floor facade, one of which is set beneath a small gable and the other is framed with white shutters. Each window has a cast stone sill and is fitted with aluminum storms. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. A black lightpost with a globe light fixture is located near the center of the front lawn.
375	3807 Fullerton Street			1937	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3807 Fullerton Street is two-stories and topped with a hipped asphalt shingle roof in very poor condition. The exterior is clad in red brick veneer laid in a running bond pattern with accents of rusticated stone veneer, wood false half-timbering, and decorative brickwork. The primary entrance is trimmed in rusticated stone and set within a rectangular gable roof projection near the east corner of the facade. A brick-clad porch surrounded by a brick kneewall accesses the entrance. A bay clad in brick and stone veneer topped with a sloping metal roof is west of entrance and contains steel casement windows. Steel casement and steel leaded glass windows are arranged on the second floor facade, one of which is set beneath a small gable with scalloped trim. Each window has a cast stone or brick sill and is fitted with aluminum storms. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. A pyramidal roof garage is at the rear of the property.
376	3810 Fullerton Street			1936	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3810 Fullerton Street is two-stories and topped with a hipped asphalt shingle roof with gable and hipped roof dormers. A large brick chimney is located at the eave near the center of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is trimmed in stone near the east corner of the facade and accessed by a large brick-clad porch surrounded by a brick kneewall sheltered by an aluminum awning with white metal posts. A bay clad in stone veneer and cast stone topped with a stone parapet is west of entrance and contains steel casement windows. Steel casement windows are arranged on the second floor facade, one of which is set beneath a small gable with decorative brickwork with the other set beneath a large gable. Window have brick or cast stone sills and are fitted with aluminum storms. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. A pyramidal roof garage is at the rear of the property.
377	3816 Fullerton Street			1936	French Eclectic	1/garage	C	Unknown	Unknown	The house at 3816 Fullerton Street is two-stories and topped with a hipped asphalt shingle roof intersected by hipped and gable roofs above the facade. A large brick chimney is located at the eave near the center of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and Klinker bricks. The primary entrance is arched, trimmed in stone, surrounded by stone veneer, and near the center of the facade. A large brick-clad concrete porch surrounded by a brick kneewall and sheltered by an aluminum awning with white metal posts accesses the entrance. A bay clad in stone veneer and cast stone topped with a flat roof is west of entrance and contains steel casement windows with leaded glass. Steel casement windows and steel casement leaded glass windows are arranged on the second floor facade, two of which are set beneath small gables with decorative brick and stonework. Windows have cast stone sills. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. A pyramidal roof garage is at the rear of the property. A black lightpost with a globe light fixture is located near the center of the front lawn.
378	3817 Fullerton Street			1937	French Eclectic	1/garage	C	Unknown	Unknown	The house at 3817 Fullerton Street is two-stories and topped with a deck (hipped and flat) asphalt shingle roof. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer that has been painted white. The primary entrance is trimmed in stone and set within a three-sided turret nested near the center of the facade. A round brick-clad concrete porch with a black metal railing sheltered by an aluminum awning supported by black metal posts accesses the entrance. A bay clad in brick veneer and cast stone topped with a metal roof is west of entrance and contains steel casement windows with leaded glass. Steel casement windows and steel casement leaded glass windows are arranged on the second floor facade, two of which have aluminum awnings. Windows have brick and cast stone sills. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. A pyramidal roof garage is at the rear of the property. A black lightpost with a globe light fixture is located near the center of the front lawn.
379	3824 Fullerton Street			1936	French Eclectic	1/garage	C	Unknown	Unknown	The house at 3824 Fullerton Street is two-stories and topped with a hipped asphalt shingle roof intersected by hipped and gable roofs above the facade. A large brick chimney is located at the eave near the center of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with copious accents of cast stone, stone veneer, decorative brickwork, and wood false half-timbering. The primary entrance is trimmed in stone, surrounded by stone veneer, and near the center of the facade. A large brick-clad concrete porch surrounded by a brick kneewall with a metal awning structure accesses the entrance. A bay clad in stone veneer and cast stone topped with a rectangular bay is west of entrance and contains steel casement windows with leaded glass and steel leaded glass windows are arranged east of the entrance. Steel casement windows and steel casement leaded glass windows are arranged on the second floor facade, two of which are set beneath small gables with decorative brickwork and bargeboard. Windows have cast stone sills. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. A pyramidal roof garage is at the rear of the property.
380	3825 Fullerton Street			1939	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 3825 Fullerton Street is two-stories and topped with a side gable asphalt shingle roof intersected by a large front gable above the facade. A brick chimney is located at the eave near the center of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer. The primary entrance is near the center of the facade and accessed by a brick-clad concrete porch surrounded by a black metal railing and sheltered by a shed roof supported by black metal posts. A wood 6-over-6 hung window is east of the entrance and a fixed single-light vinyl window is west of the entrance, with another wood hung window and a vinyl hung window on the second floor facade. Windows have brick sills. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. A pyramidal roof garage is at the rear of the property.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
381	3830 Fullerton Street			1939	French Eclectic	1/garage	C	Unknown	Unknown	The house at 3830 Fullerton Street is two-stories and topped with a hipped asphalt shingle roof intersected by two gables above the facade. A stone half-wall with a stone urn extends from the west corner of the facade. A large brick chimney is located at the eave near the center of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is trimmed in stone, topped with a stone arch, placed near the center of the facade, and accessed by a brick-clad porch surrounded by a brick kneewall. A bay clad in stone veneer and cast stone topped with a stone parapet is west of entrance and contains vinyl windows. Vinyl windows are arranged on the second floor facade, both of which are set beneath gables trimmed in bargeboard. A small arched leaded glass window is in the apex of the larger gable. Window have brick or cast stone sills. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. A pyramidal roof garage is at the rear of the property.
382	3831 Fullerton Street			1936	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3831 Fullerton Street is two-stories and topped with a pyramidal, asphalt shingle roof pierced by a pair of steeply pitched gables above the facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, decorative brickwork, and wood false half-timbering. The primary entrance is located near the east corner of the facade and is accessed by a brick-clad concrete porch surrounded by a brick kneewall. A large bay with a stone veneer-clad base topped with a metal roof with a series of vinyl hung windows is east of the entrance. A small leaded glass wood window is east of the entrance and vinyl windows are arranged on the second floor facade. Each window has a cast stone or wood sill. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. A hipped roof garage is at the rear of the property.
383	3840 Fullerton Street			1937	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3840 Fullerton Street is two-stories and topped with a hipped, asphalt shingle roof intersected by a steeply pitched catslide gable above the facade. Two large chimneys are located at the eave on the east facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer. The primary entrance is located near the center of the facade and is accessed by a brick-clad terrace surrounded by a brick kneewall and sheltered by an aluminum awning supported by white metal posts. Large steel casement windows are arranged on either side of the entrance on the first and second floors. An arched leaded glass window is set within the catside gable. Each window has a brick sill. Similar windows are arranged on other elevations, some of which have been infilled with glass block. The driveway is concrete and runs along the rear of the property, accessing a hipped roof garage.
384	3841 Fullerton Street			1939	French Eclectic	1/garage	C	Unknown	Unknown	The house at 3841 Fullerton Street is two-stories and topped with a hipped, asphalt shingle roof. A tall brick chimney is located at the eave near the north corner of the east facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of cast stone, decorative brickwork, and wood false half-timbering. The primary entrance is trimmed in stone and located near the center of the facade, accessed by a brick-clad concrete porch surrounded by a low red metal railing. A two-story bay with a series of steel casement windows is east of the entrance and a steel casement window is west of the entrance. Steel casement and steel casement leaded glass windows are arranged on the second floor of the facade. Windows have a cast stone or brick sills and are fitted with aluminum storms. Similar windows are arranged on other elevations. The driveway is concrete and runs along the rear of the property accessing a hipped roof garage. A black lightpost with a globe light fixture is located near the center of the front lawn.
385	4000 Fullerton Street			1941	Streamline Moderne	n/a	C	Unknown	Unknown	The house at 4000 Fullerton Street is two-stories and topped with a hipped, asphalt shingle roof intersected by multiple hipped roofs. The exterior is clad in blonde brick veneer laid in a running bond pattern. The primary entrance is surrounded by stone veneer near the center of the facade and is accessed by a concrete stoop. A two-story curved bay with a large glass block window and a second floor balcony projects from the facade west of the entrance. A large glass block window wraps around the southeast corner of the second floor facade, and smaller glass block and vinyl windows are arranged elsewhere on the facade and other elevations. The driveway is concrete and runs along the rear of the property accessing an attached garage, which is topped with a flat roof surrounded by a brick-clad parapet.
386	4005 Fullerton Street			1940	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4005 Fullerton Street is two-stories and topped with a hipped, asphalt shingle roof intersected by hipped roofs central pavillion topped with a gable roof. A large brick chimney is located at the eave near the center of the west facade and another is at the eave near the south corner of the east facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer and cast stone. The primary entrance is a Tudor arch and trimmed with cast stone, surrounded by stone veneer, and centered in the pavillion beneath an arched leaded glass window. The entrance is accessed by a brick-clad concrete porch surrounded with a low black metal railing. A single-story bay clad in stone veneer and topped with a flat roof is west of the entrance and contains steel casement windows. Steel casement windows are arranged elsewhere on the facade and other elevations. Window sills are cast stone. The driveway is concrete and runs along the rear of the property accessing a hipped roof garage.
387	4012 Fullerton Street			1955	Streamline Moderne	n/a	C	Unknown	likely Canvasser Brothers Building Company	The house at 4012 Fullerton Street is two-stories and topped with a hipped, asphalt shingle roof. A tall brick chimney is located at the eave near the center of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with some courses of brick set proud to create horizontal bands in the brick. The primary entrance is located near the east corner of the facade and is accessed by a brick veneer-clad concrete porch with black metal handrails. A large multi-light steel window is located west of the entrance and two multi-light steel windows are arranged symmetrically on the second floor of the facade. Each window has a limestone or cast stone sill and is fitted with aluminum storms. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. There is no garage. A black lightpost without a light fixture is located near the center of the front lawn.
388	4020 Fullerton Street			1955	Streamline Moderne	1/garage	C	Unknown	Canvasser Brothers Building Company	The house at 4020 Fullerton Street is two-stories and topped with a hipped, asphalt shingle roof. A tall brick chimney is located at the eave near the center of the west facade. The exterior is clad in blonde brick veneer laid in a running bond pattern with some courses of brick set proud to create horizontal bands in the brick. The primary entrance is located near the east corner of the facade and is accessed by a brick veneer-clad concrete porch with black metal handrails. An aluminum awning supported by black metal posts shelters the porch. A large vinyl window is located west of the entrance and two vinyl slider windows are arranged symmetrically on the second floor of the facade. Each window has a limestone or cast stone sill. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house, accessing a hipped roof garage at the rear of the property. A black lightpost without a light fixture is located near the center of the front lawn.
389	4021 Fullerton Street			1954	Colonial Revival	n/a	C	Unknown	Unknown	The house at 4021 Fullerton Street is two-stories and topped with a hipped, asphalt shingle roof. A tall brick chimney is located at the eave near the north corner of the east facade. The exterior is clad in red brick veneer laid in a running bond pattern except for the overhanging second floor of the facade which is clad in white vinyl siding. The primary entrance is located near the center of the facade and is accessed by a masonry stoop surrounded by black metal railing and sheltered by a flat roof supported by black metal posts. Large vinyl fixed windows are arranged on either side of the entrance and vinyl windows are arranged symmetrically on the second floor facade. Windows have cast stone or vinyl sill. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. There is no garage.
390	4030 Fullerton Street			1951	Streamline Moderne	1/garage	C	Unknown	likely Canvasser Brothers Building Company	The house at 4030 Fullerton Street is two-stories and topped with a hipped, asphalt shingle roof. A large brick chimney is located at the eave near the center of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with some courses of brick set proud to create horizontal bands in the brick and the area around the entrance is clad in stone veneer. The primary entrance is located near the east corner of the facade and is accessed by a brick veneer-clad concrete porch with beige metal handrails. A flat roof canopy supported by red posts shelters the porch. A large multi-light steel window within a rectangular bay is located west of the entrance and two multi-light steel windows are arranged near the corners of the second floor of the facade. Each window has a cast stone sill and is fitted with aluminum storms. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. There is no garage.
391	4031 Fullerton Street			1935c.	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4031 Fullerton Street is two-stories and topped with a hipped, asphalt shingle roof. A large brick chimney is located at the eave near the north corner of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer and cast stone. The primary entrance is located near the east corner of the facade and is accessed by a brick-clad porch surrounded by a short black metal railing and sheltered by a fabric awning supported by black metal posts. A two-story bay is west of the entrance and contains steel casement windows on the first and second floor. A steel leaded glass window on the second floor above the entrance. Each window has a cast stone sill. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. A hipped roof garage is at the rear of the property.
392	4038 Fullerton Street			1939	French Eclectic	n/a	C	Unknown	Unknown	The house at 4038 Fullerton Street is two-stories and topped with a hipped, asphalt shingle roof. A large brick chimney is located at the eave near the south corner of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer and cast stone. The primary entrance is located near the east corner of the facade and is accessed by a brick-clad porch surrounded by a brick kneewall and sheltered by a fabric awning supported by white metal posts. A single-story bay west of the entrance is topped with an asphalt shingle roof and contains steel casement windows. Vinyl slider windows are arranged on the second floor facade. Window have a cast stone and brick sill and the steel windows are fitted with aluminum storms. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. There is no garage. A black lightpost without a light fixture is located near the center of the front lawn.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
393	4046 Fullerton Street			1938	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4046 Fullerton Street is two-stories and topped with a hipped asphalt shingle roof intersected by a gable, hipped, and a polygonal roof. A brick half-wall extends from the east corner of the facade. A large brick chimney is located at the eave near the center of the east facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, rusticated cast stone, and decorative brickwork. The primary entrance is trimmed in stone and set within a turret nested near the center of the facade. A concrete porch with a black metal railing accesses the entrance. A bay clad in brick veneer and cast stone topped with an asphalt shingle roof is east of entrance and contains steel casement windows with leaded glass. Steel casement windows and steel casement leaded glass windows are arranged on the second floor facade. Windows have cast stone sills and are fitted with aluminum storms. Similar windows are arranged on other elevations. The driveway is concrete and runs along the west side of the house. An L-shaped hipped roof garage is at the rear of the property.
394	4047 Fullerton Street			1940	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4047 Fullerton Street is two-stories and topped with a hipped asphalt shingle roof. A brick chimney is on the west facade. The exterior is clad in red brick veneer with accents of stone veneer and cast stone and a curvilinear brick kneewall extends from the west corner of the facade. The door is offset on the primary facade and is trimmed in cast stone. There is a two-story bay window on the primary facade with cast stone trim and leaded glass windows on the first floor. Above the door there is a steel casement window with a white exterior storm window. The house has a partial width porch surrounded by a low metal railing. There is a large ell shaped garage behind the house with a hipped roof.
395	4055 Fullerton Street			1935c.	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4055 Fullerton Street is two-stories and topped with a hipped asphalt shingle roof intersected by two small gables above the facade. A brick chimney is at the eave near the north corner of the west facade. The exterior is clad in red brick veneer with accents of cast stone and decorative brickwork. A brick kneewall extends from the west corner of the facade. The primary entrance is trimmed in stone near the east corner of the facade and is accessed by a brick-clad concrete porch surrounded by a brick kneewall. A single-story bay topped with a flat roof is west of the entrance and contains a series of leaded glass windows. Steel casement and steel leaded glass windows are arranged on the second floor facade. Similar windows are on other elevations. The driveway is concrete and runs along the east side of the house. A hipped roof garage is at the rear of the property.
396	4060 Fullerton Street			1927	Tudor Revival	1/garage	C	Unknown	Miller-Storm Company	The house at 4060 Fullerton Street is two-stories and topped with prominent nested front gable asphalt shingle roofs. A large brick chimney is in the gable end of the tallest gable. The exterior is clad in red brick veneer laid in an English bond with some gable ends clad in yellow vinyl siding. The primary entrance is nested near the intersection of two gables and is set beneath a blind arch. A large terrace surrounded by a short metal railing and topped with a gable roof supported by brick piers is in the gable end east of the entrance. Steel casement and steel leaded glass windows with brick sills are arranged on the first and second floors of the facade. Similar windows are on other elevations. The driveway is concrete and runs along the east side of the house. A side gable roof garage is at the rear of the property.
397	4061 Fullerton Street			1930c.	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4061 Fullerton Street is two-stories and topped with a deck (hipped and flat) asphalt shingle roof intersected by a front gable above the facade. A stone half-wall extends from the west corner of the facade. A large brick chimney is located at the eave near the center of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is trimmed in stone, topped with a stone arch, placed near the center of the facade, and accessed by a brick-clad porch surrounded by a brick kneewall and topped with a metal awning structure. A bay clad in stone veneer and cast stone topped with an asphalt roof is west of entrance and contains steel casement windows. Steel casement windows are arranged elsewhere on the facade, some of which have fabric awnings. Window have cast stone sills and some are fitted with aluminum storms. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. A hipped roof garage is at the rear of the property.
398	4070 Fullerton Street			1935c.	French Eclectic	n/a	C	Unknown	Unknown	The house at 4070 Fullerton Street is two-stories and topped with a pyramidal roof intersected by a hipped roof on the facade. A sloped brick half-wall extends from the west corner of the facade. A large brick chimney is located at the eave near the center of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, decorative brickwork, and wood false half-timbering. The primary entrance is trimmed in stone near the center of the facade, and accessed by a brick-clad porch surrounded by a short black metal railing. A bay topped with sloping metal roof is west of entrance and contains steel casement windows. Steel casement and steel leaded glass windows are arranged elsewhere on the facade. Window have cast stone, brick, and wood sills. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. There is no garage.
399	4071 Fullerton Street			1955c.	Streamline Moderne	1/shed	C	Unknown	Canvasser Brothers Building Company	The house at 4071 Fullerton Street is two-stories and topped with a hipped, asphalt shingle roof. A tall brick chimney is located at the eave near the center of the west facade. The exterior is clad in blonde brick veneer laid in a running bond pattern with some courses of brick set proud to create horizontal bands in the brick. The primary entrance is located near the east corner of the facade and is accessed by a brick-clad concrete porch adjacent to a brick kneewall. An aluminum awning supported by black metal posts stretches across the porch and adjacent multi-light steel casement window. Two multi-light steel windows are arranged symmetrically on the second floor of the facade. Each window has a limestone or cast stone sill and is fitted with aluminum storms. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. A small shed is behind the house. A black lightpost with a light fixture is located near the center of the front lawn.
400	4076 Fullerton Street			1939	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4076 Fullerton Street is two-stories and topped with a hipped asphalt shingle roof. A large brick chimney is at the eave near the center of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer and cast stone. The primary entrance is trimmed in cast stone near the center of the facade. A brick-clad porch surrounded by a short black metal railing accesses the entrance. A bay with a flat roof is west of entrance and contains steel casement windows with cast stone trim. A steel casement windows is arranged east of the entrance and two are arranged on the second floor facade, one of which is set beneath a hipped roof wall dormer. Each window has a cast stone sill. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. A hipped roof garage is at the rear of the property.
401	4079 Fullerton Street			1946	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 4079 Fullerton Street is two-stories and topped with a side gable asphalt shingle roof. A brick chimney is at the eave near the center of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of cast stone. The primary entrance is set within a cast stone surround near the east corner of the facade. A brick-clad porch with a white metal railing sheltered by an aluminum awning supported by white metal posts accesses the entrance. A bay with a hipped asphalt roof is west of entrance and contains boarded over window openings and cast stone trim. Two steel casement windows framed by white shutters are arranged on the second floor facade. Windows have a cast stone or brick sill and some are fitted with aluminum storms. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. A pyramidal roof garage is at the rear of the property. A black lightpost with a light fixture is located near the center of the front lawn.
402	4084 Fullerton Street			1946	French Eclectic	n/a	C	Unknown	Harry Sosnick	The house at 4084 Fullerton Street is two-stories and topped with a hipped asphalt shingle roof intersected by a hipped roof above the facade. A large brick chimney is located at the eave near the center of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of cast stone and stone veneer. The primary entrance is trimmed in stone near the center of the facade. A brick-clad concrete porch partially surrounded by a brick kneewall accesses the entrance. A two-story bay is west of entrance and contains vinyl slider and hung windows. Similar windows are arranged elsewhere on the facade and other elevations. Windows have cast stone sills. The driveway is concrete and runs along the east side of the house. There is no garage.
403	4087 Fullerton Street			1947	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4087 Fullerton Street is two-stories and topped with a hipped asphalt shingle roof intersected by a hipped roof above the facade. A large brick chimney is located at the eave near the center of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of cast stone and stone veneer. The primary entrance is trimmed in stone near the center of the facade. A brick-clad concrete porch partially surrounded by a brick kneewall accesses the entrance. A single-story bay topped with a flared hipped roof is west of entrance and contains vinyl windows. A vinyl slider window is east of the entrance and two vinyl sliders are on the second floor facade. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. A front gable roof garage is at the rear of the property.
404	4098 Fullerton Street			1963	Modern Movement	1/garage	C	possibly Nathan Johnson	Unknown	The house at 4098 Fullerton Street is two-stories and topped with a flat membrane roof. A brick chimney is located at the eave on the rear facade. The exterior is clad in columns of red brick veneer laid in a running bond pattern and expanses of vinyl siding pierced by window openings. The primary entrance is at the south corner of the west facade, facing Petoskey Avenue, and is sheltered beneath cantilevered canopies--although only the frames remain. There are several tall, rectangular window openings but no windows are extant. A flat roof, brick-clad garage is at the rear of the property and connected to the house via an enclosed breezeway.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
405	4099 Fullerton Street			1947	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4099 Fullerton Street is two-stories and topped with a hipped asphalt shingle roof intersected by a hipped roof and gable roof above the facade. A large brick chimney is located at the eave on the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of cast stone and stone veneer. The primary entrance is trimmed in cast stone, surrounded by stone veneer, and near the center of the facade. A brick-clad concrete porch accesses the entrance. Three steel casement windows are arranged on the first floor facade and four are on the second floor. Windows have cast stone sills and are fitted with aluminum storms. Similar windows are arranged on other elevations. The driveway is concrete and runs behind the house. A pyramidal roof garage is at the rear of the property.
406	4200 Fullerton Street			1961	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 4200 Fullerton Street is a two story side gabled house clad in red brick veneer laid in a running bond pattern, with vinyl siding at the second floor which overhangs slightly creating a Garrison Colonial type of style. A brick chimney is located at the eave on the west facade. The main entrance is near the east corner of the house and is accessed by a brick and concrete stoop. There is a large vinyl slider window with brown shutters west of the entrance, and two smaller slider windows also with brown shutters on the second floor. Other facades have hung windows and cast stone sills, with glass block windows at the basement level. A concrete driveway is accessed off of Petoskey Avenue north of the house leading to a garage at the rear.
407	4205 Fullerton Street			1926	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4205 Fullerton Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by a prominent front gable as well as hipped roof dormers facing the east, south, and west facades, and a gabled wall dormer on the front facade. A brick chimney is located near the center of the house. The facade is clad in brown face brick laid in a Flemish bond pattern, with false half-timbering beneath the front gable and wall dormer. The primary entrance is near the west corner of the facade accessed by a low concrete and brick porch beneath a front gabled portico with false half-timbering. West of the entrance are four multi-light wood hung windows with brick infilled arches and keystones above, beneath two wood hung windows on the second floor. Similar windows appear on the rest of the elevations and have cast stone sills. A concrete driveway is accessed off of Petoskey Avenue south of the house leading to a pyramidal roof garage at the rear. There is a black lightpost with globe fixture in the lawn.
408	4211 Fullerton Street			1937	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4211 Fullerton Street is two-stories and topped with a cross gable asphalt shingle roof, composed of a side gable that meets a hipped roof towards the rear, intersected by a front gable. A brick chimney is located at the eave on the west facade of the house. The facade is clad in tan and brown face brick laid in a running bond pattern with distinctive decorative brickwork, and false half-timbering infilled with brick. The primary entrance is near the center of the facade accessed by a concrete and brick porch. On either side of the entrance is a one-story canted bay with steel casement windows, on the east the bay is clad in brick and on the west it is clad with cast stone veneer. The second floor is also glazed with steel casement windows. Similar windows appear on the rest of the elevations and have brick sills. A concrete driveway is east of the house leading to a front gable roof garage at the rear.
409	4212 Fullerton Street			1924	Colonial Revival	n/a	C	Unknown	Unknown	The house at 4212 Fullerton Street is two-stories and topped with a gambrel asphalt shingle roof. A brick chimney is located at the eave on the west facade. The facade is clad with brick veneer that has been painted green at the first floor, with stone veneer beneath a continuous shed dormer on the second floor, and vinyl siding beneath the gable on the second floor. The primary entrance is near the east corner of the facade beneath a hipped roof overhang with metal posts, and is accessed by a brick and concrete porch with metal railing. West of the entrance is a vinyl fixed window flanked by two small hung windows, and two pairs of vinyl hung windows beneath aluminum awnings are on the second floor. Similar windows exist on other elevations, and have cast stone sills on the first floor. There is no garage.
410	4220 Fullerton Street			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4220 Fullerton Street is two-stories and topped with a front gable asphalt shingle roof that meets a pyramidal roof towards the rear. A brick chimney with cast stone and tile accents is centered on the facade of the house. The facade is clad in brown face brick laid in a running bond pattern with decorative brickwork. The primary entrance is recessed near the west corner of the facade beneath a shed asphalt shingle roof accessed by a concrete and brick porch. On either side of the center chimney is a wood hung window, beneath two wood hung windows on the second floor and a split fanlight at the attic level. Similar windows appear on the rest of the elevations and all have cast stone sills. A concrete driveway is east of the house leading to a pyramidal roof garage at the rear.
411	4221 Fullerton Street			1924	Prairie	1/garage	C	Unknown	Unknown	The house at 4221 Fullerton Street is two-stories and topped with a hipped asphalt shingle roof with decorative brackets along the eave, intersected by a hipped roof dormer centered above the facade with brackets and containing three small wood windows. A brick chimney is at the eave on the west facade. The exterior is clad in brown brick veneer laid in a running bond pattern with some decorative brickwork. The entrance is accessed beneath a cantilevered, gabled overhang with vergeboard and brackets, accessed by a brick and concrete stoop with metal railing. Three six-over-six wood hung windows with aluminum storms are west of the entrance, topped with brick infilled arches, and two pairs of matching hung windows on the second floor. Similar windows are arranged on other elevations, and have cast stone sills. A concrete driveway runs along the east of the property to the rear where there is a gabled roof garage. There is a metal light post in the front lawn.
412	4226 Fullerton Street			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4226 Fullerton Street is two-stories and topped with a hipped asphalt shingle roof, intersected by a front gable that overlaps with a small front gable above the entrance vestibule. A brick chimney is located at the eave on the west facade of the house. The facade is clad in brown face brick laid in a running bond pattern with some decorative brickwork and stone accents. The primary entrance is an arched door at the east corner of the facade accessed by a concrete and brick porch. West of the entrance are three wood hung windows with divided upper sashes, beneath a brick lintel with stone accents. The second floor is glazed with two hung windows with divided upper sashes, and a casement window surrounded by stone quoins. Similar windows appear on the rest of the elevations and have cast stone sills. A concrete driveway is east of the house leading to a front gable roof garage at the rear. There is a black lightpost with a globe fixture on the front lawn.
413	4235 Fullerton Street			1924	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4235 Fullerton Street is two-stories and topped with a cross gable asphalt shingle roof, composed of a side gable that meets a hipped roof towards the rear, intersected by two overlapping front gables. A brick chimney is located at the eave on the west facade of the house. The facade is clad in blonde face brick laid in a running bond pattern with decorative brickwork, cast stone accents at windows and doors. A small brick buttress extends from the west corner of the facade. The primary entrance is near the east corner of the facade beneath a front gable with knee brackets and an arched window. The door is trimmed with stone quoins and a keystone, and accessed by a concrete and brick porch with a metal railing. West of the entrance are three casement windows with aluminum storms, topped with fanlights and brick arches with cast stone springers and keystones. The second floor is glazed with three hung windows with divided upper sashes and a played brick lintel with keystone. A small arched window is beneath the gable at the attic level. Similar windows appear on the rest of the elevations and windows have cast stone sills. A concrete driveway is east of the house leading to a pyramidal roof garage at the rear. A black lightpost is in the front lawn.
414	4236 Fullerton Street			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4236 Fullerton Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by a prominent front gable as well as jerkinhead dormers clad in wood shingles facing the east and west facades. A brick chimney is located at the eave on the west facade of the house. The facade is clad in brown face brick laid in an English bond pattern, with false half-timbering infilled with stucco on the second floor. The primary entrance is near the east corner of the facade accessed by a concrete and brick porch beneath a jerkinhead portico with false half-timbering supported by brick piers. West of the entrance are three vinyl hung windows with a brick quoined surround, beneath three wood hung windows on the second floor. Similar windows appear on the rest of the elevations and have cast stone sills on the first floor. A concrete ribbon driveway runs along the east of the house leading to a hipped roof garage at the rear.
415	4245 Fullerton Street			1924	Colonial Revival	n/a	C	Unknown	Unknown	The house at 4245 Fullerton Street is two-stories and topped with a side gable asphalt shingle roof with modillions along the eave. A brick chimney is located at the eave on the west facade. The facade is clad with brown brick veneer. The primary entrance is near the east corner beneath a cantilevered, metal roof overhang. The door is elaborated by a wood door surround and sidelights, and is accessed by a brick and concrete porch with metal railing. West of the entrance is a projecting bay window with a metal flared roof, but the window openings have been boarded over. Three wood hung windows with aluminum storms and white shutters are on the second floor. Similar windows exist on other elevations, and all have cast stone sills.
416	4250 Fullerton Street			1926	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4250 Fullerton Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by a prominent front gable as well as hipped roof dormers clad in asphalt shingles facing the east and west facades and a shed dormer towards the rear. A brick chimney is located at the eave on the west facade of the house. The facade is clad in brown face brick laid in a running bond pattern, with some decorative brickwork. Brick on the front portion of the first floor has been painted yellow. The primary entrance is near the east corner of the facade accessed by a concrete and brick porch beneath a jerkinhead portico with an arched opening supported by tapered brick piers. West of the entrance are three wood hung windows with aluminum storms under an asphalt shingled awning, beneath three wood hung windows on the second floor. Similar windows appear on the rest of the elevations and have cast stone sills. A concrete driveway runs along the east of the house to the rear. There is no garage.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
417	4253 Fullerton Street			1924	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4253 Fullerton Street is two-stories and topped with a side gable asphalt shingle roof, intersected by a prominent catslide front gable. A brick chimney is located at the eave on the west façade of the house. The facade is clad in brown face brick laid in a running bond pattern with decorative brickwork and cast stone accents at windows and doors. Vinyl siding is beneath the side gable at the attic level. A small brick buttress extends from the west corner of the façade. The primary entrance is near the east corner of the façade, recessed beneath the catslide through an arched opening and accessed by a concrete and brick porch. West of the entrance are three wood hung windows with divided upper sashes, topped with a cast stone arched lintel and quoins. The second floor is glazed with two hung windows with divided upper sashes and a splayed brick lintel with keystone. A small narrow window is beneath the gable at the attic level. Similar windows appear on the rest of the elevations and windows have cast stone sills. A concrete driveway is east of the house leading to a pyramidal roof garage at the rear.
418	4260 Fullerton Street			1926	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4260 Fullerton Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by a prominent front gabled jerkinhead as well as hipped roof dormers clad in vinyl siding facing the east and west facades and a shed dormer towards the rear. A brick chimney is located at the eave on the west facade of the house. The facade is clad in red and brown face brick laid in a running bond pattern, with false half-timbering beneath the jerkinhead on the second floor. The primary entrance is near the east corner of the façade accessed by a concrete and brick porch beneath a jerkinhead portico with an arched opening with cast stone keystone supported by quoined brick piers. West of the entrance is a one-story canted bay with a large fixed window at the center flanked by two narrow hung windows. There is one hung window on the second floor and a slider. Similar windows appear on the rest of the elevations and all have cast stone sills. A concrete driveway runs along the east of the house to the rear where there is a pyramidal roof garage.
419	4261 Fullerton Street			1926	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4261 Fullerton Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by a prominent front gable as well as hipped roof dormers clad in vinyl siding facing the east and rear facades. A brick chimney is located at the eave on the west facade of the house. The facade is clad in light brown face brick laid in a running bond pattern, with a small brick buttress extending from the west corner. The primary entrance is near the east corner of the façade accessed by a concrete and brick porch beneath a front gabled portico with an arched opening with cast stone tabs and keystone supported by brick piers. West of the entrance are four wood hung windows with divided upper sashes and aluminum storms, beneath matching windows on the second floor. Similar windows appear on the rest of the elevations and all have cast stone sills. A concrete driveway runs along the east of the house to the rear. There is no garage.
420	4266 Fullerton Street			1923	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4266 Fullerton Street is two-stories and topped with a front gable asphalt shingle roof. A brick chimney is located at the eave on the west facade. The facade is clad with light brown brick veneer that is laid in a running bond pattern, with a small brick buttress extending from the west corner, and wood shingle siding on the second floor. The primary entrance is near the east corner of the facade beneath a gable roof overhang supported by wood column posts, and is accessed by a brick and concrete porch with metal railing. The door is flanked by two narrow multi-light windows. West of the entrance are four hung wood windows with divided upper sashes, beneath two hung windows with divided upper sashes on the second floor. Similar windows exist on other elevations, and have cast stone sills on the first floor. There is no garage.
421	4269 Fullerton Street			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4269 Fullerton Street is two-stories and topped with a pyramidal asphalt shingle roof, intersected by a prominent front gable. A brick chimney is located at the eave on the west facade of the house. The facade is clad in red and brown face brick laid in a running bond pattern with some decorative brickwork. The primary entrance is near the east corner of the façade accessed by a concrete and brick porch beneath a front gabled portico with an arched opening and brick piers. Above the entrance on the second floor are three windows with leaded glass detailing in a diamond pattern. West of the entrance are four steel casement windows, beneath a pair of hung windows on the second floor. Similar windows appear on the rest of the elevations and all have cast stone sills. A concrete driveway runs along the east of the house to the rear where there is a front gable roof garage.
422	4274 Fullerton Street			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4274 Fullerton Street is two-and-a-half stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by a front gable, a jerkinhead facing west, and a rear gable. A prominent brick chimney is located on the front of the house. The facade is clad in reddish brown and gray face brick laid in a running bond pattern with accents of cast stone, and false half-timbering infilled with stucco at the attic level and some portions of the second floor. The primary entrance is recessed on the west façade accessed by a concrete and brick porch beneath an arched portico supported by brick piers. A small brick buttress extends from the west corner of the portico. The primary façade is glazed with steel casement windows that have aluminum storms affixed to the exterior, while hung windows appear on other elevations and all windows have brick sills. A concrete driveway runs along the east of the house leading to a side gable roof garage at the rear. Another concrete driveway runs in a semi-circular path in front of the house.
423	4277 Fullerton Street			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4277 Fullerton Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by a front gable, and a hipped roof dormer facing west and another at the rear. A brick chimney is located at the eave on the west facade of the house. The facade is clad in brown face brick laid in a running bond pattern with accents of stone. The primary entrance is located near the east corner of the façade and is accessed by a concrete and brick porch with a metal railing, beneath a front gabled portico supported by slightly tapered brick piers and a brick arched opening. Above the arch is a polychromatic tile detail. The door is arched with stone accents. West of the entrance are three wood hung windows with divided upper sashes, accented by a brick splayed lintel with stone tabs and keystone. Similar windows are on the second floor and on other elevations. Windows have cast stone sills painted black. A concrete driveway runs along the east of the house leading to a hipped roof garage at the rear.
424	4285 Fullerton Street			1929	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4285 Fullerton Street is two-stories and topped with a side gable asphalt shingle roof, intersected by a front gable that overlaps with another front gable above the entrance vestibule. A brick chimney is located at the eave on the west facade of the house. The facade is clad in red and brown face brick laid in a running bond pattern with some decorative brickwork and accents of Klinker brick. The primary entrance is slightly off-center on the façade and is accessed by a concrete stoop. The door is arched and is trimmed in brick with a keystone above. The primary façade is glazed with steel casement windows with sidelights and transoms, with brick surrounds and brick sills. Similar windows appear on the rest of the elevations. A concrete driveway runs along the east of the house to the rear where there is a garage.
425	4290 Fullerton Street			1924	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4290 Fullerton Street is two-stories and topped with a side gable asphalt shingle roof, intersected by a front gable with catslide that extends above the entrance vestibule. A brick chimney is located at the eave on the west facade of the house. The facade is clad in red and brown face brick laid in a running bond pattern with some decorative brickwork and a soldier course between the first and second floor. Wide metal siding is present beneath the side gable and at the rear. The primary entrance is recessed near the east corner of the façade beneath the catslide, which is supported by brick arched openings and is accessed by a brick and concrete porch. Three hung vinyl windows with divided upper sashes are set within a cast stone surround west of the entrance, beneath two similar windows on the second floor which are topped with a splayed brick lintel with cast stone accents. Similar windows appear on other elevations, and have cast stone sills. A concrete driveway runs along the east of the house to the rear where there is a garage with a pyramidal roof.
426	4291 Fullerton Street			1924	Georgian Revival	n/a	C	Unknown	Unknown	The house at 4291 Fullerton Street is two-stories and topped with a side gable asphalt shingle roof with modillions along the eave. There are two pedimented roof dormers on the façade and there is a hipped roof addition towards the rear. A brick chimney is located at the eave on the west facade. The facade is clad with brown brick veneer laid in a running bond pattern, with some sections set proud at the corners to give a quoined appearance. A cast stone belt course runs between the first and second floor. The primary entrance is near the east corner within an elaborated wood door surround with pilasters topped with a segmental arch. The entrance is accessed by a full width brick and concrete porch with metal railing. The façade is glazed with hung vinyl windows arranged symmetrically and all have cast stone sills. A concrete driveway runs along the east of the house to the rear where there is no garage.
427	4298 Fullerton Street			1924	Tudor Revival	n/a	C	Unknown	Miller-Storm Company	The house at 4298 Fullerton Street is two-stories and topped with a front gable asphalt shingle roof, overlapping with another front gable and intersected by multiple shed roof dormers creating varied eave lines. A brick chimney is located at the eave on the west facade of the house. The facade is clad in red and brown face brick laid in an English bond pattern on the first and second floor is clad in vinyl siding. The primary entrance is arched and recessed near the east corner of the façade and is accessed by a brick and concrete wrap-around porch with a metal railing. Two French doors open onto the porch on the front façade. The house is glazed in hung vinyl windows, except for a wood casement window at the attic level beneath the front gable. Similar windows appear on other elevations, and have cast stone sills on the first floor. A concrete driveway runs along the east of the house to the rear where there is no garage.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
428	4301 Fullerton Street			1925	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4301 Fullerton Street is two-stories and topped with a cross gable asphalt shingle roof, composed of a side gable that meets a hipped roof towards the rear, and is intersected by a front gable that overlaps with another front gable above the entrance vestibule. A brick chimney is located at the eave on the west facade of the house. The facade is clad in brown face brick laid in a running bond pattern with some decorative brickwork and cast stone accents, and vinyl siding beneath the side gable. The primary entrance is near the east corner of the facade beneath a flat roof overhang supported by square wood posts, and is accessed by a brick and concrete porch with a wood railing. Three hung vinyl windows topped with infilled arches are west of the entrance, beneath a set of three hung windows on the second floor which are topped with a splayed brick lintel with cast stone accents. Similar windows appear on other elevations, and windows have cast stone sills. A concrete driveway runs along the east of the house to the rear where there is no garage.
429	4306 Fullerton Street			1927	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4306 Fullerton Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by a front gabled jerkinhead, and a hipped roof dormer facing west and another facing east. A brick chimney is located at the eave on the west facade of the house. The facade is clad in brown face brick laid in a running bond pattern with accents of stone. The primary entrance is located near the east corner of the facade and is accessed by a concrete and brick porch with a metal railing, beneath a jerkinhead portico supported by brick piers and a brick segmental arched opening. West of the entrance are three wood hung windows with divided upper sashes, the whole set beneath a segmental arch brick lintel. Two matching windows are on the second floor beneath a splayed brick lintel. Similar windows are found on other elevations and have cast stone sills. A concrete driveway runs along the east of the house leading to a garage at the rear.
430	4307 Fullerton Street			1924	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4307 Fullerton Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by a front gable that intersects with another front gable above the entrance vestibule, and a hipped roof dormer on the front, west, and rear facades. A brick chimney is located at the eave on the west facade of the house. The facade is clad in brown face brick laid in a running bond pattern, with false half-timbering infilled with stucco beneath the front gables. The primary entrance is located near the center of the facade with an arched door, and is accessed by a concrete and brick porch with a metal railing. On either side of the entrance is a set of three wood hung windows within a segmental arch, the whole set beneath a segmental arch brick lintel. Two pairs of hung vinyl windows are on the second floor. Similar windows are found on other elevations and all have brick sills. A concrete driveway runs along the east of the house leading to a pyramidal roof garage at the rear.
431	4314 Fullerton Street			1927	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4314 Fullerton Street is two-stories and topped with a hipped asphalt shingle roof, intersected by a front gable that overlaps with a small front gable above the entrance vestibule. A brick chimney is located at the eave on the west facade of the house. The facade is clad in brown face brick laid in a running bond pattern. The primary entrance is an arched door near the east corner of the facade accessed by a concrete and brick full width porch with a metal railing. West of the entrance are three wood hung windows with wrought iron security bars, each topped with an infilled brick arch. At the second floor is a set of three hung windows beneath an aluminum metal awning, and a multi-light wood casement window at the attic level. Similar windows appear on other elevations and all have cast stone sills. A concrete driveway is east of the house leading to a pyramidal roof garage at the rear.
432	4317 Fullerton Street			1926	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4317 Fullerton Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by a front gabled catslide, and a hipped roof dormer facing east. A brick chimney is located at the eave on the front of the house with decorative brickwork including a blind pointed arch. The facade is clad in red and brown face brick laid in a running bond pattern with some decorative brickwork and stone accents. The primary entrance is located near the east corner of the facade with a pointed arched door with brick surround, and is accessed by a concrete and brick porch with a metal railing. West of the entrance, on either side of the chimney, are two pairs of wood hung windows divided upper sashes and splayed brick lintels with stone accents, beneath two matching pairs of hung windows on the second floor. Similar windows are found on other elevations and all have brick sills. A concrete driveway runs along the east of the house leading to a pyramidal roof garage at the rear.
433	4322 Fullerton Street			1924	Italian Renaissance	1/garage	C	Unknown	Unknown	The house at 4322 Fullerton Street is two-stories and topped with a hipped asphalt shingle roof intersected by a hipped roof dormer above the east facade. A large brick chimney is at the eave on the west facade of the house. The facade is clad in light brown brick laid in a running bond pattern. The primary entrance is near the east corner of the facade within a slightly projecting vestibule with cast stone molding, and accessed by a brick and concrete full-width porch. Three full height vinyl windows topped with brick arches infilled with cast stone and tile are west of the entrances and set beneath vinyl windows on the second floor which are framed by beige shutters. Windows have cast stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house. A front gable roof garage is at the rear of the property.
434	4325 Fullerton Street			1924	Tudor Revival	1/garage	C	J. Lawson Miller	Unknown	The house at 4325 Fullerton Street is two-stories and topped with a cross gable asphalt shingle roof intersected by a front gabled catslide. A large brick chimney is at the eave on the west facade of the house. The facade is clad in light brown brick laid in a running bond pattern, with some decorative brickwork and a cast stone belt course between the first and second floor. Wide metal siding is present on the second floor and attic level. The primary entrance is centered on the facade beneath a front gabled portico supported by slightly tapered brick piers with an arched opening, and accessed by a brick and concrete full-width porch. On either side of the entrance is a pair of hung windows with divided upper sashes, beneath similar windows on the second floor. Windows have cast stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house. A pyramidal roof garage is at the rear of the property.
435	4330 Fullerton Street			1924	Italian Renaissance	1/garage	C	Unknown	Unknown	The house at 4330 Fullerton Street is two-stories and topped with a pyramidal asphalt shingle roof intersected by a hipped roof dormer centered above the facade and another facing east. A large brick chimney is at the eave on the west facade of the house. The facade is clad in red and brown brick laid in a running bond pattern. The primary entrance is near the east corner of the facade, elaborated by a decorative wood surround painted black and white with pilasters and an arched top, and accessed by a brick and concrete full-width porch. Three wood hung windows have vertically divided upper sashes topped with brick arches infilled with colorful tile mosaic are west of the entrance, with similar windows on the second floor which are framed by black and white shutters. Windows have cast stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house. A pyramidal roof garage is at the rear of the property.
436	4331 Fullerton Street			1952	Colonial Revival	n/a	C	Unknown	Unknown	The house at 4331 Fullerton Street is two-stories and topped with a pyramidal asphalt shingle roof. A brick chimney is at the eave on the west facade of the house. The facade is clad in red brick laid in a running bond pattern. The primary entrance is near the east corner of the facade beneath an asphalt shingled overhang and accessed by a low brick and concrete porch. West of the entrance is a flat bay window beneath an aluminum metal awning, with two small hung windows each with an aluminum metal awning on the second floor. Windows have cast stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house. There is no garage.
437	4338 Fullerton Street			1926	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4338 Fullerton Street is two-stories and topped with a side gable asphalt shingle roof intersected by a front gabled catslide. A tall brick chimney is at the eave on the east facade of the house. The facade is clad in red brick laid in a running bond pattern, with some decorative brickwork and accents of klinker brick. Stucco is present on the second floor and attic level beneath the side gable. The primary entrance is recessed beneath the catslide overhang near the west corner of the facade, supported by brick piers with an arched opening, and accessed by a brick and concrete porch where the metal support structure for an awning is present. Centered on the facade is a vinyl slider window topped with a splayed and arched brick lintel, beneath a pair of vinyl hung windows on the second floor also with a splayed brick lintel. Windows have cast stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house. A pyramidal roof garage is at the rear of the property.
438	4341 Fullerton Street			1925	Italian Renaissance	1/garage	C	Unknown	Unknown	The house at 4341 Fullerton Street is two-stories and topped with a pyramidal asphalt shingle roof intersected by a hipped roof dormer centered above the facade. A large brick chimney is at the eave on the west facade of the house. The facade is clad in light brown brick laid in a running bond pattern. The primary entrance is near the east corner of the facade, within a slightly projecting vestibule, and accessed by a brick and concrete full-width porch. Three full height metal doors open to the porch west of the entrance and are topped with brick infilled arches each featuring a tile. The second floor windows are wood, hung, with vertically divided sashes and black shutters. Windows have cast stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house. A front gable roof garage is at the rear of the property.
439	4346 Fullerton Street			1925	Italian Renaissance	1/garage	C	Unknown	Unknown	The house at 4346 Fullerton Street is two-stories and topped with a pyramidal asphalt shingle roof intersected by a hipped roof dormer centered above the facade. A brick chimney is near the center of the house. The facade is clad in light brown brick laid in a running bond pattern. The primary entrance is near the east corner of the facade, within a slightly projecting arched vestibule matching the arched door, and accessed by a brick and concrete porch where the metal support structure for an awning is present. Three wood hung windows with divided upper sashes are west of the entrance and are topped with segmental arched surrounds. West of these are two narrow arched multi-light windows. Similar windows are on the second floor and on other elevations. Windows have cast stone sills. A concrete driveway runs along the east side of the house. A pyramidal roof garage is at the rear of the property.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
440	4349 Fullerton Street			1926	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4349 Fullerton Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by a front gable, a triangular roof dormer with leaded glass window above the façade, and a hipped roof dormer facing east. A brick chimney is located at the eave on the west facade of the house. The facade is clad in red and brown face brick laid in a running bond pattern with decorative brickwork and stone accents. The primary entrance is located near the east corner of the façade with a pointed arched door with brick surround, and is accessed by a concrete and brick porch with a metal railing. West of the entrance are four hung windows with divided upper sashes and decorative stone lintels, and similar hung windows glaze the second floor. A small pointed arch window is at the attic level beneath the front gable. Similar windows are found on other elevations and all have cast stone sills. A concrete driveway runs along the east of the house leading to a pyramidal roof garage at the rear.
441	4354 Fullerton Street			1922	Prairie	1/garage	C	Unknown	Unknown	The house at 4354 Fullerton Street is two-stories and topped with a pyramidal asphalt shingle roof with broadly overhanging eaves with modillions, intersected by a hipped roof dormer clad in wood shingles centered above the façade, and another hipped roof dormer facing east. A brick chimney is located at the eave on the west facade of the house. The facade is clad in red and brown face brick laid in a running bond pattern with some decorative brickwork and stone accents. The primary entrance is located near the east corner of the façade beneath a full width brick and concrete porch covered by a hipped roof with broadly overhanging eaves and modillions supported by brick piers. West of the entrance are four hung windows with divided upper sashes, and two pairs of matching hung windows glaze the second floor. Similar windows are found on other elevations and all have cast stone sills. A concrete driveway runs along the east of the house leading to a front gable roof garage at the rear. A black lightpost with a globe light fixture is in the front lawn.
442	4357 Fullerton Street			1926	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4357 Fullerton Street is two-stories and topped with a side gable asphalt shingle roof intersected by a front gable. A large brick chimney is at the eave on the west facade of the house. The facade is clad in red and brown brick laid in a running bond pattern, with decorative brickwork and cast stone accents. The primary entrance is near the east corner of the facade beneath a front gabled portico supported by tapered brick piers with an arched opening and stone accents, and accessed by a brick and concrete porch. West of the entrance is an aluminum awning above windows that are obscured from view by vegetation, beneath a segmental arched set of wood hung windows with divided upper sashes on the second floor. There is a narrow arched multi-light window beneath the front gable at the attic level. Windows have cast stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house. A side gable roof garage is at the rear of the property. A black lightpost with a globe light fixture is in the front lawn.
443	4362 Fullerton Street			1924	Italian Renaissance	1/garage	C	Unknown	Unknown	The house at 4362 Fullerton Street is two-stories and topped with a hipped asphalt shingle roof with dentils and modillions along the eave intersected by a hipped roof dormer centered above the façade and another facing east. A large brick chimney is at the eave on the west facade of the house. The facade is clad in light brown brick laid in a running bond pattern, with some sections set proud at the corners creating a quoined appearance. The primary entrance is near the east corner of the façade, beneath an overhang with dentils and modillions at the eave and supported by square wood posts. The entrance is accessed by a brick and concrete porch with a metal railing. West of the entrance are two wood hung windows with divided upper sashes and hood molded surrounds topped with stucco infilled arches each featuring a tile. The second floor windows are wood, hung, with divided upper sashes. Windows have cast stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house. A pyramidal roof garage is at the rear of the property. A black lightpost with a globe light fixture is in the front lawn.
444	4365 Fullerton Street			1928	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4365 Fullerton Street is two-stories and topped with a deck, flat on hipped, steeply pitched asphalt shingle roof, intersected by a front gable, an eyebrow roof dormer with a fanlight window above the façade, a hipped roof dormer facing east, and a shed roof dormer facing west. A brick chimney is located at the eave on the west facade of the house. The facade is clad in red, orange, and brown face brick laid in a running bond pattern with decorative brickwork. The primary entrance is located at the center of the façade with a slightly projected front gabled vestibule with an arched door and brick surround, and is accessed by a concrete and brick porch. West of the entrance are four narrow hung windows with divided sashes and leaded glass detailing beneath an aluminum awning. Matching windows are east of the entrance, with a splayed brick lintel. The second floor has two sets of three hung windows. Similar windows are found on other elevations and all have brick sills. A concrete driveway runs along the east of the house. There is no garage. A black lightpost with a globe light fixture is in the front lawn.
445	4370 Fullerton Street			1929	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4370 Fullerton Street is two-stories and topped with a cross gable asphalt shingle roof intersected by multiple overlapping front gables. A large brick chimney is at the eave on the east facade of the house. The facade is clad in red and brown brick laid in a running bond pattern, with cast stone accents, and stone veneer beneath the front gabled entrance vestibule. Vinyl siding is present on the second floor and attic level. The primary entrance is recessed and centered on the facade beneath an aluminum metal awning, and accessed by a low brick and concrete porch. On either side of the entrance is a vinyl slider window, and the second floor is glazed with narrow vinyl fixed windows and a hung window with a wall dormer. Windows have brick sills. Similar windows are arranged on other elevations. A concrete driveway runs along the west side of the house. A pyramidal roof garage is at the rear of the property.
446	4373 Fullerton Street			1927	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4373 Fullerton Street is two-stories and topped with a pyramidal asphalt shingle roof, intersected by a front gable, and a hipped roof dormer facing the rear. A brick chimney is located at the eave on the east facade of the house. The facade is clad in light and dark brown face brick laid in a running bond pattern with decorative brickwork and stone accents. The primary entrance is located near the center of the façade with an arched door beneath an aluminum metal awning, and is accessed by a concrete and brick porch with a metal railing. West of the entrance beneath the same awning are three wood hung windows with divided sashes, and east of the entrance are a matching set of three windows beneath a segmental arch lintel with stone accents. Two pairs of wood hung windows are on the second floor, and centered above the entrance on the second floor are two narrow casement windows with leaded glass detailing in a diamond pattern. Similar windows are found on other elevations and all have cast stone sills. A concrete driveway runs along the east of the house. There is a front gable roof garage at the rear.
447	4735 Fullerton Street			1961	Streamline Moderne	1/garage	C	Unknown	Unknown	The house at 4735 Fullerton Street is two-stories and topped with a hipped, asphalt shingle roof. A large brick chimney is located at the eave near the west corner on the front of the house. The exterior is clad in brick veneer painted blue laid in a running bond pattern, with areas of stone veneer and vertical wood siding. The primary entrance is located near the center of the facade and is accessed by a brick and concrete stoop with a metal railing. On either side of the entrance is a horizontally divided multi-light fixed window, and a smaller similar window at the east corner on the second floor. A small hung window is near the west corner on the second floor. A cast stone sill runs below the windows. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house to a pyramidal roof garage at the rear.
448	4741 Fullerton Street			1925	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 4741 Fullerton Street is two-stories and topped with a side gable asphalt shingle roof intersected by a front gabled roof dormer containing three small multi-light hung windows and clad in wood shingles centered above the façade. A large brick chimney is at the eave on the west facade of the house. The facade is clad in brown brick laid in a running bond pattern. The primary entrance is centered on the façade beneath a flat roofed portico supported by square wood posts, and is accessed by a brick and concrete porch. Two wood hung windows with divided upper sashes are on either side of the entrance and are topped with brick infilled arches. The second floor has three hung windows with divided upper sashes. Windows have cast stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house. A pyramidal roof garage is at the rear of the property. A black lightpost with a globe light fixture is in the front lawn.
449	4755 Fullerton Street			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4755 Fullerton Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by a front gable, and a hipped roof dormer facing east. A brick chimney is located at the eave on the west facade of the house. The facade is clad in reddish brown face brick laid in a Flemish bond pattern with decorative brickwork and stone accents. The primary entrance is located at the east corner of the façade beneath a front gabled portico with brick piers and a brick arched opening, and is accessed by a concrete and brick porch with a metal railing. West of the entrance are three wood hung windows with divided upper sashes beneath a segmental arched brick lintel with stone accents. A pair of matching windows on the second floor with a splayed brick lintel, next to a small pair of casement windows topped with a brick infilled arch. Similar windows are found on other elevations and all have cast stone sills. A concrete driveway runs along the east of the house to the rear where there is a pyramidal roof garage.
450	4765 Fullerton Street			1926	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4765 Fullerton Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by a front gable, a hipped roof dormer facing east, and a shed dormer facing west. A brick chimney is located at the eave on the front of the house, with decorative brickwork and stone accents. The facade is clad in reddish brown face brick laid in a running bond pattern with decorative brickwork and stone accents. The primary entrance is located at the east corner of the façade within a slightly projecting front gabled vestibule, and is accessed by a low concrete porch. West of the entrance is a wood casement window beneath a segmental arched brick lintel with stone accents. Vinyl slider windows on the second floor, one with a splayed brick lintel. Similar windows are found on other elevations and all have cast stone sills. A concrete driveway runs along the east of the house to the rear where there is a pyramidal roof garage. A black lightpost with a globe light fixture is in the front lawn.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
451	4775 Fullerton Street			1930c	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4775 Fullerton Street is two-stories and topped with a deck, flat-on-hipped asphalt shingle roof intersected by a hipped roof projecting wing at the front, with two hipped roof wall dormers across the façade, and an engaged polygonal tower capped with a polygonal roof centered on the façade at the intersection of the two wings. A tall brick chimney is located at the eave on the west facade. The exterior is clad in red and brown brick veneer laid in a running bond pattern, with accents of cast stone and rusticated stone. The primary entrance set within the tower, consisting of segmental arched door trimmed in stone and beneath a casement window topped with a fanlight on the second floor. The entrance is accessed by a brick and concrete porch. West of the entrance is a canted bay with steel casement windows that have brick sills and covered by a metal roof with flared eaves. East of the entrance is slightly projecting bay with three steel casement windows with a diamond pattern and brick sills beneath a metal roof with flared eaves. On the second floor, windows are steel casement. Similar windows are arranged on other elevations and have cast stone sills on the second floor. At the east corner of the façade the brick extends into a buttress creating porte cochere structure above the concrete driveway leading to the rear of the house where there is a side gable roof garage.
452	4795 Fullerton Street			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4795 Fullerton Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by a front gable catslide, and a flat roof. A brick chimney is located at the eave on the west façade of the house, with decorative brickwork. The facade is clad in red and brown face brick laid in a running bond pattern with decorative brickwork and stone accents. The primary entrance is centered on the façade with an arched door trimmed in stone quoins, and is accessed by a low concrete porch. East of the entrance is a full height square bay with a flat roof. Windows appear to be steel casement with aluminum storms affixed to the exterior. Windows on the first floor have brick lintels. Similar windows are found on other elevations and all have cast stone sills. A concrete driveway runs along the east of the house beneath a front gabled porte cochere structure with a segmental arch opening to the rear where there is a pyramidal roof garage.
453	4803 Fullerton Street			not listed	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4803 Fullerton Street is two-stories and topped with a hipped asphalt shingle roof, intersected by overlapping front gables, and a catslide extending from the east corner over a porte cochere structure. A hipped roof dormer faces east. A brick chimney is located at the eave on the west façade of the house. The facade is clad in brown face brick laid in a running bond pattern with decorative brickwork and areas of stucco, and false half-timbering infilled with stucco on the second floor. A brick buttress extends from the west corner of the house. The primary entrance is near the east corner of the façade with an arched door trimmed in brick quoins, and is accessed by a brick and concrete stoop with a metal railing. West of the entrance four narrow steel casement windows with a diamond pattern beneath a brick arch infilled with stucco and decorative tilework. There is a single window with a diamond pattern above. Windows have cast stone lintels and similar windows are found on other elevations. A concrete driveway runs along the east of the house to the rear where there is a pyramidal roof garage.
454	4810 Fullerton Street			1963	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4810 Fullerton Street is two-and-a-half stories and topped with a cross gable asphalt shingle roof, intersected by a front gabled entrance vestibule, a shed roof dormer to the west and a hipped roof dormer to the north. A brick chimney is located at the eave centered on the east façade of the house. The facade is clad in red and brown face brick laid in a running bond pattern with decorative brickwork. The primary entrance is near the center of the primary façade recessed within an arched stone surround, and is accessed by a concrete stoop. The façade is glazed with narrow steel casement windows with a diamond pattern, with brick surrounds and cast stone sills. A brick and concrete porch with a metal railing extends off the east façade, and another extends from the west façade off of a hipped roof one-story wing. Windows have cast stone lintels and similar windows are found on other elevations. A concrete driveway is accessed off of Fullerton Street to the west of the house where there is a hipped roof garage.
455	4815 Fullerton Street			1926	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4815 Fullerton Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by a front gable catslide, a hipped roof dormer to the east, and a shed and gabled roof dormer above the west facade. Another catslide extends to the west above a one-story wing. A brick chimney is located on the front of the house. The facade is clad in dark brown face brick laid in a running bond pattern with decorative brickwork and stone accents. The primary entrance is near the east corner of the façade in a projecting front gabled vestibule with an arched door trimmed in stone quoins and is accessed by a low brick and concrete porch. Windows across the façade are hung vinyl topped with segmental arch brick lintels with stone accents and cast stone sills. Similar windows are found on other elevations. A concrete driveway runs along the east of the house to the rear where there is a pyramidal roof garage.
456	4825 Fullerton Street			1927	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4825 Fullerton Street is two-stories and topped with a hipped asphalt shingle roof, intersected by overlapping front gables, and hipped roof dormers to the east, south, and west. A brick chimney is located at the eave on the west façade of the house. The facade is clad in red and brown face brick laid in a running bond pattern with some false half-timbering infilled with stucco. The primary entrance is near the center of the façade in a slightly projecting front gabled vestibule with an arched door trimmed in brick, and is accessed by a brick and concrete porch with a metal railing. On either side of the entrance are four narrow steel casement windows beneath a brick segmental arch lintel. There is an oriel window glazed with narrow hung windows on the second floor. Windows have cast stone lintels and similar windows are found on other elevations. A concrete driveway runs along the east of the house to the rear where there is a front gable roof garage.
457	4831 Fullerton Street			not listed	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4831 Fullerton Street is two-stories and topped with a pyramidal asphalt shingle roof, intersected by two front gables, and hipped roof dormers clad in wood shingles are centered above the east, south, and west facades. A brick chimney is located at the eave on the west façade of the house. The facade is clad in red and brown face brick laid in a running bond pattern with false half-timbering infilled with stucco beneath the front gables. The primary entrance is near the center of the façade beneath an aluminum metal awning, and is accessed by a brick and concrete porch with a metal railing. East of the entrance are three wood hung windows with divided upper sashes, and two pairs of matching windows glaze the second floor. To the west of the entrance is a set of narrow steel casement windows beneath a brick splayed arch lintel. Windows have brick lintels and similar windows are found on other elevations. A concrete driveway runs along the east of the house to the rear where there is a pyramidal roof garage.
458	4845 Fullerton Street			1941	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 4845 Fullerton Street is two-stories and topped with a side gable asphalt shingle roof, intersected by a front gabled roof at the rear and a front gabled wall dormer centered on the front. A brick chimney is located at the eave on the west façade of the house. The facade is clad in brown face brick laid in a running bond pattern with some sections set proud at the corners creating a quoined appearance, and the front gabled central bay is clad in vinyl siding. The primary entrance is centered on the façade beneath an aluminum metal awning, and is accessed by a brick and concrete porch with a metal railing. On either side of the entrance is a pair of wood hung windows with divided sashes and aluminum storms, and three similar windows glaze the second floor. Windows on the first floor have cast stone lintels and brick sills. Similar windows are found on other elevations. A concrete driveway runs along the east of the house to the rear where there is a pyramidal roof garage.
459	4851 Fullerton Street			1928c.	Tudor Revival	1/garage	C	Unknown	Solomon L. Trigg	The house at 4851 Fullerton Street is two-stories and topped with a hipped asphalt shingle roof, intersected by a front gable that overlaps with a jerkinhead above the entrance vestibule, and hipped roof dormers are centered above the east, south, and west facades. A brick chimney is located at the eave on the west façade of the house. The facade is clad in red and brown face brick laid in a running bond pattern with minimal areas of false half-timbering infilled with stucco at the second floor. The primary entrance is near the center of the façade beneath an aluminum metal awning, and is accessed by a brick and concrete porch with a metal railing. On either side of the entrance is a set of narrow steel casement windows beneath a brick lintel. Wood hung windows are at the second floor. Windows have cast stone lintels and similar windows are found on other elevations. A concrete driveway runs along the east of the house to the rear where there is a pyramidal roof garage.
460	4859 Fullerton Street			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4859 Fullerton Street is two-stories and topped with a front gable asphalt shingle roof, intersected by a side gable. A brick chimney is located at the eave on the east façade of the house. The facade is clad in stucco with false half-timbering beneath the front gable. The primary entrance is near the center of the façade beneath a front gabled overhand supported by wood posts, and is accessed by a brick and concrete stoop. East entrance is a set of three vinyl slider windows beneath an overhang on the second floor with decorative exposed rafters resembling vigas. On the second floor there are two vinyl slider windows framed by brown shutters. Wood hung windows are at the second floor. Similar windows are found on other elevations. A gable roof garage is accessed from the alley west of the house to the rear.
461	3729 Glendale Street			1948	French Eclectic	1/garage	C	Unknown	Unknown	The house at 3729 Glendale Street is two-stories topped with a hipped asphalt shingle roof intersected by a two-story front gable bay on the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer. The primary entrance is trimmed in stone, set within the bay near the east corner of the facade, and is accessed by a brick and concrete porch. West of the entrance a single-story canted bay contains steel windows, and one steel and one vinyl window are on the second floor. Windows have stone or brick sills and the steel windows have storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a hipped roof garage. A brown lightpost with a globe light fixture is in the front lawn.
462	3736 Glendale Street			1939	French Eclectic	1/garage	C	Unknown	Unknown	The house at 3736 Glendale Street is two-stories topped with a hipped asphalt shingle roof intersected by a two-story canted bay with a polygonal roof on the facade. A stone buttress extends from the west corner of the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in brown brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is trimmed in stone, near the east corner of the facade, and is accessed by a brick and concrete porch. The bay contains vinyl windows on the first and second floors and a vinyl window is above the entrance. Windows have stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a front gable roof garage at the rear.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
463	3737 Glendale Street			1948	French Eclectic	1/garage	C	Unknown	Unknown	The house at 3737 Glendale Street is two-stories topped with a hipped asphalt shingle roof intersected by a two-story hipped bay on the facade and a gabled wall dormer. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is trimmed in stone, set within the bay near the east corner of the facade, and is accessed by a brick and concrete porch with a low metal railing and an aluminum awning. West of the entrance a single-story canted bay contains steel windows, and one steel and one vinyl window are on the second floor. Windows have stone or brick sills, the steel windows have storms, and some of the windows have aluminum awnings. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a front gable roof garage. A black lightpost without a light fixture is in the front lawn.
464	3743 Glendale Street			1948c.	French Eclectic	1/garage	C	Unknown	Unknown	The house at 3743 Glendale Street is two-stories topped with a hipped asphalt shingle roof intersected by a two-story front gable bay on the facade and two gabled wall dormers. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer and cast stone. The primary entrance is trimmed in stone, set within the bay near the east corner of the facade, and is accessed by a brick and concrete porch with a low metal railing and a metal awning structure. West of the entrance a single-story canted bay contains steel windows, two glass block windows flank the entrance, and two steel windows are on the second floor. Windows have stone sills and the steel windows have storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a hipped roof garage. A black lightpost with a globe light fixture is in the front lawn.
465	3744 Glendale Street			1939	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3744 Glendale Street is two-stories topped with a hipped asphalt shingle roof intersected by a two-story front gable bay on the facade. A stone buttress extends from the west corner of the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in brown brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, decorative brickwork, and wood false half-timbering. The primary entrance is trimmed in stone, set near the east corner of the facade, and is accessed by a brick and concrete porch with a low metal railing and a roll-up fabric awning. The first floor of the bay is canted and contains steel windows, a small window is east of the entrance, and two vinyl windows are on the second floor. Windows have stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a front gable roof garage. A black lightpost with a lantern-style light fixture is in the front lawn.
466	3750 Glendale Street			1937	French Eclectic	n/a	C	Unknown	Unknown	The house at 3750 Glendale Street is two-stories topped with a hipped asphalt shingle roof intersected by a two-story canted bay with a polygonal roof and a gabled wall dormer. A stone buttress extends from the west corner of the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in brown brick veneer laid in a running bond pattern with accents of cast stone and decorative brickwork. The primary entrance is arched, trimmed in stone, near the east corner of the facade, and is accessed by a brick and concrete porch with a brick kneewall. The bay contains steel windows on the first and second floors and a steel window is above the entrance and a small window is east of the entrance. Windows have stone sills and some have storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house but there is no garage.
467	3751 Glendale Street			1960	Colonial Revival	n/a	C	Unknown	Unknown	The house at 3751 Glendale Street is two-stories and topped with a side gable asphalt shingle roof. A brick chimney is at the eave near the center of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern. The primary entrance is near the east corner of the facade and is accessed by a brick and concrete porch with an aluminum awning supported by metal posts. A series of windows are west of the entrance beneath an aluminum awning but are obscured by foliage. Three vinyl windows framed by rust-colored shutters are on the second floor. Windows have stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house but there is no garage. A black lightpost without a light fixture is in the front lawn.
468	3760 Glendale Street			1937	Tudor Revival	n/a	C	Unknown	Unknown	The house at 3760 Glendale Street is two-stories topped with a hipped asphalt shingle roof intersected by two gables on the facade. A stone buttress extends from the west corner of the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in brown brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, decorative brickwork, and wood false half-timbering. The primary entrance is trimmed in stone, near the east corner of the facade, and is accessed by a brick and concrete porch. A canted bay west of the entrance contains steel windows on the first floor, a small window is east of the entrance, and two steel windows are on the second floor. Windows have stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house but there is no garage.
469	3761 Glendale Street			1945c.	French Eclectic	1/garage	C	Unknown	Unknown	The house at 3761 Glendale Street is two-stories topped with a hipped asphalt shingle roof intersected by a gable and a hipped wall dormer. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of cast stone. The primary entrance is trimmed in stone, near the east corner of the facade, and is accessed by a brick and concrete porch with a low metal railing. West of the entrance a single-story canted bay contains steel windows and two steel windows are on the second floor. Windows have stone sills and some have storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a pyramidal roof garage.
470	3767 Glendale Street			1948	French Eclectic	1/garage	C	Unknown	Unknown	The house at 3767 Glendale Street is two-stories topped with a hipped asphalt shingle roof intersected by a gable wall dormer. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of cast stone. The primary entrance is trimmed in stone, near the east corner of the facade, and is accessed by a brick and concrete porch with a low metal railing. West of the entrance a single-story canted bay contains steel windows and two steel windows are on the second floor. Windows have stone sills and some have storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a front gable roof garage.
471	3768 Glendale Street			1946	French Eclectic	n/a	C	Unknown	Unknown	The house at 3768 Glendale Street is two-stories topped with a side gable asphalt shingle roof intersected by two hipped wall dormers. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is trimmed in stone, near the east corner of the facade, and is accessed by a brick and concrete porch. West of the entrance a single-story canted bay contains steel windows and two steel windows with aluminum awnings are on the second floor. Windows have stone sills and storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house but there is no garage.
472	3773 Glendale Street			1937	French Eclectic	1/garage	C	Unknown	Unknown	The house at 3773 Glendale Street is two-stories topped with a hipped asphalt shingle roof intersected by a two-story hipped bay with a gabled wall dormer. A chimney is near the center of the house. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is trimmed in stone, set near the center of the facade within a polygonal turret, and is accessed by a brick and concrete porch with a low metal railing. The first floor of the bay is canted and contains steel windows, two windows flank the entrance, another steel window is east of the entrance, and two steel windows are on the second floor. Windows have stone sills and storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a hipped roof garage. A black lightpost with a globe light fixture is in the front lawn.
473	3776 Glendale Street			1937	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3776 Glendale Street is two-stories topped with a hipped composite shingle roof intersected by a large gable on the facade. A chimney is at the eave near the front of the west facade. The exterior is clad in brown brick veneer laid in a running bond pattern with accents of stone veneer and decorative brickwork. The primary entrance is trimmed in stone, set near the east corner of the facade within a gable roof portico with brick piers, and accesses a brick porch with a brick kneewall. West of the entrance is a single-story canted bay with steel windows and three vinyl windows are on the second floor. Windows have stone sills and some have storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a hipped roof garage. A black lightpost with a globe light fixture is in the front lawn.
474	3782 Glendale Street			1936	French Eclectic	1/garage	C	Unknown	Unknown	The house at 3782 Glendale Street is two-stories topped with a hipped asphalt shingle roof intersected by a gabled wall dormer on the facade. A stone buttress extends from the west corner of the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in brown brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is trimmed in stone, near the east corner of the facade, and is accessed by a brick and concrete porch. A single-story canted bay contains steel windows, steel window is above the bay on the second floor, and a steel window is above the entrance. Windows have stone sills and some have storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a hipped roof garage. A black lightpost with a globe light fixture is in the front lawn.
475	3785 Glendale Street			1935	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3785 Glendale Street is two-stories topped with a hipped asphalt shingle roof intersected by a gable wall dormer and a two-story gable-on-hip bay on the facade. A stone buttress extends from the west corner of the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, decorative brickwork, and wood false half-timbering. The primary entrance is trimmed in stone, near the east corner of the facade, and is accessed by a brick and concrete porch. The first floor of the bay is canted and contains steel windows, a steel window is east of the entrance, and vinyl and steel windows are on the second floor. Windows have stone sills and the steel windows have storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a front gable roof garage.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
476	3790 Glendale Street			1937	French Eclectic	1/garage	C	Unknown	Unknown	The house at 3790 Glendale Street is two-stories topped with a hipped asphalt shingle roof intersected by a hipped bay and an eyebrow and gabled wall dormer on the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in brown brick veneer laid in a running bond pattern with accents of cast stone, decorative brickwork, and wood false half-timbering. The primary entrance is trimmed in stone, near the east corner of the facade, and is accessed by a brick and concrete porch. A single-story canted bay contains steel windows, two vinyl windows are above the bay on the second floor, and a vinyl window is above the entrance. Windows have stone sills and the steel windows have storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a hipped roof garage. A black lightpost with a globe light fixture is in the front lawn.
477	3791 Glendale Street			1937	French Eclectic	1/garage	C	Unknown	Unknown	The house at 3791 Glendale Street is two-stories topped with a hipped asphalt shingle roof intersected by a hipped and arched wall dormer on the facade. A stone buttress extends from the west corner of the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer and cast stone. The primary entrance is trimmed in stone, near the east corner of the facade, and is accessed by a brick and concrete porch with a brick kneewall and a metal awning structure. A single-story canted bay contains steel windows, a steel window is east of the entrance, and three steel windows are on the second floor. Windows have stone sills and storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a pyramidal roof garage. A black lightpost with a lantern-style light fixture is in the front lawn.
478	3800 Glendale Street			1936	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3800 Glendale Street is two-stories topped with a pyramidal asphalt shingle roof intersected by two gables on the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of cast stone and decorative brickwork. The primary entrance is arched, trimmed in stone, near the east corner of the facade, and is accessed by a brick and concrete porch with a brick kneewall and a metal awning structure. A single-story canted bay contains steel windows, a small window is east of the entrance, and two steel windows are on the second floor. Windows have stone sills and storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a pyramidal roof garage. A black lightpost with a lantern-style light fixture is in the front lawn.
479	3801 Glendale Street			1938	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3801 Glendale Street is two-stories topped with a hipped asphalt shingle roof intersected by a front gable on the facade. A stone buttress extends from the west corner of the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of cast stone. The primary entrance is trimmed in stone, near the center of the facade, and is accessed by a brick and concrete porch with a metal railing. A single-story canted bay contains steel windows, a steel window is east of the entrance, and two steel windows are on the second floor. Windows have stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a pyramidal roof garage. A black lightpost with a lantern-style light fixture is in the front lawn.
480	3806 Glendale Street			1936	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3806 Glendale Street is two-stories topped with a pyramidal asphalt shingle roof intersected by two gables on the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is trimmed in stone, near the east corner of the facade, and is accessed by a brick and concrete porch with a low metal railing. A single-story canted bay contains steel windows, a small window is east of the entrance, and two steel windows are on the second floor. Windows have stone sills and storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a hipped roof garage. A black lightpost with a globe light fixture is in the front lawn.
481	3809 Glendale Street			1935	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3809 Glendale Street is two-stories topped with a hipped asphalt shingle roof intersected by a front gable and a gabled wall dormer on the facade. A stone buttress extends from the west corner of the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is trimmed in stone, near the center of the facade, and is accessed by a brick and concrete porch with a brick kneewall and an aluminum awning. A single-story canted bay contains steel and vinyl windows, a vinyl window is east of the entrance, two vinyl windows with awnings are on the second floor, and a small arched window is in the gable end. Windows have stone sills and the steel windows have storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a pyramidal roof garage. A black lightpost with a lantern-style light fixture is in the front lawn.
482	3816 Glendale Street			1937	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3816 Glendale Street is two-stories topped with a hipped asphalt shingle roof intersected by two gables on the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, decorative brickwork, and bargeboard. The primary entrance is trimmed in stone, near the east corner of the facade, and is accessed by a brick and concrete porch with a brick kneewall and an aluminum awning. A single-story canted bay contains steel windows, a small window is east of the entrance, and two steel windows are on the second floor. Windows have stone sills, storms, and awnings. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a hipped roof garage.
483	3817 Glendale Street			1935	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3817 Glendale Street is two-stories topped with a hipped asphalt shingle roof intersected by two gables on the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in blonde brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, decorative brickwork, and bargeboard. The primary entrance is trimmed in stone, near the east corner of the facade, and is accessed by a brick and concrete porch with a brick kneewall and an aluminum awning. A single-story canted bay contains steel windows, a small window is east of the entrance, and two steel windows are on the second floor. Windows have stone sills, storms, and awnings. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a hipped roof garage. A black lightpost with a lantern-style light fixture is in the front lawn.
484	3820 Glendale Street			1937	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3820 Glendale Street is two-stories topped with a hipped asphalt shingle roof intersected by two-story hipped roof bay and two front gable wall dormers on the facade. A stone buttress extends from the west corner of the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, decorative brickwork, and wood false half-timbering. The primary entrance is arched, trimmed in stone, near the center of the facade, and is accessed by a brick and concrete porch with a brick kneewall and an aluminum awning. The first floor of the bay is canted and contains steel windows, a steel window is east of the entrance, and five steel windows are on the second floor. Windows have stone sills and storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a pyramidal roof garage.
485	3825 Glendale Street			1936	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3825 Glendale Street is two-stories topped with a hipped asphalt shingle roof intersected by a gabled wall dormer and a front gable with a brick and stone parapet on the facade. A brick and stone chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is arched, trimmed in stone, near the east corner of the facade, and is accessed by a stone and concrete porch with a stone kneewall. A single-story canted bay contains steel windows, a window is east of the entrance, and two steel windows are on the second floor. Windows have stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a pyramidal roof garage. A black lightpost with a lantern-style light fixture is in the front lawn.
486	3830 Glendale Street			1938	French Eclectic	1/garage	C	Unknown	Unknown	The house at 3830 Glendale Street is two-stories topped with a hipped asphalt shingle roof intersected by a two-story canted bay with a stone parapet and a hipped wall dormer. A brick and stone chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is arched, trimmed in stone, near the east corner of the facade, and is accessed by a stone, brick, and concrete porch with a stone and brick kneewall. The bay contains steel windows on the first and second floors and a steel window is above the entrance and a small window is east of the entrance. Windows have stone sills and storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a pyramidal roof garage. A white lightpost with an acorn-style light fixture is in the front lawn.
487	3831 Glendale Street			1937	French Eclectic	1/garage	C	Unknown	Unknown	The house at 3831 Glendale Street is two-stories topped with a hipped asphalt shingle roof intersected by a two-story canted bay with a polygonal roof and a gabled wall dormer. A chimney is at the rear of the house. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is trimmed in stone, near the center of the facade, and is accessed by a brick and concrete porch with a brick kneewall. The bay contains steel windows on the first and second floors, a steel window is east of the entrance, and two steel windows are above the entrance. Windows have stone sills and storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a hipped roof garage.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
488	3840 Glendale Street			1937	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3840 Glendale Street is two-stories topped with a front gable asphalt shingle roof intersected by a side gable roof and a polygonal roof tower. A prominent brick chimney is nested between the tower and the front gable. The exterior is clad in brown brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, decorative brickwork, and wood false half-timbering. The primary entrance is trimmed in stone, set in the tower, and is accessed by a brick and concrete stoop with a metal railing. Steel windows are arranged on each facade. Windows have brick or wood sills and some have wood lintels. Similar windows are arranged on other elevations. A concrete driveway runs along the rear of the property to a hipped roof garage.
489	3841 Glendale Street			1949	French Eclectic	1/garage	C	Unknown	Unknown	The house at 3841 Glendale Street is two-stories topped with a hipped asphalt shingle roof intersected by a two-story canted bay with a polygonal roof on the facade. A brick chimney is at the eave near the front of the east facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is trimmed in stone, near the west corner of the facade, and is accessed by a brick and concrete porch with a metal railing and an aluminum awning. The bay contains steel windows on the first and second floors and a steel window is above the entrance. Windows have stone or brick sills and storms. Similar windows are arranged on other elevations. A concrete driveway runs along the rear of the property to a hipped roof garage at the rear.
490	4000 Glendale Street			1941	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4000 Glendale Street is two-stories topped with a hipped asphalt shingle roof intersected by a two front gables on the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer and cast stone. The primary entrance is trimmed in stone, near the east corner of the facade, and is accessed by a brick and concrete porch with a brick kneewall. A single-story canted bay contains steel windows, a small window is east of the entrance, and two vinyl windows and a steel window are on the second floor. Windows have stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the rear of the property to a hipped roof garage at the rear.
491	4003 Glendale Street			1939	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4003 Glendale Street is two-stories topped with a hipped asphalt shingle roof intersected by two gabled wall dormers on the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is trimmed in stone, near the east corner of the facade, and is accessed by a brick and concrete porch with a brick kneewall and an aluminum awning. A single-story canted bay contains vinyl windows, a small window is east of the entrance, and two sets of vinyl windows are on the second floor. Windows have stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the rear of the property to a pyramidal roof garage at the rear.
492	4014 Glendale Street			1941	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 4014 Glendale Street is two-stories topped with a side gable asphalt shingle roof intersected by a front gable on the facade. A brick chimney is at the eave at the center of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer and cast stone. The primary entrance is trimmed in a classically inspired surround near the center of the facade, and is accessed by a brick and concrete porch with a low metal railing. Vinyl windows are arranged on either side of the entrance and two are on the second floor. Windows have brick or stone sills and shutters used to be present. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a front gable roof garage.
493	4015 Glendale Street			1936	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4015 Glendale Street is two-stories and topped with a hipped asphalt shingle roof intersected by two two-story bays topped with hipped-with-gable roofs. A stone buttress extends from the west corner of the facade. A brick chimney is near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is arched and trimmed in stone near the center of the facade, and is accessed by a stone and concrete porch with a stone kneewall. A single-story canted bay contains leaded glass windows, two leaded glass windows are east of the entrance, and three windows are on the second floor. Windows have stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property to a hipped roof garage at the rear. A black lightpost without a light fixture is in the front lawn.
494	4020 Glendale Street			1937	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4020 Glendale Street is two-stories topped with a deck (flat on hip) asphalt shingle roof intersected by a front gable bay on the facade. A chimney is at the rear of the house. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is beneath a Tudor arch, trimmed in stone, near the center of the facade, and is accessed by a brick and concrete porch with a brick kneewall and an aluminum awning. A single-story canted bay contains steel windows, a steel window is east of the entrance, and three steel windows are on the second floor. Windows have stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a hipped roof garage. A brown lightpost with a globe light fixture is in the front lawn.
495	4030 Glendale Street			1938	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4030 Glendale Street is two-stories topped with a hipped asphalt shingle roof intersected by a front gable on the facade. A stone buttress extends from the west corner of the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is trimmed in stone, near the center of the facade, and is accessed by a brick and concrete porch with a low metal railing and an aluminum awning. A single-story canted bay contains steel windows, a steel window is east of the entrance, and two steel windows are on the second floor. Windows have stone sills and aluminum awnings. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a hipped roof garage. A black lightpost with a lantern-style light fixture is in the front lawn.
496	4031 Glendale Street			1937	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4031 Glendale Street is two-stories topped with a hipped asphalt shingle roof intersected by a two-story canted bay on the facade. A brick and stone square arch extends over the driveway from the east corner of the facade. A brick and stone chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is arched, trimmed in stone, near the east corner of the facade, and is accessed by a brick and concrete porch with a brick kneewall. The bay contains steel windows on the first and second floors, small windows flank the entrance, and a steel window is above the entrance. Windows have stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a pyramidal roof garage.
497	4038 Glendale Street			1939	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4038 Glendale Street is two-stories topped with a hipped asphalt shingle roof intersected by a two gabled wall dormers on the facade. A stone buttress extends from the west corner of the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is arched, trimmed in stone, near the east corner of the facade, and is accessed by a stone and concrete porch with a stone kneewall and an aluminum awning. A single-story canted bay contains steel windows, a small window is east of the entrance, and two steel windows are on the second floor. Windows have stone sills and storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a pyramidal roof garage.
498	4045 Glendale Street			1948	Streamline Moderne	1/garage	C	Unknown	Unknown	The house at 4045 Glendale Street is two-stories topped with a hipped asphalt shingle roof intersected by multiple hips, one of which is a two-story semi-curved bay. A brick chimney is at the eave near the center of the west facade. The exterior is clad in blonde brick veneer laid in a running bond pattern with accents of cast stone. The primary entrance is trimmed in stone, near the center of the facade, beneath a shallow canopy, and is accessed by a brick and concrete porch. Ribbons of steel casement and glass block windows are arranged on the facade and wraparound the east and west corners, and additional steel and glass block windows are above the entrance. Windows have stone sills and the steel windows have storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a pyramidal roof garage. A green lightpost with a globe light fixture is in the front lawn.
499	4046 Glendale Street			1960	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 4046 Glendale Street is two-stories and topped with a side gable asphalt shingle roof. A brick chimney is at the eave near the center of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern except for the overhanging second floor facade which is clad in vinyl siding. The primary entrance, framed in white trim, is near the east corner of the facade and is accessed by a brick and concrete porch. An aluminum window is west of the entrance and two aluminum windows are on the second floor. Windows have stone or vinyl sills and are framed with black shutters. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a hipped roof garage.
500	4054 Glendale Street			1938	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4054 Glendale Street is two-stories topped with a hipped asphalt shingle roof intersected by two gables on the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer and cast stone. The primary entrance is trimmed in stone, near the east corner of the facade, and is accessed by a brick and concrete porch with a brick kneewall. A single-story canted bay contains steel windows, a small window is east of the entrance, and two steel windows are on the second floor. Windows have stone sills and storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a pyramidal roof garage.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
501	4055 Glendale Street			1936	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4055 Glendale Street is two-stories topped with a deck (flat on hip) asphalt shingle roof intersected by a front gable on the facade. A brick chimney is at the rear of the house. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, decorative brickwork, and wood false half-timbering. The primary entrance is trimmed in stone, near the center of the facade, and is accessed by a brick and concrete porch with a metal railing. A single-story canted bay contains steel windows, a steel window is east of the entrance, and five steel windows are on the second floor. Windows have stone or wood sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a pyramidal roof garage. A black lightpost with a globe light fixture is in the front lawn.
502	4060 Glendale Street			1940	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4060 Glendale Street is two-stories topped with a hipped asphalt shingle roof intersected by a two-story gabled bay and a gabled wall dormer on the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, decorative brickwork, and wood false half-timbering. The primary entrance is trimmed in stone, near the center of the facade, and is accessed by a brick and concrete porch with a low metal railing. A single-story canted bay contains steel windows, a steel window is east of the entrance, and two steel windows are on the second floor. Windows have stone sills and storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a pyramidal roof garage.
503	4061 Glendale Street			1939	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4061 Glendale Street is two-stories topped with a hipped asphalt shingle roof intersected by a gable roof bay on the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in brown brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is trimmed in stone, near the east corner of the facade, and is accessed by a brick and concrete porch with a low metal railing. A single-story canted bay contains steel windows and two steel windows are on the second floor. Windows have stone sills and storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a pyramidal roof garage.
504	4070 Glendale Street			1937	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4070 Glendale Street is two-stories topped with a hipped asphalt shingle roof intersected by a two-story canted bay with a polygonal roof and a jerkinhead wall dormer on the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is trimmed in stone, near the center of the facade, and is accessed by a stone and concrete porch with a stone kneewall and an aluminum awning. Steel windows are set in the bay on the first and second floors, a steel window is east of the entrance, and a steel and a vinyl window are on the second floor above the entrance. Windows have stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a pyramidal roof garage.
505	4071 Glendale Street			1939	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4071 Glendale Street is two-stories topped with a hipped asphalt shingle roof intersected by a gabled wall dormer and a two-story hipped roof bay with another gabled wall dormer on the facade. A stone buttress extends from the west corner of the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in brown brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is arched, trimmed in stone, near the east corner of the facade, and is accessed by a brick and concrete porch with a metal railing. A single-story canted bay contains steel windows and two steel windows are on the second floor. Windows have stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a pyramidal roof garage.
506	4075 Glendale Street			1939	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4075 Glendale Street is two-stories topped with a hipped asphalt shingle roof intersected by a gabled bay on the facade. A stone buttress extends from the west corner of the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer and cast stone. The primary entrance is trimmed in stone, near the center of the facade, and is accessed by a brick and concrete porch with a low metal railing and an aluminum awning. A single-story canted bay contains steel windows, a steel window is east of the entrance, and two steel windows are on the second floor. Windows have stone sills and storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a pyramidal roof garage. A black lightpost with a globe light fixture is in the front lawn.
507	4080 Glendale Street			1939	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4080 Glendale Street is two-stories topped with a hipped asphalt shingle roof intersected by a gable on the facade. A stone buttress extends from the west corner of the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of cast stone and decorative brickwork. The primary entrance is trimmed in stone, near the east corner of the facade, and is accessed by a brick and concrete porch with a low metal railing and a fabric awning. A single-story canted bay contains steel window and two steel windows are on the second floor. Windows have stone sills and storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a pyramidal roof garage. A black lightpost with a globe light fixture is in the front lawn.
508	4084 Glendale Street			1937	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4084 Glendale Street is two-stories topped with a hipped asphalt shingle roof intersected by a hipped bay with a jerkinhead wall dormer and a gabled wall dormer on the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in brown and orange brick veneer laid in a running bond pattern with accents of cast stone and decorative brickwork. The primary entrance is arched, trimmed in stone, near the east corner of the facade, and is accessed by a brick and concrete porch with a metal railing with a brick kneewall and an aluminum awning. A single-story canted bay contains steel windows, a small window is east of the entrance, and two steel windows are on the second floor. Windows have stone sills, storms, and some have awnings. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a pyramidal roof garage.
509	4087 Glendale Street			1939	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4087 Glendale Street is two-stories topped with a hipped asphalt shingle roof intersected by a two-story bay with a jerkinhead roof on the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is trimmed in stone, near the center of the facade, and is accessed by a brick and concrete porch with a low metal railing. A single-story canted bay contains steel windows, a steel window is east of the entrance, and two steel windows are on the second floor. Windows have stone sills and storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a pyramidal roof garage.
510	4094 Glendale Street			1940	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4094 Glendale Street is two-stories topped with a deck (flat on hip) asphalt shingle roof intersected by a front gable on the facade and hipped roofs above other facades. A brick chimney is at the eave near the front of the east facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of cast stone and decorative brickwork. The primary entrance has a wood surround, is near the west corner of the facade, and is accessed by a brick and concrete porch with an aluminum awning. A single-story canted bay contains wood windows, a wood window is west of the entrance, and two windows with awnings are on the second floor. Windows have stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the rear of the property to a pyramidal roof garage. A black lightpost with a globe light fixture is in the front lawn.
511	4095 Glendale Street			1945	Streamline Moderne	1/garage	C	Unknown	Unknown	The house at 4095 Glendale Street is two-stories topped with a hipped asphalt shingle roof intersected by two curved bays on the facade. A brick chimney is near the eave near the center of the west facade. The exterior is clad in brown brick veneer laid in a running bond pattern with accents of stone veneer and cast stone. The primary entrance is trimmed in stone, at the center of the facade, and is accessed by a brick and concrete porch with a metal railing. Ribbons of steel casement windows are on the first and second floors of both bays, small steel windows flank the entrance, and a steel window is centered above the entrance. Windows have stone sills and storms. Similar windows are arranged on other elevations. A concrete driveway runs along the rear of the property to a hipped roof garage.
512	4200 Glendale Street			1926	Tudor Revival	1/garage	C	Unknown	likely Dwight W. Edwards	The house at 4200 Glendale Street is one-and-a-half-stories and topped with a cross gable asphalt shingle roof forming an L-shape, intersected by two flat roof semi-hexagonal bays on the façade and two shed roof dormers above the north facade. A brick chimney is centered on the on the south façade and another is located near the north of the house. The facade is clad brown face brick laid in a running bond pattern on the first floor with accents of decorative brickwork and klinker brick, and second floor is clad in wood shingles beneath the gables and false half-timbering infilled with stucco. The primary entrance is near the center of the façade at the intersection of the L-shaped footprint, is trimmed with brick in a Tudor arch. The entrance is accessed by a low brick and concrete porch. East entrance is a set of glazed doors opening onto the porch. West of the entrance is three steel casement windows with aluminum storms affixed to the exterior, beneath three multi-light wood hung windows with aluminum storms on the second floor. Similar windows are found on other elevations, and have brick sills at the first floor. Glass block windows are at the basement level. A pyramidal roof garage is accessed from Petoskey Street north of the house to the rear.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
513	4201 Glendale Street			1925	Craftsman	1/garage	C	Unknown	Unknown	The house at 4201 Glendale Street is two-stories and topped with a cross gable asphalt shingle roof, composed of a side gable that meets a front gable at the rear, intersected by a projecting front gabled bay and front gabled portico, and wall dormers across the front and east facades. A brick chimney is located at the peak of the eave on the east façade of the house. The facade is clad in wood shingle siding. The primary entrance is near the west corner of the façade beneath a front gabled portico supported by grouped square wood columns, and is accessed by a brick and concrete porch. East of the entrance is a canted bay that creates a second floor overhang, glazed with multi-light wood hung windows. Similar windows are found on other elevations. A concrete driveway is accessed off of Petoskey Avenue to the south of the house where there is a gable roof garage.
514	4212 Glendale Street			1923	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 4212 Glendale Street is two-stories and topped with a side gable asphalt shingle roof. A brick chimney is located at the eave on west east façade of the house. The facade is clad in vinyl siding. The primary entrance is near the east corner of the façade beneath an aluminum metal awning, and is accessed by a brick and concrete stoop. Sidelights frame the door. West of the entrance is a set of four wood hung windows with divided upper sashes, and two pairs of matching windows glaze the second floor. Similar windows are found on other elevations. A concrete driveway runs along the east of the house to the rear where there is a pyramidal roof garage.
515	4215 Glendale Street			1924	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4215 Glendale Street is two-stories and topped with a side gable asphalt shingle roof intersecting by overlapping front gables. A brick chimney is located at the eave on west façade of the house. The facade is clad in wood shingle siding. The primary entrance is near the east corner of the façade within a slightly projecting entrance vestibule, and is accessed by a brick and concrete stoop. A slider vinyl window is east of the entrance and a fixed arched window above. West of the entrance is a large vinyl slider window and another is on the second floor. Similar windows are found on other elevations. A concrete driveway runs along the east of the house to the rear where there appears to be a garage.
516	4220 Glendale Street			1934	French Eclectic	n/a	C	Unknown	Unknown	The house at 4220 Glendale Street is two-stories topped with a pyramidal asphalt shingle roof intersected by two wall dormers on the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is arched and trimmed in stone, near the center of the facade, and is accessed by a brick and concrete porch with a low metal railing and covered by an aluminum metal awning. East of the entrance a single-story canted bay clad in stone veneer with metal roof and flared eaves contains steel casement windows, a steel casement window is west of the entrance, and steel casement windows are on the second floor. Windows have stone sills and aluminum storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east of the house to the rear where there appears to be no garage.
517	4221 Glendale Street			1923	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 4221 Glendale Street is two-stories and topped with a side gable asphalt shingle roof. A brick chimney is located at the eave on east façade of the house. The facade is clad in vinyl siding. The primary entrance is centered on the façade within a slightly projecting entrance vestibule with a hipped, asphalt shingle awning above an aluminum awning, and is accessed by a brick and concrete porch with a low metal railing. Slider vinyl windows are on either side of the entrance and three vinyl hung windows are on the second floor, all covered by aluminum awnings and framed by shutters painted green. Similar windows are found on other elevations. A concrete driveway runs along the east of the house to the rear where there is a side gable roof garage.
518	4224 Glendale Street			1923	Colonial Revival	n/a	C	Unknown	Unknown	The house at 4224 Glendale Street is two-stories and topped with a pyramidal asphalt shingle roof intersected by hipped roof dormers on the front and rear. A brick chimney is located at the eave on the west façade of the house. The facade is clad in vinyl siding. The primary entrance is near the east corner of the façade beneath an aluminum awning, and is accessed by a brick and concrete porch with a metal railing. Four narrow hung vinyl windows are west of the entrance and two sets of three wood hung windows with vertically divided upper sashes are on the second floor, all framed by shutters painted white. Similar windows are found on other elevations. A concrete driveway runs along the east of the house to the rear. There is no garage.
519	4229 Glendale Street			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4229 Glendale Street is two-stories and topped with a cross gable asphalt shingle roof, intersected by a roof dormer facing the front and a continuous shed dormer facing west. A brick chimney is located at the eave on west façade of the house. The facade is clad in wide metal siding. The primary entrance is near the center of the façade trimmed with a wood surround, and is accessed by a brick and concrete stoop. A canted bay contained three vinyl hung windows is west of the entrance, beneath a single hung vinyl window on the second floor framed by shutters. Similar windows are found on other elevations. A concrete driveway runs along the east of the house to the rear where there is a gable roof garage.
520	4235 Glendale Street			1923	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 4235 Glendale Street is two-stories and topped with a side gable asphalt shingle roof. A brick chimney is located at the eave on east façade of the house. The facade is clad in wide metal siding. The primary entrance is centered on the façade beneath a front gabled portico with curved underside, supported by square wood posts, and is accessed by a brick and concrete stoop. Wood hung windows with vertically divided upper sashes are on either side of the entrance arranged symmetrically with matching windows on the second floor, all framed by shutters painted black. Similar windows are found on other elevations. A concrete driveway runs along the east of the house to the rear where there is a gable roof garage.
521	4236 Glendale Street			1924	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4236 Glendale Street is two-stories and topped with a front gable asphalt shingle roof intersected by a continuous shed dormer facing east. A stone chimney is centered on the front of the house. The facade is clad in wood shingle siding painted green. The primary entrance is an arched door centered on the façade beneath a front gabled portico with curved underside, supported by decorative brackets, and is accessed by a brick stoop. Wood hung windows sashes on the façade are framed by shutters painted white. Similar windows are found on other elevations. A concrete driveway runs along the east of the house to the rear where there is a gable roof garage also clad in wood shingles painted green.
522	4242 Glendale Street			1924	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 4242 Glendale Street is two-stories and topped with a gambrel asphalt shingle roof. A brick chimney is located at the eave on the west facade. The facade is clad with brick veneer in a running bond pattern, with vinyl siding beneath a continuous shed dormer on the second floor, and vinyl siding beneath the gable on the second floor. The primary entrance is near the east corner the facade beneath a gabled overhang with curved underside supported by knee brackets, and is accessed by a brick and concrete porch with metal railing. West of the entrance is are three wood hung windows with divided upper sashes, and two pairs of matching wood hung windows framed by shutters are on the second floor. Similar windows exist on other elevations, and have cast stone sills on the first floor. A driveway runs along the east of the house to the rear where there is a pyramidal roof garage.
523	4245 Glendale Street			1928	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4245 Glendale Street is two-stories and topped with a cross gable asphalt shingle roof, intersected by overlapping front gables. A brick chimney is located at the eave on west façade of the house. The facade is clad in red and brown brick veneer laid in a running bond pattern on the first floor and parts of the second floor, with vertical metal siding beneath the front gables. The primary entrance is near the east corner of the façade trimmed with stone quoins, beneath a second floor overhang with decorative brackets and is accessed by a full width concrete porch with metal railing. Three hung windows are west of the entrance, beneath an asphalt shingled overhang, and two hung windows framed by shutters on the second floor. Similar windows are found on other elevations. A concrete ribbon driveway runs along the east of the house to the rear where there is a gable roof garage.
524	4251 Glendale Street			1924	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4251 Glendale Street is two-stories and topped with a cross gable asphalt shingle roof, intersected by a front gabled roof dormer facing the front and another facing west. A brick chimney is located at the eave on west façade of the house. The facade is clad in wide metal siding. The primary entrance is recessed near the east corner of the façade beneath an overhanging eave supported by decorative brackets, and is accessed by a concrete stoop. Windows are steel casement with aluminum storms framed by shutters painted yellow. Similar windows are found on other elevations. A concrete driveway runs along the east of the house to the rear where there is a gable roof garage.
525	4252 Glendale Street			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4252 Glendale Street is two-stories and topped with a side gable asphalt shingle roof, intersected by a front gable. A brick chimney is located at the eave on west façade of the house. The facade is clad in brown face brick laid in a running bond pattern with some decorative brickwork and stone accents. The primary entrance is near the east corner of the façade beneath a front gabled portico, supported by brick piers that form an arch, and is accessed by a brick and concrete stoop. A set of four multi-light wood hung windows are west of the entrance and two pairs of matching windows are on the second floor, all with cast stone sills painted white. Similar windows are found on other elevations. A concrete driveway runs along the east of the house to the rear where there is a pyramidal roof garage.
526	4260 Glendale Street			1924	Craftsman	1/garage	C	Unknown	Unknown	The house at 4260 Glendale Street is two-stories and topped with a side gable asphalt shingle roof, intersected by a front gable with decorative exposed rafter tails along the eave. A brick chimney is located at the eave on west façade of the house. The facade is clad in wood clapboard siding on the first floor and wood shingles on the second floor. The primary entrance is near the east corner of the façade beneath a front gabled portico with false half-timbering below the front gable, supported by metal posts, and is accessed by a brick and concrete porch. A set of three wood hung windows with divided upper sashes and aluminum storms are west of the entrance offset below matching windows are on the second floor. Similar windows are found on other elevations. A concrete driveway runs along the east of the house to the rear where there is a pyramidal roof garage.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
527	4261 Glendale Street			not listed	Craftsman	1/garage	C	Unknown	Unknown	The house at 4261 Glendale Street is one-and-a-half-stories and topped with a low-pitched cross gable asphalt shingle roof, intersected by a front gabled roof dormer above the façade and a large front gabled partial width porch projecting from the west corner. A brick chimney is located at the eave on east façade of the house. The facade is clad in red brick veneer laid in a running bond pattern on the first floor and vinyl siding beneath the gables. The primary entrance is near the east corner of the façade beneath a front gabled porch supported by brick piers, and is accessed by a brick and concrete porch with brick kneewall. A set of three wood hung windows with divided upper sashes and aluminum storms are west of the entrance. Similar windows are found on other elevations. A concrete driveway runs along the east of the house to the rear where there is a hipped roof garage.
528	4268 Glendale Street			1929	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4268 Glendale Street is two-stories and topped with a cross gable asphalt shingle roof forming an L-shape. A brick chimney is centered on the south façade. The facade is clad red and brown face brick laid in a running bond pattern, that is slightly wavy and with accents of klinker brick, giving the façade a cobbled look. There is some wide metal siding beneath the side gables. The primary entrance is near the center of the façade at the intersection of the L-shaped footprint, is trimmed with brick in a Tudor arch. The entrance is accessed by a low concrete porch. On either side of the entrance is a slider window covered by a fabric awning. Similar windows are found on other elevations, and windows have brick sills. A concrete driveway runs along the east of the house to the rear where there is a pyramidal roof garage. A black lightpost with a globe light fixture is in the front lawn.
529	4269 Glendale Street			1924	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 4269 Glendale Street is two-stories and topped with a side gable asphalt shingle roof that meets a deck, flat on hipped roof at the rear. A brick chimney is located near the center of the house. The facade is clad with a wide metal or vinyl siding. The primary entrance is near the east corner the facade beneath an aluminum awning, and is accessed by a brick and concrete porch with metal railing. West of the entrance is are three vinyl hung windows with divided upper sashes and aluminum storms, the whole set framed by white shutters. Three matching hung windows each framed by shutters are on the second floor. Similar windows exist on other elevations. A driveway runs along the east of the house to the rear where there is a gable roof garage.
530	4274 Glendale Street			1929	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 4274 Glendale Street is two-stories and topped with a side gable asphalt shingle roof, with a hipped roof one-story addition at the rear. Modillions line the eave above the façade. A brick chimney is located at the eave on the west façade of the house. The facade is clad brown face brick laid in a running bond pattern. The primary entrance is near the east corner the facade, and is accessed by a brick and concrete porch with metal railing. The door is framed with an elaborated surround with pilasters and topped with a dentiled pediment, an elliptical fanlight, and sidelights. West of the entrance is are two vinyl hung windows framed by white shutters. Three matching hung windows arranged symmetrically each framed by shutters are on the second floor. Similar windows exist on other elevations, and windows have brick sills. A driveway runs along the east of the house to the rear where there is a side gable roof garage.
531	4277 Glendale Street			1924	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4277 Glendale Street is two-stories and topped with a front gable asphalt shingle roof intersected by a continuous shed dormer facing east and west, creating a dual-pitched roof and overlapping front gables create the appearance of multi-level eaves. A brick chimney is at the eave on the west facade of the house. The facade is clad in wood shingle siding. The primary entrance is near the east corner of the house and is accessed by a brick and concrete stoop. A ribbon of six narrow windows are west of the entrance. On the second floor are two vinyl hung windows. Similar windows are found on other elevations. A concrete driveway runs along the east of the house to the rear where there is a front gable roof garage.
532	4284 Glendale Street			1924	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4284 Glendale Street is two-stories and topped with a steeply pitched cross gable asphalt shingle roof, with a prominent front gable that meets a side gable to the rear, an additional side gable projecting off the main front gable to the west, and a dormer on the east. A brick chimney is at the peak of the eave on the west façade. The facade is clad red and brown face brick laid in a running bond pattern with some decorative brickwork and tile beneath the front gable and elsewhere on the first floor, with wide metal or vinyl siding on the second floor. The primary entrance is recessed near the east corner of the facade and is trimmed with brick in an arch. The entrance is accessed by a brick and concrete wrap-around uncovered porch. West of the entrance are two French doors that open onto the porch, beneath a vinyl slider window above. Similar windows are found on other elevations, and windows have brick sills. A concrete driveway runs along the east of the house to the rear where there is a pyramidal roof garage.
533	4285 Glendale Street			1924	Craftsman	n/a	C	Unknown	Unknown	The house at 4285 Glendale Street is one-and-a-half-stories and topped with a low-pitched hipped gable asphalt shingle roof, intersected by a gabled wall dormer facing east and a large, front gabled porch projecting from the west corner. A brick chimney is located near the center of the house. The facade is clad in wood shingle siding. The primary entrance is near the east corner of the façade beneath the front gabled porch supported by taped wood columns on top of brick piers, and is accessed by a brick and concrete porch with a metal railing. A large fixed window is flanked by two hung windows. Similar windows are found on other elevations. A concrete driveway runs along the east of the house to the rear. There is no garage.
534	4292 Glendale Street			1925	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4292 Glendale Street is two-stories and topped with a front gable asphalt shingle roof intersected by multiple overlapping front gables creating the appearance of a varied roofline. A brick chimney is at the eave on the east facade of the house. The facade is clad in vinyl siding. The primary entrance is near the west corner of the house within a front gabled projecting vestibule and is accessed by a low brick and concrete stoop. The door is arched. A large vinyl slider window is east of the entrance framed by shutters. Elsewhere on the facade are vinyl hung windows, some also have shutters. Similar windows are found on other elevations. A concrete driveway runs along the east of the house to the rear. There is no garage.
535	4293 Glendale Street			1946	French Eclectic	n/a	C	Unknown	Unknown	The house at 4293 Glendale Street is one- story and topped with a cross gable asphalt shingle roof. A brick chimney is located at the eave on the west facade of the house. The facade is clad in brown brick veneer laid in a running bond pattern. The primary entrance is near the center of the façade trimmed in stone, and is accessed by a brick and concrete porch with a metal railing. West of the entrance is a canted bay clad in stone veneer with a metal roof with flared eaves, glazed by steel casement windows. Similar windows are found on other elevations. A concrete driveway runs along the east of the house to the rear. There is no garage.
536	4300 Glendale Street			1924	Tudor Revival	n/a	C	Unknown	C.E. Reichle Company	The house at 4300 Glendale Street is two-stories and topped with a cross gabled jerkinhead asphalt shingle roof. A brick chimney is located at the eave on the west facade of the house. The facade is clad in wood shingles. The primary entrance is near the west corner of the façade within a slightly projecting front gabled entrance vestibule with an arched door, and is accessed by a concrete stoop. East of the entrance is a ribbon of four narrow steel casement windows, beneath three hung wood windows on the second floor which are framed by shutters. Similar windows are found on other elevations. A concrete ribbon driveway runs along the east of the house to the rear. There is no garage.
537	4301 Glendale Street			1925c.	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4301 Glendale Street is two-stories and topped with a cross gable asphalt shingle roof, composed of a side jerkinhead that meets a hipped roof at the rear, with a prominent front gable catslide. A tall brick chimney is located at the eave on the west façade. The facade is clad brown face brick laid in a running bond pattern with some decorative brickwork and stone accents. The primary entrance is recessed near the east corner of the façade beneath the catslide overhang through an arched opening. The entrance is accessed by a metal ramp accessibility structure. West of the entrance is a ribbon of four hung vinyl windows with a played brick lintel and keystone. Two matching windows are on the second floor. Similar windows are found on other elevations, and windows have cast stone sills. A concrete driveway runs along the east of the house to the rear where there is a garage. A black lightpost with a globe light fixture is in the front lawn.
538	4309 Glendale Street			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4309 Glendale Street is two-stories and topped with a front gable asphalt shingle roof intersected by continuous shed dormers facing east and west, overlapping with another front gable and shed dormer to the rear, creating a dual-pitched roof and overlapping gables create the appearance of a multi-level roofline. A tall brick chimney is at the eave on the west facade of the house. The facade is clad in red brick veneer laid in a running bond pattern on the first floor and wide metal siding on the second floor. The primary entrance is recessed near the east corner of the house and is accessed by a low brick and concrete porch. Two pairs of multi-light wood hung windows are west of the entrance, each pair framed by shutters painted white. On the second floor is a pair of two wood hung windows. Similar windows are found on other elevations, and windows on the first floor have cast stone sills. A concrete driveway runs along the east of the house to the rear where there is a front gable roof garage.
539	4310 Glendale Street			1924	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4310 Glendale Street is two-stories and topped with a cross gable asphalt shingle roof, composed of a side jerkinhead that meets a hipped roof. A brick chimney is located at the eave on the west façade. The facade is clad in wide metal siding with stone veneer on the first floor of the primary facade. The primary entrance is near the east corner of the façade beneath a hipped roof porch overhang supported by grouped square wood posts. The entrance is accessed by a brick and concrete porch with wood railing. West of the entrance is a one-story canted bay creating a second floor overhang. The bay is glazed with steel casement windows. Wood hung windows with divided upper sashes are on the second floor. Similar windows are found on other elevations. A concrete driveway runs along the east of the house to the rear where there is a front gable roof garage. A black lightpost with a globe light fixture is in the front lawn.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
540	4316 Glendale Street			1924	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 4316 Glendale Street is two-stories and topped with a side gable asphalt shingle roof with modillions along the eave, that meets a hipped roof two story porch at the rear, and is intersected by a pedimented roof dormer centered above the façade. A brick chimney is located at the eave on the west façade of the house. The facade is clad in red brick veneer laid in a running bond pattern, with wood shingles beneath the side gables at the attic level. The primary entrance is near the east corner the facade beneath a pedimented overhang, also with modillions, supported by brick piers, and is accessed by a brick and concrete porch with stone railing. West of the entrance is a slightly projecting flat bay, clad in wood, with an asphalt shingled roof with modillions, that is glazed with vinyl slider windows. Two pairs of hung windows with aluminum storms are on the second floor. Similar windows exist on other elevations and have cast stone sills painted white. A driveway runs along the east of the house to the rear where there is a sidegable roof garage.
541	4317 Glendale Street			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4317 Glendale Street is two-stories and topped with a side gable asphalt shingle roof intersecting by a front gable that overlaps with a slightly projecting front gabled entrance vestibule. A brick chimney is located at the eave on west façade of the house. The facade is clad in light brown brick veneer laid in a running bond pattern on the first floor, with false half-timbering infilled with stucco beneath the front gable and wood shingle siding elsewhere on the second floor. The primary entrance is near the east corner of the façade with an arched door, and is accessed by a brick and concrete porch. West of the entrance is a large vinyl slider window and another is on the second floor. Similar windows are found on other elevations. A concrete driveway runs along the east of the house to the rear where there is a pyramidal roof garage.
542	4324 Glendale Street			1924	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4324 Glendale Street is two-stories and topped with a front gable asphalt shingle roof intersected by continuous shed dormers facing east and west, overlapping with a projecting front gable, creating a dual-pitched roof and creating a multi-level roofline. A brick chimney is near the center of the house. The facade is clad vinyl siding. The primary entrance is centered on the front gable trimmed with a wood surround, and is accessed by a stone porch. Directly above the entrance is a wood hung window with divided upper sashes framed by shutters. Similar windows are found across the façade and on other elevations, and have aluminum storms affixed to the exterior. A concrete driveway runs along the east of the house to the rear where there is a front gable roof garage.
543	4325 Glendale Street			1924	Craftsman	1/garage	C	Unknown	Unknown	The house at 4325 Glendale Street is one-and-a-half-stories and topped with a low-pitched side gable asphalt shingle roof, intersected by a shed dormer with two small vinyl windows above the front façade and a front gabled porch projecting from the west corner. A brick chimney is located near the eave on the east façade of the house. The facade is clad in brown brick veneer laid in a running bond pattern. The primary entrance is near the west corner of the façade beneath the front gabled porch supported by brick piers, and is accessed by a brick and concrete porch. East of the entrance are four wood hung windows with aluminum storms. Similar windows are found on other elevations. A concrete driveway runs along the east of the house to the rear where there is a front gable roof garage. A black lightpost with a globe light fixture is in the front lawn.
544	4332 Glendale Street			1927	Tudor Revival	1/garage	C	Robert W. Tempest	Unknown	The house at 4332 Glendale Street is one-and-a-half-stories and topped with a cross gable asphalt shingle roof, composed of a front gable that meets two side gables intersected by a front gabled entrance vestibule. A brick chimney is located near the eave on the west façade of the house. The facade is clad in orange and brown textured brick veneer laid in a running bond pattern. The primary entrance faces east from the projecting entrance vestibule beneath an overhang with a decorative bracket. A narrow fixed window with leaded glass detailing in a diamond pattern is centered on the vestibule. East of the entrance is a large vinyl picture window. West of the entrance is a one-story canted bay clad in vinyl siding glazed with vinyl windows. Similar windows are found on other elevations. A concrete driveway runs along the east of the house to the rear where there is a front gable roof garage. A black lightpost with a globe light fixture is in the front lawn.
545	4333 Glendale Street			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4333 Glendale Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by a front gable that overlaps with multiple front gables. A tall brick chimney is located on the front of the house. The facade is clad in brown face brick laid in a running bond pattern with decorative brickwork and stone accents. False half-timbering infilled with stucco is beneath the prominent front gable on the second floor, and the rest of the second floor is clad with wood shingle siding. The primary entrance is near the east corner of the façade in a projecting front gabled vestibule with an arched door and is accessed by a brick and concrete porch. Two vinyl slider windows are west of the entrance, and the second floor has a multi-light wood casement window and a vinyl slider. An arched wood window is at the attic level. Similar windows are found on other elevations, and some have cast stone sills. A concrete driveway runs along the east of the house to the rear where there is a pyramidal roof garage.
546	4340 Glendale Street			1927	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4340 Glendale Street is one-and-a-half-stories and topped with a cross gable asphalt shingle roof, composed of a side gable that meets a hipped roof at the rear, intersected by a front gable. A prominent stone-clad chimney is located off-center on the primary facade of the house. The facade is clad in wide wood or composite shingles. The primary entrance is near the center of the façade, and the arched door is beneath an arched awning, and is accessed by a low brick and concrete porch. East of the entrance is a large hung vinyl window, and west of the entrance is a large vinyl picture window. Similar windows are found on other elevations. A concrete driveway runs along the east of the house to the rear where there is a side gable roof garage.
547	4341 Glendale Street			1924	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4341 Glendale Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof intersecting by a front gable that overlaps with a slightly projecting front gabled entrance vestibule. A brick chimney is located at the eave on west façade of the house. The facade is clad in brown brick veneer laid in a running bond pattern on the first floor, with false half-timbering infilled with stucco beneath the front gables and wood shingle siding elsewhere on the second floor. The primary entrance is near the east corner of the façade, and is accessed by a brick and concrete porch with a metal railing. West of the entrance is are three multi-light wood hung windows window and two matching windows are on the second floor. Small hung windows are elsewhere on the façade. Similar windows are found on other elevations. A concrete driveway runs along the east of the house to the rear. There is no garage. A black lightpost with a globe light fixture is in the front lawn.
548	4348 Glendale Street			1925	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4348 Glendale Street is two-stories and topped with a side gable asphalt shingle roof, intersected by a front gable and a gabled roof dormer at the rear. There is a gabled enclosed two-story porch addition to the rear. The facade is clad in brown brick veneer laid in a running bond pattern on the first floor and beneath the front gable, with the second floor clad in wide wood or composite shingles. The primary entrance is near the center of the façade, and is accessed by a low brick and concrete porch. On either side of the entrance is a large vinyl slider window, and similar windows are found on the second floor and on other elevations. Windows have cast stone sills on the first floor. A concrete driveway runs along the east of the house to the rear. There is no garage.
549	4349 Glendale Street			1922	Craftsman	n/a	C	Unknown	Unknown	The house at 4349 Glendale Street is one-and-a-half-stories and topped with a low-pitched cross gable asphalt shingle roof. A brick chimney is located near the eave on the west façade of the house. The facade is clad in vinyl siding. The primary entrance is near the center of the façade beneath a prominent, full-width front gabled porch clad in wood shingles and with decorative exposed rafter tails. The porch overhang is supported by short tapered wood square posts on top of tapered brick piers, and is accessed by a wood porch with concrete steps. West of the entrance are three wood hung windows with vertically divided upper sashes and aluminum storms. Similar windows are found on other elevations. A concrete driveway runs along the east of the house to the rear. There is no garage.
550	4355 Glendale Street			1925	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4355 Glendale Street is two-stories and topped with a front gable asphalt shingle roof intersected by continuous shed dormers facing east and west, overlapping with a slightly projecting front gable, creating a dual-pitched roof and the appearance of a multi-level roofline. A brick chimney is at the eave on the west façade of the house. The facade is clad in tan brick veneer on the first floor and wood shingles on the second floor. The primary entrance is near the east corner of the façade with an arched door, and is accessed by a brick and concrete porch covered by a fabric awning. West the entrance are four wood hung windows with divided sashes and a cast stone sill. Similar windows are found across the façade and on other elevations. A concrete ribbon driveway runs along the east of the house to the rear. There is no garage.
551	4356 Glendale Street			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4356 Glendale Street is two-stories and topped with a side gable asphalt shingle roof intersected by continuous shed dormers facing the front and rear, creating a dual-pitched roof, and overlapping with a front gable. A brick chimney is at the eave on the west façade of the house. The facade is clad in reddish brown brick veneer laid in a running bond pattern on the first floor, and false half-timbering infilled with stucco and wood shingles on the second floor. The primary entrance is near the east corner of the façade beneath a front gabled, brick-clad overhang with an arched opening and stone accents, and is accessed by a brick and concrete porch. West the entrance is a large vinyl picture window between two vinyl hung windows and a cast stone sill. Similar windows are found across the façade and on other elevations. A concrete driveway runs along the east of the house to the rear where there is a front gable roof garage.
552	4364 Glendale Street			1927	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4364 Glendale Street is one-and-a-half-stories and topped with a cross gable asphalt shingle roof, composed of a side gable that meets a front gable roof at the rear, intersected by two front gables and gabled roof dormers above the east and west facades. A brick chimney is located at the eave on the east façade of the house. The facade is clad in brown brick veneer laid in a running bond pattern. The primary entrance is at the west corner of the façade, within a front gabled projecting vestibule, and the arched door is trimmed with a brick surround. The entrance is accessed by a brick and concrete porch. East of the entrance are three hung vinyl windows, topped with infilled brick arches and an arched window above. Similar windows are found on other elevations and have cast stone sills. A concrete driveway runs along the east of the house to the rear where there is a pyramidal roof garage.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
553	4365 Glendale Street			1947	Streamline Moderne	1/garage	C	Unknown	Unknown	The house at 4365 Glendale Street is one-story topped with a low-pitched hipped asphalt shingle roof intersected by curved bay topped with a conical roof. A brick chimney is at the eave of the west facade. The exterior is clad in blonde brick veneer laid in a running bond pattern. The primary entrance is centered on the facade, and is accessed by a brick and concrete porch with a metal railing. Steel casement windows are arranged on the facade and wraparound the curved bay as well as the east corner. Windows have stone sills. Similar windows are arranged on other elevations. A concrete ribbon driveway runs along the east side of the house to a hipped roof garage.
554	4370 Glendale Street			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4370 Glendale Street is two-stories and topped with a side gable asphalt shingle roof intersected by a front gabled catslide. A brick chimney is at the eave on the east facade of the house. The facade is clad in vinyl siding. The primary entrance is near the west corner of the façade within a slightly projecting front gabled entrance vestibule, and is accessed by a brick and concrete porch with a metal railing. East of the entrance is a small leaded glass window. The rest of the windows on the façade are vinyl hung windows with divided upper sashes. Similar windows are arranged on other elevations. A gable roof garage is at the rear and is accessed via the alley that runs along the west of the property.
555	4373 Glendale Street			1931	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4373 Glendale Street is two-stories and topped with a side gable asphalt shingle roof intersected by a front gabled catslide and a hipped roof wing at the rear. A brick chimney is centered on the front facade of the house. The facade is clad in red and brown brick veneer laid in a running bond pattern with accents of stone. The primary entrance is near the west corner of the façade within a slightly projecting front gabled entrance vestibule with a catslide roof that extends beyond the west corner of the house over an arched opening. The entrance door is arched, trimmed in brick and stone, is accessed by a full width brick and concrete porch with a metal railing. East of the entrance is a set of steel casement windows with transom and a stone lintel. Steel casement windows on the second floor are set within wall dormers. Similar windows are arranged on other elevations and have cast stone sills. A pyramidal roof garage is at the rear and is accessed via the alley that runs along the west of the property.
556	4734 Glendale Street			1923	Craftsman	1/garage	C	Unknown	Unknown	The house at 4734 Glendale Street is one-and-a-half stories topped with a side gable asphalt shingle roof, with overhanging eaves and knee brackets, intersected by a gabled dormer on the facade. A brick chimney is at the eave near the front of the east facade. The exterior is clad in wood siding. The primary entrance is near the west corner of the facade and is accessed by a full-width, partially enclosed porch with a low wood railing and a shed roof supported by square wood posts atop brick piers. Three hung windows with an aluminum awning are in the dormer. Similar windows are arranged on other elevations. An alley runs along the east side of the house but there is no garage.
557	4735 Glendale Street			1926	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4735 Glendale Street is one-and-a-half stories topped with a side gable asphalt shingle roof with an overhanging eave with brackets on the facade. A prominent stone chimney is near the center of the facade. The exterior is clad in either asbestos or wood shingles. The primary entrance is near the center of the facade, recessed within a catslide vestibule, and is accessed by a brick and concrete stoop. Three hung windows are east of the entrance, and two are west of the entrance. Similar windows are arranged on other elevations. A driveway runs along the east side of the house to a side gable roof garage at the rear.
558	4744 Glendale Street			1924	Craftsman	n/a	C	Unknown	Unknown	The house at 4744 Glendale Street is one-and-a-half stories topped with a side jerkinhead asphalt shingle roof with overhanging eaves and brackets. A large brick chimney is at the eave near the front of the east facade. The exterior is clad in wood shingles. The primary entrance is near the east corner of the facade, is framed by sidelights, and is accessed by a partially covered brick and concrete terrace, with part of the terrace sheltered by a shed roof supported by wood columns. Five hung windows with storms and shutters are east of the entrance. Similar windows are arranged on other elevations. A driveway runs along the east side of the house but there is no garage.
559	4745 Glendale Street			1926	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4745 Glendale Street is two-stories and topped with a front gable asphalt shingle roof intersected by a shed roof dormer, hipped roofs, and a side gable roof with a flared roof ridge. A large brick chimney is near the center of the facade. The first floor of the exterior is clad in brown brick veneer laid in a running bond pattern with the second floor clad in vinyl siding. The primary entrance is near the center of the facade and is accessed by a brick and concrete porch with a metal railing and an aluminum awning. Two wood windows are east of the entrance, three are west of the entrance, and two are on the second floor. Similar windows are arranged on other elevations. A driveway runs along the east side of the house to a pyramidal roof garage. A black lightpost with a globe light fixture is in the front lawn.
560	4750 Glendale Street			1926	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4750 Glendale Street is one-and-a-half stories and topped with a side jerkinhead asphalt shingle roof intersected by two gables on the facade. A brick chimney is at the eave near the center of the east facade. The first floor of the exterior is clad in brown brick veneer laid in a running bond pattern with the second floor clad in wood siding. The primary entrance is arched, trimmed in brick, near the west corner of the facade, and is accessed by a brick and concrete porch beneath a portico with a catslide roof. A single-story canted bay is east of the entrance and contains wood windows and a wood window is in the gable dormer. Windows have storms and similar windows are arranged on other elevations. A driveway runs along the east side of the house to a pyramidal roof garage. A black lightpost with a globe light fixture is in the front lawn.
561	4753 Glendale Street			1925c.	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4753 Glendale Street is two-stories and topped with a side gable asphalt shingle roof intersected by a gabled dormer and a gabled bay on the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in orange brick veneer laid in a running bond pattern. The primary entrance is arched, trimmed in brick and stone, set within a gabled vestibule near the center of the facade, and is accessed by a brick and concrete porch with a low metal railing and a metal awning structure. A series of three wood windows are on either side of the entrance and the second floor. A smaller window flanks the entrance and two are in the dormer. Windows have storms and similar windows are arranged on other elevations. A driveway runs along the east side of the house to a pyramidal roof garage. A black lightpost without a light fixture is in the front lawn.
562	4759 Glendale Street			1936	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4759 Glendale Street is one-and-a-half stories and topped with a side gable asphalt shingle roof intersected by two gables on the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer. The primary entrance is trimmed in stone, set within a gabled vestibule near the east corner of the facade, and is accessed by a concrete porch with a low metal railing and an aluminum awning. A small window is east of the entrance, a series of steel windows are west of the entrance, and a small window with an awning is in the gable end. Similar windows are arranged on other elevations. A driveway runs along the east side of the house to a front gable roof garage.
563	4760 Glendale Street			1941	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4760 Glendale Street is one-and-a-half stories and topped with a side gable asphalt shingle roof intersected by a large front gable on the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond with accents of decorative brickwork. The primary entrance is set within a gabled portico near the east corner of the facade, and is accessed by a brick and concrete porch. Three vinyl windows with black shutters are east of the entrance and two vinyl windows are in the gable end. Similar windows are arranged on other elevations. A driveway runs along the east side of the house to a front gable roof garage. A black lightpost with a globe light fixture is in the front lawn.
564	4765 Glendale Street			1926	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4765 Glendale Street is one-and-a-half stories and topped with a side gable asphalt shingle roof intersected by a large front gable on the facade. A prominent brick chimney is near the center of the facade. The exterior is clad in blonde brick veneer laid in a running bond with accents of stone. The primary entrance arched, set within a vestibule with a catslide roof at the center of the facade, and is accessed by a brick and concrete porch with a metal railing and an aluminum awning. Three vinyl windows are on the first floor facade and one is in the gable end. Similar windows are arranged on other elevations. A driveway runs along the east side of the house to a pyramidal roof garage. A black lightpost without a light fixture is in the front lawn.
565	4766 Glendale Street			1925	Craftsman	1/garage	C	Unknown	Unknown	The house at 4766 Glendale Street is one-and-a-half stories and topped with a gable-on-hip asphalt shingle roof intersected by a gable dormers. A large brick chimney is at the eave near the front of the west facade. The exterior is clad in sandy brick veneer laid in a running bond except for the second floor which is clad in vinyl siding. The primary entrance is set within a hipped roof portico supported by square posts near the east corner of the facade, and is accessed by a brick and concrete porch with a railing and an aluminum awning. A vinyl window is west of the entrance and two are on the second floor. Similar windows are arranged on other elevations. A concrete ribbon driveway runs along the east side of the house to a front gable roof garage.
566	4772 Glendale Street			1926	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4772 Glendale Street is one-and-a-half stories and topped with a side jerkinhead asphalt shingle roof. A prominent brick chimney is near the center of the facade. The exterior is clad in brown brick veneer laid in a running bond with minor accents of stone. The primary entrance arched, has an aluminum awning, is set within a vestibule with a catslide roof at the center of the facade, and is accessed by a brick and concrete porch with a low metal railing. Four wood windows are east of the entrance and two wood windows with an aluminum awning are west of the entrance. Windows have storms and similar windows are arranged on other elevations. A driveway runs along the east side of the house to a pyramidal roof garage.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
567	4779 Glendale Street			1925c.	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4779 Glendale Street is two-stories and topped with a side gable asphalt shingle roof intersected by a large front gable on the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red and orange brick laid in a running bond except for the second floor which is clad in vinyl siding. The primary entrance is set in a gabled vestibule near the east corner of the facade and is accessed by a brick and concrete porch with a low metal railing and an aluminum awning. A vinyl window is west of the entrance, four vinyl windows are on the second floor, and a blind arch is in the gable end. Similar windows are arranged on other elevations. A driveway runs along the east side of the house to a front gable roof garage.
568	4787 Glendale Street			1933	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4787 Glendale Street is one-and-a-half stories and topped with a side jerkinhead asphalt shingle roof intersected by a jerkinhead dormer and a polygonal roof on the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in yellow and brown brick veneer laid in a running bond with accents of stone veneer. The primary entrance arched, trimmed in stone, has an aluminum awning, is set within a polygonal vestibule at the east corner of the facade, and is accessed by a brick and concrete porch with a low metal railing and an aluminum awning. Vinyl windows are on either side of the entrance and in the dormer. Similar windows are arranged on other elevations. A driveway runs along the east side of the house to a pyramidal roof garage.
569	4793 Glendale Street			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4793 Glendale Street is two-stories and topped with a side gable asphalt shingle roof intersected by a front gable on the facade. A brick chimney is at the eave near the center of the west facade. The exterior is clad in red brick veneer laid in a running bond. The primary entrance is near the center of the facade but is obscured by foliage. It is accessed by a brick and concrete porch with a concrete balustrade and a flat roof canopy supported by stone columns. Two vinyl windows with aluminum awnings are on either side of the entrance and three of the same windows are on the second floor. Similar windows are arranged on other elevations. An alley runs west of the house to a concrete driveway leading to a front gable roof garage.
570	3728 Leslie Street			1962	Colonial Revival	n/a	C	Unknown	Unknown	The house at 3728 Leslie Street is two-stories and topped with a side gable asphalt shingle roof. A brick chimney is located at the eave near the center of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern except for the overhanging second floor facade which is clad in white vinyl siding. The primary entrance is near the east corner of the facade and is accessed by a brick and concrete stoop. A vinyl slider window is west of the entrance and three vinyl windows with brown shutters are on the second floor. Similar windows are arranged on other elevations. There is no driveway and no garage.
571	3734 Leslie Street			1951	Colonial Revival	n/a	C	Unknown	Unknown	The house at 3734 Leslie Street is two-stories and topped with a side gable asphalt shingle roof. A brick chimney is located at the eave near the center of the west facade. The exterior is clad in blonde brick veneer laid in a running bond pattern except for the overhanging second floor facade which is clad in white vinyl siding. The primary entrance is near the east corner of the facade, trimmed in stone, and is accessed by a concrete porch with a metal railing. A single-story canted bay with vinyl window is west of the entrance and two vinyl windows with black shutters are on the second floor. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house but there is no garage.
572	3735 Leslie Street			1960	Ranch	n/a	C	Unknown	Unknown	The house at 3735 Leslie Street is a split-level form with one story at the front and two stories at the rear both of which are topped with a hipped asphalt shingle roof. A brick chimney is located at the eave near the center of the east facade. The exterior is clad in blonde brick veneer laid in a running bond pattern. The primary entrance is near the center and is accessed by a concrete pad. A vinyl window is east of the entrance and an aluminum window is west of the entrance. Windows have stone sills and one window on the east facade has been bricked over. Similar windows are arranged on other elevations. A concrete driveway runs along the west side of the house but there is no garage.
573	3742 Leslie Street			1938	French Eclectic	1/garage	C	Unknown	Unknown	The house at 3742 Leslie Street is two-stories topped with a hipped asphalt shingle roof intersected by a two-story canted bay with a polygonal roof on the facade. A stone buttress extends from the west corner of the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is trimmed in stone, near the center of the facade, and is accessed by a brick and concrete porch with a brick kneewall and a metal awning structure. The bay contains steel casement windows and two steel windows are east of and above the entrance. Windows have stone sills and storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a hipped roof garage.
574	3745 Leslie Street			1959	Prairie	1/garage	C	Unknown	Unknown	The house at 3745 Leslie Street is two-stories and topped with a hipped, asphalt shingle roof. A brick chimney is located at the eave near the front of the east facade. The exterior is clad in sandy brick veneer laid in a running bond pattern with a denticulated brick course on the facade. The primary entrance is near the west corner of the facade and is accessed by a brick and concrete porch. A vinyl window is east of the entrance and two vinyl windows are on the second floor and are accented with brick. Windows have stone sills. Similar windows are arranged on other elevations. The driveway is concrete and runs along the west side of the house to a hipped roof garage at the rear. A black lightpost with a globe light fixture is in the front lawn.
575	3750 Leslie Street			1948	Colonial Revival	n/a	C	Unknown	Unknown	The house at 3750 Leslie Street is two-stories and topped with a side gable asphalt shingle roof. A brick chimney is located at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer and cast stone. The primary entrance is trimmed in stone, near the east corner of the facade, and is accessed by a brick and concrete porch with a metal railing. A single-story canted bay with steel and wood windows is west of the entrance and two steel windows with white shutters are on the second floor. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house but there is no garage. A black lightpost with a globe light fixture is in the front lawn.
576	3751 Leslie Street			1954	Streamline Moderne	n/a	C	Unknown	Unknown	The house at 3751 Leslie Street is two-stories and topped with a pyramidal asphalt shingle roof. A brick chimney is located at the eave near the front of the east facade. The exterior is clad in orange brick veneer laid in a running bond pattern with some courses set proud to create horizontal bands in the brick. The primary entrance is near the west corner of the facade and is accessed by a brick and concrete porch with a brick kneewall on one side. A steel window is east of the entrance and two vinyl windows are on the second floor. Windows have stone sills. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house but there is not garage.
577	3759 Leslie Street			1954	Streamline Moderne	1/garage	C	Unknown	Unknown	The house at 3759 Leslie Street is two-stories and topped with a pyramidal asphalt shingle roof. A brick chimney is located at the eave near the front of the east facade. The exterior is clad in red brick veneer laid in a running bond pattern with some courses set proud to create horizontal bands in the brick. The primary entrance is near the west corner of the facade and is accessed by a brick and concrete porch with a brick kneewall on one side, a metal railing, and an aluminum awning. A steel window is east of the entrance and two vinyl windows are on the second floor. Windows have stone sills and have aluminum awnings. Similar windows are arranged on other elevations. An infilled concrete ribbon driveway runs along the west side of the house to a hipped roof garage. A white lightpost with a globe light fixture is in the front lawn.
578	3760 Leslie Street			1951	French Eclectic	n/a	C	Unknown	Unknown	The house at 3760 Leslie Street is two-stories and topped with a pyramidal asphalt shingle roof. A brick chimney is located at the eave near the front of the west facade. The exterior is clad in brown brick veneer laid in a running bond pattern with accents of cast stone and horizontal bands of brick. The primary entrance trimmed in stone, near the east corner of the facade, and is accessed by a brick and concrete porch with a metal railing. A single-story canted bay with vinyl windows is west of the entrance and three vinyl windows are on the second floor. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house but there is no garage. A black lightpost with a globe light fixture is in the front lawn.
579	3767 Leslie Street			1940	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 3767 Leslie Street is two-stories and topped with a side gable asphalt shingle roof. A brick chimney is located at the eave near the center of the east facade. The exterior is clad in red brick veneer laid in a running bond pattern with brick quoins at the facade corners. The primary entrance trimmed in wood, near the center of the facade, and is accessed by a brick and concrete porch with a metal railing and an aluminum awning supported by metal posts. A single-story canted bay with wood windows is east of the entrance, a wood window is west of the entrance, and three wood windows are on the second floor. Windows have brick sills, some are framed by green shutters, and some have storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a hipped roof garage. A black lightpost with a globe light fixture is in the front lawn.
580	3768 Leslie Street			1951	French Eclectic	n/a	C	Unknown	Unknown	The house at 3768 Leslie Street is two-stories and topped with a pyramidal asphalt shingle roof. A brick chimney is located at the eave near the front of the west facade. The exterior is clad in brown brick veneer laid in a running bond pattern with accents of feathered brick and horizontal bands of brick. The primary entrance is near the east corner of the facade and is accessed by a brick and concrete porch. A single-story canted bay with vinyl and wood windows is west of the entrance and three vinyl windows are on the second floor. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house but there is no garage. A black lightpost with a globe light fixture is in the front lawn.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
581	3775 Leslie Street			1948	Colonial Revival	n/a	C	Unknown	Unknown	The house at 3775 Leslie Street is two-stories and topped with a side gable asphalt shingle roof. A brick chimney is located at the eave near the front of the east facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer and cast stone. The primary entrance is trimmed in stone, near the west corner of the facade, and is accessed by a brick and concrete porch. A single-story canted bay with wood windows is east of the entrance and two wood windows with white shutters are on the second floor. Similar windows are arranged on other elevations. A concrete driveway runs along the west side of the house but there is no garage. A black lightpost with a globe light fixture is in the front lawn.
582	3776 Leslie Street			1955	Colonial Revival	n/a	C	Unknown	Unknown	The house at 3776 Leslie Street is two-stories and topped with a side gable asphalt shingle roof. A brick chimney is near the center of the house. The exterior is clad in red brick veneer laid in a running bond pattern. The primary entrance is trimmed in stone, near the east corner of the facade, and is accessed by a brick and concrete porch with a metal railing and an aluminum awning supported by metal posts. An aluminum window is west of the entrance and three aluminum windows are on the second floor. Windows have stone sills and aluminum awnings. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house but there is no garage. A black lightpost with a lantern-style fixture is in the front lawn.
583	3782 Leslie Street			1959	Prairie	n/a	C	Unknown	Unknown	The house at 3782 Leslie Street is two-stories and topped with a hipped, asphalt shingle roof. A brick chimney is located at the eave near the front of the east facade. The exterior is clad in sandy brick veneer laid in a running bond pattern with a dogtooth brick course on the facade. The primary entrance is near the east corner of the facade and is accessed by a brick and concrete porch. An aluminum window is west of the entrance and two aluminum windows are on the second floor. Windows have stone sills. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house but there is no garage.
584	3785 Leslie Street			1946	French Eclectic	1/garage	C	Unknown	Unknown	The house at 3785 Leslie Street is two-stories topped with a hipped asphalt shingle roof intersected by a two-story bay with a two-story canted bay on the facade. A brick chimney is at the eave near the front of the east facade. The exterior is clad in red and orange brick veneer laid in a running bond pattern with accents of stone veneer and cast stone. The primary entrance is arched, trimmed in stone, near the center of the facade, and is accessed by a brick, stone, and concrete porch with a brick and stone kneewall. Both floors of the canted bay contain what appear to be steel windows and two steel windows are west of the entrance. Windows have stone sills and the window type and material is obscured by storms. Similar windows are arranged on other elevations. A concrete driveway runs along the west side of the house to a hipped roof garage. A black lightpost without a light fixture is in the front lawn.
585	3790 Leslie Street			1952	Prairie	n/a	C	Unknown	Unknown	The house at 3790 Leslie Street is a split-level form with two, two-story sections at different heights, both of which are topped with side gable asphalt shingle roofs. The rear two-story section is topped with a shed roof addition. A chimney is near the rear of the house. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer. The primary entrance is near the east corner of the facade, accessed by a brick and concrete porch with a metal railing, and covered by a flat roof supported by a post. Two pairs of vinyl windows are west of the entrance on the first and second floors. Four windows are in the shed roof addition. Windows have stone sills. A concrete driveway runs along the west side of the house but there is no garage. A black lightpost with a globe light fixture is in the front lawn.
586	3791 Leslie Street			1960	Modern Movement	1/garage	C	Unknown	Unknown	The house at 3791 Leslie Street is two-stories and topped with a side gable asphalt shingle roof. A chimney is at the rear of the house. The exterior is clad in gray brick veneer laid in a stacked bond pattern with large accents of stone veneer and composite paneling. The primary entrance is at the center of the facade and accessed by a brick and concrete porch. Two large aluminum windows are stacked on the first and second floor east of the entrance and are framed with composite paneling. Similar windows are on other elevations. A concrete driveway runs along the west side of the house to a hipped roof garage. A black lightpost with a globe light fixture is in the front lawn.
587	3800 Leslie Street			1948	French Eclectic	1/garage	C	Unknown	Unknown	The house at 3800 Leslie Street is two-stories topped with a hipped asphalt shingle roof intersected by a two-story bay with a two-story canted bay on the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer and cast stone. The primary entrance is trimmed in stone, near the center of the facade, and is accessed by a stone and concrete porch with a stone kneewall which has been painted red. Each floor of the bay contains steel casement windows and two steel windows are east of the entrance. Windows have stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a hipped roof garage. A black lightpost with a lantern-style light fixture is in the front lawn.
588	3801 Leslie Street			not listed	Prairie	1/garage	C	Unknown	Unknown	The house at 3801 Leslie Street is two-stories and topped with a pyramidal, asphalt shingle roof. A brick chimney is located at the eave near the front of the east facade. The exterior is clad in orange brick veneer laid in a running bond pattern with a large accent of rough-faced brick laid in a stacked bond. Rectangular voids in a linear pattern on the facade between the first and second floor suggest an awning used to stretch across the facade. The primary entrance is near the west corner of the facade and is accessed by a concrete porch with a brick planter. A vinyl window is east of the entrance and two vinyl windows are on the second floor. Windows have stone sills. Similar windows are arranged on other elevations. The driveway is concrete and runs along the west side of the house to a hipped garage.
589	3806 Leslie Street			1948	French Eclectic	n/a	C	Unknown	Unknown	The house at 3806 Leslie Street is two-stories topped with a hipped asphalt shingle roof intersected by a two-story bay with a two-story canted bay, and a gabled wall dormer, on the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in brown brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is trimmed in stone, near the center of the facade, and is accessed by a brick and concrete porch with a brick kneewall. Each floor of the bay contains vinyl windows and two vinyl windows are east of the entrance. Windows have stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house but there is no garage.
590	3807 Leslie Street			1945c.	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 3807 Leslie Street is two-stories and topped with a side gable asphalt shingle roof intersected by a front gable bay on the west half of the facade. A brick chimney is at the eave near the center of the west facade. The exterior is clad in brick veneer painted white laid in a running bond pattern except for portions of the second floor which are clad in aluminum siding. The primary entrance is near the center of the facade and is accessed by a porch covered by a shed roof supported by posts. Three vinyl windows are on either side of the entrance and two vinyl windows are on the second floor. Windows have brick or wood sills and some are framed with blue shutters. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a front gable roof garage at the rear. A black lightpost with a lantern-style light fixture is in the front lawn.
591	3814 Leslie Street			not listed	French Eclectic	1/garage	C	Unknown	Unknown	The house at 3814 Leslie Street is two-stories and topped with a hipped asphalt shingle roof intersected by two two-story bays topped with gable and gable-on-hip roofs. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is arched and trimmed in stone near the center of the facade within a gable roof bay, and is accessed by a brick, stone, and concrete porch with a brick kneewall and an aluminum awning. A single-story canted bay west of the entrance contains steel windows with an aluminum awning and two of the same windows are east of the entrance. Three steel windows are on the second floor and an arched window is in a gable dormer. Windows have stone or wood sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property to a hipped roof garage at the rear. A large, perforated brick wall with a cast stone emblem is west of the house and partially encloses the backyard.
592	3817 Leslie Street			1954	Prairie	n/a	C	Unknown	Unknown	The house at 3817 Leslie Street is two-stories and topped with a hipped asphalt shingle roof. A brick chimney is located at the eave near the front of the east facade. The exterior is clad in red brick veneer laid in a running bond pattern. The primary entrance is trimmed in stone near the west corner of the facade and is accessed by a brick and concrete porch. A wood window is east of the entrance beneath a flat canopy and two wood windows framed by black shutters are on the second floor. Windows have stone sills. Similar windows are arranged on other elevations. The driveway is concrete and runs along the west side of the house but there is no garage.
593	3830 Leslie Street			1939	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3830 Leslie Street is two-stories topped with a hipped asphalt shingle roof intersected by a two-story bay with a front gable roof and a gabled wall dormer on the facade. A stone buttress extends from the west corner of the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer and cast stone. The primary entrance is trimmed in stone, near the center of the facade, and is accessed by a brick and concrete porch with a brick kneewall. A single-story canted bay with steel windows is west of the entrance, a steel window is east of the entrance, two vinyl windows are on the second floor, and an arched window is in the gable end. Windows have stone sills and the steel windows have storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a partially demolished pyramidal roof garage.
594	3831 Leslie Street			not listed	Ranch	n/a	C	Unknown	Unknown	The house at 3831 Leslie Street is a split-level form with a central two-story section with a front gable roof flanked by one-story sections with side gable roofs. A chimney brick chimney is near the west eave of the central section. The exterior is clad in orange Roman brick veneer laid in a running bond pattern except for the second floor of the central section which is clad in vinyl siding. The primary entrance is near the east corner of the facade and accessed by a brick and concrete porch. A picture window is east of the entrance and west of the entrance are three windows—two on the upper floor of the central section and one on the lower floor. Windows have stone and vinyl sills. A concrete driveway runs along the west side of the property to an attached garage is at the west end of the house.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
595	3838 Leslie Street			1948	French Eclectic	1/garage	C	Unknown	Unknown	The house at 3838 Leslie Street is two-stories and topped with a hipped asphalt shingle roof intersected by a two-story bay topped with a polygonal roof. A brick chimney is at the eave near the front of the east facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is trimmed in stone near the west corner of the facade and is accessed by a brick and concrete porch with a low metal railing and an aluminum awning. The bay contains vinyl windows on each floor, a glass block window is west of the entrance, and a vinyl window is above the entrance on the second floor. Windows have stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the rear of the property to a hipped roof garage.
596	3839 Leslie Street			1951	Prairie	1/garage	C	Unknown	Unknown	The house at 3839 Leslie Street is two-stories and topped with a hipped asphalt shingle roof intersected by a two-story bay. A brick chimney is at the eave near the front of the east facade. The exterior is clad in blonde brick veneer laid in a running bond pattern with mortar joints that create Dutch bond appearance and a stone stringcourse is on the facade. The primary entrance is near the center of the facade, is accessed by a concrete porch, and is covered by a flat canopy that stretches over the east half of the facade. Wood picture windows are on either side of the entrance and three vinyl windows are on the second floor. Windows have stone sills. Similar windows are arranged on other elevations. There is no driveway or garage.
597	4000 Leslie Street			1939	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4000 Leslie Street is two-stories topped with a hipped asphalt shingle roof intersected by a front gable and hipped roof on the facade. A brick chimney is at the eave near the center of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer and decorative brickwork. The primary entrance is arched, trimmed in stone, near the center of the facade, and is accessed by a brick and concrete porch with a brick kneewall, a low metal railing, and a metal awning structure. Two sets of steel windows are on either side of the entrance on the first and second floors and an arched leaded glass window is centered above the entrance. Windows have stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the rear side of the property to a hipped roof garage.
598	4001 Leslie Street			1954	Prairie	1/garage	C	Unknown	Unknown	The house at 4001 Leslie Street is two-stories and topped with a hipped asphalt shingle roof intersected by a two-story hipped roof bay at the center of the facade. A brick chimney is at the eave near the center of the west facade. The exterior is clad in grey brick veneer laid in a running bond pattern with a horizontal brick band and inset brickwork. The primary entrance is trimmed in stone, at the center of the facade, and accessed by a stone and concrete porch. Two series of steel windows are on the first and second floors west of the entrance, a steel window is above the entrance on the second floor, a small window is east of the entrance, and a large rectangular fixed window is east of the entrance. Windows have stone sills and some steel windows have storms. Similar windows are arranged on other elevations. A concrete driveway runs along the rear side of the property to a hipped roof garage.
599	4012 Leslie Street			1935c.	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4012 Leslie Street is two-stories topped with a hipped asphalt shingle roof intersected by a two-story bay with a hipped roof on the facade. A stone and brick vutress extends from the west corner of the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, decorative brickwork, and wood false half-timbering. The primary entrance is trimmed in brick, near the center of the facade, and is accessed by a brick and concrete porch with a low metal railing and a metal awning structure. West of the entrance a single-story canted bay contains steel windows, a steel window is east of the entrance, and two vinyl windows are on the second floor. Windows have stone sills and the steel windows have storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a pyramidal roof garage. A black lightpost without a light fixture is in the front lawn.
600	4015 Leslie Street			1950	Streamline Moderne	1/garage	C	Unknown	Unknown	The house at 4015 Leslie Street is two-stories and topped with a pyramidal asphalt shingle roof. A chimney is not visible from the right-of-way. The exterior is clad in blonde brick veneer laid in a running bond pattern. The primary entrance is at the center of the facade and set within a brick square arch. Foliage obscures much of the facade but it appears that two series of steel windows are on the first and second floors on either side of the entrance. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a hipped roof garage.
601	4022 Leslie Street			1941	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4022 Leslie Street is two-stories topped with a hipped asphalt shingle roof intersected by a two-story gable roof bay on the facade. A brick buttress extends from the west corner of the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is trimmed in stone, near the center of the facade, and is accessed by a brick and concrete porch with a low metal railing. West of the entrance a single-story canted bay contains steel windows, a steel window is east of the entrance, and two steel windows are on the second floor. Windows have stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a hipped roof garage.
602	4023 Leslie Street			1952	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4023 Leslie Street is two-stories topped with a hipped asphalt shingle roof. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with two applied metal panels. The primary entrance is trimmed in stone, near the east corner of the facade, and is accessed by a brick and concrete porch with a low metal railing and a metal awning structure. West of the entrance a single-story canted bay contains vinyl windows and two vinyl windows are on the second floor. Windows have stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a hipped roof garage.
603	4031 Leslie Street			1939	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4031 Leslie Street is two-stories topped with a hipped asphalt shingle roof intersected by two gables on the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, decorative brickwork, and wood false half-timbering. The primary entrance is arched, trimmed in stone, near the east corner of the facade, and is accessed by a brick and concrete porch with a brick kneewall and a metal awning structure. West of the entrance a single-story canted bay contains steel leaded glass windows, a small window is east of the entrance, and two steel windows are on the second floor. Windows have stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house but there is no garage.
604	4039 Leslie Street			1945c.	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4039 Leslie Street is two-stories topped with a hipped asphalt shingle roof intersected by a two-story bay with a gabled wall dormer. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of cast stone and decorative brickwork. The primary entrance is trimmed in stone, near the center of the facade, and is accessed by a brick and concrete porch with a metal railing and a metal awning structure. West of the entrance a single-story canted bay contains vinyl windows, a vinyl window is east of the entrance, and two vinyl windows are on the second floor. Windows have stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a hipped roof garage.
605	4044 Leslie Street			1939	Tudor Revival	2/garage	C	Unknown	Unknown	The house at 4044 Leslie Street is two-stories topped with a hipped asphalt shingle roof intersected by a two-story gable roof bay on the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, decorative brickwork, and metal-clad false half-timbering. The primary entrance is trimmed in stone, near the center of the facade, and is accessed by a brick and concrete porch with a low metal railing and a fabric awning. The first floor of the bay is canted and contains steel casement windows, a steel window is east of the entrance, and two steel windows are on the second floor. Windows have stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a pyramidal roof garage which is adjacent to another hipped roof garage. A black lightpost with a globe light fixture is in the front lawn.
606	4045 Leslie Street			1938	French Eclectic	n/a	C	Unknown	Unknown	The house at 4045 Leslie Street is two-stories topped with a hipped asphalt shingle roof intersected by a two-story canted bay with a polygonal roof and a hipped wall dormer on the facade. A stone buttress extends from the west corner of the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is trimmed in stone, near the center of the facade, and is accessed by a wood porch with a wood railing. The bay contains steel windows on the first and second floors, a steel window is east of the entrance, and a steel window is above the entrance. Windows have stone sills and storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house but there is no garage.
607	4054 Leslie Street			1946	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4054 Leslie Street is two-stories topped with a hipped asphalt shingle roof intersected by a two-story canted bay with a polygonal roof and a hipped wall dormer on the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer and cast stone. The primary entrance is trimmed in stone, near the center of the facade, and is accessed by a stone, brick, and concrete porch with a stone and brick kneewall and a metal aluminum structure. The bay contains steel windows on the first and second floors, a steel window is east of the entrance, and a steel window is above the entrance below the dormer. A curved glass block window is near the front of the east facade. Windows have stone or brick sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a hipped roof garage. A black lightpost with a globe light fixture is in the front lawn.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
608	4055 Leslie Street			1955	Streamline Moderne	n/a	C	Unknown	Unknown	The house at 4055 Leslie Street is two-stories and topped with a pyramidal asphalt shingle roof. Two brick chimneys are located at the eave on the west facade. The exterior is clad in yellow brick veneer laid in a running bond pattern with some courses set proud to create horizontal bands in the brick. The primary entrance is near the east corner of the facade and is accessed by a brick and concrete porch with a brick planter west of the entrance. A steel window is west of the entrance and two steel windows with black shutters are on the second floor. Windows have stone sills. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house but there is no garage.
609	4061 Leslie Street			1949	French Eclectic	n/a	C	Unknown	Unknown	The house at 4061 Leslie Street is two-stories topped with a hipped asphalt shingle roof intersected by a two-story canted bay with a polygonal roof on the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer and cast stone. The primary entrance is trimmed in stone, near the east corner of the facade, and is accessed by a brick and concrete porch with a low metal railing. The bay contains slynteel windows on the first and second floors and a vinyl window is above the entrance. Windows have stone or brick sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house but there is no garage.
610	4062 Leslie Street			1941	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4062 Leslie Street is two-stories topped with a hipped asphalt shingle roof intersected by a two-story bay on the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer and cast stone. The primary entrance is arched, trimmed in stone, near the east corner of the facade, and is accessed by a brick and concrete porch with a low metal railing and a metal awning structure. A single-story canted bay west of the entrance contains steel windows, two steel windows flank the entrance, and two steel windows are on the second floor, one of which is arched. Windows have stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a hipped roof garage. A black lightpost with a lantern-style light fixture is in the front lawn.
611	4070 Leslie Street			1942	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4070 Leslie Street is two-stories topped with a hipped asphalt shingle roof intersected by a two-story canted bay with a polygonal roof on the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of cast stone and decorative brickwork. The primary entrance is trimmed in stone, near the east corner of the facade, beneath a flared roof awning, and is accessed by a brick and concrete porch with a low metal railing. The bay contains wood leaded glass windows on the first and second floors and a leaded glass window is above the entrance. Windows have stone sills and storms that obscure the windows. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a hipped roof garage. A black lightpost without a light fixture is in the front lawn.
612	4071 Leslie Street			1941	French Eclectic	n/a	C	Unknown	Unknown	The house at 4071 Leslie Street is two-stories topped with a hipped asphalt shingle roof intersected by a two-story bay with a jerkinhead roof and a gabled wall dormer on the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer and cast stone. The primary entrance is arched, trimmed in stone, near the east corner of the facade, and is accessed by a brick and concrete porch with a low metal railing. West of the entrance a single-story canted bay contains steel windows, two small windows flank the entrance, and two steel windows are on the second floor. Windows have stone sills and storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a hipped roof garage.
613	4078 Leslie Street			1940	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4078 Leslie Street is two-stories topped with a hipped asphalt shingle roof intersected by a gable roof and a gabled wall dormer on the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in brown brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is arched, trimmed in stone, near the center of the facade, and is accessed by a brick and concrete porch with a brick kneewall and a metal awning structure. West of the entrance a single-story canted bay contains steel windows, another single-story canted bay with steel windows is east of the entrance, and two steel windows are on the second floor. Windows have stone sills and storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a pyramidal roof garage. A black lightpost with a globe light fixture is in the front lawn.
614	4086 Leslie Street			1938	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4086 Leslie Street is two-stories topped with a hipped asphalt shingle roof intersected by a gable roof and a gabled wall dormer on the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in brown brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is arched, trimmed in stone, near the center of the facade, and is accessed by a brick and concrete porch with a metal railing. West of the entrance a single-story canted bay contains steel windows, another single-story canted bay with steel windows is east of the entrance, and two steel windows are on the second floor. Windows have stone sills and storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house but there is no garage.
615	4087 Leslie Street			1959	Prairie	1/garage	C	Unknown	Unknown	The house at 4087 Leslie Street is two-stories topped with a hipped asphalt shingle roof intersected by a hipped roof bay on the facade. A brick chimney is near the eave near the center of the west facade. The exterior is clad in blonde brick veneer laid in a running bond pattern. The primary entrance is near the east corner of the facade, is accessed by a brick and concrete porch with a metal railing and brick planter, and is partially covered by a flat awning that stretches across the facade. West of the entrance is a rectangular vinyl window and a vinyl picture window, and two vinyl windows are on the second floor. Windows have stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house to a hipped roof garage.
616	4095 Leslie Street			1941	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4095 Leslie Street is two-stories topped with a hipped asphalt shingle roof intersected by a two gabled wall dormers on the facade. A stone buttress extends from the east corner of the facade. A brick chimney is at the eave near the front of the east facade. The exterior is clad in brown brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is arched, trimmed in stone, near the center of the facade, and is accessed by a brick and concrete porch with a low metal railing and a metal awning structure. East of the entrance a single-story canted bay contains steel windows, a steel window is east of the entrance, and two steel windows are on the second floor. Windows have stone sills and some have storms. Similar windows are arranged on other elevations. A concrete driveway runs along the rear of the house to a pyramidal roof garage. A black lightpost with a lantern-style light fixture is in the front lawn.
617	4096 Leslie Street			1939	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4096 Leslie Street is two-stories topped with a side gable asphalt shingle roof intersected by a large from gable, a gabled wall dormer, and a polygonal wall dormer on the facade. A large brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, decorative brickwork, and wood false half-timbering. The primary entrance is arched, near the center of the facade, and is accessed by a brick and concrete porch beneath a shed roof supported by wood posts. West of the entrance a single-story canted bay contains steel windows, a steel window is east of the entrance, and two steel windows are on the second floor. Windows have stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the rear of the house to a pyramidal roof garage. A gold lightpost with a lantern-style light fixture is in the front lawn.
618	4202 Leslie Street			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4202 Leslie Street is two-stories topped with a deck, flat on hipped asphalt shingle roof intersected by a jerkinhead and a front gable roof dormer above the facade, and hipped roof dormers facing east and to the rear. A brick chimney is at the eave on the east facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of cast stone, and decorative brickwork. The primary entrance is trimmed in stone quoins, near the center of the facade within a front gabled slightly projecting entrance vestibule, and is accessed by a brick and concrete porch beneath an aluminum awning. Windows on the first floor appear to be wood hung, with cast stone sills beneath brick arched lintels and keystones. Windows on the second floor are wood hung with brick sills, and have aluminum awnings. Similar windows are arranged on other elevations. A concrete driveway is accessed off of Petoskey Avenue to the east leading to a pyramidal roof garage at the rear of the house.
619	4203 Leslie Street			1948	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4203 Leslie Street is two-stories topped with a hipped asphalt shingle roof. A brick chimney is at the eave on the west facade. The exterior is clad in red brick veneer laid in a running bond pattern. The primary entrance is trimmed in stone, near the east corner of the facade, and is accessed by a brick and concrete porch with a low metal railing and a metal awning. West of the entrance a single-story canted bay clad in stone veneer contains vinyl windows and two vinyl windows are on the second floor. Windows have stone sills. Similar windows are arranged on other elevations, and towards the rear there is a louvered window that wraps the southeast corner on the second floor. A concrete driveway is accessed off of Petoskey Avenue to the east leading to a pyramidal roof garage at the rear of the house.
620	4211 Leslie Street			1924	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 4211 Leslie Street is two-stories and topped with a side gambrel asphalt shingle roof. A brick chimney is located at the eave on the west facade. The facade is clad with brown brick veneer in a running bond pattern, with wood shingle siding beneath a continuous shed dormer on the second floor, and beneath the side gable on the second floor. The primary entrance is near the east corner of the facade beneath a gabled overhang with curved underside supported by square wood posts, and is accessed by a brick and concrete porch. West of the entrance is four wood hung windows with a wood paneled surround beneath an aluminum awning, and two pairs of matching wood hung windows framed by shutters and beneath aluminum awnings are on the second floor. Similar windows exist on other elevations, and have cast stone sills on the first floor. A concrete ribbon driveway runs along the east of the house to the rear where there is a front gable roof garage.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
621	4212 Leslie Street			1924	Prairie	1/garage	C	Unknown	Unknown	The house at 4212 Leslie Street is two-stories and topped with a hipped asphalt shingle roof, intersected by hipped roof dormers centered above the façade on the front and east containing two small hung windows. A brick chimney is at the eave on the west facade. The exterior is clad in orange-brown brick veneer laid in a running bond pattern. The entrance is accessed beneath a flat-roofed overhang supported by metal posts, accessed by a full width brick and concrete porch with metal railing. Three vinyl hung windows are west of the entrance, topped with brick-infilled arches with keystones and beneath an aluminum metal awning. A set of three and a pair of matching hung windows on the second floor. Similar windows are arranged on other elevations, and have cast stone sills. A concrete driveway runs along the east of the property to the rear where there is a hipped roof garage.
622	4220 Leslie Street			1925	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4220 Leslie Street is two-stories and topped with a side gable asphalt shingle roof intersected by a front gable, with a hipped roof dormer and two front gables at the rear. A brick chimney is at the eave on the west facade of the house. The facade is clad in red and brown brick veneer laid in a running bond pattern with accents of stone. The primary entrance is near the east corner of the façade beneath a front gabled portico support by brick piers with an arched opening accented in stone. The entrance door is accessed by a brick and concrete porch. West of the entrance the view of the façade is obscured by vegetation. On the second floor, a set of three wood windows with divided upper sashes together form a segmental arch, topped with a brick lintel with keystone. A narrow arched window is at the attic level beneath the front gable. Similar windows are arranged on other elevations and all windows have cast stone sills painted white. A concrete driveway runs along the east of the property to the rear. There is no garage.
623	4221 Leslie Street			1924	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4221 Leslie Street is two-stories and topped with a hipped asphalt shingle roof, intersected by a front gable and a hipped roof dormer above the east facade. A brick chimney is located at the eave on west façade of the house. The facade is clad in brown face brick laid in a running bond pattern with some decorative brickwork and stone accents. The primary entrance is near the west corner of the façade beneath a front gabled portico, supported by brick piers with arched openings on all sides, and is accessed by a brick and concrete porch. A set of three windows east of the entrance has a brick lintel, and two pairs of windows that appear to be wood with vertically divided upper sashes are on the second floor, all with cast stone sills. Similar windows are found on other elevations. A concrete driveway runs along the east of the house to the rear where there is a pyramidal roof garage. A black lightpost with a globe light fixture is in the front lawn.
624	4228 Leslie Street			1925	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4228 Leslie Street is two-stories and topped with a side gable asphalt shingle roof, intersected by a front gable. A brick chimney is located at the eave on west façade of the house. The facade is clad in red face brick laid in a running bond pattern with some decorative brickwork and stone accents. The primary entrance is near the east corner of the façade beneath a front gabled portico, clad in brick with stone accents and supported by brick piers that form an arch. The batten door is arched and is accessed by a brick and concrete porch. A set of four wood hung windows with divided upper sashes and a stone lintel are west of the entrance beneath two pairs of similar windows on the second floor, all with cast stone sills. Similar windows are found on other elevations. A concrete driveway runs along the east of the house to the rear. There is no garage.
625	4229 Leslie Street			1928	Georgian Revival	1/garage	C	Unknown	Unknown	The house at 4229 Leslie Street is two-stories and topped with a side gable asphalt shingle roof, with a parapet on the gable ends with stone coping, and a shed roof dormer above the rear facade. Modillions line the eave above the façade. A brick chimney is located at the eave on the west façade of the house. The facade is clad in light brown face brick laid in a running bond pattern. The primary entrance is near the east corner of the facade, and is accessed by a low concrete stoop. The door is framed with an elaborated surround including pilasters and a dentiled segmental broken pediment and a transom above the door. West of the entrance is are two vinyl hung windows with wood panels below and framed by full height wood shutters. Three matching hung windows are arranged symmetrically each framed by shutters are on the second floor. Similar windows exist on other elevations, and windows have cast stone sills. A driveway runs along the east of the house to the rear where there is a pyramidal roof garage.
626	4236 Leslie Street			1926	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4236 Leslie Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof intersected by a front gable with flared eaves and vergeboards, a triangular roof dormer above the façade and gabled roof dormers clad in wood shingles on the east and rear, and a shed roof addition at the rear above a two-story enclosed porch. A large brick chimney is located at the eave on the west facade of the house. The exterior is clad in reddish brown brick veneer laid in a unique alternating triple-stacked and header bond pattern with decorative brickwork. The primary entrance is near the east corner of the facade within a front gabled vestibule with flared eaves and vergeboard, and the arched door is recessed within an arched brick surround. The entrance is accessed by a brick and concrete porch. West of the entrance is a segmental arched set of four wood, hung, multi-light windows, with brick lintel accented by rusticated stone. A pair and a single wood hung window glaze the second floor. Similar windows exist on other elevations and windows have brick sills. There is a concrete driveway to the east of the house leading to a hipped roof garage at the rear.
627	4241 Leslie Street			1926	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4241 Leslie Street is two-stories and topped with a hipped asphalt shingle roof, with shed roof dormers above the east, west, and rear facades, and intersected by a slightly projecting front gabled entrance vestibule. A brick chimney is located at the center of the house. The facade is clad in brown face brick laid in a running bond pattern. The primary entrance is centered on the façade, and the arched door is trimmed in brick with stone accents above. The entrance is accessed by a brick and concrete porch, a portion of which is clad in stone and beneath an aluminum awning. On either side of the entrance is a pair of wood hung windows with divided upper sashes and brick lintels directly beneath two pairs of similar windows on the second floor, all with brick sills. Similar windows are found on other elevations. A concrete driveway runs along the east of the house to the rear where there is a front gable roof garage. A black lightpost with a globe light fixture is in the front lawn.
628	4244 Leslie Street			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4244 Leslie Street is two-stories topped with a deck, flat on hipped asphalt shingle roof intersected by a front gable and shed roof dormers above the east and rear façades. A brick chimney is at the eave on the west facade. The exterior is clad in brown brick veneer laid in a running bond pattern with accents of stone and decorative brickwork. The primary entrance is at the center of the façade beneath a front gabled portico with wide metal cladding and supported by grouped square wood posts, and is accessed by a brick and concrete porch. On either side of the entrance is a large slider vinyl window, the set on the east is beneath an aluminum awning. Windows on the second floor appear to be wood hung, with aluminum storms. Similar windows are arranged on other elevations and windows have cast stone sills. A concrete driveway runs along the east of the house to the rear where there is pyramidal roof garage. A black lightpost with a globe light fixture is in the front lawn.
629	4245 Leslie Street			1923	Prairie	n/a	C	Unknown	Unknown	The house at 4245 Leslie Street is two-stories and topped with a hipped asphalt shingle roof with modillions along the eave, intersected by a hipped roof dormer centered above the façade containing two small hung windows and a hipped roof at the rear. A brick chimney is at the eave on the west facade. The exterior is clad in brown brick veneer laid in a running bond pattern, with accents of decorative brickwork. The entrance is accessed beneath a hipped overhang supported by brick piers, accessed by a full width brick and concrete porch with a brick kneewall. Three wood hung windows are west of the entrance, topped with an asphalt shingle overhang with dentils and modillions and a fabric awning. Two pairs of hung windows are on the second floor. Similar windows are arranged on other elevations, and all windows have cast stone sills. A concrete driveway runs along the east of the property to the rear. There is no garage. A black lightpost with a globe light fixture is in the front lawn.
630	4252 Leslie Street			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4252 Leslie Street is two-stories and topped with a cross gable asphalt shingle roof, composed of a front gable that meets a hipped roof at the rear, intersected by a front gable that overlaps with another front gable with knee brackets. A brick chimney is located near the eave on the west façade of the house. The facade is clad in light brown brick veneer laid in a running bond pattern with accents of cast stone, and vinyl siding beneath the side gable. The primary entrance is near the east corner of the house beneath an overhang that creates a second floor balcony with a metal railing, and is supported by white fluted columns. The door is trimmed with cast stone and brick and is accessed by a full width brick and concrete porch with a metal railing. West of the entrance are three wood, hung, multi-light windows with aluminum storms beneath a fabric awning, beneath a set of three similar windows on the second floor. Similar windows are found on other elevations and windows have cast stone sills. A concrete driveway runs along the east of the house to the rear where there is a pyramidal roof garage. A black lightpost with a globe light fixture is in the front lawn.
631	4253 Leslie Street			1927	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4253 Leslie Street is two-stories and topped with a cross gable asphalt shingle roof, intersected by a front gable that overlaps with a projecting front gabled entrance vestibule. A brick chimney is located at the eave on the west facade of the house. The facade is clad in brown face brick laid in a running bond pattern with decorative brickwork and stone accents. The primary entrance is near the east corner of the façade, and the door is trimmed in brick with stone accents above. The entrance is accessed by a brick and concrete porch, with a metal railing and the support structure of an awning that has been removed. West of the entrance are three hung vinyl windows with divided upper sashes beneath a brick lintel with keystone directly beneath a two pair of similar windows on the second floor. Similar windows are found on other elevations and windows all have brick sills. A concrete driveway runs along the east of the house to the rear where there is a pyramidal roof garage. A black lightpost with a globe light fixture is in the front lawn.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
632	4260 Leslie Street			1925c.	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4260 Leslie Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by a front gable, and a hipped roof dormer facing west and another at the rear. A brick chimney is located at the eave on the west facade of the house. The facade is clad in red and brown face brick laid in a running bond pattern with accents of stone. The primary entrance is located near the east corner of the façade and is accessed by a concrete and brick porch with a metal railing, beneath a front gabled brick-clad portico supported by slightly tapered brick piers and a brick arched opening. Above the arch is a polychromatic tile detail. The door is segmentally arched with stone accents. West of the entrance is a large vinyl slider window trimmed in stone with quoins. Vinyl hung windows are on the second floor with brick played lintels and stone accents. Similar windows are found on other elevations and windows have cast stone sills. A concrete driveway runs along the east of the house leading to the rear. There is no garage.
633	4261 Leslie Street			1925c.	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4261 Leslie Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by a front gable that overlaps with a projecting front gabled entrance vestibule, and a shed roof dormer facing east. A tall brick chimney is located at the eave on the west facade of the house. The facade is clad in red, dark and light brown face brick laid in a running bond pattern with accents of stone, with false half-timbering beneath the front gable infilled with decorative brickwork. The primary entrance is located near the east corner of the façade and is accessed by a concrete and brick porch with a metal railing, and the support structure of an awning that has been removed. The arched door is recessed within a stone trimmed arch. West of the entrance is a steel casement window with sidelights and transom, with a brick splayed lintel and stone accents. Similar steel casement windows are on the second floor and on other elevations, and windows have brick sills. A concrete driveway runs along the east of the house leading to the rear. There is no garage. A black lightpost with a globe light fixture is in the front lawn.
634	4268 Leslie Street			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4268 Leslie Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by a front gable, and a hipped roof dormer facing west and another at the rear. A brick chimney is located at the eave on the west facade of the house with stone accents. The facade is clad in red and brown face brick laid in a running bond pattern with accents of stone, with some false half-timbering on the second floor infilled with decorative brickwork. The primary entrance is located near the east corner of the façade and is accessed by a concrete and brick porch, beneath a jerkinhead portico supported by slightly tapered brick piers and a segmental arch opening trimmed in stone. West of the entrance is a ribbon of four steel casement windows with leaded glass detailing trimmed in stone. A matching ribbon of three windows are on the second floor. Similar windows are found on other elevations and windows have cast stone sills. A concrete driveway runs along the east of the house leading to the rear where there is a pyramidal roof garage.
635	4269 Leslie Street			1925c.	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4269 Leslie Street is two-and-a-half-stories and topped with a cross gable asphalt shingle roof, intersected by a front gable that overlaps with a projecting front gabled entrance vestibule, and shed roof dormer above the facade. A brick chimney is located at the eave on the west facade of the house. The first floor and parts of the second floor are clad in brick laid in a running bond pattern that has been painted on the primary façade, with vinyl siding beneath the front gables and at the attic level on the side gables. The primary entrance is centered on the façade, and the arched door is accessed by a brick and concrete porch with a metal railing. On either side of the entrance is a large vinyl slider window framed by shutters painted white. Vinyl hung windows glaze the second floor, and similar windows are found on other elevations, some with cast stone sills. A concrete ribbon driveway runs along the east of the house to the rear where there is a pyramidal roof garage.
636	4276 Leslie Street			1928	Tudor Revival	1/garage	C	Unknown	Miller-Storm Company	The house at 4276 Leslie Street is two-stories and topped with a cross gable asphalt shingle roof, composed of a deck, flat on hipped intersected by two front gables, and a side gable roof at the rear with a shed roof dormer. A tall brick chimney is located at the eave on the west facade of the house. The facade is clad in red and brown face brick laid in a running bond pattern with accents of stone. The primary entrance is located near the east corner of the façade and is accessed by a concrete and brick porch, beneath the support structure of an awning that has been removed. The pointed arch door is trimmed in stone, beneath an arched window at the second floor with leaded glass in a diamond pattern. West of the entrance is a bay window topped with a metal roof with flare eaves, and glazed with a steel casement window with sidelights and transom. Steel casement windows are on the second floor. Similar windows are found on other elevations and windows have cast stone sills. One of the front gables extends into a catslide that extends off the east corner into a drive-through arch, above a concrete driveway runs along the east of the house leading to the rear where there is a side gable roof garage.
637	4277 Leslie Street			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4277 Leslie Street is two-stories and topped with a deck, flat on hipped intersected by two front gables, and a shed roof dormer facing west. A tall brick chimney is located at the eave on the west facade of the house. The facade is clad in light brown face brick laid in a running bond pattern with false half-timbering infilled with stucco beneath the front gables. The primary entrance is located near the east corner of the façade within a slightly projecting front gabled entrance vestibule and is accessed by a concrete and brick porch. Above and to the east of the door are casement windows with leaded glass in a diamond pattern. West of the entrance are three vinyl hung windows beneath a splayed brick lintel. Similar windows are found on other elevations and windows have cast stone sills. A concrete driveway runs along the east of the house leading to the rear where there is a pyramidal roof garage.
638	4284 Leslie Street			1926	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4284 Leslie Street is two-stories and topped with a hipped asphalt shingle roof, intersected by a hipped roof projecting bay towards the front, and hipped wall dormers across the facades. A tall brick chimney is located at the eave on the west facade of the house. The façade is clad in light and dark brown brick laid in a running bond pattern with accents of stone, with false half-timbering infilled with stucco at the second floor which overhangs with decorative brackets. The primary entrance is near the east corner of the façade, and the arched door is accented by stone and is accessed by a brick and concrete stoop. The first floor is glazed with a steel casement window with sidelights and transom, and similar windows are found on other elevations, some with brick sills. A concrete driveway runs along the east of the house to the rear. There is no garage.
639	4285 Leslie Street			1925c.	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4285 Leslie Street is two-stories and topped with a cross gable asphalt shingle roof, intersected by a front gable, and a two-story canted bay with a flat roof. A brick chimney is located at the peak of the eave on the west facade of the house. The facade is clad in red and brown face brick laid in a running bond pattern with accents of decorative brickwork. The primary entrance is located near the center of the façade and is accessed by a concrete and brick stoop with metal railing. The arched door is trimmed in brick. East of the entrance are multi-light, wood hung windows beneath a splayed brick lintel, and a single multi-light, wood hung window on the second floor framed by shutters. West of the entrance is a two-story canted bay clad in wood and stucco, with vinyl hung windows at the first floor and multi-light, wood hung windows at the second floor. Similar windows are found on other elevations and windows have cast stone sills. A concrete driveway runs along the east of the house leading to the rear where there is a hipped roof garage. A black lightpost with a globe light fixture is in the front lawn.
640	4290 Leslie Street			1925	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4290 Leslie Street is two-stories and topped with a cross gable asphalt shingle roof, intersected by a front gable. A brick chimney is located at the eave on the west facade of the house. The facade is clad in reddish brown face brick laid in a running bond pattern with a soldier course running between the first and second floor. Vinyl siding is present beneath the side gables at the attic level and on a two-story enclosed porch at the rear. The primary entrance is located near the east corner of the façade and is accessed by a concrete and brick porch, beneath a jerkinhead portico supported by brick piers and an arched opening with stone accents. West of the entrance is a large vinyl slider window trimmed in stone and topped with a segmental arch lintel. Two hung vinyl windows are on the second floor. Similar windows are found on other elevations and windows have cast stone sills. A concrete driveway runs along the east of the house leading to the rear. There is no garage.
641	4295 Leslie Street			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4295 Leslie Street is two-stories and topped with a deck, flat on hipped intersected by a front gable, and hipped roof dormers facing west and to the rear. A tall brick chimney is located at the eave on the west facade of the house. The facade is clad in red, brown, and gray brick laid in an English bond pattern with false half-timbering infilled with decorative brickwork at the second floor. A brick buttress extends from the west corner. The primary entrance is located near the east corner of the façade beneath a jerkinhead portico supported by slightly tapered brick piers and a segmentally arched opening with stone trim, and is accessed by a concrete and brick stoop. Above the door are three narrow casement windows with leaded glass in a diamond pattern. West of the entrance is a large vinyl slider window trimmed in stone. A set of three wood hung windows with divided upper sashes together form a segmental arch, beneath a narrow arched window at the attic level. Similar windows are found on other elevations and windows have cast stone sills. A concrete driveway runs along the east of the house leading to the rear where there is a front gable roof garage.
642	4300 Leslie Street			1923	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4300 Leslie Street is two-stories and topped with a hipped intersected by a hipped roof wing at the rear and a shed roof dormer above the east facade. A tall brick chimney is located at the eave on the west facade of the house. The facade is clad in red and brown brick veneer laid in a running bond. The primary entrance is recessed at the east corner of the house within an arched opening with stone quoins, and the arched infilled with stucco and tile. West of the entrance is a large vinyl slider window trimmed in stone. A vinyl slider window and a hung vinyl window are at the second floor. Similar windows are found on other elevations and windows have cast stone sills. A concrete driveway runs along the east of the house leading to the rear where there is a hipped roof garage.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
643	4301 Leslie Street			1924	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4301 Leslie Street is two-stories and topped with a deck, flat on hipped intersected by a front gable, and hipped roof dormers facing west and to the rear. A tall brick chimney is located at the eave on the west facade of the house. The facade is clad in brown brick laid in a running bond pattern with decorative brickwork. A brick buttress extends from the west corner. The primary entrance is located near the east corner of the facade beneath a front gabled portico supported by brick piers and an arched opening, and is accessed by a full width concrete and brick porch with a metal railing. West of the entrance are three vinyl hung windows beneath a segmental arch lintel. A pair of two vinyl hung windows with divided upper sashes are at the second floor, next to a pair of two narrow vinyl hung windows with stone label mold accents, both beneath a narrow arched window at the attic level. Similar windows are found on other elevations and windows have cast stone sills. A concrete ribbon driveway runs along the east of the house leading to the rear where there is a hipped roof garage.
644	4308 Leslie Street			1936	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4308 Leslie Street is two-stories and topped with a deck, flat on hipped intersected by a hipped roof overhang and a front gable. A brick chimney is located at the eave on the west facade of the house. The facade is clad in red and brown gray brick laid in a running bond pattern with false half-timbering infilled with decorative brickwork at the second floor overhanging bay. The primary entrance is located slightly off-center on the facade with an arched door trimmed with stone, and is accessed by a concrete stoop. To the east of the door is a small stained glass window, and above are two casement windows with leaded glass detailing trimmed in stone and a decorative metal balcony railing. West of the entrance is a one-story canted bay trimmed in stone glazed with steel casement windows with leaded glass detailing, beneath the second floor overhanging bay supported by decorative brackets. Other windows are steel casement with transoms and/or sidelights, and windows have cast stone sills. A concrete driveway runs along the east of the house leading to the rear where there is a pyramidal roof garage.
645	4309 Leslie Street			1926	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4309 Leslie Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof intersected by a front gable with flared eaves and vergeboards, a triangular roof dormer above the facade and hipped roof dormers clad in wood shingles on the east and west. A large brick chimney is located at the eave on the west facade of the house. The exterior is clad in reddish brown brick veneer laid in a unique alternating triple-stacked and header bond pattern with decorative brickwork. The primary entrance is near the center of the facade within a front gabled vestibule with flared eaves and vergeboard, and the arched door is within an arched brick surround. The entrance is accessed by a brick and concrete full-width porch with metal railing. West of the entrance is a set of three wood, hung, multi-light windows, with brick splayed lintel. Similar windows are found at the second floor and across the other elevations, and windows have brick sills. There is a concrete driveway to the east of the house leading to a pyramidal roof garage at the rear. A lightpost is in the front lawn.
646	4316 Leslie Street			1924	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4316 Leslie Street is two-stories and topped with a hipped asphalt shingle roof, with shed roof dormers above the east and west facades, and intersected by a slightly projecting front gabled entrance vestibule. A brick chimney is located at the center of the house. The facade is clad in brown face brick laid in a running bond pattern. The primary entrance is centered on the facade, and the arched door has been boarded over but is trimmed in brick with stone accents above. The entrance is accessed by a concrete stoop. On either side of the entrance is a window that has been boarded over, directly beneath two vinyl slider windows on the second floor, all with cast stone sills. Similar windows are found on other elevations. A concrete driveway runs along the east of the house to the rear where there is a hipped roof garage.
647	4317 Leslie Street			1925c.	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4317 Leslie Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by a front gable that overlaps with slightly projecting front gabled entrance vestibule, with a front gabled roof dormer centered above the facade containing three small wood windows, shed roof dormers above the east and west facades, and a hipped roof dormer at the rear. A brick chimney is located at the eave on the west facade of the house. The facade is clad in red, tan, and brown face brick laid in a running bond pattern. The primary entrance is centered on the facade, accessed by a concrete and brick porch. On either side of the entrance is a set of three wood hung windows with aluminum storms, directly beneath two pairs of matching windows on the second floor, all with brick sills. Similar windows are found on other elevations. A concrete driveway runs along the east of the house to the rear where there is a pyramidal roof garage.
648	4324 Leslie Street			1924	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4324 Leslie Street is two-stories and topped with a side gable that meets a deck, flat on hipped roof towards the rear, and is intersected by overlapping front gables. A brick chimney is located at the peak of the eave on the west facade of the house. The facade is clad in brown face brick laid in a running bond pattern with false half-timbering infilled with stucco at the second floor. The primary entrance is located near the east corner of the facade within a slightly projecting front gabled entrance vestibule and is accessed by a low concrete and brick porch with a metal railing. West of the entrance are four wood hung windows beneath a brick lintel, beneath four casement windows with leaded glass in a diamond pattern at the second floor. Aluminum storms are affixed to the exterior. Similar windows are found on other elevations and windows on the first floor have brick sills. A concrete driveway runs along the east of the house leading to the rear. There is no garage.
649	4325 Leslie Street			1928	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4325 Leslie Street is two-stories and topped with a cross gable that is intersected by overlapping front gables. A brick chimney is located at the peak of the eave on the west facade of the house. The facade is clad in brown face brick laid in a running bond pattern with some false half-timbering infilled with stucco at the second floor. The primary entrance is located near the east corner of the facade within a slightly projecting front gabled entrance vestibule and is accessed by a concrete porch. Windows across the facade are hung vinyl or slider, with brick sills. Aluminum storms are affixed to the exterior. Similar windows are found on other elevation. A concrete driveway runs along the east of the house leading to the rear where there is a side gable roof garage.
650	4334 Leslie Street			1924	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4334 Leslie Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, with an eyebrow dormer, shed roof dormers above the east and rear facades, and intersected by a front gable. A brick chimney is located at the eave on the west facade of the house. The facade is clad in brown face brick laid in a running bond pattern with some decorative brickwork. The primary entrance is centered on the facade beneath a front gabled portico supported by brick piers, and is accessed by a concrete block porch with a metal railing. On either side of the entrance is a set of three steel casement windows that together are set beneath a segmental arch brick lintel, beneath two pairs of similar windows on the second floor, all with brick sills. Similar windows are found on other elevations. A concrete driveway runs along the east of the house to the rear where there is a pyramidal roof garage.
651	4335 Leslie Street			1924	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4335 Leslie Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, with hipped roof dormers above the front, east, and rear facades, and intersected by a front gable. A brick chimney is located at the eave on the west facade of the house. The facade is clad in blonde face brick laid in a running bond pattern, with false half-timbering beneath the front gables. The primary entrance is centered on the facade within a slightly projecting front gabled entrance vestibule, and is accessed by a brick and concrete porch. On either side of the entrance is a set of three wood, multi-light, hung windows that together are set beneath a segmental arch brick lintel, beneath two pairs of similar hung windows on the second floor, all with brick sills. Similar windows are found on other elevations. A concrete driveway runs along the east of the house to the rear where there is a pyramidal roof garage. A black lightpost with a globe light fixture is in the front lawn.
652	4340 Leslie Street			1924	Italian Renaissance	1/garage	C	Unknown	Unknown	The house at 4340 Leslie Street is two-stories and topped with a hipped asphalt shingle roof with modillions along the eave, intersected by a hipped roof dormer centered above the facade containing three small hung windows and a hipped roof dormer facing east. A brick chimney is at the eave on the west facade. The exterior is clad in brown brick veneer laid in a running bond pattern, with some sections set proud at the corners creating a quoined appearance. The entrance is accessed beneath a hipped overhang with modillions supported by slightly tapered brick piers, accessed by a full width brick and concrete porch with a brick kneewall. Three vinyl hung windows are west of the entrance, topped with cast stone arched hood molds with stucco infill. Two pairs of hung vinyl windows are on the second floor. Similar windows are arranged on other elevations, and all windows have cast stone sills. A concrete driveway runs along the east of the property to the rear where there is a front gable roof garage.
653	4343 Leslie Street			1926	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4343 Leslie Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof intersected by a front gable, and hipped roof dormers on the west and rear. A brick chimney is located at the eave on the west facade of the house. The exterior is clad in reddish brown brick veneer laid in a unique alternating triple-stacked and header bond pattern with decorative brickwork. The primary entrance is near the east corner of the facade within a front gabled vestibule clad in stone veneer, and the arched door is within an arched stone surround. The entrance is accessed by a brick and concrete full-width porch with metal railing. West of the entrance is a set of four vinyl windows, beneath a segmental arch brick lintel. Similar windows are found at the second floor and across the other elevations, and windows have brick sills. There is a concrete driveway to the east of the house leading to the rear. There is no garage.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
654	4348 Leslie Street			1927	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4348 Leslie Street is two-stories and topped with a cross gable asphalt shingle roof, composed of a front gable that meets a deck, flat on hipped roof to the east where the roofline extends down above the entrance. The roof is intersected by a hexagonal dormer clad in wood shingles and an eyebrow-shaped overhang above the entrance. A tall brick chimney is located at the eave on the west façade of the house. The facade is clad in brown face brick laid in a running bond pattern with false half-timbering beneath the front gable at the attic level. The primary entrance is recessed near the east corner of the house, and is trimmed in stone, and is accessed by a concrete block porch with a metal railing. West of the entrance is a set of four steel casement windows with a cast stone surround, beneath three wood hung windows on the second floor, all with aluminum storms. Similar windows are found on other elevations, and windows have cast stone sills on the first floor. A concrete driveway runs along the east of the house to the rear where there is a pyramidal roof garage.
655	4349 Leslie Street			1929	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4349 Leslie Street is two-stories and topped with a deck, flat on hipped intersected by a front gable, and a hipped roof dormer facing east. A tall brick chimney is located at the eave on the west facade of the house. The facade is clad in brown brick veneer laid in a running bond pattern with areas of false half-timbering infilled with decorative brickwork. The primary entrance is located near the center of the façade and is accessed by a concrete and brick porch, within a slightly projecting front gabled entrance vestibule clad in stone veneer. The arch door is beneath a fabric awning. West of the entrance is a steel casement window with sidelights and transom. Steel casement windows are on the second floor. Similar windows are found on other elevations and windows have brick sills. The roofline extends off the east corner into a drive-through above a concrete driveway runs along the east of the house leading to the rear where there is a front gable roof garage. A lightpost is in the front lawn.
656	4356 Leslie Street			1927	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4356 Leslie Street is two-stories and topped with a front gable asphalt shingle roof that meets a side gable, and has a continuous shed dormer facing the rear. A tall brick chimney is located at the eave on the east facade of the house. The facade is clad in red brick veneer laid in a running bond pattern, with some decorative brickwork and areas on the second floor clad in false half-timbering infilled with stucco. The primary entrance is recessed near the west corner of the façade and is accessed by a concrete stoop, the second floor overhang supported by wood spindle posts. West of the entrance is a flat bay window with flared metal roof, glazed by steel casement windows with aluminum storms. Steel casement windows with leaded glass in a diamond pattern are on the second floor. Similar windows are found on other elevations and most windows have cast stone sills. A concrete driveway runs along the east of the house leading to the rear where there is a front gable roof garage. A lightpost is in the front lawn.
657	4357 Leslie Street			1926	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4357 Leslie Street is two-stories and topped with a deck, flat on hipped intersected by a front gable, a front gabled roof dormer, and a jerkinhead roof above a slightly projecting entrance vestibule. A tall brick chimney is located at the eave on the west facade of the house. The facade is clad in brown brick veneer laid in a running bond pattern with some decorative brickwork. The primary entrance is located near the center of the façade and the arched door is accessed by a concrete stoop. West of the entrance is a large vinyl slider window. Similar windows are found across the facade and on other elevations, and windows have brick sills. A concrete driveway runs along the east of the house leading to the rear where there is a front gable roof garage. A lightpost is in the front lawn.
658	4364 Leslie Street			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4364 Leslie Street is two-and-a-half-stories and topped with a side gable asphalt shingle roof, intersected by overlapping front gables. A brick chimney is at the eave on the west facade. The exterior is clad in tan brick veneer laid in a running bond pattern. The entrance is accessed beneath a front gabled overhang with modillions, supported by brick piers, accessed by a brick and concrete porch with a brick kneewall. West of the entrance are four vinyl hung windows, topped with cast stone arched hood molds with stucco and tile infill, beneath an aluminum awning. A set of three hung vinyl windows are on the second floor, also beneath an aluminum awning. Two arched windows are at the attic level. Similar windows are arranged on other elevations, and all windows have cast stone sills. A concrete driveway runs along the east of the property to the rear where there is a front gable roof garage.
659	4365 Leslie Street			1928	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4365 Leslie Street is two-stories and topped with a deck, flat on hipped intersected by overlapping front gables, a shed roof dormer facing west, a hipped roof dormer to the rear, and a crenellated tower with a flat roof at the west corner of the house. A brick chimney is located at the eave on the west facade of the house. The facade is clad in brown brick veneer laid in a running bond pattern with some areas of false half-timbering infilled with decorative brickwork. The primary entrance is recessed near the east corner of the façade within a front gabled overhang with an arched opening, and is accessed by a concrete stoop. West of the entrance are three steel casement windows with aluminum storms. Similar windows are found across the facade and on other elevations, and windows have brick sills. A concrete driveway runs along the east of the house leading to the rear. There is no garage. A black lightpost is in the front lawn.
660	4372 Leslie Street			1926	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4372 Leslie Street is two-stories and topped with a side gable asphalt shingle roof, intersected by overlapping front gables with knee brackets and a hipped roof towards the rear. A brick chimney is at the eave on the east facade. The exterior is clad in blonde brick veneer laid in a running bond pattern with some decorative brickwork, and vinyl siding beneath the side gables at the attic level. The entrance is accessed beneath an asphalt shingled overhang, supported by brick piers with an arched opening, accessed by a brick and concrete full width porch with a metal railing. East of the entrance are three vinyl windows, topped with brick infilled arches with cast stone accents. A set of three vinyl casement windows with a brick lintel are on the second floor. An arched fixed window is at the attic level. Windows on other elevations appear to be vinyl and hung, and all windows have cast stone sills. An alley runs along the west of the property to the rear where there is a hipped roof garage.
661	4373 Leslie Street			1925	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4373 Leslie Street is two-stories and topped with a side gable asphalt shingle roof, that meets a hipped roof towards the front of the house, with a front gable and a triangular roof dormer above the façade. A brick chimney is located at the eave on the west façade of the house. The facade is clad in brown face brick laid in a running bond pattern with vinyl siding beneath the side gables at the attic level. The primary entrance is trimmed in stone, beneath a front gabled overhang clad in vinyl and supported by brick piers with cast stone caps, and is accessed by a brick and concrete stoop. On either side of the entrance is a set of three hung vinyl windows with cast stone surrounds, beneath similar windows on the second floor also trimmed in stone. Similar windows are found on other elevations, and windows have cast stone sills. A former alley runs along the west of the house to the rear. There is no garage.
662	4400 Leslie Street			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4400 Leslie Street is two-stories and topped with a cross gable asphalt shingle roof, composed of a front gable that meets a hipped roof to the west and is intersected by a front gabled two story bay that projects above the entrance. A large brick chimney is located at the eave on the west façade of the house. The facade is clad in red face brick laid in an English bond pattern with some false half-timbering infilled with brick. A brick buttress extends from the east corner of the house. The primary entrance is recessed near the center of the facade, trimmed in stone and topped with a low segmental arch, and is accessed by a concrete stoop. The façade is glazed with hung vinyl windows, and windows have brick sills. A one-story enclosed porch is at the rear. A concrete driveway runs along the east of the house to the rear where there is a pyramidal roof garage off of the alley.
663	4734 Leslie Street			1935	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4734 Leslie Street is two-stories and topped with a pyramidal asphalt shingle roof intersected by a hipped roof towards the front and a hipped roof dormer above the east facade. A tall brick chimney is located at the eave on the west facade of the house. The facade is clad in red and tan brick veneer laid in a running bond. The primary entrance is recessed at the center of the façade within a stone surround topped with a cast stone label mold, and is accessed by a concrete and brick porch with a metal railing. East of the entrance is a steel casement window with sidelights and transom, trimmed in stone, beneath similar windows on the second floor. West of the entrance is a one-story canted bay with a metal roof, clad in stone veneer, and with steel casement windows. Similar windows are found on other elevations and windows have brick sills. A concrete driveway runs along the east of the house leading to the rear where there is a pyramidal roof garage.
664	4744 Leslie Street			1924	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 4744 Leslie Street is two-stories and topped with a side gable asphalt shingle roof. A brick chimney is located at the eave on the west facade of the house. The facade is clad in red brick veneer laid in a running bond, with a soldier course running between the first and second floors. The primary entrance is near the east corner of the façade, topped with a fanlight beneath a cantilevered arched awning with decorative brackets, and is accessed by a concrete and brick porch with a metal railing. West of the entrance is a one-story canted bay with a metal roof, framed by shutters and glazed with vinyl hung windows. Similar windows with shutters are found on other elevations and windows have cast stone sills. A concrete driveway runs along the east of the house leading to the rear where there is a front gable roof garage.
665	4750 Leslie Street			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4750 Leslie Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by a front gable above the façade, a hipped roof dormer facing east, and a shed roof dormer facing the rear. A brick chimney is at the eave on the west facade. The exterior is clad in brown brick veneer laid in a running bond pattern, with some decorative brickwork. The entrance is beneath a front gabled overhang with flared eaves, supported by slightly tapered brick piers forming an arched opening with stone accents, and accessed by a full width brick and concrete porch with a metal railing. Three multi-light hung windows are west of the entrance, topped with a cast stone segmental arched lintel and stone quoins. Two pairs of windows on the second floor are accented by decorative brickwork. Similar windows are arranged on other elevations, and all windows have cast stone sills. A concrete driveway runs along the east of the property to the rear where there is a pyramidal roof garage.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
666	4760 Leslie Street			1926	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4760 Leslie Street is two-stories and topped with a pyramidal asphalt shingle roof, intersected by a front gable above the façade, a shed roof dormer facing east, and gabled roof dormers facing the west and rear. A brick chimney is at the eave on the west facade. The exterior is clad in brown brick veneer laid in a running bond pattern, with some decorative brickwork and stone accents. The arched entrance is beneath a front gabled overhang, supported by brick piers forming a wide arched opening, and accessed by a full width brick and concrete porch. A large vinyl picture window framed by two hung windows is west of the entrance, beneath three hung vinyl windows on the second floor. Similar windows are arranged on other elevations, and all windows have brick sills. A concrete driveway runs along the east of the property to the rear. There is no garage.
667	4770 Leslie Street			1927	Tudor Revival	1/garage	C	Unknown	Claude A. Dock	The house at 4770 Leslie Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by a front gable above the façade, and a shed roof dormer facing the rear. A brick chimney with decorative brickwork is slightly off-center on the front of the house. The exterior is clad in dark brown brick veneer laid in a running bond pattern, with some decorative brickwork and stone accents. The entrance is within a front gabled slightly projecting entrance vestibule clad in stone veneer, accessed by a low concrete porch. Two steel casement windows are west of the entrance, on either side of the chimney, and topped with brick arched lintels with stone accents. Two pairs of hung vinyl windows are on the second floor. Similar windows are arranged on other elevations, and all windows have cast stone sills. A concrete ribbon driveway runs along the east of the property to the rear where there is a pyramidal roof garage.
668	4782 Leslie Street			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4782 Leslie Street is two-stories and topped with a pyramidal asphalt shingle roof, intersected by a front gable above the façade, and a hipped roof dormers facing the rear. A brick chimney is at the eave on the west facade. The exterior is clad in red brick veneer laid in a running bond pattern, with some decorative brickwork and stone accents at the corners, and a small area of false half-timbering infilled with brick at the peak of the front gable. The arched entrance is surrounded by a brick arched portal, beneath a front gabled overhang, and accessed by a brick and concrete porch. East of the entrance, an aluminum metal awning covers a large vinyl slider window topped with a splayed brick lintel, and matching windows are west of the entrance as well as on the second floor. Similar windows are arranged on other elevations, and all windows have brick sills. A concrete driveway runs along the east of the property to the rear where there is a pyramidal roof garage.
669	4794 Leslie Street			1926	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4794 Leslie Street is two-stories and topped with a side gable asphalt shingle roof, intersected by a front gable above the façade, and a one-story hipped roof bay at the west corner. A brick chimney is at the eave on the west facade. The exterior is clad in brown brick veneer laid in a running bond pattern, with some decorative brickwork, and wide metal siding beneath the gables. The entrance is beneath a front gabled overhang supported by slightly tapered brick piers, and the arched door is accessed by a full width brick and concrete porch with a metal railing. Windows west of the entrance and on the second floor are hung, and each set covered by an aluminum awning. The one-story bay to the west features a canted bay window with casement windows. Similar windows are arranged on other elevations, and all windows have cast stone sills. A concrete driveway runs along the east of the property to the rear where there is a side gable roof garage.
670	4800 Leslie Street			1925c.	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 4229 Leslie Street is two-stories and topped with a side gable asphalt shingle roof. A brick chimney is located at the eave on the east façade of the house. The facade is clad in stone veneer on the first floor and wide metal siding on the second floor. The primary entrance is centered on the facade, and is accessed by a low concrete stoop. The door is framed with a wood surround including pilasters, and sidelights. Windows are arranged symmetrically each framed by shutters painted blue. Similar windows exist on other elevations. A driveway runs along the east of the house to the rear where there is a pyramidal roof garage.
671	4814 Leslie Street			1932	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4814 Leslie Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by a front gable above the façade, and a hipped roof dormer facing east. A brick chimney is located at the eave on the west façade of the house. The exterior is clad in red and brown brick veneer laid in a running bond pattern, with areas of stone veneer stone accents. The entrance is centered on the façade, trimmed in stone, and accessed by a concrete porch with a metal railing. West of the entrance is a two-story canted bay clad in stone veneer with casement windows on the first floor and hung windows on the second floor. Similar windows are arranged on other elevations, and all windows have brick sills. A concrete driveway runs along the east of the property to the rear where there is a pyramidal roof garage.
672	12617 Old Mill Place			1928	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 12617 Old Mill Place is two-stories and topped with a hipped asphalt shingle roof that meets a deck, flat on hipped roof at the rear, and is intersected by a prominent front gable. A large brick chimney is near the center of the façade and another is located at the eave on the north facade of the house. The facade is clad in light and dark brown brick veneer laid in a running bond pattern with decorative brickwork and accents of stone. The primary entrance is recessed near the north corner of the façade within an arched, carved stone surround, and is accessed by a brick and concrete porch. South of the entrance, on either side of the chimney is a steel casement window with transom. Similar windows are found across the facade and on other elevations, and windows have brick sills. The front gable extends into a catslide that extends off the north corner into a drive-through flat arch supported by a brick pier above a concrete ribbon driveway runs along the north of the house leading to the rear where there is a side gable roof garage. A black lightpost with a globe light fixture is in the front lawn.
673	12629 Old Mill Place			1931	French Eclectic	1/garage	C	Unknown	Unknown	The house at 12629 Old Mill Place is two-stories and topped with a deck, flat on hipped asphalt shingle roof that meets a hipped roof wing with an eyebrow dormer projecting off the front façade, another hipped roof towards the rear, shed dormers facing north and south, and an engaged round tower capped with a conical roof at the center of the façade. A large brick chimney is at the eave on the south facade of the house. The facade is clad in light and dark brown brick veneer laid in a running bond pattern with decorative brickwork and accents of stone. The primary entrance is within the tower on the center of the façade within an arched stone surround, and is accessed by a brick and concrete porch. South of the entrance is a one-story canted bay clad in stone veneer and topped with a metal roof with flared eaves. The bay is glazed with hung vinyl windows. North of the entrance are three wood hung windows with leaded glass detailing and aluminum storms beneath a cast stone lintel. Similar windows are found across the facade and on other elevations, and windows have cast stone sills. An asphalt shingled overhang supported by a brick pier extends off the north corner into a drive-through flat arch above a concrete driveway that runs along the north of the house leading to the rear where there is a pyramidal roof garage.
674	12651 Old Mill Place	Broadside Press	12651 Old Mill Place	1927	Modern Movement	n/a	C	possibly Nathan Johnson	Unknown	The house at 12651 Old Mill Place is clad in red brick and is split into two stories tall and one-story with a raised basement. The roof is a low-pitched hipped and clad in asphalt shingles. A large brick chimney is at the eave centered on the north façade. The facade is clad with red brick veneer laid in a running bond pattern, divided vertically by spandrel panels consisting of painted wood siding that runs between windows on the first and second floor. The entrance is centered on the façade beneath an overhang supported by metal posts and accessed by a low concrete and brick porch. Windows across all facades are vinyl sliders with cast stone sills. There is a concrete driveway accessed from Leslie Street to the north of the house leading to the rear where there is no garage.
675	3728 Sturtevant Street			1925c.	Tudor Revival	n/a	C	Unknown	Unknown	The house at 3728 Sturtevant Street is two-stories and topped with a deck (flat on hipped) asphalt shingle roof intersected by a large front gable on the facade and a hipped roof dormer above the east facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer and decorative brickwork. The primary entrance is near the east corner of the facade set within a gable portico supported by brick piers, which accesses a brick and concrete porch with a brick kneewall. A series of wood leaded glass windows and three of the same types of windows are on the second floor. Windows have brick sills and are fitted with storms. Similar windows are arranged on other elevations. A concrete alley runs along the east side of the property. There is no garage.
676	3734 Sturtevant Street			1927	Italian Renaissance	1/garage	C	Unknown	Unknown	The house at 3734 Sturtevant Street is two-stories and topped with a hipped asphalt shingle roof intersected by a hipped roof on the facade and a hipped roof dormer above the east facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in brown brick veneer laid in a running bond pattern. The primary entrance is near the center of the facade and is accessed by a brick and concrete porch with low metal railings, sheltered by an arched loggia with a balcony above. A series of leaded glass windows are west of the entrance and a pair are east of the entrance. Two pairs of the same windows are arranged on the second floor and one pair is accented by a metal balcony. Windows have stone sills and are fitted with storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property. A hipped roof garage is at the rear of the property. A grey lightpost with a globe light fixture is in the front lawn.
677	3737 Sturtevant Street			1937	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3737 Sturtevant Street is two-stories and topped with a hipped asphalt shingle roof intersected by two front gables on the facade. A stone kneewall extends outward from the west corner of the facade. A large brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with copious accents of stone veneer, decorative brickwork, and bargeboard. The primary entrance is trimmed in stone near the center of the facade and is accessed a brick and concrete porch with a low metal railing. A bay west of the entrance contains steel leaded glass windows and another steel leaded glass window is east of the entrance. A steel arched window and vinyl windows are on the second floor. Windows have stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property. A pyramidal roof garage is at the rear of the property.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
678	3742 Sturtevant Street			1936	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3742 Sturtevant Street is two-stories and topped with a hipped asphalt shingle roof intersected by hipped roof two-story bay with a front gable on the facade. A stone kneewall extends outward from the west corner of the facade. A large brick chimney is at the eave near the front of the west facade. The exterior is clad in brown brick veneer laid in a running bond pattern with accents of cast stone, decorative brickwork, and wood false half-timbering. The primary entrance is arched, trimmed in stone, near the center of the facade, and is accessed a brick and concrete porch with a brick kneewall and a metal awning structure. The first floor of the bay is canted and contains steel leaded glass windows, and another steel leaded glass window is east of the entrance. Three steel windows are on the second floor. Windows have stone or wood sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property. A hipped roof garage is at the rear of the property.
679	3743 Sturtevant Street			1960	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 3743 Sturtevant Street is two-stories and topped with a side gable, asphalt shingle roof intersected by a small gable. A brick chimney is located at the eave near the center of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern except for the overhanging second floor facade which is clad in white aluminum siding. The primary entrance surrounded by white trim is near the east corner of the facade and is accessed by a brick and concrete stoop. A vinyl slider window with brown shutters and a cast stone sill is east of the entrance, and two vinyl windows with brown shutters are on the second floor. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. A hipped roof garage is at the rear of the property.
680	3750 Sturtevant Street			1936	French Eclectic	1/garage	C	Unknown	Unknown	The house at 3750 Sturtevant Street is two-stories and topped with a hipped asphalt shingle roof intersected by hipped roof with hipped roof wall dormer on the facade and an engaged circular turret capped with a conical roof at the center of the facade. A stone kneewall extends outward from the west corner of the facade. A large brick chimney is at the eave near the front of the west facade. The exterior is clad in brown brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is arched, trimmed in stone, set within the turret, and is accessed a brick and concrete porch with a brick kneewall and a metal awning structure. A canted bay is west of the entrance and contains steel windows, another steel window is east of the entrance, and three steel windows are on the second floor. Windows have stone sills and are fitted with storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property. A hipped roof garage is at the rear of the property.
681	3751 Sturtevant Street			1929	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3751 Sturtevant Street is two-stories and topped with a side gable asphalt shingle roof intersected by two large front gables on the facade. A large brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer and decorative brickwork. The primary entrance is near the east corner of the facade beneath a catslide vestibule, the east eave of which extends over the driveway. The entrance is arched and trimmed with brick and stone, framed on either side with leaded glass windows, and accessed by a brick and concrete porch with a low metal railing and a metal awning structure. A series of wood leaded glass windows are west of the entrance and a series of the same windows are on the second floor and have a fabric awning. Windows have brick sills and are fitted with storms. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. A hipped roof garage is at the rear of the property. A black lightpost without a light fixture is in the front lawn.
682	3761 Sturtevant Street			1929	French Eclectic	1/garage	C	Unknown	Edward J. Mason	The house at 3761 Sturtevant Street is two-stories and topped with a side gable asphalt shingle roof. A stone buttress extends outward from the west corner of the facade. A large brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer and klinker bricks. The primary entrance is near the east corner of the facade within an engaged polygonal turret topped with a polygonal roof, accessed by a brick and concrete full-width terrace with a short metal railing and a metal awning structure. Wood Leaded glass windows are arranged on the turret and a series of the same windows are west of the entrance beneath a canted oriel window with vinyl windows on the second floor. Windows have brick sills. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. A hipped roof garage is at the rear of the property. A black lightpost with a globe light fixture is in the front lawn.
683	3766 Sturtevant Street			1927	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3766 Sturtevant Street is two-and-a-half stories and topped with a deck (flat on hipped) asphalt shingle roof intersected by a large front gable and arched dormer on the facade and dormers on the other facades. A brick buttress extends outward from the west corner of the facade. A large brick chimney is at the eave near the front of the west facade. The exterior is clad in brown brick veneer laid in a running bond pattern with accents of stone veneer and decorative brickwork. The primary entrance is arched, trimmed in brick, and near the center of the facade within a gabled vestibule accessed by a brick and concrete porch with a brick kneewall and a metal awning structure. Wood leaded glass windows are arranged on either side of the entrance and on the upper stories. Windows have brick sills. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. A hipped roof garage is at the rear of the property. A black lightpost with a globe light fixture is in the front lawn.
684	3774 Sturtevant Street			1926	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3774 Sturtevant Street is two-stories and topped with a deck (flat on hipped) asphalt shingle roof intersected by a large front gable and eyebrow dormer on the facade and dormers on the other facades. A brick buttress extends outward from the west corner of the facade. A large brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer and decorative brickwork. The primary entrance is arched, trimmed in brick, and near the east corner of the facade within a gabled portico supported by brick piers which accesses by a brick and concrete porch with a brick kneewall and an aluminum awning. Four wood leaded glass windows are west of the entrance and two pairs are on the upper stories. Windows have brick sills and are fitted with storms. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. A pyramidal roof garage is at the rear of the property. A black lightpost without a light fixture is in the front lawn.
685	3777 Sturtevant Street			1936	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3777 Sturtevant Street is two-stories and topped with a hipped asphalt shingle roof intersected by hipped roof two-story bay with a front gable and a gable wall dormer on the facade. A stone kneewall extends outward from the west corner of the facade. A large brick chimney is at the eave near the front of the west facade. The exterior is clad in brown brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is arched, trimmed in stone, near the center of the facade, and is accessed a brick and concrete porch with a brick kneewall and a metal awning structure. The first floor of the bay is canted and contains steel leaded glass windows, and another steel leaded glass window is east of the entrance. Three steel windows are on the second floor. Windows have stone sills and are fitted with storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property. A hipped roof garage is at the rear of the property.
686	3784 Sturtevant Street			1928	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3784 Sturtevant Street is two-stories and topped with a side gable asphalt shingle roof intersected by a large gable above the facade. A large brick chimney is at the eave near the center of the west facade. The exterior is clad in brown brick veneer laid in a running bond pattern with accents of decorative brickwork. The primary entrance is near the east corner of the facade within a curved jerkinghead vestibule, and is accessed by a brick and concrete porch with a low metal railing. A series of four wood windows are west of the entrance beneath a series of three of the same windows above on the second floor. A small arched window with a metal railing is in the gable end. Windows have brick sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property. A side gable roof garage is at the rear of the property.
687	3790 Sturtevant Street			1926	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3790 Sturtevant Street is two-stories and topped with a deck (flared hip topped with flat) asphalt shingle roof intersected by a large gable above the facade and hipped and gable roof dormers. A brick buttress extends outward from the west corner of the facade. A large brick chimney is at the eave near the front of the west facade. The exterior is clad in brown brick veneer laid in a running bond pattern with accents of stone veneer and decorative brickwork. The primary entrance is trimmed in stone veneer and brick near the east corner of the facade within a gabled vestibule, and is accessed by a brick and concrete porch with a low metal railing. Four leaded glass windows are west of the entrance beneath a segmental arch and three of the same windows are on the second floor. Windows have brick sills and some are fitted with storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property. A front gable roof garage is at the rear of the property.
688	3793 Sturtevant Street			1927	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3793 Sturtevant Street is two-stories and topped with a deck (hipped topped with flat) asphalt shingle roof intersected by a large front gable and a gabled roof dormer on the facade and shed and hipped dormers above other facades. A brick buttress extends outward from the west corner of the facade. A large brick chimney is at the eave near the front of the west facade. The exterior is clad in brown brick veneer laid in a running bond pattern with accents of stone veneer and decorative brickwork. The primary entrance is arched and trimmed in brick with stone near the center of the facade, set within a jerkinhead vestibule, and is accessed by a brick and concrete porch with a brick kneewall and a metal awning structure. A partial bay west of the entrance contains wood leaded glass windows and a pair of the same windows are east of the entrance. A series of three and a pair of wood windows are on the second floor, and a small window is in the gable end. Windows have brick sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property. A hipped roof garage is at the rear of the property.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
689	3800 Sturtevant Street			1927	Tudor Revival	n/a	C	Unknown	Unknown	The house at 3800 Sturtevant Street is two-stories and topped with a deck (hipped topped with flat) asphalt shingle roof intersected by a large front gable and a gabled roof dormer on the facade and shed and hipped dormers above other facades. A brick buttress extends outward from the west corner of the facade. A large chimney covered in ivy is at the eave near the front of the west facade. The exterior is clad in brown brick veneer laid in a running bond pattern with accents of stone veneer and decorative brickwork. The primary entrance is arched and trimmed in brick with stone near the center of the facade, set within a gabled vestibule, and is accessed by a brick and concrete porch with a brick kneewall and a metal awning structure. A series of wood leaded glass windows are west of the entrance and a pair of the same windows are east of the entrance. A series of three and a pair of wood windows are on the second floor, and a small window is in the gable end. Windows have brick sills and some are fitted with storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property. There is no garage.
690	3801 Sturtevant Street			1941	Tudor Revival	n/a	C	Unknown	Unknown	The house at 3801 Sturtevant Street is two-stories and topped with a hipped asphalt shingle roof intersected on the west half of the facade by a two-story bay with a gable roof. A large chimney covered in ivy is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of cast stone and decorative brickwork. The primary entrance is trimmed in stone near the east corner of the facade and is accessed by a brick and concrete porch with a metal railing, a metal awning structure, and a metal ramp. The first floor of the bay is canted and contains vinyl windows and a glass block is east of the entrance. A steel and a vinyl window are on the second floor. Windows have stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property. There is no garage. A black lightpost with a globe light fixture is in the front lawn.
691	3809 Sturtevant Street			1937	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3809 Sturtevant Street is two-stories and topped with a hipped asphalt shingle roof intersected by a gable wall dormer and a hipped roof two-story bay with a front gable on the west half of the facade. A stone kneewall extends outward from the west corner of the facade. A large brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of cast stone, wood false half-timbering, decorative brickwork, and bargeboard. The primary entrance is arched, trimmed in stone, near the center of the facade, and is accessed a brick and concrete porch with a brick kneewall and a metal awning structure. The first floor of the bay is canted and contains steel leaded glass windows and another steel leaded glass window is east of the entrance. Three steel windows and two vinyl windows are on the second floor. Windows have stone sills and some are fitted with storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property. A hipped roof garage is at the rear of the property.
692	3816 Sturtevant Street			1933	French Eclectic	1/garage	C	Unknown	Unknown	The house at 3816 Sturtevant Street is two-stories and topped with a hipped asphalt shingle roof intersected by hipped roof with a gabled wall dormer on the facade and an engaged polygonal turret capped with a polygonal roof near the center of the facade. A stone buttress extends outward from the west corner of the facade. A large brick chimney is at the eave near the front of the west facade. The exterior is clad in brown brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is arched, trimmed in stone which has been painted, set within the turret, and is accessed a brick, stone, and concrete porch with a brick kneewall. A one-story canted bay is west of the entrance and contains steel windows, another steel window is east of the entrance beneath a flared roof, and three steel windows are on the second floor. Windows have stone sills and are fitted with storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property. A hipped roof garage is at the rear of the property.
693	3817 Sturtevant Street			1936	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3817 Sturtevant Street is two-stories and topped with a hipped asphalt shingle roof intersected by two front gables on the facade. A large brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with copious accents of cast stone, decorative brickwork, and wood false half-timbering. The primary entrance is trimmed in stone near the east corner of the facade and is accessed a brick and concrete porch with a brick kneewall. A single-story bay west of the entrance contains steel windows and another steel window is east of the entrance. Two steel windows are on the second floor. Windows have stone or wood sills and some are fitted with storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property. A hipped roof garage is at the rear of the property. A black lightpost with a globe light fixture is in the front lawn.
694	3824 Sturtevant Street			1927	Tudor Revival	n/a	C	Unknown	Unknown	The house at 3824 Sturtevant Street is two-stories and topped with a deck (hipped topped with flat) asphalt shingle roof intersected by a large front jerkinhead and a jerkinhead roof dormer on the facade and shed and hipped dormers above other facades. A brick wall extends outward from the west corner of the facade. A large chimney is at the eave near the front of the west facade. The exterior is clad in brown brick veneer laid in a running bond pattern with accents of stone veneer and decorative brickwork. The primary entrance is arched and trimmed in brick with stone near the center of the facade, set within a jerkinhead vestibule, and is accessed by a brick and concrete porch with a brick kneewall. A series of vinyl windows are west of the entrance and one vinyl window is east of the entrance. A series of three and a pair of vinyl windows are on the second floor, and a small louvered opening is in the gable end. Windows have brick sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property. There is no garage.
695	3825 Sturtevant Street			1937	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3825 Sturtevant Street is two-stories and topped with a hipped asphalt shingle roof intersected by two two-story bays topped with a front gable and a hipped-with-gable roof. A stone wall extends outward from the west corner of the facade. A large brick chimney is at the eave near the front of the west facade. The exterior is clad in brown brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is arched and trimmed in stone near the center of the facade, set within the hipped roof bay, and is accessed by a brick and concrete porch with a brick and concrete kneewall. A single-story canted bay is west of the entrance and contains wood leaded glass windows and a steel window is east of the entrance. Three steel windows are on the second floor. Windows have stone sills and are fitted with storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property. A hipped roof garage is at the rear of the property.
696	3832 Sturtevant Street			1947	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 3832 Sturtevant Street is two-stories and topped with a hipped asphalt shingle roof intersected by a small gable above the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of cast stone. The primary entrance is near the east corner of the facade and is accessed by a brick and concrete porch beneath a fabric awning. A single-story canted bay is west of the entrance and appears to contain wood windows, but foliage obscures the bay. Two wood multi-light windows framed by black shutters are on the second floor. Windows have stone sills and are fitted with storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property. A hipped roof garage is at the rear of the property.
697	3833 Sturtevant Street			1935	Tudor Revival	n/a	C	Unknown	Unknown	The house at 3833 Sturtevant Street is two-stories and topped with a hipped asphalt shingle roof intersected by a gable wall dormer and a hipped roof two-story bay with a front gable on the west half of the facade. A stone kneewall extends outward from the west corner of the facade. A large brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of cast stone, wood false half-timbering, and decorative brickwork. The primary entrance is arched, trimmed in painted stone, near the center of the facade, and is accessed a brick and concrete porch with a brick kneewall and a metal awning structure. The first floor of the bay is canted and contains steel leaded glass windows and another steel window is east of the entrance. Three steel windows are on the second floor. Windows have stone and wood sills and are fitted with storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property. There is no garage. A brown lightpost with a globe light fixture is in the front lawn.
698	3840 Sturtevant Street			1935	French Eclectic	1/garage	C	Unknown	Unknown	The house at 3840 Sturtevant Street is two-stories and topped with a hipped asphalt shingle roof intersected by a hipped wall dormer and a hipped roof two-story bay with a hipped wall dormer gable on the east half of the facade. A brick buttress extends outward from the west corner of the facade and a brick arch extends from the east corner. A large brick chimney is at the eave near the front of the west facade. The exterior is clad in brown and orange brick veneer laid in a running bond pattern with accents of decorative brickwork. The primary entrance is arched, trimmed in brick, near the center of the facade, and is accessed a brick and concrete porch with a metal railing. A single-story bay with vinyl windows is west of the entrance, a vinyl window is east of the entrance, and two vinyl windows are on the second floor beneath the dormers. Windows have brick sills. Similar windows are arranged on other elevations. A concrete driveway runs along the rear of the property to a pyramidal roof garage.
699	3841 Sturtevant Street			1948	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 3841 Sturtevant Street is two-stories and topped with a hipped asphalt shingle roof. A brick chimney is at the eave near the front of the east facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer and cast stone. The primary entrance is trimmed in stone near the center of the facade and is accessed by a brick and concrete porch with a metal railing. A shed roof supported by white posts covers the porch. A single-story canted bay is west of the entrance and contains vinyl windows, a vinyl window is east of the entrance, and two vinyl windows are on the second floor. Windows have stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the rear of the property to a pyramidal roof garage.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
700	4000 Sturtevant Street			1949	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 4000 Sturtevant Street is two-stories and topped with a side gable asphalt shingle roof intersected by a front gable bay on the west half of the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern except for portions of the second floor which are clad in vinyl siding. The primary entrance is near the center of the facade and is accessed by a brick and concrete porch covered by a shed roof supported by white posts. A vinyl window is on either side of the entrance and two vinyl windows are on the second floor. Windows have stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the rear of the property to a pyramidal roof garage.
701	4003 Sturtevant Street			1939	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4003 Sturtevant Street is two-stories and topped with a hipped asphalt shingle roof intersected by a gable wall dormer and a gabled two-story bay on the west half of the facade. A stone buttress extends outward from the west corner of the facade. A large brick chimney is at the eave near the front of the east facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is arched, trimmed in stone, set within the bay, and is accessed by a brick and concrete porch with a metal railing. A single-story canted bay with wood windows and a small arched window are west of the entrance. Three wood windows are on the second floor. Windows have stone sills and are fitted with storms. Similar windows are arranged on other elevations. A concrete driveway runs along the rear of the property to a hipped roof garage.
702	4014 Sturtevant Street			1935	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4014 Sturtevant Street is two-stories and topped with a hipped asphalt shingle roof intersected by two two-story bays topped with hipped-with-gable roofs. A stone buttress extends from the west corner of the facade. A brick chimney is near the rear of the house. The exterior is clad in brown brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is arched and trimmed in stone near the center of the facade, set within a hipped roof bay, and is accessed by a partially demolished brick and concrete porch with a brick and concrete kneewall and a metal awning structure. A single-story canted bay is west of the entrance and contains leaded glass windows and two windows are east of the entrance. Three steel windows are on the second floor. Windows have stone sills and are fitted with storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property to a pyramidal roof garage at the rear.
703	4015 Sturtevant Street			1936	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4015 Sturtevant Street is two-stories and topped with a hipped asphalt shingle roof intersected by a hipped roof two-story bay with a front gable on the west half of the facade. A stone kneewall extends outward from the west corner of the facade. A large brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of cast stone, wood false half-timbering, and decorative brickwork. The primary entrance is topped with a Tudor arch, trimmed in stone, near the center of the facade, and is accessed by a brick and concrete porch with a brick kneewall. The first floor of the bay is canted and contains leaded glass windows and another steel window is east of the entrance. Five steel windows are on the second floor. Windows have stone or wood sills and are fitted with storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property to a hipped roof garage at the rear.
704	4020 Sturtevant Street			1936	Tudor Revival	1/garage	C	Unknown	Max Schwartz	The house at 4020 Sturtevant Street is two-stories and topped with a hipped asphalt shingle roof intersected by two two-story bays topped with front gable roofs. A stone buttress extends from the west corner of the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in brown brick veneer laid in a running bond pattern with accents of stone veneer, and cast stone. The primary entrance is arched and trimmed in stone near the center of the facade, set within a front gable roof bay, and is accessed by a brick, stone, and concrete porch with a brick and kneewall and a metal awning structure. A single-story canted bay is west of the entrance and contains leaded glass windows and two windows are east of the entrance. Three steel windows are on the second floor and an arched window is in one gable end. Windows have stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property to a pyramidal roof garage at the rear.
705	4021 Sturtevant Street			1936	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4021 Sturtevant Street is two-stories and topped with a pyramidal asphalt shingle roof intersected by two front gables on the facade. A stone and brick kneewall extends from the west corner of the facade. A brick chimney is near the rear facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is arched, trimmed in stone, near the east corner of the facade, and is accessed by a brick and concrete porch with a brick kneewall and a metal awning structure. A single-story canted bay west of the entrance contains steel windows and another steel window is east of the entrance. Two steel windows are on the second floor. Windows have stone sills and are fitted with storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property but there is no garage.
706	4027 Sturtevant Street			1935c.	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4027 Sturtevant Street is two-stories and topped with a pyramidal asphalt shingle roof intersected by two front gables on the facade. A stone and brick kneewall extends from the west corner of the facade. A brick chimney is near the rear facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, decorative brickwork, and wood false half-timbering. The primary entrance is arched, trimmed in stone, near the east corner of the facade, and is accessed by a brick and concrete porch with a brick kneewall and an aluminum awning. A single-story canted bay west of the entrance contains steel windows and another steel window is east of the entrance. Two steel windows are on the second floor. Windows have stone or wood sills and are fitted with storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property to a hipped roof garage.
707	4030 Sturtevant Street			1937	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4030 Sturtevant Street is two-stories and topped with a hipped asphalt shingle roof intersected by a front gable bay and an engaged circular tower on the facade and hipped roofs on other facades. A stone buttress extends from the west corner of the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is arched and trimmed in stone near the center of the facade, set within the tower, and is accessed by a brick and concrete porch with a brick and kneewall and a metal awning structure. A single-story canted bay is west of the entrance and contains leaded glass windows and two of the same types of windows are east of the entrance. Three sets of the same windows are on the second floor and an arched window is in the gable end. Windows have stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property to a hipped roof garage at the rear.
708	4034 Sturtevant Street			1936	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4034 Sturtevant Street is two-stories and topped with a hipped asphalt shingle roof intersected by two two-story bays topped with hipped-with-gable roofs. A stone buttress extends from the west corner of the facade. A brick chimney is near the front of the west facade. The exterior is clad in brown brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, decorative brickwork, wood false half-timbering, and bargeboard. The primary entrance is arched and trimmed in stone near the center of the facade, set within a hipped roof bay, and is accessed by a partially demolished stone and concrete porch with a stone kneewall and a metal awning structure. The first floor of the west bay is canted bay and contains leaded glass windows and two of the same windows are east of the entrance. Three steel windows are on the second floor. Windows have stone sills and some are fitted with storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property to a hipped roof garage at the rear.
709	4037 Sturtevant Street			1938	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4037 Sturtevant Street is two-stories and topped with a hipped asphalt shingle roof intersected by two gables above the facade. A stone buttress extends from the west corner of the facade. A large brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is arched, trimmed in stone, placed near the center of the facade, and accessed by a brick and concrete porch with a brick kneewall. A single-story canted bay is west of entrance and contains steel windows and a steel window is east of the entrance. Two steel windows are on the second floor. Windows have stone sills. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house to a hipped roof garage at the rear.
710	4044 Sturtevant Street			1936	French Eclectic	n/a	C	Unknown	Ginn Building Company	The house at 4044 Sturtevant Street is two-stories and topped with a hipped asphalt shingle roof intersected by a large hipped bay on the facade. A brick chimney is at the eave on the rear facade. The exterior is clad in red brick veneer laid in a running bond pattern, the first floor of the facade is clad in stone veneer, and there accents of cast stone. The primary entrance is arched, trimmed in stone, placed near the center of the facade, and accessed by a stone and concrete porch with a stone kneewall. A single-story canted bay is west of entrance and contains steel windows and a steel window is east of the entrance. Three steel windows are on the second floor. Windows have stone sills and are fitted with storms. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house but there is no garage. A black lightpost with a lantern style fixture is in the front lawn.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
711	4045 Sturtevant Street			1936	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4045 Sturtevant Street is two-stories and topped with a hipped asphalt shingle roof intersected by two two-story bays topped with gable roofs. A stone buttress extends from the west corner of the facade. A brick chimney is at the eave on the rear facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, decorative brickwork, and wood false half-timbering. The primary entrance is arched and trimmed in stone near the center of the facade within a gable roof bay, and is accessed by a brick and concrete porch with a brick kneewall and a metal awning structure. The single-story canted bay contains steel windows west of the entrance and two of the same windows are east of the entrance. Three steel windows are on the second floor. Windows have stone or wood sills and some are fitted with storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property to a hipped roof garage at the rear.
712	4052 Sturtevant Street			1939	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4052 Sturtevant Street is two-stories and topped with a hipped asphalt shingle roof intersected by two gables above the facade. A stone buttress extends from the west corner of the facade. A large brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is arched, trimmed in stone, placed near the center of the facade, and accessed by a brick and concrete porch with a brick kneewall. A single-story canted bay is west of entrance and contains steel windows and a steel window is east of the entrance. Two steel windows are on the second floor and an arched window is in the gable end. Window have stone sills and some are fitted with storms. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house to a hipped roof garage at the rear.
713	4053 Sturtevant Street			1935c.	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4053 Sturtevant Street is two-stories and topped with a hipped asphalt shingle roof intersected by two two-story bays topped with hipped roofs and dormers. A stone buttress extends from the west corner of the facade. A brick chimney is near the front of the west facade. The exterior is clad in red and orange brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, decorative brickwork, and wood false half-timbering. The primary entrance is trimmed in stone near the center of the facade, set within a hipped roof bay, and is accessed by a concrete porch. The first floor of the west bay is canted and contains leaded glass windows and a wood and vinyl window are east of the entrance. One steel and two vinyl windows are on the second floor. Windows have stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property to a hipped roof garage at the rear.
714	4060 Sturtevant Street			1939	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4060 Sturtevant Street is two-stories and topped with a hipped asphalt shingle roof intersected by two two-story bays topped with hipped roofs and gabled dormers. A stone buttress extends from the west corner of the facade. A brick chimney is near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, decorative brickwork, and wood false half-timbering. The primary entrance is arched, trimmed in stone near the center of the facade, set within a hipped roof bay, and is accessed by a stone and concrete porch with a stone kneewall. The first floor of the west bay is canted and contains leaded glass windows and a steel window is east of the entrance. Three steel windows are on the second floor. Windows have stone sills and storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property to a hipped roof garage at the rear.
715	4061 Sturtevant Street			1935	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4061 Sturtevant Street is two-stories and topped with a hipped asphalt shingle roof intersected by a hipped dormer and two two-story bays topped with hipped roofs and gabled dormers. A stone buttress extends from the west corner of the facade. A brick chimney is near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is arched, trimmed in stone, near the center of the facade within a hipped roof bay, and is accessed by a brick and concrete porch with a brick kneewall. A single-story canted bay with leaded glass windows is west of the entrance and a steel and window are east of the entrance. Three steel windows are on the second floor. Windows have stone sills and storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property to a hipped roof garage at the rear.
716	4068 Sturtevant Street			1935c.	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4068 Sturtevant Street is two-stories and topped with a hipped asphalt shingle roof intersected by a gable and a hipped-with-gable wall dormer above the facade and hipped dormers above other facades. A stone buttress wall extends from the west corner of the facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is trimmed in stone near the east corner of the facade and is accessed by a brick and concrete porch with a metal railing and an aluminum awning. A one-story canted bay with steel windows is west of the entrance and two vinyl windows are on the second floor. Windows have stone sills and some have storms. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house to a pyramidal roof garage at the rear.
717	4069 Sturtevant Street			1935	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4069 Sturtevant Street is two-stories and topped with a pyramidal asphalt shingle roof intersected by two front gables on the facade. A stone and brick kneewall extends from the west corner of the facade. A brick chimney is near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, decorative brickwork, and wood false half-timbering. The primary entrance is arched, trimmed in stone, near the east corner of the facade, and is accessed a brick and concrete porch with a brick kneewall. A single-story canted bay west of the entrance contains steel windows and another window is east of the entrance. Two steel windows are on the second floor. Windows have stone or wood sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property to a pyramidal roof garage. A black lightpost with a globe light fixture is in the front lawn.
718	4076 Sturtevant Street			1935	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4076 Sturtevant Street is two-stories and topped with a hipped asphalt shingle roof intersected by a two-story hipped bay on the facade. A brick buttress extends from the west corner of the facade. A brick chimney is near the center of the house. The exterior is clad in red brick veneer laid in a running bond pattern with accents of cast stone painted white, decorative brickwork, and wood false half-timbering. The primary entrance is trimmed in stone, placed near the east corner of the facade, and accessed by a concrete porch with a low metal railing and a metal awning structure. The first floor of the bay is canted and contains vinyl windows three vinyl windows are on the second floor. Window have stone or wood sills. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house to a pyramidal roof garage at the rear.
719	4077 Sturtevant Street			1936	French Eclectic	n/a	C	Unknown	Spoon Brothers	The house at 4077 Sturtevant Street is two-stories and topped with a hipped asphalt shingle roof intersected by two two-story bays topped with hipped roofs and gabled dormers. A stone buttress extends from the west corner of the facade. A brick chimney is near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, decorative brickwork, and wood false half-timbering. The primary entrance is arched, trimmed in stone near the center of the facade, set within a hipped roof bay, and is accessed by a stone and concrete porch with a stone kneewall. The first floor of the west bay is canted and contains leaded glass windows and two steel windows are east of the entrance. Three steel windows are on the second floor. Windows have stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house but there is no garage.
720	4085 Sturtevant Street			1936	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4085 Sturtevant Street is two-stories and topped with a hipped asphalt shingle roof intersected by a hipped bay and an engaged circular tower on the facade. A stone buttress extends from the west corner of the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is arched and trimmed in stone near the center of the facade, set within the tower, and is accessed by a brick and concrete porch with a low metal railing. A single-story canted bay is west of the entrance and contains leaded glass windows and two of the same types of windows are on either side of the entrance. Three windows are on the second floor. Windows have stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property to a hipped roof garage at the rear.
721	4086 Sturtevant Street			1936	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4086 Sturtevant Street is two-stories and topped with a hipped asphalt shingle roof intersected by two two-story bays topped with hipped and gabled roofs. A stone buttress extends from the west corner of the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in brown brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is arched, trimmed in stone near the center of the facade, set within a gabled bay, and is accessed by a brick, stone, and concrete porch with a brick kneewall and a metal awning structure. A single-story canted bay with steel windows is west of the entrance and two windows are east of the entrance. Three steel windows are on the second floor and an arched window is in a gabled dormer. Windows have stone sills and some have storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property to a hipped roof garage at the rear. A black lightpost with a lantern-style fixture is in the front lawn.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
722	4092 Sturtevant Street			1941	Streamline Moderne	1/garage	C	Unknown	Unknown	The house at 4092 Sturtevant Street is two-stories and topped with a hipped asphalt shingle roof intersected by multiple hips. A brick chimney is near the front of the east facade. The exterior is clad in light brown brick veneer laid in a running bond pattern with horizontal banded brick accents. The primary entrance is near the center of the facade accessed by a concrete porch topped with a flat roof supported by a metal post. A two-story curved bay with steel and glass block windows on the first and second floor is east of the entrance, two steel windows are west of the entrance on the first and second floor, and a ribbon of steel windows wraps around the southwest corner of the facade on the first and second floors. Windows have stone sills and storms. Similar windows are arranged on other elevations. A concrete driveway runs along the rear of the property to a pyramidal roof garage.
723	4093 Sturtevant Street			1949	Georgian Revival	1/garage	C	Unknown	Unknown	The house at 4093 Sturtevant Street is two-stories and topped with a deck (flat on hipped) asphalt shingle roof. A brick chimney is at the eave near the center of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of cast stone and decorative brickwork. The primary entrance is at the center of the facade, surrounded by a wood frontispiece, and accessed by a brick and concrete porch. Vinyl windows are on either side of the entrance and five vinyl windows are on the second floor. Windows have stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the rear of the property to a hipped roof garage.
724	4202 Sturtevant Street			1925	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 4202 Sturtevant Street is two-stories and topped with a side gable asphalt shingle roof intersected by a front gable bay on the west half of the façade, with shed roof dormers above the front and rear facades. A brick chimney is at the peak of the eave on the east facade. The exterior is clad in red brick veneer laid in a running bond pattern except for beneath the front and side gables at the attic level which are clad in vinyl siding. The primary entrance is near the center of the facade and is accessed by a concrete stoop covered by a pedimented overhang roof supported by brackets. A vinyl slider window is on either side of the entrance, each topped with a splayed brick lintel, and two vinyl slider windows are on the second floor. Windows have brick sills. Similar windows are arranged on other elevations. A concrete driveway is accessed off of Petoskey Avenue to the east leading to a pyramidal roof garage at the rear of the property.
725	4203 Sturtevant Street			1924	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4203 Sturtevant Street is two-stories and topped with a cross gable asphalt shingle roof, composed of a steeply pitched side gable intersected by a front gable, with shed roof dormers above the front and rear facades. A brick chimney is at the peak of the eave on the east facade. The exterior is clad in brown brick veneer laid in a running bond pattern, with false half-timbering infilled with decorative brickwork beneath the front gable and the shed dormers are clad in a wide metal or vinyl siding. The primary entrance is near the west corner of the façade, trimmed in stone between two small fixed windows and is accessed by a concrete step. A ribbon of four vinyl hung windows with divided upper sashes framed by white shutters is east of the entrance topped with a brick lintel, beneath a matching set on the second floor. Windows have brick sills. Similar windows are arranged on other elevations. A concrete driveway is accessed off of Petoskey Avenue to the east leading to a side gable roof garage at the rear of the property.
726	4211 Sturtevant Street			1925	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4211 Sturtevant Street is two-stories and topped with a deck, flat on pyramidal asphalt shingle roof intersected by a front gable and a front gabled roof dormer, and a jerkinhead roof above a slightly projecting entrance vestibule. A tall brick chimney is located at the eave on the west facade of the house. The facade is clad in dark and light brown brick veneer laid in a running bond pattern with accents of stone. The primary entrance is located slightly off-center of the façade and the arched door is accessed by a brick and concrete porch. West of the entrance is a bay window glazed in vinyl hung windows. Similar windows are found across the facade and on other elevations, and windows have brick sills. A concrete driveway runs along the east of the house leading to the rear where it is unknown if there is a garage.
727	4212 Sturtevant Street			1926	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4212 Sturtevant Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof intersected by a front gable, and hipped roof dormers on the west and rear. A brick chimney is located at the eave on the west facade of the house. The exterior is clad in reddish brown brick veneer laid in a unique alternating triple-stacked and header bond pattern with decorative brickwork. The primary entrance is near the east corner of the facade within a front gabled vestibule and the arched door is covered by an aluminum metal awning. The entrance is accessed by a brick and concrete full-width porch. West of the entrance is a large vinyl window, covered by an aluminum awning. Similar windows are found at the second floor and across the other elevations, and windows have brick sills. There is a concrete driveway to the east of the house leading to the rear where there is a pyramidal roof garage.
728	4220 Sturtevant Street			1925	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4220 Sturtevant Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by overlapping front gables and hipped roof dormers facing west and north, with a hipped roof projecting off the rear. A brick chimney is located at the eave on the west facade of the house. The facade is clad in brown face brick laid in a running bond pattern on the first floor, with false half-timbering infilled with stucco beneath the front gable, and wood shingle siding on the rest of the second floor. The primary entrance is near the east corner of the façade within a projecting front gabled vestibule and is accessed by a brick and concrete porch. West of the entrance are two pairs of hung vinyl windows with divided upper sashes, beneath similar windows on the second floor and arranged on other elevations. Windows have cast stone sills on the first floor. A driveway runs along the east of the property to the rear. There is no garage.
729	4221 Sturtevant Street			1924	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4221 Sturtevant Street is two-stories and topped with a hipped asphalt shingle roof intersected by a segmental arched roof dormer centered above the facade. A brick chimney is located at the eave on the east facade of the house. The exterior is clad in reddish brown brick veneer laid in a running bond pattern with accents of decorative brickwork. The primary entrance is recessed near the west corner of the facade beneath a front gabled overhang supported by brick piers with an arched opening. The entrance is accessed by a brick and concrete porch. East of the entrance is a set of four wood hung windows with divided upper sashes, separated by wood spindle mullions beneath a brick segmental arched lintel. A pair of wood hung windows are found at the second floor framed by shutters painted yellow. Similar windows are found across the other elevations, and windows have cast stone sills. There is a concrete driveway to the east of the house leading to the rear where there is a pyramidal roof garage.
730	4228 Sturtevant Street			1925	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4228 Sturtevant Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by overlapping front gables. A brick chimney is located at the eave on the west facade of the house. The facade is clad in red face brick laid in a running bond pattern with false half-timbering infilled with stucco beneath the front gables. The primary entrance is centered on the façade beneath a projecting front gabled overhang supported by brick piers with arched openings and is accessed by a brick and concrete porch with a metal railing. On either side of the entrance is a set of three hung wood windows with divided upper sashes, beneath similar windows on the second floor and arranged on other elevations. Windows have cast stone sills. A driveway runs along the east of the property to the rear. There is no garage.
731	4229 Sturtevant Street			1925	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4229 Sturtevant Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by a front gable and an eyebrow dormer above the façade and a hipped roof projecting from the rear. A brick chimney is located at the eave on the west facade of the house. The facade is clad in blonde brick laid in a running bond pattern with wood shingles on the second floor and beneath the front gables. The primary entrance is recessed near the east corner of the façade beneath a parapeted, brick-clad vestibule projecting slightly from the façade with an arched opening and decorative brickwork. The entrance is accessed by a brick and concrete full width porch. West of the entrance is a set of three hung wood windows with divided upper sashes topped with a brick segmental arched lintel, beneath matching windows on the second floor. Two casement windows with leaded glass in a diamond pattern are on the second floor. Similar windows are arranged on other elevations. Most windows have cast stone sills. A driveway runs along the east of the property to the rear. There is no garage.
732	4236 Sturtevant Street			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4236 Sturtevant Street is two-stories and topped with a front gable asphalt shingle roof that meets a hipped roof towards the rear. A brick chimney with cast stone and tile accents is centered on the façade of the house. The facade is clad in brown face brick laid in a running bond pattern with decorative brickwork. The primary entrance is recessed near the west corner of the façade beneath a shed asphalt shingle roof accessed by a concrete and brick porch. On either side of the center chimney is a wood hung window, beneath two wood hung windows on the second floor and a split fanlight at the attic level. Similar windows appear on the rest of the elevations and all have cast stone sills. A concrete driveway is east of the house leading to a front gable roof garage at the rear.
733	4237 Sturtevant Street			1926	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4237 Sturtevant Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof that intersects with a front gable and meets a hipped roof towards the rear, with a hipped roof dormer facing east. A brick chimney is on the front façade of the house. The facade is clad in red and brown face brick laid in a running bond pattern with some areas of decorative brickwork. The primary entrance is arched and located near the east corner of the façade beneath an aluminum metal awning accessed by a concrete and brick porch with a metal railing. On either side of the center chimney is a pair of wood hung windows with aluminum storms, beneath two pairs of matching hung windows on the second floor. Similar windows appear on the rest of the elevations and all have cast stone sills. A concrete driveway is east of the house leading to a front gable roof garage at the rear.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
734	4244 Sturtevant Street			1924	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4244 Sturtevant Street is two-stories and topped with a pyramidal asphalt shingle roof, intersected by a front gable that overlaps with a slightly projecting front gabled entrance vestibule. A brick chimney is located at the eave on the west facade of the house. The facade is clad in blonde face brick laid in a running bond pattern on the first floor with vinyl siding on the second floor. The primary entrance is near the east corner of the façade, arched and trimmed with stone accents, and is accessed by a brick and concrete porch with a metal railing. West of the entrance is a large vinyl slider window with a cast stone sill and accents, beneath a matching window on the second floor. Similar windows are arranged on other elevations. Windows have cast stone sills on the first floor. A driveway runs along the east of the property to the rear where there is a side gable roof garage.
735	4245 Sturtevant Street			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4245 Sturtevant Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by a front gable that overlaps with a slightly projecting front gabled entrance vestibule and a hipped roof projecting from the rear. A brick chimney is located at the eave on the west facade of the house. The facade is clad in blonde brick laid in a running bond pattern with wood shingles on the second floor and false half-timbering infilled with stucco beneath the front gable. The primary entrance is near the east corner of the façade, trimmed with a segmental brick arch and decorative brickwork. The entrance is accessed by a full width brick and concrete full width porch with metal railing. West of the entrance is a set of three hung windows with divided upper sashes topped with a brick segmental arched lintel, beneath three vinyl hung windows on the second floor. Similar windows are arranged on other elevations. Most windows have cast stone sills. A driveway runs along the east of the property to the rear where there is a pyramidal roof garage.
736	4252 Sturtevant Street			1955	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4252 Sturtevant Street is one-and-a-half-stories and topped with a cross gable asphalt shingle roof, composed of side gable intersected by a front gable, that meets a hipped roof at the rear. A brick chimney is at the eave on the west facade. The exterior is clad in red brick veneer laid in a running bond pattern. The primary entrance is near the east corner of the façade, slightly recessed beneath a cantilevered overhang and is accessed by a small brick and concrete porch. A steel casement window divided horizontally with aluminum storms is west of the entrance. Similar windows are arranged on other elevations and have cast stone sills. A concrete driveway runs along the east of the property to the rear where there is a front gable roof garage.
737	4253 Sturtevant Street			1925	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4253 Sturtevant Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by a round roof dormer with fanlight and a jerkinhead front gable that overlaps with a slightly projecting jerkinhead entrance vestibule and a hipped roof projecting from the rear. A brick chimney is located at the eave on the west facade of the house. The facade is clad in red brick laid in a running bond pattern, with wood shingles on the second floor and false half-timbering infilled with stucco beneath the front gable. The primary entrance is near the east corner of the façade, trimmed with a brick arch and decorative brickwork. The entrance is accessed by a full width brick and concrete full width porch with metal railing. West of the entrance is a set of wood hung windows with divided upper sashes beneath an aluminum shingled awning. Three wood hung windows with divided upper sashes are on the second floor. Similar windows are arranged on other elevations. Most windows have cast stone sills. A driveway runs along the east of the property to the rear. There is no garage.
738	4260 Sturtevant Street			1926	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4260 Sturtevant Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by a jerkinhead front gable, and hipped roof dormers above the east, west, and rear facades. A brick chimney is located at the eave on the west facade of the house. The facade is clad in brown brick veneer laid in a running bond pattern, with areas of decorative brickwork and stone accents. The primary entrance is near the east corner of the façade, beneath a parapeted overhang supported by brick piers with an arched opening and curved underside. The entrance is accessed by a brick and concrete porch with metal railing. West of the entrance windows are obscured from view by vegetation, beneath an aluminum metal awning. Three wood hung windows with divided upper sashes are on the second floor with aluminum storms. Similar windows are arranged on other elevations and windows have cast stone sills. A driveway runs along the east of the property to the rear where there is a pyramidal roof garage.
739	4261 Sturtevant Street			1925	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4261 Sturtevant Street is two-stories and topped with a cross gable asphalt shingle roof, composed of a front gable that meets a steeply pitched hipped roof at the rear encompassing the second story and creating an L-shaped footprint. The roof is intersected by a triangular and a hipped roof dormer above the façade. A tall brick chimney is located on the front of the house. The facade is clad in red brick laid in a running bond pattern, with false half-timbering infilled with stucco beneath the front gable. The primary entrance is beneath a catslide near the intersection of the L-shape, and the arched door is trimmed with brick. The entrance is accessed by a brick and concrete porch. West of the entrance are two doors framed by shutters that open on to a second porch. The second floor is glazed with wood hung windows with divided upper sashes. Similar windows are arranged on other elevations. Most windows have cast stone sills. A driveway runs along the east of the property to the rear. There is no garage.
740	4268 Sturtevant Street			1925	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4268 Sturtevant Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by dormers above the front and east facades. A brick chimney is located at the eave on the west facade of the house. The facade is clad in brown brick laid in a running bond pattern, with small brick buttresses extending from the corners. The primary entrance is near the east corner of the façade within a slightly projecting catslide entrance vestibule, trimmed with a brick arch, and is accessed by a brick and concrete porch. West of the entrance is a set of wood hung windows with divided upper sashes topped with a segmental arch brick lintel. Two pairs of wood hung windows with divided upper sashes are on the second floor. Similar windows are arranged on other elevations and windows have cast stone sills. A driveway runs along the east of the property to the rear. There is no garage.
741	4269 Sturtevant Street			1925	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4269 Sturtevant Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by overlapping front gables, hipped roof dormers facing east and west, and a hipped roof projecting from the rear. A brick chimney is located at the eave on the west facade of the house. The facade is clad in red face brick laid in a running bond pattern with some decorative brickwork and false half-timbering infilled with stucco beneath the front gables. The primary entrance is near the east corner of the façade beneath a projecting front gabled overhang supported by buttressed brick piers and is accessed by a brick and concrete porch. West of the entrance is a set of three hung vinyl windows with divided upper sashes each topped with a cast stone arch infilled with brick. Three vinyl windows are on the second floor and similar windows are arranged on other elevations. Windows have cast stone sills. A driveway runs along the east of the property to the rear. There is no garage.
742	4276 Sturtevant Street			1926	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4276 Sturtevant Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by a front gable, jerkinhead roof dormers facing east and west, and a hipped roof projecting from the rear. A brick chimney is located at the eave on the west facade of the house. The facade is clad in brown brick veneer laid in a running bond pattern with false half-timbering infilled with decorative brickwork at the second floor. The primary entrance is near the east corner of the façade beneath a projecting jerkinhead overhang with a curved underside supported by brick piers, and is accessed by a brick and concrete porch. West of the entrance is a ribbon of four hung wood windows with divided upper sashes and aluminum storms, trimmed with decorative brickwork. Three similar windows are on the second floor and are arranged on other elevations. Most windows have cast stone sills. A driveway runs along the east of the property to the rear. There is no garage.
743	4277 Sturtevant Street			1924	Prairie	n/a	C	Unknown	Unknown	The house at 4277 Sturtevant Street is two-stories and topped with a side gable asphalt shingle roof, intersected by a hipped roof dormer centered above the façade and a hipped roof projecting from the rear. A brick chimney is located at the eave on the west facade of the house. The facade is clad in brown brick veneer laid in a running bond pattern on the first floor, with wood shingles on the second floor. The primary entrance is near the east corner of the façade, beneath a hipped roof overhang supported by brick piers, and is accessed by a brick and concrete porch with a brick kneewall. West of the entrance is a set of wood hung windows with aluminum storm. Two pairs of wood hung windows are on the second floor. Similar windows are arranged on other elevations, and windows have cast stone sills on the first floor. A driveway runs along the east of the property to the rear. There is no garage.
744	4284 Sturtevant Street			not listed	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4284 Sturtevant Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by a front gable, a hipped roof dormer facing east, a shed dormer facing west, and a hipped roof projecting from the rear. A brick chimney is located at the eave on the west facade of the house. The facade is clad in blonde brick veneer laid in a running bond pattern with some decorative brickwork. The primary entrance is near the east corner of the façade beneath a projecting front gabled overhang supported by buttressed brick piers, with an arched opening and stone accents, and is accessed by a brick and concrete porch. West of the entrance is a set of three wood hung windows with divided upper sashes beneath an asphalt shingled awning. Three matching windows are on the second floor and similar windows are arranged on other elevations. Windows have cast stone sills. A driveway runs along the east of the property to the rear where there is a pyramidal roof garage.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
745	4285 Sturtevant Street			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4285 Sturtevant Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by a front gable, and a hipped roof dormer facing the rear. A brick chimney is located at the eave on the west facade of the house. The facade is clad in light brown brick veneer laid in a running bond pattern with some decorative brickwork, and wood shingle siding on the second floor. The primary entrance is near the east corner of the façade within a slightly projecting front gabled vestibule, with an arched door and stone accents, and is accessed by a brick and concrete porch. West of the entrance is a large vinyl slider window beneath an asphalt shingled awning. A matching window is on the second floor and vinyl hung windows are arranged on other elevations. Many windows have cast stone sills. A driveway runs along the east of the property to the rear where there is a pyramidal roof garage. A black lightpost with a globe light fixture is in the front lawn.
746	4292 Sturtevant Street			1926	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4292 Sturtevant Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by a front gable, and hipped roof dormer facing west and to the rear. A brick chimney is located at the eave on the west facade of the house. The facade is clad in brown brick veneer laid in a running bond pattern, and vinyl siding on the second floor beneath the front gable. The primary entrance is near the east corner of the façade within a slightly projecting front gabled vestibule, with an arched door and stone accents, and is accessed by a brick and concrete porch. West of the entrance are two pairs of wood hung windows with divided upper sashes and aluminum storms. A matching pair of windows is on the second floor along with a small casement window with leaded glass in a diamond pattern. Similar windows are arranged on other elevations. Most windows have cast stone sills. A driveway runs along the east of the property to the rear where there is a front gable roof garage.
747	4293 Sturtevant Street			1930	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4293 Sturtevant Street is two-stories and topped with a side gable asphalt shingle roof, that meets a hipped roof towards the rear and intersected by a polygonal roof oriel window and another polygonal roof on top of a one-story canted bay. A brick chimney is located at the eave on the west facade of the house. The facade is clad in brown and red brick veneer laid in a running bond pattern with accents ofklinker brick and stone veneer. The primary entrance is near the east corner of the façade within the canted bay and is accessed by a brick and concrete porch with a metal railing. East of the entrance are three stained glass windows. West of the entrance is a steel casement window with transom above and aluminum storms, casement windows also glaze the oriel window. Similar windows are arranged on other elevations and have cast stone sills. A driveway runs along the east of the property to the rear where there is a pyramidal roof garage.
748	4300 Sturtevant Street			1924	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4300 Sturtevant Street is two-stories and topped with a steeply pitched hipped asphalt shingle roof that encompasses the second story, intersected by a front jerkinhead bay that projects at the west corner of the facade, and a hipped roof dormer above the façade. A brick chimney is located near the center of the house. The facade is clad in red and brown brick veneer laid in a running bond pattern. The primary entrance is near the center of the façade beneath a slightly projecting front gabled vestibule and is accessed by a brick and concrete porch. East of the entrance is a flat bay window glazed with four steel casement windows with aluminum storms. Similar windows are on the second floor and are arranged on other elevations. Some windows have brick sills. A brick buttress extends from the west corner above an arched opening towards the rear. A driveway runs along the east of the property to the rear. There is no garage.
749	4301 Sturtevant Street			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4301 Sturtevant Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by overlapping front gables, and a hipped roof projecting to the rear. A brick chimney is located at the eave on the west facade of the house. The facade is clad in brick veneer painted white, with a wide metal siding on the second floor and stone veneer around the entrance. The primary entrance is near the east corner of the façade within a slightly projecting front gabled vestibule, and is accessed by a brick and concrete porch with a metal railing. West of the entrance are three vinyl hung windows topped with a segmental arch lintel. Three vinyl hung windows are on the second floor and similar windows are arranged on other elevations. Most windows have cast stone sills. A driveway runs along the east of the property to the rear where there is a garage.
750	4308 Sturtevant Street			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4308 Sturtevant Street is two-stories and topped with a front gable asphalt shingle roof intersected by a continuous shed dormer facing east and west, creating a dual-pitched roof and overlapping front gables create the appearance of multi-level eaves. A brick chimney is at the eave on the west facade of the house. The facade is clad in blonde brick veneer on the first floor and wide metal or vinyl siding on the second floor. The primary entrance is near the east corner of the house beneath an aluminum metal awning and is accessed by a brick and concrete porch. A ribbon of four windows are west of the entrance. On the second floor are two hung windows. Similar windows are found on other elevations and have cast stone sills on the first floor. A concrete driveway runs along the east of the house to the rear where there is a pyramidal roof garage.
751	4309 Sturtevant Street			not listed	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4309 Sturtevant Street is two-stories and topped with a hipped asphalt shingle roof intersected by a front gable and hipped roof dormers facing east and to the rear. A tall brick chimney is at the eave on the west facade of the house. The facade is clad in brown brick veneer laid in a running bond pattern. The primary entrance is near the center of the facade within a slightly projecting entrance vestibule, the arched door trimmed in brick with cast stone accents, and is accessed by a brick and concrete porch. On either side of the entrance are three windows, steel casement windows to the east and wood hung windows with divided upper sashes to the west. On the second floor is a pair of hung windows with divided upper sashes and a large picture window. Similar windows are found on other elevations and have cast stone sills on the first floor and brick sills on the second floor. A concrete driveway runs along the east of the house to the rear. There is no garage.
752	4316 Sturtevant Street			1925c.	Prairie	1/garage	C	Unknown	Unknown	The house at 4316 Sturtevant Street is two-stories and topped with a side gable asphalt shingle roof, intersected by a hipped roof dormer centered above the façade and a hipped roof projecting from the rear. A brick chimney is located at the eave on the west facade of the house. The facade is clad in reddish brown brick veneer laid in a running bond pattern on the first floor, with wide metal siding on the second floor. The primary entrance is near the east corner of the façade, beneath a pedimented overhang supported by brick piers, and is accessed by a brick and concrete porch. West of the entrance are four wood hung windows with divided upper sashes and aluminum storms, beneath a fabric awning. Two pairs of matching windows are on the second floor. Similar windows are arranged on other elevations, and windows have cast stone sills on the first floor. A driveway runs along the east of the property to the rear where there is a front gabled garage.
753	4317 Sturtevant Street			1925	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4317 Sturtevant Street is two-stories and topped with a side gable asphalt shingle roof, intersected by a jerkinhead above the façade. A brick chimney is located at the eave on the west facade of the house. The facade is clad in blonde brick veneer laid in a running bond pattern, with vinyl siding on the second floor. The primary entrance is near the east corner of the façade, beneath a hipped roof overhang supported by metal piers, and is accessed by a brick and concrete porch with metal railing. West of the entrance are three hung windows with aluminum storms, beneath an asphalt shingled awning. Three matching windows are on the second floor. Similar windows are arranged on other elevations, and windows have cast stone sills. A driveway runs along the east of the property to the rear. There is no garage.
754	4324 Sturtevant Street			1925	Italian Renaissance	1/garage	C	Unknown	Unknown	The house at 4324 Sturtevant Street is two-stories and topped with a pyramidal asphalt shingle roof with modillions along the eave, intersected by a hipped roof dormer centered above the façade containing three small hung windows and another hipped roof dormer facing east. A brick chimney is at the eave on the west facade. The exterior is clad in red brick veneer laid in a running bond pattern. The entrance is accessed beneath a hipped overhang with modillions supported by fluted columns, accessed by a full width brick and concrete porch. Three vinyl hung windows are west of the entrance, topped with cast stone arched hood molds with stucco and tile infill. Hung vinyl windows with aluminum storm are on the second floor. Similar windows are arranged on other elevations, and all windows have cast stone sills. A concrete driveway runs along the east of the property to the rear where there is a pyramidal roof garage.
755	4325 Sturtevant Street			1925	French Eclectic	n/a	C	Unknown	Unknown	The house at 4325 Sturtevant Street is two-stories and topped with a side jerkinhead asphalt shingle roof, intersected by a gabled through-the-cornice wall dormer above the façade. A brick chimney is located at the eave on the west facade of the house. The facade is clad in red brick veneer laid in a running bond pattern. The primary entrance is slightly off-center on the façade, beneath a hipped roof overhang supported by wood posts, and is accessed by a brick and concrete stoop. West of the entrance are three wood casement windows with aluminum storms, beneath similar windows are on the second floor and arranged on other elevations, and windows have brick sills. A concrete ribbon driveway runs along the east of the property to the rear. There is no garage.
756	4332 Sturtevant Street			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4332 Sturtevant Street is two-stories and topped with cross gable asphalt shingle roof composed of a side gable intersected by a front jerkinhead that overlaps with a jerkinhead overhang above the entrance, both with vergeboards. A brick chimney is located at the eave on the west facade of the house. The exterior is clad in reddish brown brick veneer laid with decorative brickwork. The primary entrance is near the east corner of the facade beneath a jerkinhead overhang supported by brick piers with an arched opening and cast stone accents. The entrance is accessed by a brick and concrete porch with metal railing. West of the entrance is a set of three wood, hung, multi-light windows, with a cast stone surround and segmental arched lintel. Two hung windows are found at the second floor with a splayed brick lintel and cast stone accents. Similar windows are found on other elevations, and windows have cast stone sills. There is a concrete ribbon driveway to the east of the house leading to a pyramidal roof garage at the rear. A black lightpost with globe light fixture is in the front lawn.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
757	4333 Sturtevant Street			1926	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4333 Sturtevant Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by a front gable, and a hipped roof bay projecting to the rear. A brick chimney is located at the eave on the west facade of the house. The facade is clad in brown brick veneer laid in a running bond pattern, with vinyl siding beneath the front gable at the attic level. The primary entrance is near the east corner of the façade within a slightly projecting front gabled vestibule, is trimmed in stone and accessed by a brick and concrete porch with a metal railing. West of the entrance are three vinyl fixed windows set within brick segmental arches with keystones above. Three vinyl hung windows are on the second floor and similar windows are arranged on other elevations. Windows have cast stone sills. A driveway runs along the east of the property to the rear where there is a front gable roof garage.
758	4340 Sturtevant Street			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4340 Sturtevant Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by overlapping front gables and an eyebrow dormer above the facade. A brick chimney is located at the eave on the west facade of the house. The facade is clad in red and brown brick veneer laid in a running bond pattern. The primary entrance is centered on the façade beneath a projecting front gabled overhang supported by brick piers with an arched opening and is accessed by a brick and concrete porch with a metal railing. On either side of the entrance is a set of three hung wood windows with segmental arched lintel, beneath similar windows on the second floor and arranged on other elevations. Windows have brick sills. A driveway runs along the east of the property to the rear where there is a pyramidal roof garage.
759	4341 Sturtevant Street			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4341 Sturtevant Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by overlapping front gables. A brick chimney is located at the eave on the west facade of the house. The facade is clad in light brown brick veneer laid in a running bond pattern. The primary entrance is centered on the façade beneath a projecting front gabled overhang supported by brick piers with an arched opening and is accessed by a brick and concrete porch. On either side of the entrance is a set of three hung wood windows with segmental arched lintel, beneath similar windows on the second floor and arranged on other elevations. Windows have brick sills. A driveway runs along the east of the property to the rear where there is a pyramidal roof garage.
760	4348 Sturtevant Street			1924	Prairie	1/garage	C	Unknown	Unknown	The house at 4348 Sturtevant Street is two-stories and topped with a hipped asphalt shingle roof, intersected by a hipped roof dormer centered above the façade and a hipped roof bay projecting from the rear. A brick chimney is located at the eave on the west facade of the house. The facade is clad in red brick veneer laid in a running bond pattern with some decorative brickwork. The primary entrance is near the east corner of the façade, beneath a hipped overhang with modillions and dentils along the eave and supported by brick piers, and is accessed by a brick and concrete porch with a metal railing. West of the entrance are four wood hung windows with divided upper sashes and aluminum storms, beneath a fabric awning. Two pairs of matching windows are on the second floor. Similar windows are arranged on other elevations, and windows have cast stone sills. A driveway runs along the east of the property to the rear where there is a pyramidal roof garage.
761	4349 Sturtevant Street			1927	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4349 Sturtevant Street is two-stories and topped with a hipped asphalt shingle roof, intersected by a front gable, and a hipped roof dormer to the rear. A brick chimney is located at the eave on the west facade of the house. The facade is clad in red and brown brick veneer laid in a running bond pattern, with some decorative brickwork. The primary entrance is near the east corner of the façade within a slightly projecting front gabled vestibule, and the arched door is trimmed in brick and stone and accessed by a brick and concrete porch with a wood railing. West of the entrance are three hung windows beneath splayed brick lintels with stone accents. On the second floor is a pair of hung windows and two narrow casement windows with a diamond pattern and stone surround. Similar windows are arranged on other elevations. Windows have cast stone sills. A brick buttress extends from the west corner of the façade. A driveway runs along the east of the property to the rear where there is a pyramidal roof garage.
762	4356 Sturtevant Street			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4356 Sturtevant Street is two-stories and topped with cross gable asphalt shingle roof composed of a side gable that meets a hipped roof towards the rear, intersected by overlapping front gables. A brick chimney is located at the eave on the west facade of the house. The exterior is clad in blonde brick veneer laid in a running bond pattern, wood shingle siding on the secondary facades of the second floor, and false half-timbering beneath the front gables at the attic level. The primary entrance is near the east corner of the facade beneath a low pitched gable overhang supported by square wood posts, and is accessed by a brick and concrete porch. West of the entrance is a set of three wood, hung windows with vertically divided upper sashes, with a cast stone hood mold and stucco infilled arches. Similar windows are found at the second floor and on other elevations, and windows have cast stone sills. There is a concrete driveway to the east of the house leading to a front gable roof garage at the rear. A black lightpost with globe light fixture is in the front lawn.
763	4357 Sturtevant Street			1924	Tudor Revival	1/garage	C	J. Lawson Miller	Unknown	The house at 4357 Sturtevant Street is two-stories and topped with cross gable asphalt shingle roof composed of a front gable that meets a hipped roof at the middle, intersected by a front gable and shed roof dormer. A large brick chimney with decorative brickwork is located at the eave on the west facade of the house. The exterior is clad in brown brick veneer laid in a running bond pattern, with some decorative brickwork accents. The primary entrance is near the center of the facade beneath a front gable overhang supported by slightly tapered brick piers that form an arch, and is accessed by a brick and concrete porch. On either side of the entrance is a pair of wood hung windows with divided upper sashes beneath aluminum metal awnings. Similar windows are found at the second floor and on other elevations, and windows have cast stone sills. There is a concrete driveway to the east of the house leading to a pyramidal roof garage at the rear.
764	4364 Sturtevant Street			1925	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 4364 Sturtevant Street is two-stories and topped with a hipped asphalt shingle roof with modillions along the eave, intersected by a shed roof dormers centered above each façade containing three small hung windows. A brick chimney is at the eave on the west facade. The exterior is clad in red brick veneer laid in a running bond pattern. The entrance is centered on the façade within a pedimented projecting entrance vestibule with dentils, accessed by a brick and concrete stoop. Sets of three vinyl hung windows beneath a brick arched lintel with stone accents are on either side of the entrance. Two pairs of hung vinyl windows are on the second floor and similar windows are arranged on other elevations, all windows have cast stone sills. A concrete driveway runs along the east of the property to the rear where there is a pyramidal roof garage.
765	4365 Sturtevant Street			1926	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4365 Sturtevant Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by overlapping front gables. A brick chimney is located at the eave on the west facade of the house. The facade is clad in brown brick veneer laid in a running bond pattern. The primary entrance is near the east corner of the façade within a projecting front gabled vestibule, trimmed with an arched brick surround and is accessed by a brick and concrete porch with a metal railing. Above the entrance are two wood casement windows with leaded glass in a diamond pattern. West of the entrance is a set of three hung wood windows with brick splayed lintel, beneath similar windows on the second floor and arranged on other elevations. Windows have brick sills. A brick buttress extends from the west corner of the facade. A driveway runs along the east of the property to the rear where there appears to be a garage.
766	4372 Sturtevant Street			1926	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4372 Sturtevant Street is two-stories and topped with a hipped asphalt shingle roof, intersected by an eyebrow dormer above the façade, shed roof dormers facing east and west, and a hipped roof dormer towards the rear. A brick chimney is at the eave on the west facade. The exterior is clad in red brick veneer laid in a running bond pattern. The entrance is near the east corner of the façade beneath a front gabled overhang with slightly tapered brick piers and an arched opening, accessed by a brick and concrete full width porch with a metal railing. Three vinyl hung windows are west of the entrance beneath a brick segmental arched lintel and an aluminum metal awning. On the second floor, a canted bay window is supported by decorative brackets and has a large vinyl picture window in the center between two small vinyl hung windows. Similar windows are arranged on other elevations, and all windows have cast stone sills. There is no garage.
767	4373 Sturtevant Street			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4373 Sturtevant Street is two-stories and topped with a hipped asphalt shingle roof, intersected by a front gable, and a hipped roof dormer above the east facade. A brick chimney is at the eave on the west facade. The exterior is clad in red brick veneer laid in a running bond pattern. The entrance is near the east corner of the façade within a projecting front gabled vestibule, the arched door is trimmed in brick and accessed by a brick and concrete full width porch with a metal railing. Three arched windows are west of the entrance. On the second floor, two pairs of hung windows have aluminum storms. Similar windows are arranged on other elevations, and all windows have cast stone sills. A pyramidal roof garage is accessed off the alley.
768	4734 Sturtevant Street			1926	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 4734 Sturtevant Street is two-stories and topped with a side gambrel asphalt shingle roof. A brick chimney is located at the eave on the west facade. The facade is clad with brown brick veneer in a running bond pattern, with wide metal siding beneath a continuous shed dormer on the second floor, and beneath the side gable on the second floor. The primary entrance is near the east corner the facade beneath a gabled overhang supported by square wood posts, and is accessed by a brick and concrete porch with a metal railing. West of the entrance is are four wood hung windows with divided upper sashes, and two pairs of matching wood hung windows with aluminum storms on the second floor. Similar windows exist on other elevations, and have cast stone sills on the first floor. A side gable roof garage at the rear of the property is accessed off of the alley.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
769	4735 Sturtevant Street			not listed	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4735 Sturtevant Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by a front gable, and a hipped roof bay projecting to the rear. A brick chimney is located at the eave on the west facade of the house. The facade is clad in red and brown brick veneer laid in a running bond pattern, with wood shingle siding on the second floor and deteriorated false half-timbering beneath the front gable at the attic level. The primary entrance is near the east corner of the façade within a slightly projecting front gabled vestibule, is trimmed in stone and accessed by a brick and concrete porch with a metal railing. West of the entrance are boarded over windows with brick arches with keystones above. Two wood hung windows and one opening with window missing are on the second floor and similar windows are arranged on other elevations. Windows have cast stone sills. There is no garage.
770	4742 Sturtevant Street			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4742 Sturtevant Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by a front gable with catslide, and a hipped roof bay projecting to the rear. A brick chimney is located on the front facade of the house with decorative brickwork. The facade is clad in light brown brick veneer laid in a running bond pattern. The primary entrance is near the east corner of the façade and the arched door is accessed by a brick and concrete porch with a metal railing and beneath a metal awning. Windows on the first floor are obscured by vegetation. Wood hung windows with aluminum storms are on the second floor and similar windows are arranged on other elevations. Windows have cast stone sills. A concrete driveway runs along the east of the property to the rear where there is a pyramidal roof garage.
771	4743 Sturtevant Street			1925	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4743 Sturtevant Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by overlapping front gables, and a hipped roof bay projecting to the rear. A brick chimney is located at the eave on the west facade of the house. The facade is clad in red brick veneer laid in a running bond pattern, with wood shingle siding on the second floor and vinyl siding beneath the main front gable. The primary entrance is near the east corner of the façade within a slightly projecting front gabled vestibule, and the arched entrance is trimmed in brick with stone accents and accessed by a brick and concrete porch with a metal railing. West of the entrance is a large fixed vinyl window and two hung vinyl windows, beneath a vinyl slider and a hung window on the second floor. Similar windows are arranged on other elevations. Windows have cast stone sills on the first floor. A concrete driveway runs along the east of the property to the rear. There is no garage.
772	4750 Sturtevant Street			1925	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4750 Sturtevant Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by overlapping front gables, and a hipped roof bay projecting to the rear. A brick chimney is located at the eave on the west facade of the house. The facade is clad in red brick veneer laid in a running bond pattern, with wood shingle siding on the second floor and false half-timbering infilled with stucco and decorative brickwork beneath the front gables. The primary entrance is near the east corner of the façade within a slightly projecting front gabled vestibule, and is accessed by a brick and concrete full-width porch with a metal railing. West of the entrance are three wood hung six-over-six windows with a brick sill, beneath a pair of matching windows covered by an aluminum awning on the second floor. Other windows on the second floor are casement with leaded glass in a diamond pattern, also covered by aluminum awnings. Similar windows are arranged on other elevations. Windows have brick sills on the first floor. A concrete driveway runs along the east of the property to the rear. There is no garage.
773	4751 Sturtevant Street			1927	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4751 Sturtevant Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by overlapping front gables, hipped roof dormers to the east and west, and a hipped roof bay projecting to the rear. A brick chimney is located at the eave on the west facade of the house. The facade is clad in brown brick veneer laid in a running bond pattern. The primary entrance is near the east corner of the façade beneath a projecting front gabled overhang supported by brick piers, and is accessed by a brick and concrete full-width porch with a metal and wood railing. West of the entrance are three wood hung windows with divided upper sashes beneath an aluminum awning, and three similar windows are on the second floor. Similar windows are arranged on other elevations. Windows have cast stone sills. A concrete driveway runs along the east of the property to the rear. There is no garage.
774	4758 Sturtevant Street			not listed	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4758 Sturtevant Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by a front gable, and shed roof dormers facing east and west. A brick chimney is located on the front facade of the house with decorative brickwork and stone accents. The facade is clad in red and brown brick veneer laid in a running bond pattern with decorative brickwork and accents of klinker brick. The primary entrance is near the east corner of the façade, trimmed in cast stone and topped with a label mold, and is accessed by a brick and concrete porch. Windows on either side of the chimney are steel casement windows topped with fanlights. Window openings are arranged on other elevations, some missing sashes. Windows have cast stone sills. A concrete driveway runs along the east of the property to the rear where there is a pyramidal roof garage.
775	4759 Sturtevant Street			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4759 Sturtevant Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by overlapping front gables, a hipped roof dormer facing east, and a hipped roof bay projecting to the rear. A brick chimney is located at the eave on the west facade of the house. The facade is clad in red brick veneer laid in a running bond pattern, with wood shingle siding on the second floor and false half-timbering infilled with stucco and decorative brickwork beneath the front gables. The primary entrance is near the east corner of the façade within a slightly projecting front gabled vestibule next to a glass block window, and is accessed by a brick and concrete full-width porch with a metal railing. West of the entrance are three hung windows with a brick sill, beneath an aluminum awning. A pair of hung windows and two fixed windows are on the second floor. Similar windows are arranged on other elevations. Windows have brick sills on the first floor. A concrete driveway runs along the east of the property to the rear where there is a front gable roof garage.
776	4764 Sturtevant Street			not listed	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4764 Sturtevant Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, with shed roof dormers facing east and west. A brick chimney is located on the front facade of the house with decorative brickwork. The facade is clad in red and brown brick veneer laid in a running bond pattern with decorative brickwork and accents of klinker brick. The primary entrance is near the east corner of the façade, trimmed in cast stone, and is accessed by a brick and concrete porch with a metal railing beneath an aluminum metal awning. Windows on either side of the chimney are wood, hung, multi-light windows topped with fanlights. Similar windows are arranged across the front façade and on other elevations. Windows have cast stone sills. A concrete driveway runs along the east of the property to the rear where there is a pyramidal roof garage.
777	4767 Sturtevant Street			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4767 Sturtevant Street is two-stories and topped with a pyramidal asphalt shingle roof, intersected by a front gable with a hipped roof bay projecting at the rear. A brick chimney is located on the front facade of the house. The facade is clad in light brown brick veneer laid in a running bond pattern with some decorative brickwork. The primary entrance is near the east corner of the façade, beneath a projecting front gabled overhang supported by brick piers with an arched opening, and is accessed by a brick and concrete porch with a metal railing. Windows on either side of the chimney are hung, beneath two narrow hung windows on the second floor. Similar windows are arranged on other elevations. Windows have cast stone sills. A concrete driveway runs along the east of the property to the rear where there is a pyramidal roof garage.
778	4770 Sturtevant Street			1927	Italian Renaissance	1/garage	C	Unknown	Unknown	The house at 4770 Sturtevant Street is two-stories and topped with a cross hipped asphalt shingle roof. A brick chimney is located at the eave on the west facade of the house. The facade is clad in blonde, orange and red brick veneer laid in a running bond pattern, with some decorative brickwork. The primary entrance is near the east corner of the façade, recessed beneath an arched brick porch that supports a balcony above topped with an aluminum metal awning. West of the entrance is a vinyl slider window, beneath a slider window on the second floor with a decorative metal railing. A pair of hung windows and two fixed windows are on the second floor. Similar windows are arranged on other elevations and have cast stone sills. A concrete driveway runs along the east of the property to the rear where there is a front gable roof garage.
779	4775 Sturtevant Street			1926	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4775 Sturtevant Street is two-stories and topped with cross gable asphalt shingle roof composed of a front gable that meets a side gable roof at the middle, intersected by a hipped roof bay projecting from the rear. A brick chimney is located at the eave on the west facade of the house. The exterior is clad in red and brown brick veneer laid in a running bond pattern, with some decorative brickwork and stone accents. The primary entrance is near the east corner of the facade beneath a front gabled overhang supported by brick piers that form an arch, and is accessed by a brick and concrete porch with a metal railing. West of the entrance are three vinyl hung windows topped with brick arches infilled with cast stone. Three additional vinyl hung windows are at the second floor, and on other elevations, and windows have cast stone sills. A narrow arched window is at the attic level. There is a concrete driveway to the east of the house leading to the rear. There is no garage.
780	4784 Sturtevant Street			1924	Colonial Revival	n/a	C	Unknown	Unknown	The house at 4784 Sturtevant Street is two-stories and topped with a side gambrel asphalt shingle roof. A brick chimney is located at the eave on the west facade. The facade is clad with brown brick veneer in a running bond pattern on the first floor, with stone veneer siding beneath a continuous shed dormer on the second floor, and beneath the side gables on the second floor. The primary entrance is near the east corner the facade beneath a pedimented overhang supported by white fluted columns, and is accessed by a brick and concrete full width porch with a metal railing. West of the entrance is are four vinyl hung windows with divided upper sashes covered by an aluminum metal awning, and two pairs of matching wood hung windows each pair covered by an aluminum awning on the second floor. Similar windows exist on other elevations, and have cast stone sills on the first floor. There is a concrete driveway to the east of the house leading to the rear. There is no garage.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
781	4785 Sturtevant Street			1927	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4785 Sturtevant Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof intersected by a front gable, hipped roof dormers facing east and west, and a hipped roof bay projecting from the rear. A brick chimney is located at the eave on the west facade of the house. The exterior is clad brown brick veneer laid in a running bond pattern, with some decorative brickwork and stone accents. The primary entrance is near the east corner of the facade beneath a front gabled overhang supported by brick piers that form a segmental arch, and is accessed by a brick and concrete full width porch with a metal railing. West of the entrance are three hung windows beneath a brick segmental arched lintel. Three additional hung windows are at the second floor and on other elevations, and windows have cast stone sills. There is a concrete driveway to the east of the house leading to the rear where there is a pyramidal roof garage.
782	4790 Sturtevant Street			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4790 Sturtevant Street is two-stories and topped with a pyramidal asphalt shingle roof, intersected by a front gable, a hipped roof dormer facing east, and a hipped roof bay projecting to the rear. A brick chimney is located at the eave on the west facade of the house. The facade is clad in blonde brick veneer laid in a running bond pattern on the first floor, with wood shingle siding on the second floor and false half-timbering infilled with stucco beneath the front gable. The primary entrance is near the east corner of the facade beneath a hipped roof overhang supported by metal posts, and is accessed by a brick and concrete full-width porch with a metal railing. West of the entrance are casement windows beneath an aluminum awning and an asphalt shingled awning. Two pairs of hung windows are on the second floor with divided upper sashes and aluminum storms. Similar windows are arranged on other elevations. Windows have cast stone sills on the first floor. A concrete driveway runs along the east of the property to the rear where there is a pyramidal roof garage.
783	4791 Sturtevant Street			1927	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4791 Sturtevant Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by a front gable, and with shed roof dormers facing east and west. A brick double-shafted chimney is located on the front facade of the house with decorative brickwork. The facade is clad in dark and light brown brick veneer laid in a running bond pattern with decorative brickwork, with a small area of false half-timbering beneath the front gable. The primary entrance is near the east corner of the facade, flanked by brick engaged columns with ornamental wrought iron garland above, and is accessed by a brick and concrete stoop with a metal railing. Windows on the facade are vinyl slider. Similar windows are arranged on other elevations and have cast stone sills. A concrete driveway runs along the east of the property to the rear. There is no garage.
784	4800 Sturtevant Street			1926	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4800 Sturtevant Street is two-stories and topped with cross gable asphalt shingle roof composed of a front gable that meets a side gable roof at the middle, intersected by a hipped roof bay projecting from the rear. A brick chimney is located at the eave on the west facade of the house. The exterior is clad in red and brown brick veneer laid in a running bond pattern on the first floor and beneath the front gable, with some decorative brickwork and stone accents, and the second floor is clad in wood shingles. The primary entrance is near the east corner of the facade beneath a front gabled overhang supported by brick piers that form an arch, and is accessed by a brick and concrete porch with a metal railing. West of the entrance are three wood hung windows with aluminum storms topped with brick arches infilled with stucco, covered by an aluminum awning. Three additional wood hung windows are at the second floor and on other elevations, and windows have cast stone sills. A narrow arched window is at the attic level. There is a concrete driveway to the east of the house leading to the rear where there is a front gable roof garage.
785	4801 Sturtevant Street			1925	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4801 Sturtevant Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof intersected by a front gable, a hipped roof dormer facing east, and a hipped roof bay projecting from the rear. A brick chimney is located at the eave on the west facade of the house. The exterior is clad red brick veneer laid in a running bond pattern that is slightly wavy and with accents of glinker brick, giving the facade a somewhat cobbled look. The primary entrance is near the east corner of the facade within a front gabled vestibule, and is accessed by a brick and concrete full width porch with a metal railing. West of the entrance are three hung vinyl windows beneath a brick segmental arched lintel. Three additional hung windows are at the second floor and similar windows are found on other elevations, and windows have cast stone sills. There is a concrete driveway to the east of the house leading to the rear. There is no garage.
786	4806 Sturtevant Street			1926	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4806 Sturtevant Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof intersected by a front gable, and a gabled roof dormer at the rear. A brick chimney is located at the eave on the west facade of the house. The exterior is clad red brick veneer laid in a running bond pattern and beneath the front gable, and stone veneer on the second floor. The primary entrance is near the east corner of the facade within a front gabled vestibule, with an arched door trimmed in stone accents and is accessed by a brick and concrete full width porch with a metal railing. West of the entrance are three hung vinyl windows beneath a brick segmental arched lintel with stone accents. Three additional hung windows, and a wood casement window with leaded glass detailing in a diamond pattern are at the second floor. Similar windows are found on other elevations, and windows have cast stone sills on the first floor. There is a concrete driveway to the east of the house leading to the rear where there is a pyramidal roof garage.
787	4814 Sturtevant Street			1928	Tudor Revival	n/a	C	Unknown	Miller-Storm Company	The house at 4814 Sturtevant Street is two-stories and topped with a pyramidal asphalt shingle roof. A large brick chimney is at the eave near the center of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer and cast stone. The primary entrance is near the east corner of the facade and trimmed in cast stone and brick, beneath a stone belt course and the structure for an awning that has been removed. The entrance is accessed by a brick and concrete stoop. A one story canted bay topped with an asphalt shingle roof is west of entrance and contains steel casement windows and cast stone trim. Vinyl windows are arranged on the second floor facade, each set beneath a wall dormer. Each window has a cast stone sill. Similar windows are arranged on other elevations. The driveway is concrete and runs along the east side of the house. A pyramidal roof garage is at the rear of the property.
788	4817 Sturtevant Street			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4817 Sturtevant Street is two-stories and topped with a cross gable asphalt shingle roof, composed of a front-jerkinhead intersected by a side-jerkinhead, giving the roof an L-shape. A tall brick chimney is located at the eave on the west facade of the house. The facade is clad in red brick veneer laid in a running bond pattern, with some wide metal siding on the second floor on secondary facades. The primary entrance is located near the west corner of the facade within a front gabled vestibule and is accessed by a concrete stoop. The arched door is trimmed in brick. West of the entrance is a ribbon of four wood casement windows, beneath three vinyl hung windows on the second floor. Similar windows are found on other elevations and windows have cast stone sills. The roofline extends into a catslide that extends off the east corner into a porte-cochere, above a concrete driveway runs along the east of the house leading to the rear where there is a front gable roof garage.
789	4822 Sturtevant Street			1923	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 4822 Sturtevant Street is two-stories and topped with a side gambrel asphalt shingle roof. A brick chimney is located at the eave on the west facade. The facade is clad with blonde brick veneer in a running bond pattern on the first floor, with wood shingle siding beneath a continuous shed dormer on the second floor, and beneath the side gables on the second floor. The primary entrance is near the east corner the facade beneath a hipped roof overhang supported by square wood posts, and is accessed by a brick and concrete full width porch. West of the entrance is a one-story canted bay with vinyl hung windows, and two pairs of matching vinyl hung windows on the second floor. Similar windows exist on other elevations, and have cast stone sills on the first floor. There is a concrete driveway to the east of the house leading to the rear where there is a pyramidal roof garage.
790	4825 Sturtevant Street			1927	Colonial Revival	n/a	C	J. Lawson Miller	Unknown	The house at 4825 Sturtevant Street is two-stories and topped with a side gable asphalt shingle roof with a shed roof dormer facing the rear. A brick chimney is located at the eave on west facade of the house. The facade is clad in red brick veneer laid in a running bond pattern with a soldier course above the first floor. The primary entrance is slightly off-center on the facade beneath a front gabled portico with curved underside, supported by pair of square wood posts, and is accessed by a brick and concrete porch. West of the entrance is a flat bay with three vinyl hung windows with divided upper sashes, and matching windows are arranged across the facade and on other elevations, all with cast stone sills. A concrete driveway runs along the east of the house to the rear. There is no garage.
791	4830 Sturtevant Street			1925c.	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4830 Sturtevant Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by a front gable, a shed roof dormer facing east, and a hipped roof bay projecting to the rear. A brick chimney is located at the eave on the west facade of the house. The facade is clad in red brick veneer laid in a running bond pattern on the first floor and beneath the front gable, with some decorative brickwork, and wood shingle siding at the second floor. The primary entrance is near the east corner of the facade within a slightly projecting front gabled vestibule, and the arched door is trimmed in brick with stone accents, and accessed by a brick and concrete stoop. West of the entrance are three hung vinyl windows beneath a splayed brick lintel. On the second floor are three hung vinyl windows, and a small casement window with a diamond pattern at the attic level. Similar windows are arranged on other elevations. Some windows have brick sills. A brick buttress extends from the west corner of the facade. A driveway runs along the east of the property to the rear where there is a pyramidal roof garage.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
792	4833 Sturtevant Street			not listed	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4833 Sturtevant Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof intersected by a front gable, a hipped roof dormer facing west, a shed roof dormer to the rear, and a hipped roof bay projecting from the west half of the façade with a flat roofed tower centered on the gable. A brick chimney is located at the eave on the west facade of the house. The facade is clad in red and brown brick veneer laid in a running bond pattern, the different colors of brick arranged vertically giving a striped appearance, with accents of Klinker brick. Vinyl siding is present beneath the front gable. The primary entrance is near the east corner of the façade, and the arched door is trimmed in stone and brick, and is accessed by a brick and concrete porch. East of the entrance are two wood casement windows. West of the entrance are two full-height arched casement windows with decorative metal railings. The second floor is glazed with vinyl slider windows. Similar windows are found across the facade and on other elevations, and most windows have cast stone sills. A concrete driveway runs along the east of the house leading to the rear where there is a pyramidal roof garage.
793	4840 Sturtevant Street			1926	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4840 Sturtevant Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof intersected by a front gable, shed roof dormer facing east and west, and a hipped roof bay projecting from the rear. A brick chimney is located at the eave on the west facade of the house. The exterior is clad in red, blonde, and brown brick veneer laid in a running bond pattern. The primary entrance is near the east corner of the facade beneath a front gabled overhang supported by brick piers that form an arch, and is accessed by a brick and concrete full width porch with a metal railing. West of the entrance are three wood hung windows with aluminum storms, covered by an aluminum awning. A pair of wood hung windows with aluminum storms are also covered by an aluminum awning at the second floor, beneath a wood casement window with a diamond pattern at the attic level. Similar window are arranged on other elevations, and windows have cast stone sills. There is a concrete driveway to the east of the house leading to the rear where there is a pyramidal roof garage. A black lightpost with globe light fixture is in the front lawn.
794	4841 Sturtevant Street			1930	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4841 Sturtevant Street is two-stories and topped with a hipped asphalt shingle roof intersected by shed roof dormers towards the east, west, and rear facades. A tall brick chimney is located at the eave on the west facade of the house. The facade is clad in red, blonde, and brown brick veneer laid in a running bond pattern with decorative brickwork and accents of stone. The primary entrance is recessed at the east corner of the façade beneath a front gabled catslide vestibule accessed by a cast stone stoop and is trimmed in stone. West of the entrance is a steel casement window with sidelights and transom, trimmed in stone and brick, beneath hung windows with leaded glass detailing on the second floor. Similar windows are found on other elevations and windows have brick sills. A concrete driveway runs along the east of the house leading to the rear. There is no garage.
795	4846 Sturtevant Street			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4846 Sturtevant Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof intersected by shed roof dormers towards the east and west, and a hipped roof projecting bay at the rear. A brick chimney is located at the eave on the west facade of the house. The facade is clad in red and brown brick veneer laid in a running bond pattern with decorative brickwork and accents of stone. The primary entrance is near the east corner of the façade within a front gabled vestibule accessed by a brick and concrete stoop, and the arched door is trimmed in brick and stone. West of the entrance are three hung windows with divided upper sashes topped with a segmental arch brick lintel with stone accents. Three similar hung windows are on the second floor and found on other elevations. Windows have brick sills. A concrete driveway runs along the east of the house leading to the rear where there is a pyramidal roof garage.
796	4849 Sturtevant Street			1924	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4849 Sturtevant Street is two-stories and topped with a front gable asphalt shingle roof that meets a pyramidal roof towards the rear. A brick chimney is centered on the façade of the house. The facade is clad in brown face brick laid in a running bond pattern at the first floor and vinyl siding at the second floor. The primary entrance is recessed near the west corner of the façade beneath a shed asphalt shingle roof accessed by a concrete and brick porch. On either side of the center chimney are window openings that have been boarded over, beneath two vinyl hung windows on the second floor and a split fanlight at the attic level. Similar windows appear on the rest of the elevations and have brick sills on the first floor. A concrete driveway is east of the house leading to a pyramidal roof garage at the rear.
797	4854 Sturtevant Street			1926	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4854 Sturtevant Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof intersected by a front jerkinhead, a shed roof dormer facing west, a hipped roof dormer facing east, and a hipped roof bay projecting from the rear. A brick chimney is located at the eave on the west facade of the house. The exterior is clad in brown brick veneer laid in a running bond pattern with some decorative brickwork and stone accents. The primary entrance is near the east corner of the facade beneath a front jerkinhead overhang supported by brick piers that form a segmental arch opening, and is accessed by a brick and concrete porch with a metal railing. West of the entrance are three vinyl hung windows beneath a segmental arch brick lintel. Three vinyl hung windows with a splayed brick lintel are at the second floor, beneath a small wood hung window at the attic level. Similar window are arranged on other elevations, and windows have cast stone sills. There is a concrete driveway to the east of the house leading to the rear where there is a pyramidal roof garage.
798	4859 Sturtevant Street			1926	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4859 Sturtevant Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by shed roof dormers facing east, west, and to the rear, with a hipped roof bay projecting off the rear. A brick chimney is located on the front facade of the house with decorative brickwork and a blind arch with stone trim. The facade is clad in red and brown brick veneer laid in a running bond pattern with decorative brickwork and accents of klinker brick. The primary entrance is near the east corner of the façade, beneath a cantilevered semi-circular awning with decorative brackets, and is accessed by a brick and concrete stoop. West of the chimney are three narrow casement windows with a stone label mold above. Two pairs of casement windows are on the second floor with meal siding below. Similar windows are arranged on other elevations and have cast stone sills. A concrete driveway runs along the east of the property to the rear where there is a pyramidal roof garage.
799	4862 Sturtevant Street			1926	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4862 Sturtevant Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof intersected by a hipped roof dormer towards the east, and a hipped roof projecting bay at the rear. A brick chimney is located at the eave on the west facade of the house. The facade is clad in red and brown brick veneer laid in a running bond pattern with decorative brickwork and tile-roofed projections. The primary entrance is near the east corner of the façade within a front gabled vestibule, covered by an aluminum metal awning accessed by a brick and concrete stoop, and the arched door is trimmed in stone. West of the entrance are three hung windows covered by an aluminum metal awning. Three wood hung windows with divided upper sashes and aluminum storms are on the second floor and found on other elevations. Windows have cast stone sills. A concrete driveway runs along the east of the house leading to the rear where there is a pyramidal roof garage.
800	4865 Sturtevant Street			1924	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4865 Sturtevant Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof, intersected by a front gable bay projecting at the front creating an L-shaped footprint. A brick chimney is located at the eave on the west facade of the house. The facade is clad in brown brick veneer laid in a running bond pattern, with some decorative brickwork, and wide metal or vinyl siding is present on the secondary facades. The primary entrance is beneath a front gabled vestibule near the intersection of the L-shape, and the door is trimmed with a brick infilled arch. The entrance is accessed by a low brick and concrete porch. West of the entrance are four vinyl casement windows, beneath three similar window on the second floor. Similar windows are arranged on other elevations and have brick sills. A driveway runs along the east of the property to the rear where there is a pyramidal roof garage.
801	4870 Sturtevant Street			1927	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4870 Sturtevant Street is two-stories and topped with a pyramidal asphalt shingle roof intersected by a front jerkinhead, and a hipped roof dormer facing east. A brick chimney is located at the eave on the west facade of the house. The exterior is clad red and brown brick veneer laid in a running bond pattern. The primary entrance is near the east corner of the facade within a projecting front jerkinhead vestibule, with an arched door trimmed in brick, and accessed by a brick and concrete porch with a metal railing. West of the entrance are three hung vinyl windows beneath a brick segmental arched lintel with stone accents. Two vinyl hung windows and a wood casement window with leaded glass detailing in a diamond pattern are at the second floor. Similar windows are found on other elevations, and windows have cast stone sills. There is a concrete driveway to the east of the house leading to the rear where there is a pyramidal roof garage.
802	4871 Sturtevant Street			1926	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4871 Sturtevant Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof intersected by a front gable, a hipped roof dormer facing east, a shed roof dormer facing west, and a hipped dormer at the rear. A brick chimney is located at the eave on the west facade of the house. The exterior is clad in brown brick veneer laid in a Flemish bond pattern with some decorative brickwork and stone accents. The primary entrance is near the east corner of the facade beneath a front gabled overhang supported by brick piers that form an arched opening, and is accessed by a brick and concrete porch with a metal railing. West of the entrance is a ribbon of five vinyl windows beneath a segmental arch brick lintel with stone accents. At the second floor is a pair of vinyl hung windows with a brick lintel, and an oriel window with vinyl casement windows. Similar window are arranged on other elevations, and windows have cast stone sills. There is a concrete driveway to the east of the house leading to the rear. There is no garage.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
803	4880 Sturtevant Street			1939	Streamline Moderne	1/garage	C	Unknown	Unknown	The house at 4880 Sturtevant Street is two-stories and topped with a cross gable asphalt shingle roof forming an L-shape. A brick chimney is centered on the west façade. The facade is clad in blonde face brick laid in a running bond pattern with areas of decorative brickwork including a soldier course and belt courses. The primary entrance is near the center of the façade within a projecting flat-roof vestibule, is trimmed in brick and stone next to a round window. The entrance is accessed by a brick and concrete porch. Windows are steel casement across the facades, including corner windows. Similar windows are found on other elevations, and windows have brick sills. A hipped roof garage is at the rear of the property, accessed from the alley to the west.
804	4881 Sturtevant Street			1925	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4881 Sturtevant Street is two-stories and topped with a hipped asphalt shingle roof, intersected by a front gable and a gable roof dormer to the rear. A brick chimney is located on the front facade of the house. The facade is clad in red brick veneer laid in a running bond pattern. The primary entrance is near the east corner of the façade, within a front gabled entrance vestibule, and is accessed by a wood porch. West of the chimney is a pair of vinyl hung windows. Two narrow casement windows are on the second floor. Similar windows are arranged on other elevations and have cast stone sills. A concrete driveway runs along the east of the property to the rear where there is a pyramidal roof garage.
805	4891 Sturtevant Street			1926	Mediterranean Revival	1/garage	C	Unknown	Thomas King	The house at 4891 Sturtevant Street is one-and-a-half-stories and topped with a cross gable asphalt shingle roof composed of a front gable and side gable. A chimney is at the eave on the west façade. The facade is clad in stucco. The primary entrance is near the east corner of the façade, and the arched door is accessed by a concrete porch. West of the entrance are three arched full height casement windows, topped with clay tile accent above. Windows are steel casement across the facades, and windows have brick sills. A garage is at the rear of the property, accessed from the alley to the west.
806	3726 Tyler Street			1927	Italian Renaissance	n/a	C	Unknown	Unknown	The house at 3726 Tyler Street is two-stories and topped with a hipped asphalt shingle roof with modillions intersected by a hipped roof dormer with three windows above the facade and a shed roof dormer above the east facade. A large brick chimney is near the center of the house. The facade is clad in red face brick laid in a running bond pattern with accents of cast stone and decorative brickwork, with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the east corner of the facade beneath a two-story brick-clad porch with an arched opening supported by brick piers and accessed by a full-width porch. The first and second floor porches are surrounded by a brick kneewall. Three casement windows topped with decorative cast stone hoods are west of the entrances and set beneath a series of five casement windows on the second floor. Windows have cast stone sills and several are missing glass. Similar windows are arranged on other elevations. There is no driveway or garage.
807	3727 Tyler Street			1927	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3727 Tyler Street is two-stories and topped with a hipped asphalt shingle roof with modillions intersected by a jerkinhead dormer with two windows above the facade, a large jerkinhead roof with knee brackets above the facade, and a shed roof dormer above the east facade. A large brick chimney is near the center of the house. The facade is clad in blonde face brick laid in a running bond pattern with accents of cast stone and decorative brickwork, with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the east corner of the facade beneath a two-story brick-clad porch with an arched opening supported by brick piers and accessed by a full-width porch. The first and second floor porches are surrounded by a brick kneewall. Three casement windows topped with transoms and decorative cast stone hoods are west of the entrances and set beneath a large fixed window on the second floor. Windows have cast stone sills. Similar windows are arranged on other elevations. There is no driveway. A hipped roof garage is at the rear of the property.
808	3731 Tyler Street			1927	Italian Renaissance	n/a	C	Unknown	Unknown	The house at 3731 Tyler Street is two-stories and topped with a hipped asphalt shingle roof intersected by a hipped roof dormer with three windows above the facade and a shed roof dormer above the east facade. A large brick chimney is near the center of the house. The facade is clad in blonde face brick laid in a running bond pattern with accents of cast stone and decorative brickwork, with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the east corner of the facade beneath a two-story brick-clad porch with an arched opening supported by brick piers and accessed by a full-width porch. The first and second floor porches are surrounded by a brick kneewall. Three casement windows topped with transoms beneath arched cast stone arches are west of the entrances and set beneath a series of five hung windows framed by brown shutters on the second floor. Windows have cast stone sills and are fitted with aluminum storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house. There is no garage.
809	3732 Tyler Street			1927	Italian Renaissance	n/a	C	Unknown	Unknown	The house at 3732 Tyler Street is two-stories and topped with a hipped asphalt shingle roof with a denticulated cornice intersected by a hipped roof dormer with two windows above the facade and a shed roof dormer above the east facade. A large brick chimney is near the center of the house. The facade is clad in blonde and brown face brick laid in a Dutch bond pattern with accents of cast stone and decorative brickwork, with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the east corner of the facade beneath a two-story brick-clad porch with an arched opening supported by brick piers and accessed by a full-width porch. The second-floor balcony is topped with a hipped roof supported by brick piers. The first and second floor porches are surrounded by a brick kneewall and the first floor porch is sheltered by an aluminum awning. Three casement windows topped with transoms are west of the entrances and set beneath a large vinyl window framed by beige shutters on the second floor. Windows have cast stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house. There is no garage.
810	3740 Tyler Street			1927	Italian Renaissance	n/a	C	Unknown	Unknown	The house at 3740 Tyler Street is two-stories and topped with a hipped asphalt shingle roof intersected by a hipped roof dormer clad in vinyl siding above the facade and a shed roof dormer above the east facade. A large brick chimney is near the center of the house. The facade is clad in red face brick laid in a running bond pattern with accents of cast stone and decorative brickwork, with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the east corner of the facade beneath a two-story brick-clad porch with an arched opening supported by brick piers and accessed by a full-width porch. The first and second floor porches are surrounded by a brick kneewall. Three vinyl windows topped with decorative cast stone hoods are west of the entrances and set beneath a large vinyl windows framed by white shutters on the second floor. Windows have cast stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house. There is no garage.
811	3741 Tyler Street			1927	Italian Renaissance	1/garage	C	Unknown	Unknown	The house at 3741 Tyler Street is two-stories and topped with a hipped asphalt shingle roof intersected by an eyebrow dormer above the facade and a shed roof dormer above the east facade. A large brick chimney is near the center of the house. The facade is clad in red face brick laid in a running bond pattern with accents of cast stone and decorative brickwork, with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the east corner of the facade beneath a two-story brick-clad porch with an arched opening supported by brick piers and accessed by a full-width porch. The first and second floor porches are surrounded by a brick kneewall, which has been demolished in some areas. Three vinyl windows topped with transoms and decorative cast stone hoods painted pink are west of the entrances and set beneath a series of five vinyl windows framed by pink shutters on the second floor. Windows have cast stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house. A garage is at the rear of the property.
812	3746 Tyler Street			1927	Italian Renaissance	n/a	C	Unknown	Unknown	The house at 3746 Tyler Street is two-stories and topped with a hipped asphalt shingle roof intersected by an eyebrow dormer above the facade, a clipped gable above the facade, and a shed roof dormer above the east facade. A large brick chimney is near the center of the house. The facade is clad in brown face brick laid in a Dutch bond pattern with accents of cast stone and decorative brickwork, with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the east corner of the facade beneath a two-story brick-clad porch with an arched opening supported by brick piers and accessed by a full-width porch. The first and second floor porches are surrounded by a brick kneewall and both porches have aluminum awnings. Three vinyl windows topped with blind arches are west of the entrances and set beneath a series of five vinyl windows framed by black shutters on the second floor. Windows have cast stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house. There is no garage.
813	3747 Tyler Street			1927	Italian Renaissance	1/garage	C	Unknown	Unknown	The house at 3747 Tyler Street is two-stories and topped with a hipped asphalt shingle roof intersected by a hipped roof dormer with three window openings above the facade and a shed roof dormer above the east facade. A large brick chimney is near the center of the house. The facade is clad in red face brick laid in a running bond pattern with accents of cast stone and decorative brickwork, with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the east corner of the facade beneath a two-story brick-clad porch with an arched opening supported by brick piers and accessed by a full-width porch. The first and second floor porches are surrounded by a brick kneewall. Three vinyl windows topped with decorative cast stone hoods are west of the entrances and set beneath a large vinyl windows framed by beige shutters on the second floor. Windows have cast stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house. A front gable roof garage is at the rear of the property.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
814	3754 Tyler Street			1927	Italian Renaissance	n/a	C	Unknown	Unknown	The house at 3754 Tyler Street is two-stories and topped with a hipped asphalt shingle roof with modillions, intersected by a hipped roof dormer with three windows above the facade and a shed roof dormer above the east facade. A large brick chimney is near the center of the house. The facade is clad in blonde face brick laid in a running bond pattern with accents of cast stone and decorative brickwork, with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the east corner of the facade beneath a two-story brick-clad porch with an arched opening supported by brick piers and accessed by a full-width porch. The first and second floor porches are surrounded by a brick kneewall. Three vinyl windows topped with transoms beneath cast stone arches are west of the entrances and set beneath a series of five hung windows framed by red shutters on the second floor. Windows have cast stone sills which are painted red. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house. There is no garage.
815	3755 Tyler Street			1927	Italian Renaissance	1/garage	C	Unknown	Unknown	The house at 3755 Tyler Street is two-stories and topped with a hipped asphalt shingle roof with a denticulated cornice, intersected by a hipped roof dormer with two windows above the facade and a shed roof dormer above the east facade. A large brick chimney is near the center of the house. The facade is clad in brown face brick laid in a running bond pattern with accents of cast stone and decorative brickwork, with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the east corner of the facade beneath a two-story brick-clad porch with an arched opening supported by brick piers and accessed by a full-width porch. The second-floor balcony is topped with a hipped roof supported by brick piers. The first and second floor porches are surrounded by a brick kneewall. Three wood windows topped with transoms beneath cast stone arches are west of the entrances and set beneath a series of five hung windows framed by white shutters on the second floor. Windows have cast stone sills and are fitted with wood storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house. A hipped roof garage is at the rear of the property.
816	3759 Tyler Street			1927	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3759 Tyler Street is two-stories and topped with a side jerkinhead asphalt shingle roof intersected by two front jerkinhead roofs with knee brackets above the facade and a front jerkinhead roof at the rear. A large brick chimney is near the center of the house. The facade is clad in blonde and brown face brick laid in a Dutch bond pattern with accents of cast stone, decorative brickwork, shingles, stucco, and wood false half-timbering, with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the east corner of the facade beneath a two-story brick-clad porch with a square opening supported by brick piers and accessed by a full-width porch. The first and second floor porches are surrounded by low metal railings and are sheltered by aluminum awnings. Three casement windows topped with arched transoms are west of the entrances and set beneath a series of five casement windows on the second floor. Windows have cast stone sills and are fitted with aluminum storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house. A pyramidal roof garage is at the rear of the property.
817	3760 Tyler Street			1927	Tudor Revival	n/a	C	Unknown	Unknown	The house at 3760 Tyler Street is two-stories and topped with a hipped asphalt shingle roof intersected by a jerkinhead dormer with two windows above the facade, a large gable roof with knee brackets above the facade, and a shed roof dormer above the east facade. A large brick chimney is near the center of the house. The facade is clad in brown face brick laid in a running bond pattern with accents of cast stone and decorative brickwork, with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the east corner of the facade beneath a two-story brick-clad porch with an arched opening supported by brick piers and accessed by a full-width porch. The first and second floor porches are surrounded by a brick kneewall. Three casement windows topped with transoms and decorative cast stone hoods are west of the entrances and set beneath a series of five casement windows on the second floor. Windows have cast stone sills. Similar windows are arranged on other elevations. There is no driveway and no garage.
818	3768 Tyler Street			1927	Italian Renaissance	n/a	C	Unknown	Unknown	The house at 3768 Tyler Street is two-stories and topped with a side jerkinhead asphalt shingle roof intersected by three front jerkinhead dormers clad in shingles and a front jerkinhead roof at the rear. A large brick chimney is near the center of the house. The facade is clad in blonde, brown, and red face brick laid in a running bond pattern with accents of cast stone, decorative brickwork, and shingles, with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the east corner of the facade beneath a two-story brick-clad porch with a square opening supported by brick piers and accessed by a full-width porch. The second floor porch is surrounded by a low metal railing and is sheltered by an aluminum awning, while the first floor railings have been removed. Three casement windows topped with blind arch transoms are west of the entrances and set beneath a series of five casement windows framed by green shutters and sheltered by an aluminum awning on the second floor. Windows have cast stone sills that are painted green and some are fitted with storms. Similar windows are arranged on other elevations. There is no driveway. A garage is at the rear of the property accessed by the alley.
819	3769 Tyler Street			1927	Italian Renaissance	1/garage	C	Unknown	Unknown	The house at 3769 Tyler Street is two-stories and topped with a hipped asphalt shingle roof intersected by a hipped roof dormer with three windows above the facade and a shed roof dormer above the east facade. A large brick chimney is near the center of the house. The facade is clad in blonde face brick laid in a running bond pattern with accents of cast stone and decorative brickwork, with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the east corner of the facade beneath a two-story, partially demolished brick-clad porch supported by brick piers and accessed by a full-width porch. The first and second floor porches are surrounded by a brick kneewall. Three vinyl windows topped with transoms and decorative cast stone hoods are west of the entrances and set beneath a series of five hung windows framed by white shutters on the second floor. Windows have cast stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house. A side gable roof garage is at the rear of the property.
820	3774 Tyler Street			1927	Italian Renaissance	n/a	C	Unknown	Unknown	The house at 3774 Tyler Street is two-stories and topped with a hipped asphalt shingle roof with modillions, intersected by a hipped roof dormer with three windows above the facade. A large brick chimney is near the center of the house. The facade is clad in brown face brick laid in a running bond pattern with accents of cast stone and decorative brickwork, with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the east corner of the facade beneath a two-story brick-clad porch with an arched opening supported by brick piers and accessed by a full-width porch. The first and second floor porches are surrounded by a brick kneewall. Three casement windows topped with leaded glass transoms are west of the entrances and set beneath a series of five casement windows framed by yellow shutters on the second floor. Windows have cast stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house. There is no garage.
821	3775 Tyler Street			1927	Tudor Revival	n/a	C	Unknown	Unknown	The house at 3775 Tyler Street is two-stories and topped with a side jerkinhead asphalt shingle roof intersected by a hipped, vinyl-clad roof dormer with two windows above the facade, a prominent curved bay on the facade, and a hipped roof at the rear. A large brick chimney is near the center of the house. The facade is clad in red face brick laid in a running bond pattern with accents of cast stone and decorative brickwork, with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the east corner of the facade beneath a two-story brick-clad porch with square openings supported by brick piers and accessed by a full-width porch. The first and second floor porches are surrounded by a brick kneewall and have aluminum awnings. Four vinyl windows topped with vinyl transoms are set within the bay west of the entrances and set beneath a series of four vinyl windows with transoms on the second floor. Windows have cast stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house. There is no garage.
822	3782 Tyler Street			1927	Tudor Revival	n/a	C	Unknown	Unknown	The house at 3782 Tyler Street is two-stories and topped with a hipped asphalt shingle roof intersected by a single-clad jerkinhead dormer with two windows above the facade, a large jerkinhead gable with knee brackets above the facade, and a shed roof dormer above the east facade. A large brick chimney is near the center of the house. The facade is clad in blonde face brick laid in a running bond pattern with accents of cast stone and decorative brickwork, with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the east corner of the facade beneath a two-story brick-clad porch with an arched opening supported by brick piers and accessed by a full-width porch. The first and second floor porches are surrounded by a brick kneewall. Three casement windows topped with transoms and decorative cast stone hoods are west of the entrances and set beneath a series of five hung windows on the second floor. Windows have cast stone sills and are fitted with aluminum storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house. There is no garage.
823	3783 Tyler Street			1927	Tudor Revival	n/a	C	Unknown	L.F. Crane	The house at 3783 Tyler Street is two-stories and topped with a side jerkinhead asphalt shingle roof intersected by two jerkinhead gables above the facade and a hipped roof at the rear. A large brick chimney is near the center of the house. The facade is clad in blonde face brick laid in a running bond pattern with accents of cast stone, decorative brickwork, stucco, wood false half-timbering, and shingles with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the west corner of the facade beneath a two-story brick-clad porch with square openings supported by brick piers and accessed by a full-width porch. The first floor porch is surrounded by a brick kneewall and the second floor has black metal railings. Both have aluminum awnings. Three vinyl windows are east of the entrances and set beneath two series of three vinyl windows on the second floor. Windows have cast stone sills that have been painted white. Similar windows are arranged on other elevations. A concrete driveway runs along the west side of the house. There is no garage.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
824	3788 Tyler Street			1927	Italian Renaissance	n/a	C	Unknown	Unknown	The house at 3788 Tyler Street is two-stories and topped with a hipped asphalt shingle roof with a denticulated cornice, intersected by a hipped roof dormer with two windows above the facade. A brick chimney is near the center of the house. The facade is clad in red-brown face brick laid in a running bond pattern with accents of cast stone and decorative brickwork, with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the east corner of the facade beneath a two-story brick-clad porch with an arched opening supported by brick piers and accessed by a full-width porch screened porch topped with an aluminum awning. The second-floor balcony is topped with a hipped roof supported by brick piers. The first and second floor porches are surrounded by a brick kneewall. Three windows topped with cast stone arches are west of the entrances and set beneath a large vinyl window framed by white shutters on the second floor. Windows have cast stone sills which have been painted white. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house. There is no garage.
825	3789 Tyler Street			1927	Tudor Revival	n/a	C	Unknown	Unknown	The house at 3789 Tyler Street is two-stories and topped with a side jerkinhead asphalt shingle roof intersected by two front jerkinhead roofs above the facade and a hipped roof at the rear. A brick chimney is near the center of the house. The facade is clad in blonde and brown face brick laid in a Dutch bond pattern with accents of cast stone, decorative brickwork, and aluminum siding, with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the east corner of the facade beneath a two-story brick-clad porch with a square opening supported by brick piers and accessed by a full-width porch. The first and second floor porches are surrounded by low metal railings and are sheltered by aluminum awnings. Three casement windows topped with arched transoms are west of the entrances and set beneath a series of five leaded glass casement windows on the second floor. Windows have cast stone sills and are fitted with aluminum storms. Similar windows are arranged on other elevations. An infilled concrete ribbon driveway runs along the east side of the house. There is no garage.
826	3794 Tyler Street			1927	Italian Renaissance	n/a	C	Unknown	Unknown	The house at 3794 Tyler Street is two-stories and topped with a hipped asphalt shingle roof with a denticulated cornice, intersected by a hipped roof dormer with two windows above the facade. A brick chimney is near the center of the house. The facade is clad in blonde and brown face brick laid in a Dutch bond pattern with accents of cast stone and decorative brickwork, with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is west the east corner of the facade beneath a two-story brick-clad porch with an arched opening supported by brick piers and accessed by a full-width porch. The second-floor balcony is topped with a hipped roof supported by brick piers. The first floor porch is surrounded by a brick kneewall and the second floor balcony has a brick kneewall. Three monopane windows topped with transoms beneath cast stone arches are east of the entrances and set beneath a series of five windows framed by cream shutters on the second floor. Windows have cast stone sills some of which are painted. Similar windows are arranged on other elevations. A concrete driveway runs along the west side of the house. There is no garage.
827	3795 Tyler Street			1927	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3795 Tyler Street is two-stories and topped with a side jerkinhead asphalt shingle roof intersected by a hipped, aluminum-clad roof dormer with two windows above the facade, a prominent curved bay on the facade, and a hipped roof at the rear. A brick chimney is near the center of the house. The facade is clad in red face brick laid in a running bond pattern with accents of cast stone and decorative brickwork, with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the west corner of the facade beneath a two-story brick-clad porch with square openings supported by brick piers and accessed by a full-width porch. The first floor porch is surrounded by a short metal railing and the second floor porch is surrounded by a brick kneewall. Both have aluminum awnings. Four leaded glass windows are set within the bay east of the entrances and set beneath four leaded glass windows on the second floor. Windows have cast stone sills and are fitted with aluminum storms. Similar windows are arranged on other elevations. A concrete driveway runs along the west side of the house. A hipped roof garage is at the rear of the property.
828	3800 Tyler Street			1927	Tudor Revival	n/a	C	Unknown	Unknown	The house at 3800 Tyler Street is two-stories and topped with a side jerkinhead asphalt shingle roof intersected by two jerkinhead gables above the facade and a hipped roof at the rear. A brick chimney is near the center of the house. The facade is clad in orange face brick laid in a running bond pattern with accents of cast stone, vinyl, and shingles with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the east corner of the facade beneath a two-story brick-clad porch with square openings supported by brick piers and accessed by a full-width porch. The first floor porch is surrounded by a brick kneewall and the second floor has black metal railings and is sheltered by an aluminum awning. Three vinyl windows topped with cast stone arches are west of the entrances and set beneath two series of three vinyl windows on the second floor. Windows have cast stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the west side of the house. There is no garage.
829	3803 Tyler Street			1927	Italian Renaissance	1/garage	C	Unknown	Unknown	The house at 3803 Tyler Street is two-stories and topped with a hipped asphalt shingle roof intersected by a hipped roof dormer with no windows above the facade. A brick chimney is near the center of the house. The facade is clad in orange face brick laid in a running bond pattern with accents of cast stone, with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the east corner of the facade beneath a two-story brick-clad porch with square openings supported by brick piers and accessed by a full-width porch. The second-floor balcony is topped with a hipped roof supported by brick piers. The first floor porch is surrounded by a brick kneewall and has an aluminum awnings and the second floor has black metal railings. Three leaded glass windows set beneath a blind brick arch are west of the entrances and set beneath two series of three vinyl and wood windows on the second floor. Windows have cast stone sills which are painted white and some are fitted with aluminum storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house. A front gable roof garage is at the rear of the property.
830	3810 Tyler Street			1927	Italian Renaissance	n/a	C	Unknown	Unknown	The house at 3810 Tyler Street is two-stories and topped with a hipped asphalt shingle roof with modillions, intersected by a hipped roof dormer with two windows above the facade. A brick chimney is near the center of the house. The facade is clad in red-brown face brick laid in a running bond pattern with accents of cast stone and decorative brickwork, with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the west corner of the facade beneath a two-story brick-clad porch with an arched opening supported by brick piers and accessed by a full-width porch. The second-floor balcony is topped with a hipped roof supported by brick piers. The first floor porch and the second floor balcony have a brick kneewall. Three casement windows topped with transoms are east of the entrances and set beneath a series of five windows on the second floor. Windows have cast stone sills and some are fitted with aluminum storms. Similar windows are arranged on other elevations. A concrete driveway runs along the west side of the house. There is no garage.
831	3811 Tyler Street			1927	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3811 Tyler Street is two-stories and topped with a side gable asphalt shingle roof intersected by two jerkinhead gables above the facade and a hipped roof at the rear. A brick chimney is near the center of the house. The facade is clad in red-brown face brick laid in a running bond pattern with accents of cast stone, decorative brickwork, stucco, and wood false half-timbering, with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the west corner of the facade beneath a two-story brick-clad porch with square openings supported by brick piers and accessed by a full-width porch. The first floor porch and second floor balcony are surrounded by a brick kneewall. Vinyl windows are east of the entrances and set beneath two series of three vinyl windows on the second floor. Windows have cast stone sills that have been painted white. Similar windows are arranged on other elevations. A concrete driveway runs along the west side of the house. A hipped roof garage is at the rear of the property.
832	3816 Tyler Street			1928	Tudor Revival	n/a	C	Unknown	Unknown	The house at 3816 Tyler Street is two-stories and topped with a hipped asphalt shingle roof intersected by two front jerkinhead gables above the facade. A brick chimney is near the center of the house. The facade is clad in honey-colored face brick laid in a running bond pattern with accents of cast stone, decorative brickwork, stucco, and wood false half-timbering, with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the east corner of the facade beneath a two-story brick-clad porch with a square opening supported by brick piers and accessed by a full-width porch. The first floor porch is surrounded by a brick kneewall and the second floor balcony has wood railings. Both are sheltered by aluminum awnings. A large vinyl window is west of the entrances and set beneath a series of three vinyl windows on the second floor. Windows have cast stone sills which have been painted. Similar windows are arranged on other elevations. An concrete driveway runs along the east side of the house. There is no garage.
833	3817 Tyler Street			1927	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 3817 Tyler Street is two-stories and topped with a side gable asphalt shingle roof with modillions intersected by a large front gable above the facade and a hipped roof at the rear. A brick chimney is near the center of the house. The facade is clad in blonde face brick laid in a running bond pattern with accents of cast stone and decorative brickwork, with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the east corner of the facade beneath a two-story, full-width porch topped with the large front gable roof supported by square wood columns. Neither porch has railings. Three wood windows set beneath a blind brick arch (obscured by the second floor porch) are west of the entrances and set beneath two series of three wood windows on the second floor. Windows have cast stone sills and some are fitted with aluminum storms. Similar windows are arranged on other elevations. A concrete ribbon driveway runs along the east side of the house. A hipped roof garage is at the rear of the property.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
834	3824 Tyler Street			1928	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3824 Tyler Street is two-stories and topped with a hipped asphalt shingle roof intersected by two front jerkinhead gables above the facade. A brick chimney is near the center of the house. The facade is clad in blonde and brown face brick laid in a Dutch bond pattern with accents of cast stone, decorative brickwork, and shingles, with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the west corner of the facade beneath a two-story brick-clad porch with a square opening supported by brick piers and accessed by a full-width porch. The first floor porch does not have a railing and the second floor porch surrounded by a wood railing. Three vinyl windows topped with arched leaded glass transoms are east of the entrances and set beneath a large vinyl window on the second floor. Windows have cast stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house. A hipped roof garage is at the rear of the property.
835	3825 Tyler Street			1928	Tudor Revival	n/a	C	Unknown	Unknown	The house at 3825 Tyler Street is two-stories and topped with a hipped asphalt shingle roof with a denticulated cornice intersected by two front jerkinhead gables above the facade. A brick chimney is near the center of the house. The facade is clad in orange face brick laid in a running bond pattern with accents of cast stone, decorative brickwork, stucco, and wood false half-timbering, with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the west corner of the facade beneath a two-story brick-clad porch with an arched opening supported by brick piers and accessed by a full-width porch. The first floor porch and second floor balcony are surrounded by brick kneewalls. The second floor balcony has metal framing for a canopy. A series of three wood leaded glass windows are east of the entrances and set beneath a series of three wood leaded glass windows on the second floor. Windows have cast stone sills and are fitted with aluminum storms. Similar windows are arranged on other elevations. A concrete driveway runs along the west side of the house. There is no garage.
836	3830 Tyler Street			1928	Prairie	n/a	C	Unknown	Unknown	The house at 3830 Tyler Street is two-stories and topped with a hipped asphalt shingle roof with modillions, intersected by a gable roof dormer with two windows above the facade. A brick chimney is near the center of the house. The facade is clad in red-brown face brick laid in a running bond pattern with accents of cast stone and decorative brickwork, with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the east corner of the facade beneath a two-story brick-clad porch with a square opening supported by brick piers and accessed by a full-width porch. The second-floor balcony is topped with a gable roof supported by brick piers. The first floor porch and the second floor balcony have brick kneewalls. Three windows, two with leaded glass upper sashes, are west of the entrances and set beneath the same types of windows on the second floor. Windows have cast stone sills which have been painted green. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house. There is no garage.
837	3831 Tyler Street			1928	Prairie	1/garage	C	Unknown	Unknown	The house at 3831 Tyler Street is two-stories and topped with a hipped asphalt shingle roof with a denticulated cornice, intersected by a gable roof dormer with two windows above the facade. A brick chimney is near the center of the house. The facade is clad in red face brick laid in a running bond pattern with accents of cast stone and decorative brickwork, with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the east corner of the facade beneath a two-story brick-clad porch with squared openings supported by brick piers and accessed by a full-width porch. The second-floor balcony is topped with a gable roof with false half-timbering enclosed by a pent roof supported by brick piers. The first floor porch and the second floor balcony have brick kneewalls. Three windows with leaded glass upper sashes are west of the entrances and set beneath the same types of windows on the second floor. Windows have cast stone sills and are fitted with aluminum storms. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house. A front gable roof garage is at the rear of the property.
838	3838 Tyler Street			1940	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3838 Tyler Street is one-and-a-half-stories and topped with a side gable asphalt shingle roof intersected by a large jerkinhead gable above the facade. A prominent brick chimney is at the eave near the center of the west facade. The exterior is clad in orange brick veneer laid in a running bond pattern with accents of cast stone and decorative brickwork. The primary entrance to both units is framed by brick, sheltered by a metal awning with heraldic details, and is near the east corner of the facade set within a protruding front gable. The entrance is accessed by a full-width brick-clad concrete porch. Glass block windows are on either side of the entrance, and a pair of vinyl windows are on the first and second floor facades. Windows have brick sills. Similar windows are arranged on other elevations. A concrete driveway runs along the rear side of the property. A front gable roof garage is at the rear of the property.
839	3839 Tyler Street			1939	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 3839 Tyler Street is one-and-a-half-stories and topped with a side gable asphalt shingle roof intersected by two front gables above the facade. A large brick chimney is at the eave near the center of the east facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of cast stone. The primary entrance is near the center of the facade and trimmed with stone and set within a projecting front gable. The entrance is accessed by a large, partially demolished brick-clad concrete porch with a low metal railing. The adjacent projecting gable contains a bay with casement or fixed windows east of the entrance and set beneath a steel casement window on the second floor. A vinyl window is west of the entrance. Windows have stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the rear side of the property. A hipped roof garage is at the rear of the property.
840	4000 Tyler Street			1940	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4000 Tyler Street is one-and-a-half-stories and topped with a side gable asphalt shingle roof intersected by two jerkinhead gables above the facade. A large brick chimney is at the eave near the center of the east facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of cast stone and decorative brickwork. The primary entrance is near the west corner of the facade, trimmed with stone and framed with casement windows, and set within a projecting front gable. The entrance is accessed by a partially demolished brick-clad concrete porch. The adjacent gable east of the entrance contains a bay with casement windows topped with leaded glass transoms set beneath a steel casement window on the second floor. Windows have stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the rear side of the property. There is no garage.
841	4003 Tyler Street			1940c.	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4003 Tyler Street is one-and-a-half-stories and topped with a side gable asphalt shingle roof intersected by a large front gable above the facade and a front gable roof at the rear. A large brick chimney is at the eave near the center of the west facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of cast stone, some of which has been painted purple. The primary entrance is near the east corner of the facade, trimmed with stone, and set within a projecting, shallow front gable. The entrance is accessed by a brick-clad concrete porch. A bay with vinyl windows is west of the entrance and a vinyl window is centered on the second floor of the front gable. Windows have stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the rear side of the property. A front gable roof garage is at the rear of the property. A black lightpost topped with a lantern-style fixture is near the center of the front lawn.
842	4010 Tyler Street			1940	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4010 Tyler Street is one-and-a-half-stories and topped with a side gable asphalt shingle roof intersected by two front gables above the facade. A large brick chimney is at the eave near the center of the east facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of cast stone. The primary entrance is trimmed in cast stone, sheltered by a metal awning with heraldic details, and is near the west corner of the facade set within a protruding front gable. The entrance is accessed by a full-width brick-clad concrete porch surrounded by a low metal railing. Leaded glass windows are on either side of the entrance and a bay with steel casement windows is east of the entrance. Above the bay is a brick veneer and aluminum clad front gable with a vinyl window. Windows have cast stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the west side of the property. There is not garage.
843	4011 Tyler Street			1939	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4011 Tyler Street is one-and-a-half-stories and topped with a side gable asphalt shingle roof intersected by a front gable and a polygonal roof on the facade. A large brick chimney is at the eave near the front of the east facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer and cast stone. The primary entrance is trimmed in cast stone near the west corner of the facade and set within a polygonal vestibule topped with a polygonal roof. The entrance is accessed by a full-width brick-clad concrete porch surrounded by a low metal railing. Leaded glass windows are on either side of the entrance and a bay with four leaded glass windows is east of the entrance. Above the bay is a window trimmed in stone beneath a stone and brick blind arch. Windows have cast stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the west side of the property. A pyramidal roof garage is at the rear of the property. A black lightpost topped with a lantern-style fixture is near the center of the front lawn.
844	4019 Tyler Street			1939	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4019 Tyler Street is one-and-a-half-stories and topped with a side gable asphalt shingle roof intersected by two front gables above the facade. A large brick chimney is at the eave near the front of the east facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer and cast stone. The primary entrance is trimmed in cast stone near the west corner of the facade and set within a front gable vestibule. The entrance is accessed by a full-width brick-clad concrete porch. A series of three wood 6-over-1 windows glass windows set beneath a single wood 6-over-1 window are centered in the larger front gable. The porch, entrance, and second floor window are sheltered by aluminum awnings. Windows have brick sills. Similar windows are arranged on other elevations. A concrete driveway runs along the west side of the property. A pyramidal roof garage is at the rear of the property. A white lightpost topped with a lantern-style fixture is near the center of the front lawn.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
845	4020 Tyler Street			1940	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4020 Tyler Street is one-and-a-half-stories and topped with a side gable asphalt shingle roof intersected by two front gables above the facade. A large brick chimney is at the eave near the front of the east facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of cast stone and decorative brickwork. The primary entrance is trimmed in cast stone near the west corner of the facade and set within a front gable vestibule. The entrance is accessed by a full-width brick-clad concrete porch with a low metal railing and a metal awning structure. Vinyl windows are on either side of the entrance, a bay with vinyl windows is east of the entrance, and a vinyl window is centered above the bay on the second floor. Windows have cast stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the west side of the property. A pyramidal roof garage is at the rear of the property. A white lightpost topped with a lantern-style fixture is near the center of the front lawn.
846	4024 Tyler Street			1938	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4024 Tyler Street is two-stories and topped with a hipped asphalt shingle roof intersected by a small gable above the facade. A brick kneewall extends outward from the east corner of the facade. A large brick chimney is at the eave near the front of the east facade. The exterior is clad in red-brown brick veneer laid in a running bond pattern with accents of cast stone and decorative brickwork. The primary entrance is trimmed in cast stone near the west corner of the facade, is sheltered by an aluminum awning, and is accessed by a brick-clad concrete porch. A bay containing steel casement and leaded glass windows is east of the entrance and a steel casement and a leaded glass window are arranged on the second floor. Windows have cast stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the west side of the property. A pyramidal roof garage is at the rear of the property. A white lightpost topped with an acorn-style fixture is near the center of the front lawn.
847	4025 Tyler Street			1940	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4025 Tyler Street is one-and-a-half-stories and topped with a side gable asphalt shingle roof intersected by a large front gable above the facade. A large brick chimney is at the eave near the front of the east facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of cast stone, decorative brickwork, and wood false half-timbering. The primary entrance is trimmed in fluted cast stone near the west corner of the facade, set within a front gable vestibule, and is accessed by a full-width brick-clad concrete porch with a low metal railing. The porch and entrance have aluminum awnings. A series of three vinyl windows are east of the entrance and a vinyl window is centered in the gable on the second floor. Windows have cast stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the west side of the property. A front gable roof garage is at the rear of the property.
848	4031 Tyler Street			1940	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4031 Tyler Street is one-and-a-half-stories and topped with a side gable asphalt shingle roof intersected by a large front gable above the facade. A large brick chimney is at the eave near the front of the east facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of cast stone and decorative brickwork. The primary entrance is trimmed in cast stone near the west corner of the facade, set within a front gable vestibule, and is accessed by a full-width brick-clad concrete porch with a metal railing. The entrance has an aluminum awning. A bay with windows sheltered by aluminum awnings is east of the entrance but obscured by foliage. A steel casement window with an awning is centered in the front gable on the second floor. Windows have cast stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the west side of the property. A hipped roof garage is at the rear of the property.
849	4032 Tyler Street			1938	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4032 Tyler Street is two-stories and topped with a hipped asphalt shingle roof intersected by a small gable and polygonal roof above the facade. A stone battered wall extends outward from the east corner of the facade. A large brick chimney is at the eave near the front of the east facade. The exterior is clad in red-brown brick veneer laid in a running bond pattern with accents of cast stone, stone veneer, and decorative brickwork. The primary entrance is trimmed in cast stone near the west corner of the facade and is accessed by a brick-clad concrete porch with a low metal railing and a metal awning structure. A two-story bay with a polygonal roof is east of the entrance and contains vinyl windows on the first floor and steel windows on the second floor. A steel leaded glass window is west of the bay on the second floor. Windows have cast stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the west side of the property. A pyramidal roof garage is at the rear of the property. A white lightpost topped with a lantern-style fixture is near the center of the front lawn.
850	4040 Tyler Street			1940	French Eclectic	n/a	C	Unknown	Unknown	The house at 4040 Tyler Street is two-stories and topped with a hipped asphalt shingle roof intersected by a small gable above the facade. A large brick chimney is at the eave near the front of the east facade. The exterior is clad in red-brown brick veneer laid in a running bond pattern with accents of cast stone. The primary entrance is trimmed in cast stone near the west corner of the facade, is sheltered by an aluminum awning, and is accessed by a brick-clad concrete porch with a low metal railing. A bay containing vinyl windows is east of the entrance and vinyl windows are arranged on the second floor. Windows have cast stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the west side of the property. There is no garage. A black lightpost topped with a lantern-style fixture is near the center of the front lawn.
851	4041 Tyler Street			1939	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4041 Tyler Street is one-and-a-half-stories and topped with a side gable asphalt shingle roof intersected by two front gables above the facade. A large brick chimney is at the eave near the front of the east facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of cast stone and decorative brickwork. The primary entrance is trimmed in cast stone near the west corner of the facade, set within a front gable vestibule, and is accessed by a full-width brick-clad concrete porch with a low metal railing. A series of three wood 6-over-1 windows are east of the entrance and set beneath a wood 6-over-1 window centered in the gable on the second floor. The entrance, porch, and second floor windows have aluminum awnings. Windows have cast stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the west side of the property. A hipped roof garage is at the rear of the property. A white lightpost topped with a lantern-style fixture is near the center of the front lawn.
852	4046 Tyler Street			1941	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4046 Tyler Street is one-and-a-half-stories and topped with a side gable asphalt shingle roof intersected by a large front gable above the facade. A large brick chimney is at the eave near the front of the east facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of cast stone and decorative brickwork. The primary entrance is trimmed in cast stone near the west corner of the facade, set within a polygonal vestibule topped with a polygonal roof, and is accessed by a full-width brick-clad concrete porch with a low metal railing. A steel casement window is east of the entrance and set beneath a vinyl window in the gable end on the second floor. Windows have cast stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the west side of the property. A front gable roof garage is at the rear of the property.
853	4047 Tyler Street			1939	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4047 Tyler Street is one-and-a-half-stories and topped with a side gable asphalt shingle roof intersected by a large front gable above the facade. A large brick chimney is at the eave near the front of the east facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of cast stone and decorative brickwork. The primary entrance is trimmed in cast stone near the west corner of the facade, set within a front gable vestibule, and is accessed by a brick-clad concrete porch with a low metal railing. The entrance has an aluminum awning. A bay with wood windows is east of the entrance and set beneath a pair of wood windows on the second floor. Windows have brick sills. Similar windows are arranged on other elevations. A concrete driveway runs along the west side of the property. A hipped roof garage is at the rear of the property.
854	4052 Tyler Street			1930	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4052 Tyler Street is two-stories and topped with a hipped asphalt shingle roof intersected by hipped and gable roofs above the facade. A battered stone wall extends from the east corner of the facade. A brick chimney is near the center of the house. The exterior is clad in red brick veneer laid in a running bond pattern with copious accents of cast stone. The primary entrance is trimmed in cast stone near the west corner of the facade, is set within a two-story rectangular bay, and is accessed by a brick and concrete porch with a metal railing. A single-story stone veneer-clad bay containing vinyl windows is east of the entrance and vinyl windows are arranged above on the second floor. Windows have cast stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the west side of the property. There is no garage. A black lightpost without a light fixture is near the center of the front lawn.
855	4053 Tyler Street			1930	French Eclectic	n/a	C	Unknown	Unknown	The house at 4053 Tyler Street is two-stories and topped with a hipped asphalt shingle roof intersected by an eyebrow wall dormer and conical tower on the facade. A battered stone wall extends from the east corner of the facade. A large brick chimney is at the eave near the front of the east facade. The exterior is clad in red brick veneer laid in a running bond pattern with copious accents of cast stone and decorative brickwork. The primary entrance is trimmed in brick near the west corner of the facade, is set within a two-story circular tower topped with a conical roof, and is accessed by a brick and stone porch with a low metal railing. A single-story bay containing vinyl windows is east of the entrance, vinyl windows with aluminum awnings are above on the second floor, and arched window openings are set within the tower. Windows have cast stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the west side of the property. There is no garage. A black lightpost with a lantern-style fixture is near the center of the front lawn.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
856	4058 Tyler Street			1930	French Eclectic	n/a	C	Unknown	Unknown	The house at 4058 Tyler Street is two-stories and topped with a hipped asphalt shingle roof intersected by a hipped tower on the facade. A brick chimney is at the eave near the front of the west facade. The exterior is clad in brown brick veneer laid in a running bond pattern with copious accents of cast stone and decorative brickwork. The primary entrance is trimmed in brick and cast stone and is set within a two-story tower near the east corner of the facade. The entrance is accessed by a brick and concrete porch. Three wood 9-over-1 windows are west of the entrance and set beneath three of the same windows, but topped with brick arches, on the second floor. Another wood window is centered above the entrance. Windows have cast stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the west side of the property. There is no garage.
857	4059 Tyler Street			1930	French Eclectic	n/a	C	Unknown	Unknown	The house at 4059 Tyler Street is two-stories and topped with a hipped asphalt shingle roof intersected by a shed roof wall dormer and conical tower on the facade. A battered stone wall extends from the west corner of the facade. A large brick chimney is at the eave near the front of the west facade. The exterior is clad in orange brick veneer laid in a running bond pattern with copious accents of cast stone and decorative brickwork. The primary entrance is trimmed in stone near the east corner of the facade, is set within a two-story circular tower topped with a conical roof, and is accessed by a full-width brick and stone porch with a low metal railing and an aluminum awning. A large vinyl window is west of the entrance, three vinyl windows with blind arch transoms are centered above on the second floor, and arched window openings are set within the tower. Windows have cast stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property. There is no garage.
858	4066 Tyler Street			1930	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4066 Tyler Street is two-stories and topped with a side gable asphalt shingle roof intersected by front gable roof, conical roof, and a small gable roof dormer above the facade and a hipped roof at the rear. A battered stone wall extends from the east corner of the facade. A brick chimney is near the center of the house. The exterior is clad in brown brick veneer laid in a running bond pattern with copious accents of cast stone and decorative brickwork. The primary entrance is trimmed in stone near the west corner of the facade, is set within a rectangular bay with a second-story porch, and is accessed by a full-width brick and stone porch with a low metal railing. A two-story conical tower is nested near the entrance bay and opens onto the second-story balcony. A series of three vinyl windows are east of the entrance and set beneath the same windows on the second floor. Other small windows are arranged on the facade and on the tower. Windows have cast stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property. A hipped roof garage is at the rear of the property. A white lightpost with a lantern-style fixture is near the center of the front lawn.
859	4067 Tyler Street			1931	French Eclectic	n/a	C	Unknown	Unknown	The house at 4067 Tyler Street is two-stories and topped with a hipped asphalt shingle roof intersected by a flared hipped roof and eyebrow wall dormer above the facade. A battered stone wall extends from the east corner of the facade. A brick chimney is at the east facade. The exterior is clad in red brick veneer laid in a running bond pattern with copious accents of stone veneer. The primary entrance is trimmed in cast stone beneath a segmental arch near the west corner of the facade, is set within a two-story rectangular bay, and is accessed by a brick and concrete porch. A single-story bay containing vinyl windows is east of the entrance, a vinyl window is arranged above on the second floor, and a vinyl window is above the entrance. Windows have cast stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the west side of the property. There is no garage. A white lightpost with a lantern-style fixture is near the center of the front lawn.
860	4074 Tyler Street			1930	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4074 Tyler Street is two-stories and topped with a side gable asphalt shingle roof intersected by two flared hipped roofs with eyebrow wall dormers above the facade and a hipped roof at the rear. A battered stone wall extends from the west corner of the facade. A brick chimney is near the center of the house. The exterior is clad in red brick veneer laid in a running bond pattern with copious accents of stone veneer. The primary entrance is trimmed in cast stone near the east corner of the facade, is set within a two-story rectangular bay, and is accessed by a brick and concrete porch with a metal railing and an aluminum awnings. A single-story bay containing boarded window openings is west of the entrance, three window openings are above on the second floor, and a window opening is above the entrance. Window openings have cast stone sills. Wood or steel windows are arranged on other elevations. A concrete driveway runs along the east side of the property. A side gable roof garage is at the rear of the property.
861	4075 Tyler Street			1930	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4075 Tyler Street is two-stories and topped with a side gable asphalt shingle roof intersected by two hipped roofs, one with an eyebrow wall dormer, above the facade and a hipped roof at the rear. A battered stone wall extends from the west corner of the facade. A brick chimney is near the center of the house. The exterior is clad in brown brick veneer laid in a running bond pattern with copious accents of stone veneer. The primary entrance is trimmed in cast stone near the east corner of the facade, is set within a two-story rectangular bay, and is accessed by a stone and concrete porch with a metal railing and a fabric awning. A single-story bay containing windows is west of the entrance, a series of three wood windows are above on the second floor, and a wood window is above the entrance. A second-story bay window is near the center of the east facade. Windows have cast stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property. A gable roof garage is at the rear of the property.
862	4080 Tyler Street			1930	French Eclectic	1/garage	C	Unknown	Unknown	The house at 4080 Tyler Street is two-stories and topped with a side gable asphalt shingle roof intersected by front gable roof above the facade and a hipped roof at the rear. A battered brick wall extends from the east corner of the facade. A brick chimney is near the center of the house and a decorative chimney is near the center of the facade. The exterior is clad in red brick veneer laid in a running bond pattern with copious accents of stone veneer. The primary entrance is trimmed in brick near the west corner of the facade, is set within a rectangular bay with a second-story porch, and is accessed by a full-width brick and concrete porch with a low metal railing. A stepped parapet is above the entrance to the second floor balcony which is surrounded by a brick parapet. A large wood window within a shed roof bay is east of the entrance and a large vinyl window is on the second floor. Other small windows are arranged on the facade and on the tower. Windows have cast stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the west side of the property. A hipped roof garage is at the rear of the property. A black lightpost with a globe fixture is near the center of the front lawn.
863	4081 Tyler Street			1930	French Eclectic	n/a	C	Unknown	Unknown	The house at 4081 Tyler Street is two-stories and topped with a hipped asphalt shingle roof intersected by an eyebrow wall dormer and conical tower on the facade. A battered stone wall extends from the east corner of the facade. A brick chimney is near the center of the house. The exterior is clad in orange brick veneer laid in a running bond pattern with copious accents of cast stone and decorative brickwork. The primary entrance is arched and trimmed in brick near the west corner of the facade, is set within a two-story circular tower with a second floor balcony and topped with a conical roof, and is accessed by a brick and concrete porch with a metal railing. A single-story bay containing wood windows is east of the entrance, a series of wood windows are above on the second floor, arched windows are on either side of the entrance, and arched openings are on the second floor of the tower. Windows and openings have cast stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the west side of the property. There is no garage. A black lightpost with a lantern-style fixture is near the center of the front lawn.
864	4088 Tyler Street			1930	French Eclectic	n/a	C	Unknown	Unknown	The house at 4088 Tyler Street is two-stories and topped with a side gable asphalt shingle roof intersected by front gable roof, conical roof, and a hipped roof at the rear. A buttress is applied to the west corner of the facade. A brick chimney is near the center of the house. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer and decorative brickwork. The primary entrance is trimmed in stone near the east corner of the facade, is set within a rectangular bay with a second-story porch, and is accessed by a full-width brick and concrete porch. A two-story conical tower is nested near the entrance bay and opens onto the second-story balcony. A series of three wood windows are west of the entrance and set beneath three window openings on the second floor. Other small windows are arranged on the facade and on the tower. Windows have cast stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property. There is no garage.
865	4089 Tyler Street			1930	French Eclectic	n/a	C	Unknown	Unknown	The house at 4089 Tyler Street is two-stories and topped with a hipped asphalt shingle roof intersected by two front gables above the facade and a hipped roof at the rear. A battered stone wall extends from the west corner of the facade. A brick chimney is near the center of the house and a decorative chimney is near the center of the facade. The exterior is clad in red brick veneer laid in a running bond pattern with copious accents of stone veneer. The primary entrance is trimmed in cast stone near the east corner of the facade, is set within a two-story rectangular bay, and is accessed by a brick and concrete porch with a metal railing. A vinyl window is west of the entrance, a series of four vinyl windows are above on the second floor, and a hung window is above the entrance. Windows have cast stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property. There is no garage. A black lightpost with a lantern-style fixture is near the center of the front lawn.
866	4096 Tyler Street			1939	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4096 Tyler Street is one-and-a-half-stories and topped with a side gable asphalt shingle roof intersected by a front gable and a polygonal roof on the facade. A large brick chimney is at the eave near the front of the east facade. The exterior is clad in red brick veneer laid in a running bond pattern with accents of stone veneer and cast stone. The primary entrance is trimmed in cast stone near the center of the facade and set within a polygonal vestibule topped with a polygonal roof. The entrance is accessed by a full-width brick and concrete porch surrounded by a low metal railing. Small windows are west of the entrance, a bay with steel windows is east of the entrance, and a small window is above the bay. Windows have brick sills. Similar windows are arranged on other elevations, and another bay is on the west facade. A concrete driveway runs along the rear of the property. A front gable roof garage is at the rear of the property. A black lightpost topped with a lantern-style fixture is in the front lawn.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
867	4097 Tyler Street			1940	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4097 Tyler Street is one-and-a-half-stories and topped with a side gable asphalt shingle roof intersected by a large front gable above the facade and a hipped roof at the rear. A large brick chimney is at the eave near the front of the west facade. The exterior is clad in red and brown brick veneer laid in a running bond pattern with accents of stone veneer, cast stone, and decorative brickwork. The primary entrance is arched near the east corner of the facade, trimmed with stone and framed by windows, and set within a rectangular vestibule topped with a balcony with a low metal railing. The entrance is accessed by a full-width brick-clad concrete porch with a metal railing. A steel window is west of the entrance, a steel window is above on the second floor, and a small steel window is centered above in the attic space. Windows have brick sills and some have aluminum awnings. Similar windows are arranged on other elevations. A concrete driveway runs along the rear side of the property. A hipped roof garage is at the rear of the property. A black lightpost topped with a lantern-style fixture is near the center of the front lawn.
868	4200 Tyler Street			1925	Prairie	1/garage	C	Unknown	Unknown	The quadplex at 4200 Tyler Street is two-stories and topped with a hipped asphalt shingle roof, intersected by a hipped roof dormer centered above the primary facade. A brick chimney is at the eave on the east facade and another on the west facade of the house. The facade is clad in blonde and brown face brick laid in a running bond pattern. The primary entrance is centered the facade beneath a two-story porch supported by brick piers with brick kneewall, and the second floor balcony has a wood railing. Two-story canted bays sit on either side of the entrance, glazed by hung wood windows with divided upper sashes and aluminum storms. Windows have cast stone sills. Similar windows are arranged on other elevations. A garage with a hipped roof faces the alley.
869	4203 Tyler Street			1928	Spanish Eclectic	n/a	C	Unknown	John St John	The apartment building at 4203 Tyler Street is two-stories and topped with a deck, flat on hipped asphalt shingle roof intersected by a rear wing that has a combination of gabled roof and flat roof with parapet. A brick chimney topped with a bell tower is located the east facade near the center of the house. The facades are clad in brown face brick laid in a running bond pattern with accents of klinker brick. The primary entrance is centered on the facade beneath a brick arcaded portico with spiral cast stone columns and brick piers. The entrance is accessed by a brick and concrete porch with a metal railing. Three entrances to units are accessed along the east facade, with a combination of arched and flat top doors, each covered by a fabric awning and with a brick and concrete porch and a metal railing. Windows are steel casement across the facade, the larger sets with fixed transom and sidelights. On the east facade, one casement window has an arched fanlight and wrought iron Juliet balcony at the second floor. Windows have brick sills and rusticated stone lintels. There is no driveway or garage.
870	4210 Tyler Street			1925	Prairie	n/a	C	Unknown	Unknown	The duplex at 4210 Tyler Street is two-stories and topped with a hipped asphalt shingle roof, with a hipped roof dormer with two windows centered above the facade and a shed roof dormer facing east. A brick chimney is located near the center of the house. The facade is clad in blonde brick, with red common brick on the secondary facades, all laid in a running bond pattern with some decorative brickwork. The primary entrance to each unit is near the east corner the facade beneath an aluminum metal awning accessed by a brick and concrete porch with brick kneewall. West of the entrance is a two-story porch, the second-floor balcony has a wood railing and supported by brick piers. Wood casement windows with leaded glass detailing frame a door that opens onto the porch on both the first and second floor. Windows have aluminum storms and cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear. There is no garage.
871	4211 Tyler Street			1926	Tudor Revival	1/garage	C	Unknown	Unknown	The duplex at 4211 Tyler Street is two-stories and topped with a cross gable asphalt shingle roof, composed of a side gable that meets a hipped roof towards the rear, intersecting by two overlapping front gables, and with a hipped roof dormer facing east. A brick chimney is located near the center of the house. The facade is clad in red and brown brick, with red common brick on the secondary facades, all laid in a running bond pattern. There is false half-timbering beneath the front gables. The primary entrance to each unit is near the east corner the facade beneath a second floor balcony with a metal railing covered by an aluminum metal awning supported by brick piers. The entrance is accessed by a brick and concrete porch with a metal railing. West of the entrance are three wood casement windows with leaded glass detailing and transoms above, covered by an aluminum metal awning. Matching windows are on the second floor. Windows have aluminum storms and cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear where there is a front gable roof garage.
872	4216 Tyler Street			1926	Tudor Revival	n/a	C	Unknown	Unknown	The duplex at 4216 Tyler Street is two-stories and topped with a cross gable asphalt shingle roof, composed of a side gable that meets a hipped roof toward the rear, intersected by two overlapping front gables. A brick chimney is located near the eave on the west facade and another is near the center of the house. The facade is clad in light and dark brown face brick and secondary facades composed of red common brick, both laid in a running bond pattern, with wood shingles beneath the front gable and the side gables at the attic level. The primary entrance to each unit is near the east corner of the facade beneath a second floor balcony with metal awning and railing, supported by brick piers. The entrance is accessed by a concrete and brick full width porch West of the entrance are windows that have been boarded over, topped with brick arched surrounds and stone accents, beneath a large window opening on the second floor that has also been boarded over. Windows have cast stone sills. A concrete driveway runs along the east of the house to the rear. There is no garage.
873	4217 Tyler Street			1927	Prairie	1/garage	C	Unknown	Unknown	The duplex at 4217 Tyler Street is two-stories and topped with a hipped asphalt shingle roof, with a front gabled and an eyebrow dormer above the facade and a gable roof dormer facing east. A brick chimney is located near the center of the house. The facade is clad in brown brick, with red common brick on the secondary facades, all laid in a running bond pattern. The primary entrance to each unit is near the east corner the facade a second-floor balcony with metal awning and railing, supported by brick piers. The entrance is accessed by a brick and concrete porch with brick kneewall. West of the entrance are three wood casement windows with transoms that have leaded glass detailing, beneath matching windows on the second floor. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear where there is a hipped roof garage.
874	4224 Tyler Street			1925	Italian Renaissance	n/a	C	Unknown	Unknown	The duplex at 4224 Tyler Street is two-stories and topped with a hipped asphalt shingle roof, intersected by a hipped roof dormer above the facade and a shed roof dormer facing east. A brick chimney is located at the eave on the west facade and another is near the center of the house. The facade is clad in blonde face brick laid in a running bond pattern with accents of cast stone and decorative brickwork, with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the east corner of the facade accessed by a full-width porch with metal railing. Above the entrance are two narrow fixed windows with arched brick surrounds. West of the entrance are three vinyl hung windows recessed within brick arched surrounds, beneath three vinyl hung windows on the second floor. Windows have cast stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the west side of the house. There is no garage.
875	4225 Tyler Street			1924	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4225 Tyler Street is two-stories and topped with a front gable asphalt shingle roof intersected by continuous shed dormers facing east and west, creating a dual-pitched roof and overlapping front gable create the appearance of multi-level eaves. A brick chimney is at the eave on the west facade of the house. The facade is clad in wood clapboard siding. The primary entrance is near the east corner of the house beneath an aluminum metal awning and is accessed by a brick and concrete porch. Three wood windows are west of the entrance. On the second floor are three narrow wood casement windows. Similar windows are found on other elevations. A concrete driveway runs along the west of the house to the rear where there is a front gable roof garage.
876	4232 Tyler Street			1925	Prairie	n/a	C	Unknown	Unknown	The duplex at 4232 Tyler Street is two-stories and topped with a hipped asphalt shingle roof, with a hipped roof dormer with two windows centered above the facade and another hipped roof dormer facing east. A brick chimney is located at the eave on the west facade and another is near the center of the house. The facade is clad in brown brick, with red common brick on the secondary facades, all laid in a running bond pattern. The primary entrance to each unit is near the east corner the facade beneath a second-floor balcony with metal awning supported by brick piers that form an arched opening. The entrance is accessed by a brick and concrete porch with a metal railing. West of the entrance are three wood hung windows with leaded glass detailing on the upper sashes, topped with stucco-infilled arches and covered by an aluminum awning. Three similar windows are on the second floor. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear. There is no garage.
877	4238 Tyler Street			1925	Prairie	n/a	C	Unknown	Unknown	The duplex at 4238 Tyler Street is two-stories and topped with a hipped asphalt shingle roof, with a hipped roof dormer with three windows centered above the facade. A brick chimney is located near the center of the house. The facade is clad in blonde face brick with some decorative brickwork, and red common brick on the secondary facades laid in a running bond pattern. The primary entrance to each unit is near the east corner the facade beneath a second-floor balcony with metal awning supported by brick piers. The entrance is accessed by a brick and concrete porch with a brick kneewall. West of the entrance are three wood hung windows beneath three vinyl hung windows on the second floor. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear. There is no garage.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
878	4239 Tyler Street			1926	Tudor Revival	1/garage	C	Unknown	Unknown	The duplex at 4239 Tyler Street is two-stories and topped with a hipped asphalt shingle roof, intersected by a front gable, a shed roof dormer to the east, and a gabled roof dormer to the rear. A brick chimney is located near the center of the house. The facade is clad in red and brown face brick, with some decorative brickwork and cast stone accents, and secondary facades composed of red common brick, both laid in a running bond pattern. False half-timbering is present beneath the front gable at the attic level. The primary entrance to each unit is near the east corner of the facade beneath a second-floor balcony with metal awning and railing, supported by brick piers. The entrance is accessed by a concrete and brick full width porch. West of the entrance are casement windows that have aluminum storms affixed to the exterior, topped with brick infilled arched surrounds and stone accents, beneath a four narrow wood casement windows with leaded glass detailing on the second floor. Windows have cast stone sills. A concrete driveway runs along the east of the house to the rear where there is a pyramidal roof garage.
879	4245 Tyler Street			1925c.	Prairie	1/garage	C	Unknown	Unknown	The duplex at 4245 Tyler Street is two-stories and topped with a hipped asphalt shingle roof, with a hipped roof dormer above the facade and a hipped roof two story bay projecting off the west half of the facade. A brick chimney is located near the center of the house. The facade is clad in brown face brick with some decorative brickwork, and red common brick on the secondary facades laid in a running bond pattern. The primary entrance to each unit is near the east corner of the facade beneath and is accessed by a brick and concrete porch with a brick kneewall. Windows on the facade are wood hung with leaded glass detailing on the upper sashes. Windows have aluminum storms and cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear where there is a pyramidal roof garage.
880	4246 Tyler Street			1925	Prairie	n/a	C	Unknown	Unknown	The duplex at 4246 Tyler Street is two-stories and topped with a hipped asphalt shingle roof, with a hipped roof dormer clad in vinyl siding centered above the facade. A brick chimney is located near the center of the house. The facade is clad in light brown brick, with red common brick on the secondary facades, all laid in a running bond pattern. The primary entrance to each unit is near the east corner of the facade beneath a full width overhang that creates a second-floor balcony with metal awning supported by brick piers. The entrance is accessed by a brick and concrete porch with a brick kneewall. West of the entrance are three vinyl hung windows topped with stucco-infilled arches. Three similar windows are on the second floor. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear. There is no garage.
881	4254 Tyler Street			1923	Colonial Revival	n/a	C	Unknown	Unknown	The house at 4254 Tyler Street is two-stories and topped with a side gambrel asphalt shingle roof. A brick chimney is located at the eave on the west facade. The facade is clad with wood clapboard siding on the first floor, with wood shingle siding beneath a continuous shed dormer on the second floor, and beneath the side gable on the second floor. The primary entrance is near the east corner of the facade beneath a gabled overhang supported by metal posts, and is accessed by a brick and concrete porch. West of the entrance is are three wood hung windows with vertically divided upper sashes, and two pairs of matching wood hung windows with shutters on the second floor. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear. There is no garage.
882	4255 Tyler Street			1924	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 4255 Tyler Street is two-stories and topped with a side gambrel asphalt shingle roof. A brick chimney is located at the eave on the west facade. The facade is clad with vinyl siding on the first floor, with wood shingle siding beneath a continuous shed dormer on the second floor, and beneath the side gable on the second floor. The primary entrance is near the east corner of the facade beneath a gabled overhang supported by round wood columns, and is accessed by a brick and concrete porch with a brick kneewall. West of the entrance is are three wood hung windows with divided upper sashes, and two pairs of matching wood hung windows with shutters are on the second floor. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear where there is a pyramidal roof garage.
883	4260 Tyler Street			1924	Prairie	n/a	C	Unknown	Unknown	The duplex at 4260 Tyler Street is two-stories and topped with a hipped asphalt shingle roof, with a hipped roof dormer with four windows centered above the facade and another hipped roof dormer facing east. A brick chimney is located near the center of the house. The facade is clad in red and brown brick, with red common brick on the secondary facades, all laid in a running bond pattern. The primary entrance to each unit is near the east corner of the facade beneath a second-floor balcony with metal railing supported by brick piers. The entrance is accessed by a brick and concrete porch with a brick kneewall. West of the entrance are three vinyl hung windows, topped with stucco-infilled brick arches. Three similar windows are on the second floor. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear. There is no garage.
884	4261 Tyler Street			1924	Prairie	1/garage	C	Unknown	Unknown	The duplex at 4261 Tyler Street is two-stories and topped with a hipped asphalt shingle roof with modillions along the eave, with a hipped roof dormer with modillions centered above the facade and another hipped roof dormer facing east. A brick chimney is located at the eave on the west facade and another is near the center of the house. The facade is clad in blonde brick, with red common brick on the secondary facades, all laid in a running bond pattern. The primary entrance to each unit is near the east corner of the facade beneath a cantilevered wood awning with decorative brackets, and is accessed by a brick and concrete stoop. Above the entrance are two wood hung windows with vertically divided upper sashes. West of the entrance is a glazed enclosed porch, supporting a second-floor balcony above which is covered by an aluminum metal awning. Three casement windows are on the second floor. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear where there is a pyramidal roof garage.
885	4266 Tyler Street			1925	Prairie	n/a	C	Unknown	Unknown	The duplex at 4266 Tyler Street is two-stories and topped with a hipped asphalt shingle roof, with a hipped roof dormer with three leaded glass windows centered above the facade. A brick chimney is located near the center of the house. The facade is clad in red face brick, with red common brick on the secondary facades, all laid in a running bond pattern. The primary entrance to each unit is near the east corner of the facade beneath a second-floor balcony with metal railing supported by brick piers. The entrance is accessed by a brick and concrete porch with a brick kneewall. West of the entrance are three vinyl hung windows, topped with brick infilled arches. Three similar windows are on the second floor. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear. There is no garage.
886	4267 Tyler Street			1926	Prairie	n/a	C	Unknown	Unknown	The duplex at 4267 Tyler Street is two-stories and topped with a hipped asphalt shingle roof, with a hipped roof dormer with three leaded glass windows centered above the facade. A brick chimney is located near the center of the house. The facade is clad in blonde face brick, with red common brick on the secondary facades, all laid in a running bond pattern. The primary entrance to each unit is near the east corner of the facade beneath a second-floor balcony with metal railing and awning, supported by brick piers. The entrance is accessed by a brick and concrete porch with a brick kneewall. West of the entrance are three vinyl hung windows, topped with brick infilled arches, covered by an aluminum metal awning. Three similar windows are on the second floor. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear. There is no garage.
887	4273 Tyler Street			1926	Prairie	1/garage	C	Unknown	Unknown	The duplex at 4273 Tyler Street is two-stories and topped with a hipped asphalt shingle roof, with a hipped roof dormer with three leaded glass windows centered above the facade. A brick chimney is located at the eave on the west facade and another is near the center of the house. The facade is clad in brown face brick, with red common brick on the secondary facades, all laid in a running bond pattern and with some stone accents. The primary entrance to each unit is near the east corner of the facade beneath a second-floor balcony with metal railing and awning, supported by brick piers. The entrance is accessed by a brick and concrete porch with a brick kneewall. West of the entrance are three vinyl hung windows, beneath an asphalt shingled awning, and topped with brick infilled arches with keystone accents. Three vinyl hung windows are on the second floor. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear where there is a pyramidal roof garage.
888	4274 Tyler Street			1925	Prairie	1/garage	C	Unknown	Unknown	The duplex at 4274 Tyler Street is two-stories and topped with a hipped asphalt shingle roof, with a hipped roof dormer with three leaded glass windows centered above the facade. A brick chimney is located near the center of the house. The facade is clad in blonde face brick, with red common brick on the secondary facades, all laid in a running bond pattern. The primary entrance to each unit is near the east corner of the facade beneath a second-floor balcony with metal railing and awning, supported by brick piers. The entrance is accessed by a brick and concrete porch. West of the entrance are three wood hung windows with leaded glass detailing and aluminum storms. Three matching windows are on the second floor. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear where there is a pyramidal roof garage.
889	4280 Tyler Street			1925	Prairie	n/a	C	Unknown	Unknown	The duplex at 4280 Tyler Street is two-stories and topped with a hipped asphalt shingle roof, with a hipped roof dormer with three windows centered above the facade. A brick chimney is located near the center of the house. The facade is clad in blonde face brick, with red common brick on the secondary facades, all laid in a running bond pattern. The primary entrance to each unit is near the east corner of the facade beneath a second-floor balcony with metal railing and corrugated panel awning, supported by brick piers. The entrance is accessed by a brick and concrete porch with a brick kneewall. West of the entrance are three wood hung windows with leaded glass detailing covered by a corrugated panel awning. Three matching windows are on the second floor. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear. There is no garage.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
890	4288 Tyler Street			1925	Prairie	1/garage	C	Unknown	Unknown	The duplex at 4288 Tyler Street is two-stories and topped with a hipped asphalt shingle roof, with a hipped roof dormer with three leaded glass windows centered above the façade. A brick chimney is located near the center of the house. The facade is clad in red and brown face brick, with red common brick on the secondary facades, all laid in a running bond pattern with some decorative brickwork and cast stone accents. The primary entrance to each unit is near the east corner of the facade beneath a second-floor balcony with a wood railing supported by brick piers. The entrance is accessed by a brick and concrete porch with a brick kneewall. West of the entrance are three wood hung windows with leaded glass detailing, topped with brick infilled arches. Three similar windows are on the second floor. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear where there is a pyramidal roof garage.
891	4289 Tyler Street			1926	Tudor Revival	n/a	C	Unknown	Unknown	The duplex at 4289 Tyler Street is two-stories and topped with a cross gable asphalt shingle roof, composed of a side gable that meets a hipped roof toward the rear, intersected by two overlapping front gables. A brick chimney is located near the eave on the west façade and another is near the center of the house. The facade is clad in brown face brick and secondary facades composed of red common brick, both laid in a running bond pattern, with vinyl siding beneath the front gable and the side gables at the attic level. The primary entrance to each unit is near the east corner of the facade beneath a second-floor balcony with metal awning and railing, supported by brick piers. The entrance is arched and accessed by a concrete and brick full width porch. West of the entrance are three vinyl windows beneath an aluminum awning, topped with brick arched surrounds and stone accents, beneath a ribbon of four vinyl windows on the second floor. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear. There is no garage.
892	4294 Tyler Street			1922	Craftsman	n/a	C	Unknown	Unknown	The house at 4294 Tyler Street is one-and-a-half-stories and topped with a front gable asphalt shingle roof. A brick chimney is at the eave on the east facade. The exterior is clad in asbestos or vinyl siding. The primary entrance is near the west corner of the façade, beneath a front gabled overhang supported by brick piers and is accessed by a wood porch. A ribbon of four wood hung windows with vertically divided upper sashes is east of the entrance. Similar windows are arranged on other elevations. A concrete driveway runs along the east of the property to the rear. There is no garage.
893	4295 Tyler Street			1925	Prairie	n/a	C	Unknown	Unknown	The duplex at 4295 Tyler Street is two-stories and topped with a hipped asphalt shingle roof, with a hipped roof dormer with two windows centered above the façade and a shed roof dormer facing east. A brick chimney is located near the center of the house. The facade is clad in blonde face brick, with red common brick on the secondary facades, all laid in a running bond pattern with some decorative brickwork and cast stone accents. The primary entrance to each unit is near the east corner of the facade beneath an aluminum metal awning and is accessed by a brick and concrete porch with a brick kneewall. Above the entrance is a narrow window with leaded glass detailing. West of the entrance are two wood casement windows with aluminum storms on either side of a door that opens onto the porch, beneath a second-floor balcony with a wood railing supported by brick piers. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear. There is no garage.
894	4301 Tyler Street			1925	Prairie	n/a	C	Unknown	Unknown	The duplex at 4301 Tyler Street is two-stories and topped with a hipped asphalt shingle roof, with a hipped roof dormer centered above the façade and another at the rear. A brick chimney is located at the eave on the west façade and another is near the center of the house. The facade is clad in red and brown face brick, with red common brick on the secondary facades, all laid in a running bond pattern with some decorative brickwork and cast stone accents. The primary entrance to each unit is near the east corner of the facade beneath a second-floor balcony supported by brick piers with a metal railing and awning. The entrance is accessed by a brick and concrete porch with a brick kneewall. West of the entrance are three wood hung windows with aluminum storms, topped with keystones and stucco-infilled arches, beneath an aluminum metal awning. Three similar windows are on the second floor. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear. There is no garage.
895	4302 Tyler Street			1925	Prairie	1/garage	C	Unknown	Unknown	The duplex at 4302 Tyler Street is two-stories and topped with a hipped asphalt shingle roof, with a hipped roof dormer with three leaded glass windows centered above the façade. A brick chimney is located at the eave on the west façade and another is near the center of the house. The facade is clad in orange face brick, with red common brick on the secondary facades, all laid in a running bond pattern with some decorative brickwork and cast stone accents. The primary entrance to each unit is near the east corner of the facade beneath a second-floor balcony supported by brick piers, with a metal railing and awning. The entrance is accessed by a brick and concrete porch with a brick kneewall. West of the entrance are three wood hung windows with leaded glass detailing, topped with brick infilled arches and covered by an aluminum metal awning. Three similar windows are on the second floor. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear where there is a pyramidal roof garage.
896	4308 Tyler Street			1925	Prairie	1/garage	C	Unknown	Unknown	The duplex at 4308 Tyler Street is two-stories and topped with a hipped asphalt shingle roof, with a hipped roof dormer with three leaded glass windows centered above the façade and a shed roof dormer facing east. A brick chimney is located at the eave on the west façade and another is near the center of the house. The facade is clad in blonde face brick, with red common brick on the secondary facades, all laid in a running bond pattern with some decorative brickwork and cast stone accents. The primary entrance to each unit is near the east corner of the facade beneath a second-floor balcony supported by brick piers, with a metal railing and awning. The entrance is accessed by a brick and concrete porch with a brick kneewall. West of the entrance is a screened-in porch covered by an aluminum metal awning. A large vinyl slider window is on the second floor covered by an aluminum metal awning. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear where there is a pyramidal roof garage.
897	4309 Tyler Street			1925	Prairie	1/garage	C	Unknown	Unknown	The duplex at 4309 Tyler Street is two-stories and topped with a hipped asphalt shingle roof, with a hipped roof dormer with three wood windows centered above the façade. A brick chimney is located near the center of the house. The facade is clad in blonde face brick, with red common brick on the secondary facades, all laid in a running bond pattern with some decorative brickwork. The primary entrance to each unit is near the east corner of the facade accessed by a brick and concrete stoop. West of the entrance are three wood casement windows with leaded glass detailing and aluminum storms. Three matching windows are on the second floor. At the west corner of the facade is a two-story porch, with a brick kneewall on the first floor and a metal railing and awning structure on the second floor, supported by brick piers. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear where there is a pyramidal roof garage.
898	4316 Tyler Street			1925	Prairie	1/garage	C	Unknown	Unknown	The duplex at 4316 Tyler Street is two-stories and topped with a hipped asphalt shingle roof, with a hipped roof dormer with three wood windows centered above the façade and a shed roof dormer facing east. A brick chimney is located at the eave on the west façade and another is near the center of the house. The facade is clad in blonde face brick, with red common brick on the secondary facades, all laid in a running bond pattern with some decorative brickwork and cast stone accents. The primary entrance to each unit is near the east corner of the facade beneath a second-floor balcony supported by brick piers that form an arch, with a metal railing and metal structure for an awning. The entrance is accessed by a brick and concrete porch with a brick kneewall. West of the entrance are three wood windows with aluminum storms, beneath matching windows on the second floor. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear where there is a pyramidal roof garage.
899	4317 Tyler Street			1924	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4317 Tyler Street is two-stories and topped with a side gable asphalt shingle roof intersecting by a front gable. A brick chimney is located at the eave on the west façade. The facade is clad with wood clapboard siding on the first floor, with wood shingle siding beneath a continuous shed dormer on the second floor, and beneath the side gable on the second floor. The primary entrance is near the east corner the facade beneath a gabled overhang supported by fluted, round wood columns, and is accessed by a brick and concrete porch. West of the entrance are three wood hung windows with vertically divided upper sashes, and two pairs of matching wood hung windows on the second floor. Similar windows exist on other elevations, and windows have aluminum storms. A concrete driveway runs along the east of the house to the rear. There is no garage.
900	4324 Tyler Street			1922	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4324 Tyler Street is two-stories and topped with a side gable asphalt shingle roof intersected by a front gable and a wall dormer. A brick chimney is located at the eave on the west facade. The facade is clad with vinyl siding. An asphalt shingled overhang spans the façade above the first floor. The primary entrance is near the east corner the facade beneath the overhang, and is accessed by a brick and concrete porch. West of the entrance are three vinyl hung windows, and matching vinyl hung windows on the second floor. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear. There is no garage.
901	4325 Tyler Street			1924	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 4325 Tyler Street is two-stories and topped with a front gambrel asphalt shingle roof. A brick chimney is located at the eave on the west facade. The facade is clad with wood clapboard siding. An asphalt shingled overhang spans the façade above the first floor. The primary entrance is near the east corner the facade beneath a front gabled portico with square wood columns, and is accessed by a brick and concrete porch. West of the entrance are wood casement windows with leaded glass detailing, and three wood hung windows with leaded glass detailing and shutters on the second floor. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear where there is a pyramidal roof garage.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
902	4328 Tyler Street			1925	French Eclectic	n/a	C	Unknown	Unknown	The duplex at 4328 Tyler Street is two-stories and topped with a cross gable asphalt shingle roof, composed of a side gable that meets a front gable towards the rear, with a shed roof dormer above the west façade and a hipped roof two story bay projecting off the east half of the front facade. A brick chimney is located at the eave on the east facade of the house. The facade is clad in red face brick laid in a running bond pattern with a stone belt course above the first floor. The primary entrance to each unit is near the west corner the façade, and is accessed by a brick and concrete stoop beneath an aluminum metal awning. Windows on the façade are steel casement. Windows have aluminum storms and cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear. There is no garage.
903	4329 Tyler Street			1926	Tudor Revival	n/a	C	Unknown	Unknown	The duplex at 4329 Tyler Street is two-stories and topped with a cross gable asphalt shingle roof, composed of a side gable that meets a hipped roof toward the rear, intersected by two overlapping front gables. A brick chimney is located near the eave on the west façade and another is near the center of the house. The facade is clad in red and brown face brick and secondary facades composed of red common brick, both laid in a running bond pattern, with vinyl siding beneath the front gable and the side gables at the attic level. The primary entrance to each unit is near the east corner of the facade beneath a second-floor balcony with metal awning and railing, supported by brick piers. The entrance is accessed by a concrete and brick full width porch. West of the entrance are three wood hung windows beneath an aluminum awning, topped with brick arched surrounds and stone accents, beneath a ribbon of four wood casement windows on the second floor. Windows have aluminum storms and cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear. There is no garage.
904	4335 Tyler Street			1925	Prairie	n/a	C	Unknown	Unknown	The duplex at 4335 Tyler Street is two-stories and topped with a hipped asphalt shingle roof, with a hipped roof dormer with three wood windows centered above the façade. A brick chimney is near the center of the house. The facade is clad in red face brick, with red common brick on the secondary facades, all laid in a running bond pattern with some decorative brickwork and cast stone accents. The primary entrance to each unit is near the east corner of the facade beneath a second-floor balcony supported by brick piers with a metal railing. The entrance is accessed by a brick and concrete porch with a brick kneewall. West of the entrance are three vinyl windows topped with brick infilled arches, beneath matching windows on the second floor. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear. There is no garage.
905	4336 Tyler Street			not listed	Tudor Revival	n/a	C	Unknown	Unknown	The duplex at 4336 Tyler Street is two-stories and topped with a cross gable asphalt shingle roof, composed of a side gable that meets a hipped roof toward the rear, intersected by a jerkinhead front gable. A brick chimney is located at the eave on the west façade. The facade is clad in red and brown face brick and secondary facades composed of red common brick, both laid in a running bond pattern. The primary entrance to each unit is near the east corner of the facade and is accessed by a concrete and brick porch. West of the entrance is a large window opening that has been boarded over, beneath a ribbon of four wood hung windows on the second floor. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear. There is no garage.
906	4342 Tyler Street			1925	Prairie	1/garage	C	Unknown	Unknown	The duplex at 4342 Tyler Street is two-stories and topped with a hipped asphalt shingle roof, with a hipped roof dormer with three wood windows centered above the façade and another hipped roof dormer on the east facade. A brick chimney is located on the eave at the west façade and another is near the center of the house. The facade is clad in blonde face brick, with red common brick on the secondary facades, all laid in a running bond pattern with some decorative brickwork and cast stone accents. The primary entrance to each unit is near the east corner of the facade beneath a cantilevered overhang supported by decorative brackets and is accessed by a brick and concrete full width porch with a brick kneewall. The west half of the porch is covered by a second-floor balcony supported by brick piers with a wood railing. West of the entrance are three wood casement windows with aluminum storms, beneath similar windows on the second floor. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear where there is a pyramidal roof garage.
907	4347 Tyler Street			1925c.	Prairie	n/a	C	Unknown	Unknown	The duplex at 4347 Tyler Street is two-stories and topped with a hipped asphalt shingle roof, with a hipped roof dormer centered above the façade. A brick chimney is near the center of the house. The facade is clad in light brown face brick, with red common brick on the secondary facades, all laid in a running bond pattern with some decorative brickwork and cast stone accents. A former door opening onto the balcony on the second floor has been covered with vinyl siding. The primary entrance to each unit is near the east corner of the facade beneath a second-floor balcony supported by brick piers with a metal railing. The entrance is accessed by a brick and concrete porch with a brick kneewall. West of the entrance are three vinyl windows topped with brick infilled arches, beneath matching windows on the second floor. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear. There is no garage.
908	4350 Tyler Street			1925	Prairie	n/a	C	Unknown	Unknown	The duplex at 4350 Tyler Street is two-stories and topped with a hipped asphalt shingle roof, with a hipped roof dormer clad in wood shingles with wood windows centered above the façade. A brick chimney is located near the center of the house. The facade is clad in light brown face brick, with red common brick on the secondary facades, all laid in a running bond pattern with some decorative brickwork and cast stone accents. The primary entrance to each unit is near the west corner of the facade beneath a second-floor balcony supported by metal posts, with a metal railing and awning. The entrance is accessed by a brick and concrete full width porch with a metal railing. West of the entrance are three vinyl fixed windows beneath three similar windows above. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear. There is no garage.
909	4351 Tyler Street			1925	Prairie	1/garage	C	Unknown	Unknown	The duplex at 4351 Tyler Street is two-stories and topped with a hipped asphalt shingle roof, with a hipped roof dormer clad in with three wood windows centered above the façade. A brick chimney is located near the center of the house. The facade is clad in blonde face brick, with red common brick on the secondary facades, all laid in a running bond pattern with some decorative brickwork and cast stone accents. The primary entrance to each unit is near the east corner of the facade beneath a second-floor balcony supported by brick piers, that has been enclosed with vinyl siding and slider windows. The entrance is accessed by a brick and concrete porch with a brick kneewall. West of the entrance are three wood hung windows, two which have leaded glass detailing, beneath three similar windows above. Windows have cast stone sills and some have aluminum storms. Similar windows exist on other elevations. A concrete ribbon driveway runs along the east of the house to the rear where there is a hipped roof garage.
910	4357 Tyler Street			1925	Prairie	n/a	C	Unknown	Unknown	The duplex at 4357 Tyler Street is two-stories and topped with a hipped asphalt shingle roof, with a hipped roof dormer above the façade and a hipped roof two story bay projecting off the west half of the front facade. A brick chimney is located at the eave on the west facade of the house. The facade is clad in red and brown face brick laid in a running bond pattern with some decorative brickwork and cast stone accents. The primary entrance to each unit is near the east corner the façade, and is accessed by a brick and concrete porch beneath a second-floor balcony supported by a brick pier, with a metal railing and covered by an aluminum metal awning. Windows on the second floor of the front facade are wood hung with leaded glass detailing, above a large aluminum window on the first floor. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear. There is no garage.
911	4360 Tyler Street			1925	Prairie	n/a	C	Unknown	Unknown	The duplex at 4360 Tyler Street is two-stories and topped with a hipped asphalt shingle roof, with a hipped roof dormer centered above the façade. A brick chimney is located near the center of the house. The facade is clad in brown and red brown face brick, with red common brick on the secondary facades, all laid in a running bond pattern with some decorative brickwork. The primary entrance to each unit is near the east corner of the facade beneath an aluminum metal awning, accessed by a concrete porch. West of the entrance is a large vinyl slider window, beneath a matching window on the second floor. At the west corner of the facade is a two-story porch supported by brick piers, that has been enclosed on the first floor and is uncovered on the second floor. Windows have cast stone sills. A concrete driveway runs along the east of the house to the rear. There is no garage.
912	4364 Tyler Street			1926	Prairie	1/garage	C	Unknown	Unknown	The duplex at 4364 Tyler Street is two-stories and topped with a hipped asphalt shingle roof, with a hipped roof dormer with two wood windows centered above the façade and a hipped roof dormer facing east. A brick chimney is located near the center of the house. The facade is clad in brown face brick, with red common brick on the secondary facades, all laid in a running bond pattern with some decorative brickwork and cast stone accents. The primary entrance to each unit is near the east corner of the facade beneath a second-floor balcony supported by brick piers that form an arch, with a brick kneewall and an asphalt shingled shed awning supported by square wood posts. The entrance is accessed by a brick and concrete full width porch with a brick kneewall. West of the entrance are three vinyl hung windows, beneath three matching windows on the second floor. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear where there is a hipped roof garage.
913	4365 Tyler Street			1925	Prairie	n/a	C	Unknown	Unknown	The duplex at 4365 Tyler Street is two-stories and topped with a hipped asphalt shingle roof, with a hipped roof dormer above the façade and a hipped roof two story bay projecting off the west half of the front facade. A brick chimney is located at the eave on the west facade and another is near the center of the house. The facade is clad in blonde face brick, with red common brick on the secondary facades, all laid in a running bond pattern with some decorative brickwork and cast stone accents. The primary entrance to each unit is near the east corner the façade, and is accessed by a brick and concrete porch with a brick kneewall. Windows are vinyl hung or slider. Windows have cast stone sills. Similar windows exist on other elevations. A concrete driveway runs along the east of the house to the rear. There is no garage.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
914	4370 Tyler Street			1925	Prairie	1/garage	C	Unknown	Unknown	The duplex at 4370 Tyler Street is two-stories and topped with a hipped asphalt shingle roof, with a hipped roof dormer centered above the front and rear façades, and a shed roof dormer facing west. A brick chimney is located at the eave on the west facade and another is near the center of the house. The facade is clad in blonde face brick, with red common brick on the secondary facades, all laid in a running bond pattern with some decorative brickwork. The primary entrance to each unit is near the west corner of the facade beneath a second-floor balcony supported by brick piers, with a metal railing and awning. The arched door is accessed by a brick and concrete full width porch with a metal railing. West of the entrance are hung windows topped with stucco-infill arches, covered by an aluminum metal awning, and beneath three similar windows above. Windows have cast stone sills. Similar windows exist on other elevations. A garage is at the rear of the property, accessed off of the alley to the west.
915	4373 Tyler Street			1926	Prairie	1/garage	C	Unknown	Unknown	The duplex at 4373 Tyler Street is two-stories and topped with a hipped asphalt shingle roof, with a hipped roof dormer above the facade and a hipped roof two story bay projecting off the west half of the front facade. A brick chimney is located near the center of the house. The facade is clad in brown face brick, with red common brick on the secondary facades, all laid in a running bond pattern with some decorative brickwork and cast stone accents. The primary entrance to each unit is near the east corner the facade, beneath a second-floor balcony covered with an aluminum awning, and is accessed by a brick and concrete porch with a brick kneewall. Windows are vinyl hung with cast stone sills. Similar windows exist on other elevations. An alley runs along the west of the property. There is no garage.
916	3727 Waverly Street			1928	Tudor Revival	n/a	C	Unknown	Unknown	The duplex at 3727 Waverly Street is two-stories and topped with a hipped asphalt shingle roof, intersected by a front gable which overlaps with a jerkinhead roof, both with vinyl cladding and knee brackets. A brick chimney is near the center of the house. The facade is clad in warm-toned blonde face brick laid in a running bond pattern with accents of cast stone and decorative brickwork, with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the east corner of the facade beneath a two-story brick-clad porch with an arched opening supported by brick piers and accessed by a full-width porch. The first-floor porch and second-floor balcony are each covered by an aluminum awning. The first and second floor porches are surrounded by a brick kneewall. Three vinyl windows are west of the entrances and set beneath a slider window on the second floor. Windows have cast stone sills. Similar windows are arranged on other elevations. A sidewalk runs along the west side of the house. There is no driveway or garage.
917	3733 Waverly Street			1928	Prairie	n/a	C	Unknown	Unknown	The duplex at 3733 Waverly Street is two-stories and topped with a hipped asphalt shingle roof, intersected by a pedimented dormer clad in vinyl and asphalt shingle. A brick chimney is near the center of the house. The facade is clad in red-brown face brick laid in a running bond pattern with accents of cast stone and decorative brickwork, with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the east corner of the facade beneath a two-story brick-clad porch supported by brick piers and accessed by a full-width porch topped with an aluminum awning. The second-floor balcony is topped with a pedimented front gabled roof supported by brick piers. The first and second floor porches are surrounded by a brick kneewall. Three vinyl windows are west of the entrances and set beneath three vinyl windows on the second floor. Windows have cast stone sills which have been painted white. Similar windows are arranged on other elevations. A concrete sidewalk runs along the west side of the house. There is no driveway or garage.
918	3741 Waverly Street			not listed	Tudor Revival	n/a	C	Unknown	Unknown	The house at 3741 Waverly Street is two-stories and topped with an asphalt shingle side jerkinhead roof intersected by overlapping front gable and jerkinhead roofs above the primary facade and a hipped roof at the rear. A brick chimney is near the center of the house. The facade is clad in blonde and brown face brick laid in a running bond pattern with accents of cast stone, decorative brickwork, and wood false half-timbering. Other facades are composed of wood shingle at each side gable, with red common brick laid in a running bond pattern with a soldier course dividing the second floor and attic. The entrance is arched and trimmed with rusticated cast stone painted red, framed on either side with arched windows that are leaded glass in a diamond pattern, set beneath decorative brickwork and a single hung window on the second floor, and accessed by a partially intact brick and concrete full width porch. A large fixed window opening is west of the entrances and offset beneath three fixed window openings on the second floor. A single hung window with simulated diamond pattern sits between the front gables on the second floor. Windows have cast stone sills that are painted red. Windows on other elevations contain wood upper sashes divided into three lites. There is no driveway or garage.
919	3769 Waverly Street			not listed	Tudor Revival	n/a	C	Unknown	Unknown	The duplex at 3769 Waverly Street is two-stories and topped with a hipped asphalt shingle roof, intersected by a front gable clad in wood shingles. A brick chimney is near the center of the house. The facade is clad in warm-toned blonde face brick laid in a running bond pattern with accents of cast stone and decorative brickwork, with a soldier course dividing the second floor from the attic. The other facades are clad in beige vinyl. The primary entrance to each flat is near the east corner of the facade beneath a two-story brick-clad porch supported by brick piers and accessed by a full-width porch. The first and second floor porches are surrounded by a brick kneewall. A large slider window is west of the entrances and set beneath a large slider window on the second floor. Windows have cast stone sills. Other elevations contain hung and fixed vinyl windows, with glass block windows at the basement. A sidewalk runs along the east side of the house. There is no driveway or garage.
920	3775 Waverly Street			1928	Tudor Revival	n/a	C	Unknown	Unknown	The duplex at 3775 Waverly Street is two-stories and topped with a hipped asphalt shingle roof intersected by two front jerkinhead gables with false half-timbering and knee brackets above the facade. A brick chimney is near the center of the house. The facade is clad in warm-toned blonde and red face brick laid in a running bond pattern with accents of cast stone and decorative brickwork, with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the east corner of the facade beneath a two-story brick-clad porch with an arched opening supported by brick piers and accessed by a partially intact full-width porch. The first and second floor porches are surrounded by a brick knee wall. A large window opening is east of the entrances and set beneath three window openings on the second floor. Windows have cast stone sills. Windows on other elevations are hung with three-over-one wood sashes. A concrete sidewalk runs along the east side of the house. There is no garage.
921	3791 Waverly Street			1928	Tudor Revival	n/a	C	Unknown	Unknown	The duplex at 3791 Waverly Street is two-stories and topped with a hipped asphalt shingle roof, intersected by a jerkinhead and a front gable roof with a knee bracket. A brick chimney is near the center of the house. The facade is clad in blonde and red face brick laid in a running bond pattern with accents of cast stone, decorative brickwork, and false half-timbering with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the east corner of the facade beneath a two-story brick-clad porch with an arched opening supported by brick piers and accessed by a full-width porch. The second floor porch is covered by an aluminum awning. The first and second floor porches are surrounded by a brick kneewall. Three hung vinyl windows are west of the entrances covered by a hipped, shingled awning with decorative brackets, set beneath three hung vinyl windows on the second floor. Windows have cast stone sills. Similar windows are arranged on other elevations. A chain link fence encloses the property along with the east adjacent lot with is currently used as a driveway. There is no garage.
922	3797 Waverly Street			1929	Tudor Revival	n/a	C	Unknown	Unknown	The duplex at 3797 Waverly Street is two-stories and topped with a hipped asphalt shingle roof, intersected by a jerkinhead with vinyl cladding and knee brackets which overlaps with a front gable roof. A brick chimney is near the center of the house. The facade is clad in red face brick laid in a running bond pattern with decorative brickwork, with other facades composed of red common brick laid in a running bond pattern. The primary entrance sits below a hung wood window with leaded glass detailing near the west corner of the facade and is accessed by a full-width uncovered porch with a metal railing. East of the entrance, a large fixed vinyl window sits between two hung vinyl windows, set beneath a slider window on the second floor. Windows have brick sills. Similar windows are arranged on other elevations. A sidewalk runs along the west side of the house. There is no driveway or garage.
923	3803 Waverly Street			1929	Tudor Revival	1/garage	C	Unknown	Unknown	The duplex at 3803 Waverly Street is two-stories and topped with a hipped asphalt shingle roof, intersected by two overlapping front gables with vinyl cladding and knee brackets. A brick chimney is near the center of the house. The facade is clad in red face brick laid in a running bond pattern with accents of decorative brickwork, with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the east corner of the facade beneath a two-story brick-clad porch with an arched opening supported by brick piers and accessed by a former full-width porch that has been enclosed with vinyl siding. The first and second floor porches are covered by aluminum awnings are surrounded by metal railings. Four hung vinyl windows are west of the entrances on the first floor, set beneath a vinyl slider window on the second floor. Windows have brick sills. Similar windows are arranged on other elevations. A concrete sidewalk runs along the east of the house to a garage with a pyramidal roof.
924	3811 Waverly Street			1929	Prairie	1/garage	C	Unknown	Unknown	The duplex at 3811 Waverly Street is two-stories and topped with a hipped asphalt shingle roof, intersected by a hipped asphalt roof dormer clad in wood shingles with a small fixed leaded-glass window between two vents. A brick chimney is near the center of the house. The facade is clad in red-brown face brick laid in a running bond pattern with accents of cast stone and decorative brickwork, with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the west corner of the facade beneath a two-story brick-clad porch with an arched opening supported by brick piers and accessed by a full-width porch. The first and second floor porches are each topped with an aluminum awning and surrounded by a brick kneewall. Three hung vinyl windows topped with round brick arches are west of the entrances and set beneath three hung vinyl windows on the second floor. Windows have cast stone sills. Similar windows are arranged on other elevations. A concrete sidewalk runs along the west side of the house to a garage with a hipped roof.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
925	3817 Waverly Street			1929	Tudor Revival	n/a	C	Unknown	Unknown	The duplex at 3817 Waverly Street is two-stories and topped with a hipped asphalt shingle roof, intersected by a jerkinhead with knee brackets and a jerkinhead dormer with vinyl cladding. A brick chimney is near the center of the house. The facade is clad in warm-toned blonde face brick laid in a running bond pattern with accents of rusticated cast stone and decorative brickwork, with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the east corner of the facade beneath a two-story brick-clad porch with an arched opening and accessed by a full-width porch with slanted square piers. The first and second floor porches are each topped with an aluminum awning and surrounded by a brick kneewall. A large vinyl slider window is west of the entrances and set beneath a large vinyl slider window on the second floor. Other elevations appear to have hung and fixed vinyl windows. All windows have cast stone sills. A concrete sidewalk runs along the east side of the house. There is a vinyl-clad addition on the rear façade.
926	3825 Waverly Street			1929	Tudor Revival	n/a	C	Unknown	Unknown	The duplex at 3825 Waverly Street is two-stories and topped with a hipped asphalt shingle roof, intersected by two overlapping front gables, the easternmost of which has false half-timbering and knee brackets. A brick chimney is near the center of the house. The facade is clad in red, blonde, and brown face brick laid in a running bond pattern with decorative brickwork and rusticated cast stone accents, with other facades composed of red common brick laid in a running bond pattern. The primary entrance sits below a hung vinyl near the west corner of the facade and is accessed by a full-width uncovered brick-clad porch with a kneewall. East of the entrance, a large vinyl slider window is beneath a large vinyl slider window on the second floor. Windows have cast stone sills. Similar windows are arranged on other elevations. A sidewalk runs along the west side of the house. There is no driveway or garage.
927	3831 Waverly Street			1929	Tudor Revival	n/a	C	Unknown	Unknown	The duplex at 3831 Waverly Street is two-stories and topped with a hipped asphalt shingle roof, intersected by a front gable and a parapet. A brick chimney is near the center of the house. The facade is clad in red and brown face brick laid in a running bond pattern with decorative brickwork and rusticated cast stone accents, with other facades composed of red common brick laid in a running bond pattern. The primary entrance sits below a fixed and a hung window with leaded glass detailing near the east corner of the facade and is accessed by a full-width uncovered brick-clad porch with a kneewall. West of the entrance, three vinyl hung windows are set beneath another set of three hung vinyl windows on the second floor. Windows have cast stone sills. Similar windows are arranged on other elevations. A sidewalk runs along the east side of the house. There is no driveway or garage.
928	3839 Waverly Street			1950	French Eclectic	n/a	C	Unknown	Unknown	The duplex at 3839 Waverly Street is two-stories and topped with a hipped asphalt shingle roof. A large brick chimney is located at the eave near the front of the west facade. The exterior is clad in brown brick veneer laid in a running bond pattern with accents of cast stone and a soldier course below the eave. The primary entrance, near the east corner of the façade, is trimmed in stone quoins and supports a second floor balcony and is accessed by a brick and concrete porch. A single-story canted bay clad in stone with vinyl windows and metal roof with flared eaves is west of the entrance and three vinyl windows surrounded by stone quoins are on the second floor. Similar windows are arranged on other elevations and all have cast stone sills. A concrete sidewalk runs along the east side of the house. There is no driveway or garage.
929	4025 Waverly Street						NC	Unknown	Unknown	Parking lot
930	4202 Waverly Street			1925	Prairie	1/garage	C	Unknown	Unknown	The quadplex at 4202 Waverly Street is two-stories and topped with a hipped asphalt shingle roof, intersected by a hipped roof dormer with three wood windows centered above the primary façade and another dormer of the same configuration facing the rear façade. A brick chimney is near the center of the house. The facade is clad in red face brick laid in a running bond pattern, with other facades composed of red common brick laid in a running bond pattern. The primary entrance is centered the façade between glass block sidelights beneath a two-story porch supported by brick piers and square wood columns. The first floor has brick kneewalls with cast stone accents and the second floor balcony and railing is constructed of wood. Two-story canted bays sit on either side of the entrance each with three 3-over-1 hung wood windows, and are set beneath the same types of windows on the second floor. Windows have been painted yellow and all have cast stone sills. Similar windows are arranged on other elevations along with glass block and some vinyl hung windows. A brick garage with a hipped roof faces the alley.
931	4203 Waverly Street			1924	Prairie	n/a	C	Unknown	Unknown	The quadplex at 4203 Waverly Street is two-stories and topped with a hipped asphalt shingle roof, intersected by a hipped roof dormer with four wood multi-lite fixed windows centered above the primary façade. A brick chimney is near the center of the house. The facades are clad in red face brick laid in a running bond pattern with a decorative header course. The primary entrance is centered on the façade within a one-story canting bay and is surrounded by cast stone quoins and label molding that has been painted yellow, and is accessed by a concrete and brick uncovered porch with metal pipe railing. On either side of the entrance sits a two-story porch supported by brick piers with brick kneewalls and aluminum awnings covering the second floor balcony. Balcony doors are multi-pane glazed with aluminum screen doors. Windows are wood with aluminum storms and are a mix of six-over-one and one-over-one. Windows on the two street-facing facades have soldier course lintels. All windows have cast stone sills and with casing painted yellow. Similar windows are arranged on other elevations along with glass block and some vinyl hung windows. A concrete sidewalk runs long the west of the house. There is no driveway or garage.
932	4210 Waverly Street			1925	Tudor Revival	n/a	C	Unknown	Unknown	The duplex at 4210 Waverly Street is two-stories and topped with a side gable asphalt shingle roof intersected by front gable dormer clad in wood shingles with two fixed windows above the facade and a hipped roof at the rear which is intersected by a hipped dormer. A brick chimney is near the rear of the house. The exterior is clad in red brick veneer laid in a running bond pattern. The primary entrance is trimmed in brick centered on the facade, and is accessed by a brick and concrete porch with a brick knee wall and brick piers supported a wood balcony on the second floor. On either side of the entrance is a group of three wood hung windows with leaded glass detailing, set below windows of the same configuration on the second floor. Windows have cast stone sills. Similar windows are arranged on other elevations. A concrete sidewalk runs along the east side of the property. There is no driveway or garage.
933	4213 Waverly Street			1946	French Eclectic	n/a	C	Unknown	Unknown	The duplex at 4213 Waverly Street is two-stories and topped with a hipped asphalt shingle roof. The exterior is clad in brown brick veneer laid in a running bond pattern with some decorative brickwork. The primary entrance is near the east corner of the facade and is accessed by a brick and concrete porch with wood stairs, a metal railing, and an aluminum awning. A set of three hung vinyl windows is west of the entrance set beneath three vinyl windows on the second floor. Windows have brick sills. Similar windows are arranged on other elevations. A concrete sidewalk runs along the east side of the house. A white lightpost with a globe light fixture is in the front lawn. There is no driveway or garage.
934	4218 Waverly Street			1925	Tudor Revival	n/a	C	Unknown	Unknown	The duplex at 4218 Waverly Street is two-stories and topped with a side gable asphalt shingle roof intersected by a jerkinhead with one small multi-lite window above the facade and a hipped roof at the rear. A brick chimney is located at the eave on the west façade near the front of the house, and another brick chimney is near the center of the house. The exterior is clad in red brick veneer laid in a running bond pattern. The primary entrance, framed by white shutters, is located near the east corner of the facade beneath an asphalt shed dormer, and is accessed by a brick and concrete uncovered porch with a brick knee wall. Above the entrance is a vinyl-clad former window opening on the second floor. West of the entrance are three arched wood hung windows with multi-pane upper sashes and decorated with cast stone keystones and springers. On the second floor, a set of four nine-over-nine hung ribbon windows form a segmented arch beneath a cast stone segmented arch lintel. Windows have cast stone sills. Windows on other elevations appear to be wood hung with a glass block window at the basement. A concrete driveway runs along the east side of the property. There is no garage.
935	4219 Waverly Street			1925	Craftsman	1/garage	C	Unknown	Unknown	The duplex at 4219 Waverly Street is two-stories and topped with a side gable asphalt shingle roof, interrupted by a continuous shed dormer inset into the main roof line, which extends in order to form the overhang for the full width front porch. A brick chimney is located at the eave on the east façade near the front of the house, and another brick chimney is located near the center of the house. The exterior is clad in wood painted white on the first floor and wood shingle siding on the second floor. The primary entrance is located near the west corner of the facade, and is accessed by a brick and concrete porch covered by the overhanging roof above which is supported by grouped classical columns. East of the entrance are three multi-lite wood hung windows with aluminum storm windows. Centered on the facade is a balcony within the inset dormer at the second floor which is covered by an aluminum awning. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property to a garage with a pyramidal roof in the rear.
936	4224 Waverly Street			1926	Craftsman	n/a	C	Unknown	Unknown	The house at 4224 Waverly Street is two-stories and topped with a side gable asphalt shingle roof, intersected by central front gable dormer clad in wood shingles with three hung windows above the facade, and a hipped dormer at the rear. A brick chimney is located at the eave on the east facade. The exterior is clad in red brick veneer laid in a running bond pattern and a few cast stone details on the first floor, the second floor is clad in wood shingles beneath the each of the gables. The primary entrance is located near the west corner of the facade and is accessed by a brick and concrete porch with a brick knee wall. The entrance is covered by a front gabled overhang clad in wood shingles supported by brick piers, while the east portion of the porch is covered by an aluminum awning. To the east of the entrance is a group of three wood hung windows. Windows on the first floor have cast stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property. A black lightpost with a globe light fixture is in the front lawn. There is no garage.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
937	4232 Waverly Street			1927	Tudor Revival	1/garage	C	Unknown	Unknown	The duplex at 4232 Waverly Street is two-stories and topped with a hipped asphalt shingle roof intersected by overlapping front gables with false half-timbering above the facade. A brick chimney is near the center of the house. The facade is clad in blonde face brick laid in a running bond pattern, with other facades composed of red common brick laid in a running bond pattern. The primary entrances to each flat are near the east corner of the facade beneath a two-story porch supported by brick piers and accessed by a brick and concrete porch with metal railings. The first and second story porches are covered with aluminum metal awnings. Three hung windows are west of the entrances and set beneath three hung windows on the second floor. Windows have cast stone sills. Windows on other elevations are hung or slider, with glass block at the basement windows. A concrete driveway runs along the east side of the house to a garage with a gable roof at the rear.
938	4235 Waverly Street			1924	Colonial Revival	1/garage	C	Unknown	Unknown	The house at 4235 Waverly Street is two-stories and topped with a side gambrel asphalt shingle roof, interrupted by a full width shed dormer with wood cladding. A brick chimney is located at the eave on the west facade near the front of the house. The exterior is clad in wood. The primary entrance is located near the east corner of the facade, and is accessed by a brick and concrete porch covered by pedimented overhang supported by slender wood columns with a metal railing. West of the entrance is a set of 3 three-over-one hung wood windows, framed by flat wood shutters with a trefoil detail painted tan. Similar windows are arranged on the second floor and other elevations, as well as some glass block and fixed windows. A concrete driveway runs along the east side of the property to the yard which includes the adjacent lot and is enclosed by a wood privacy fence. There appear to be two overhangs covering a rear porch and a two temporary shed structures at the rear.
939	4240 Waverly Street			1926	Colonial Revival	n/a	C	Unknown	Unknown	The duplex at 4240 Waverly Street is two-stories and topped with a side gambrel asphalt shingle roof, interrupted by a full width shed dormer with wood shingle cladding. A brick chimney is located at the center of the house. The exterior is clad in warm-toned blonde face brick at the first floor and wood shingles beneath the gambrels at the second floor. The primary entrance is located near the east corner of the facade, and is accessed by a brick and concrete uncovered porch with metal railing. West of the entrance are three hung vinyl windows, set beneath three vinyl hung windows on the second floor. Windows on the other facades appear to be a mix of wood and vinyl, and all windows on the first floor have cast stone sills. A concrete driveway runs along the east side of the property. There is no garage.
940	4241 Waverly Street			1924	Colonial Revival	n/a	C	Unknown	Unknown	The house at 4241 Waverly Street is two-stories and topped with a side gable asphalt shingle roof. A brick chimney is located at the eave on the west facade near the front of the house. The exterior is composed of wood clapboard siding on the first floor and wood shingles on the second floor. The primary entrance is located near the east corner of the facade, and is accessed by a wood porch with wood railings covered by a front gabled overhang supported by square wood columns on top of brick piers. West of the entrance is a set of three six-over-one hung wood windows, framed by flat wood shutters with a trefoil detail painted white. Matching windows and shutters are arranged in pairs on the second floor. Windows on other elevations appear to be wood hung. A concrete driveway runs along the east side of the property to the rear. There is no garage.
941	4244 Waverly Street			1924	Prairie	n/a	C	Unknown	Unknown	The duplex at 4244 Waverly Street is two-stories and topped with a hipped asphalt shingle roof intersected by a hipped roof dormer with three wood windows above the facade. A large brick chimney is located at the eave on the west facade and another brick chimney sits near the center of the house. The facade is clad in blonde face brick laid in a running bond pattern with accents of decorative brickwork, with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the east corner of the facade beneath an aluminum metal awning and is accessed by a brick and concrete stoop with metal handrails. A screened in porch at the west corner of the facade is clad in brick with brick piers supporting a second floor balcony with metal railing above. Centered on the facade are three casement wood windows and set beneath a set of three casement wood windows on the second floor. Windows have cast stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house. There is no garage.
942	4247 Waverly Street			1926	Tudor Revival	n/a	C	Unknown	Unknown	The duplex at 4247 Waverly Street is two-stories and topped with a hipped asphalt shingle roof intersected by a side gable roof with wood shingle cladding and overlapping front gables above the facade. A brick chimney is located at the eave on the west facade. The facade is clad in red face brick laid in a running bond pattern, with other facades composed of red common brick laid in a running bond pattern. The primary entrances to each flat are near the east corner of the facade beneath a two-story porch with flared eaves and an arched opening supported by brick piers and accessed by a brick and concrete porch. Three hung windows are west of the entrances and set beneath three hung windows on the second floor. Windows have cast stone sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the house. There is no garage.
943	4252 Waverly Street			1924	Prairie	n/a	C	Unknown	Unknown	The duplex at 4252 Waverly Street is two-stories and topped with a hipped asphalt shingle roof intersected by a hipped roof dormer with two wood windows above the facade. A brick chimney is located near the center of the house. The facade is clad in red face brick laid in a running bond pattern, with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the east corner of the facade beneath an arched wood hood molding and is accessed by a brick and concrete stoop. West of the entrance is a set of two casement windows with aluminum storm winds. A screened in porch at the west corner of the facade is clad in brick with brick piers supporting a second floor balcony with wood railing above. Windows on the second floor are casement with leaded glass detailing. Windows have cast stone sills. Windows on other elevations appear to be wood, hung, with aluminum storms. A concrete driveway runs along the east side of the house. There is no garage.
944	4255 Waverly Street			1925	Tudor Revival	n/a	C	Unknown	Unknown	The duplex at 4255 Waverly Street is two-stories and topped with a hipped asphalt shingle roof intersected by a front gable above the facade. A brick chimney is near the center of the house. The facade is clad in brown face brick laid in a running bond pattern with some decorative brickwork and cast stone accents on the first floor and beneath the front gable on the first and second floor. Outside of the gable, wood shingle cladding wraps the rest of the second story, while facades are composed of red common brick laid in a running bond pattern on the first floor. The primary entrances to each flat are near the east corner of the facade beneath a two-story porch supported by brick piers and accessed by a brick and concrete porch with metal railings. The second story balcony is uncovered with metal railings. Four narrow multi-lite casement windows are west of the entrances and set similar windows on the second floor. Windows have cast stone sills. There appear to be wood hung windows on other elevations. A concrete driveway runs along the east side of the house. There is no garage.
945	4260 Waverly Street			1925	Colonial Revival	n/a	C	Unknown	Unknown	The house at 4260 Waverly Street is two-stories and topped with a side gambrel asphalt shingle roof, interrupted by a shed dormer with vinyl cladding. A brick chimney is located at the center of the house. The exterior is clad in vinyl siding. The primary entrance is located near the east corner of the facade, and is accessed by a brick and concrete porch with front gabled overhang. West of the entrance, covering the rest of the porch is an aluminum metal awning above three hung wood windows, set beneath three wood hung windows within the dormer on the second floor framed by white shutters. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property. There is no garage.
946	4261 Waverly Street			1923	Colonial Revival	n/a	C	Unknown	Unknown	The house at 4261 Waverly Street is two-stories and topped with a deck (flat on hipped) asphalt shingle roof. A brick chimney is located near the rear of the house. The exterior is composed of wood clapboard siding on the first floor and wood shingles on the second floor. The primary entrance is located near the west corner of the facade, and is accessed by a brick and concrete porch covered by a front gabled overhang supported by square wood posts. West of the entrance is a set of four three-over-one hung wood windows. The second floor is glazed with three four-over-one hung windows. Windows on other elevations appear to be wood hung. All windows have aluminum storms affixed to the exterior. A concrete ribbon driveway runs along the east side of the property to the rear. There is no garage.
947	4266 Waverly Street			1927	Prairie	n/a	C	Unknown	Unknown	The duplex at 4266 Waverly Street is two-stories and topped with a hipped asphalt shingle roof intersected by a hipped roof dormer clad in vinyl siding above the facade and another hipped roof dormer above the east facade. A large brick chimney is located at the eave on the west facade, and another brick and concrete chimney is near the rear of the house. The facade is clad in red face brick laid in a running bond pattern, with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the east corner of the facade beneath a brick two-story porch supported by brick piers and is accessed by a brick and concrete porch. West of the entrance is a large window opening that has been boarded up beneath a window opening of the same size on the second floor. Windows have cast stone sills. Other elevations appear to have wood hung windows and some glass block windows at the basement level with many openings boarded up. A concrete driveway runs along the east side of the house. There is no garage.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
948	4267 Waverly Street			1927	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4267 Waverly Street is two-stories and topped with an asphalt shingle side gambrel roof intersected by a shed dormer clad in wood shingles which is intersected by overlapping front gables above the primary façade, and a shed dormer roof at the rear. A brick chimney is located at the eave on the west façade near the front of the house. Beneath the front gables, the facade is clad red face brick laid in a running bond pattern. Other facades are clad with red common brick laid in a running bond pattern on the first floor while the second floor is clad in wood shingles at each side gambrel. The entrance, located near the east corner of the façade, is arched and trimmed with brick and rusticated cast stone, accessed by a brick and concrete full width porch with brick piers and metal railings. West of the entrance, the porch is covered with an aluminum metal awning and there are four wood hung windows with divided lites on the upper sash, offset beneath three similar windows on the second floor topped with a soldier course lintel. Windows have cast stone sills and aluminum storm windows. Similar windows appear on other elevations. A driveway runs along the east of the house to a garage with a pyramidal roof at the rear.
949	4274 Waverly Street			1924	Prairie	1/garage	C	Unknown	Unknown	The duplex at 4274 Waverly Street is two-stories and topped with a hipped asphalt shingle roof intersected by a hipped roof dormer clad in vinyl siding with three small fixed windows centered above the façade. A brick chimney is located at the eave on the west façade, and another brick and concrete chimney is near the rear of the house. The facade is clad in light brown brick laid in a running bond pattern, with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the east corner of the facade beneath a triangular hood molding supported by knee brackets, and is accessed by a concrete stoop clad in cast stone with metal railings. West of the entrance are two small hung windows set beneath the same windows on the second floor. At the west corner of the façade is a two-story porch supported by brick piers that is screened in on the first floor, while the second floor balcony is covered with an aluminum metal awning and has metal railings. Some windows have divided lites and all have cast stone sills with aluminum storms. Similar windows appear on other elevations. A concrete driveway runs along the east of the house to the rear where it is unknown if there is a garage through overgrown vegetation.
950	4275 Waverly Street			1924	Tudor Revival	n/a	C	Unknown	Unknown	The duplex at 4275 Waverly Street is two-stories and topped with a deck (flat on hipped) asphalt shingle roof intersected a front gable. A brick chimney is located at the eave on the west façade near the front of the house, and another brick chimney is located near the center of the house. The exterior is composed of wood clapboard siding on the first floor and wood shingles on the second floor. The primary entrance is located near the east corner of the façade, covered by a front gabled overhang, and is accessed by a brick and concrete full-width uncovered porch with metal railings. West of the entrance are 3 three-over-one hung wood windows, offset beneath three similar windows centered on the façade at the second floor. A narrow fixed window sits beneath the peak of the front gable at the attic level. Windows on other elevations appear to be wood hung. Similar windows appear on other elevations. A concrete driveway runs along the east side of the property to the rear. There is no garage.
951	4282 Waverly Street			1924	Prairie	n/a	C	Unknown	Unknown	The duplex at 4282 Waverly Street is two-stories and topped with a hipped asphalt shingle roof intersected by a hipped roof dormer clad in wood shingles with two small multi-pane casement windows centered above the façade. A brick chimney is located at the eave on the west façade, and another brick and concrete chimney is near the rear of the house. The facade is clad in blonde brick laid in a running bond pattern with some decorative brickwork, with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the east corner of the facade beneath a metal, flared-eave hood molding supported by knee brackets and a wood casement window on the second floor. The entrance is accessed by concrete stairs. West of the entrance are three wood casement windows with leaded-glass detailing set beneath the same windows on the second floor. At the west corner of the façade is a two-story porch supported by brick piers with a brick kneewall on the first floor, while the second floor balcony is uncovered and has wood railings. Windows have cast stone sills with aluminum storms. Windows on other elevations appear to be hung. A concrete driveway runs along the east of the house to the rear. There is no garage.
952	4287 Waverly Street			1925	Tudor Revival	n/a	C	Unknown	Unknown	The duplex at 4287 Waverly Street is two-stories and topped with a side gabled asphalt shingle roof intersected a front gable. A brick chimney is located at the eave on the west façade near the front of the house. The exterior is composed of wood clapboard siding on the first floor and wood shingles on the second floor. The primary entrance is located near the east corner of the façade, covered by a front gabled overhang supported by square wood posts, and is accessed by a brick and concrete porch with metal railings and an aluminum metal awning. West of the entrance are three hung wood windows with divided lites on the upper sash, set directly beneath three similar windows centered on the façade at the second floor. A small hung window sits beneath the peak of the front gable at the attic level. Windows on other elevations appear to be wood hung. Similar windows appear on other elevations. A concrete driveway runs along the east side of the property to the rear. There is no garage.
953	4289 Waverly Street			1926	Tudor Revival	n/a	C	Unknown	Unknown	The duplex at 4289 Waverly Street is two-stories and topped with a hipped asphalt shingle roof intersected a front gable. A brick chimney is located near the center of the house. The exterior is composed of vinyl siding. The primary entrances are located near the east corner of the façade, accessed by a CMU and wood porch with metal railings, beneath a second-floor balcony supported by brick piers with wood railings. West of the entrance are three six-over-one hung wood windows, offset beneath a large slider window at the second floor. A small multi-pane wood window sits beneath the peak of the front gable at the attic level. Windows on other elevations appear to be wood hung. Similar windows appear on other elevations. A concrete driveway runs along the east side of the property to the rear. There is no garage.
954	4294 Waverly Street			1927	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4294 Waverly Street is two-stories and topped with an asphalt shingle side gable roof intersected by continuous shed dormers on the front and rear. A brick chimney is located at the eave on the east façade near the front of the house. The façade is clad in red face brick laid in a running bond pattern with some decorative brickwork on the first story, while the second story is clad in false half-timbering. The entrance, located near the west corner of the façade, is arched and trimmed with brick, accessed by a concrete and painted brick full width porch. East of the entrance, the porch is covered with an aluminum metal awning with wood post supports and railings. Under the awning there are four wood hung windows with divided lites, set beneath three similar windows on the second floor. Windows on the first story have cast stone sills and all windows have aluminum storm windows. Hung windows appear on other elevations. A driveway runs along the east of the house. There is no garage.
955	4295 Waverly Street			1922	Colonial Revival	n/a	C	Unknown	Unknown	The house at 4295 Waverly Street is two-stories and topped with a side gambrel asphalt shingle roof, interrupted by a continuous shed dormer with vinyl cladding on the front and rear. A brick chimney is located at the eave on the west façade of the house. The exterior is clad in vinyl siding. The primary entrance is located slightly offcenter towards the west corner of the facade, and is accessed by a brick and concrete porch that has been screened in with an aluminum awning that wraps around a front gabled overhang. West of the entrance is a six-over-one hung wood window with aluminum storms, four matching windows glaze the second floor in sets of two. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the property to a front-gabled garage.
956	4302 Waverly Street			1928	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4302 Waverly Street is two-stories and topped with an asphalt shingle side gable roof intersected by continuous shed dormers on the front and rear, intersected by a front gable that overlaps with another front gable above the entrance. A brick chimney is located at the eave centered on the front façade. The façade is clad in brown face brick laid in a running bond pattern with rusticated stone decorative accents first story beneath the front gables, while the second story shed dormer is clad in false half-timbering which is also found beneath the side gable on the second story east elevation. The entrance, located near the east corner of the façade, is trimmed with rusticated stone accents, and accessed by a concrete and brick porch. East of the entrance there is a vinyl slider window with brick sill set beneath a vinyl slider window on the second floor. A small hung window sits beneath the peak of the front gable above the entrance. Windows on the first story have cast stone sills and all windows have aluminum storm windows. Similar windows appear on other elevations. A driveway runs along the east of the house. There is no garage.
957	4303 Waverly Street			1925	Colonial Revival	n/a	C	Unknown	Unknown	The house at 4303 Waverly Street is two-stories and topped with a front gambrel asphalt shingle roof intersected by continuous shed dormers clad in vinyl that contain the second story. A brick chimney is located at the eave on the west façade of the house. The exterior is clad in vinyl siding. The primary entrance is located at the east corner of the facade, and is accessed by a CMU porch covered by a hipped gabled overhang supported by square wood posts. West of the entrance is a set of three hung vinyl windows with a simulated diamond pattern. The second floor is glazed with two sets of two hung windows with divided upper sashes. Similar windows appear on other elevations. A concrete ribbon driveway runs along the east side of the property to the rear. There is no garage.
958	4309 Waverly Street			1927	Tudor Revival	n/a	C	Unknown	Unknown	The duplex at 4309 Waverly Street is two-stories and topped with a hipped asphalt shingle roof, intersected by a front gable with a small hung wood window above the front facade. A brick chimney is near the center of the house. The facade is clad in red-brown face brick laid in a running bond pattern with accents of cast stone and decorative brickwork, with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the east corner of the facade beneath a two-story brick-clad porch with an arched opening supported by brick piers and accessed by a full-width brick-clad porch. The first and second floor porches are each topped with an aluminum awning and surrounded by a brick kneewall. Three wood hung windows topped with decorative brick arches are west of the entrances and set beneath three hung wood windows with divided upper sashes on the second floor. Windows have cast stone sills. Similar windows are arranged on other elevations. A concrete ribbon driveway runs along the east side of the duplex. There is no garage.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
959	4310 Waverly Street			1924	Colonial Revival	n/a	C	Unknown	Brownwell Corporation	The house at 4310 Waverly Street is two-stories and topped with a side gambrel asphalt shingle roof intersected by continuous shed dormers clad that contain the second story. A brick chimney is located at the eave on the west facade of the house. The exterior is clad in vinyl siding. The primary entrance is located at the east corner of the facade, and is accessed by a concrete porch. West of the entrance is a set of three hung vinyl windows. The second floor is glazed with two hung vinyl windows. Similar windows appear on other elevations. A concrete ribbon driveway runs along the east side of the property to the rear. There is no garage.
960	4314 Waverly Street			1925	Tudor Revival	n/a	C	Unknown	Unknown	The duplex at 4314 Waverly Street is two-stories and topped with a hipped asphalt shingle roof, intersected by a side gable, which is intersected by a front gable roof with knee brackets and false half-timbering, and a front gable dormer clad in false half-timbering and wood shingles. A brick chimney is located at the eave on the west facade of the house. The facade is clad in red face brick laid in a running bond pattern with some decorative brickwork, with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the east corner of the facade beneath a second floor balcony with wood railings supported by brick piers and accessed by a full-width brick and concrete porch. A wide casement window is west of the entrances and set beneath three hung wood windows on the second floor. Windows brick sills. Similar windows are arranged on other elevations. A concrete driveway runs along the east side of the duplex. There is no garage.
961	4317 Waverly Street			1926	Prairie	n/a	C	Unknown	Unknown	The duplex at 4317 Waverly Street is two-stories and topped with a hipped asphalt shingle roof intersected by a hipped roof dormer clad in wood shingles with two small casement windows with leaded-glass detailing centered above the facade. A brick chimney is located near the center of the house. The facade is clad in blonde brick laid in a running bond pattern with some decorative brickwork, with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the east corner of the facade beneath a second floor balcony supported by brick piers with a wood railing. The entrance is accessed by a brick and concrete porch with a brick kneewall. West of the entrance are three wood hung windows with leaded-glass detailing set beneath the same windows on the second floor. Windows have cast stone sills with aluminum storms. Similar windows appear on other elevations. A concrete ribbon driveway runs along the east of the house to the rear. There is no garage.
962	4322 Waverly Street			1925	Prairie	n/a	C	Unknown	Unknown	The duplex at 4322 Waverly Street is two-stories and topped with a hipped asphalt shingle roof intersected by a front gabled roof dormer clad in wood shingles with three small wood multi-paned windows centered above the facade. A brick chimney is located at the eave on the west facade. The facade is clad in blonde brick laid in a running bond pattern with a brick belt course at the second story and cast stone accents at the corners, with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the east corner of the facade beneath a second floor balcony supported by brick piers with a metal railing. The entrance is accessed by a brick and concrete porch with a wood railing. West of the entrance are three wood hung windows with divided upper sashes, set beneath matching windows on the second floor. First floor windows are trimmed with brick arches infilled with decorative cast stone, featuring garland ornamentation above the center window. Windows have cast stone sills. Similar windows appear on other elevations. A concrete driveway runs along the east of the house to the rear. There is no garage.
963	4325 Waverly Street			1926	Prairie	n/a	C	Unknown	Unknown	The duplex at 4325 Waverly Street is two-stories and topped with a hipped asphalt shingle roof intersected by a hipped roof dormer clad in wood shingles with two small wood multi-paned windows centered above the facade and a shed roof dormer above the east facade. A brick chimney is located near the center of the house. The facade is clad in brown and red face brick laid in a running bond pattern with cast stone accents, with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the east corner of the facade beneath a second floor balcony supported by brick piers with a metal railing. The entrance is accessed by a brick and concrete porch with a metal railing. West of the entrance are three wood hung windows with divided upper sashes, set beneath matching windows on the second floor. Windows have cast stone sills. Similar windows appear on other elevations. A concrete driveway runs along the east of the house to the rear. There is no garage.
964	4331 Waverly Street			1923	Prairie	1/garage	C	Unknown	Unknown	The house at 4331 Waverly Street is two-stories and topped with a hipped asphalt shingle roof intersected by a hipped roof dormer clad in wood shingles with two small wood multi-paned casement windows centered above the facade. A brick chimney is located at the eave on the west facade near the front of the house. The facade is clad in wood clapboard siding on the first story, with wood shingles on the second story. The primary entrance is near the east corner of the facade beneath a hipped overhang supported by tapered square columns on top of brick piers and is accessed by a full-width wood porch with wood railing. West of the entrance are three wood hung windows with divided upper sashes, and second story is glazed by two sets of two windows matching those on the first story. Similar windows appear on other elevations. A concrete driveway runs along the east of the house to the rear to a front gabled garage.
965	4332 Waverly Street			1924	Colonial Revival	n/a	C	Unknown	Unknown	The house at 4332 Waverly Street is two-stories and topped with a side gambrel asphalt shingle roof intersected by continuous shed dormers clad that contain the second story. A brick chimney is located at the eave on the west facade near the front of the house. The exterior is clad in vinyl siding on the first story, with wood shingles at the second story. The primary entrance is located at the east corner of the facade beneath a wood arched overhang with false half-timbering, and is accessed by a brick and concrete porch. West of the entrance is a set of three hung vinyl windows. The second floor is glazed with two sets of two hung vinyl windows. Similar windows appear on other elevations. A concrete ribbon driveway runs along the east side of the property to the rear. There is no garage.
966	4337 Waverly Street			1931	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4337 Waverly Street is two-stories and topped with an asphalt shingle hipped roof intersected by a catslide front gable that overlaps with another catslide front gable above the entrance. A brick chimney is located at the eave centered on the rear facade. The facade is clad in brown and red face brick laid in a running bond pattern with decorative brickwork and rusticated stone decorative accents beneath the front gables. The arched entrance is located near the east corner of the facade and accessed by a concrete and brick porch with metal railing. The entrance is accessed by a brick and concrete porch with a metal railing. West of the entrance there is a large multipaned wood casement window with fixed transom. Two smaller casement wood windows with similar configurations glaze the second floor. Windows have brick sills. Similar windows appear on other elevations. A driveway runs along the east of the house. There is no garage.
967	4338 Waverly Street			1926	Tudor Revival	1/garage	C	Unknown	Unknown	The house at 4338 Waverly Street is one-and-a-half-stories and topped with an asphalt shingle side gabled roof, intersected by an inset arched dormer with two hung wood windows and catslide front gable that extends over a pointed arch opening off of the east corner of the facade. A prominent brick and stucco chimney is located at the front facade. The facade is clad in vinyl siding. The arched entrance is located near the east corner of the facade within a catslide vestibule and accessed by a concrete and brick porch with a metal handrailing. West of the entrance are three wood hung windows with divided upper sashes. Similar windows appear on other elevations. A sidewalk runs along the east side of the house beneath the pointed arch leading to the rear. There is no garage.
968	4343 Waverly Street			1925	Prairie	1/garage	C	Unknown	Unknown	The duplex at 4343 Waverly Street is two-stories and topped with a hipped asphalt shingle roof intersected by a hipped roof dormer clad in wood shingles with a vinyl slider window centered above the facade. A brick chimney is located near the center of the house. The facade is clad in brown and red face brick laid in a running bond pattern, with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the east corner of the facade beneath a second floor balcony supported by brick piers with a metal railing. The entrance is accessed by a brick and concrete porch with a metal railing. West of the entrance, the porch is covered by an aluminum metal awning which covers three vinyl hung windows, set beneath matching windows on the second floor. Windows have cast stone sills. Similar windows appear on other elevations. A concrete driveway runs along the east of the house to the rear where there is a garage with a pyramidal roof.
969	4344 Waverly Street			1926	Prairie	n/a	C	Unknown	Unknown	The duplex at 4344 Waverly Street is two-stories and topped with a hipped asphalt shingle roof intersected by a hipped roof dormer clad in wood shingles with three small wood casement windows centered above the front facade, and another centered above the east facade. A brick chimney is located near the center of the house. The facade is clad in blonde brick laid in a running bond pattern, with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the east corner of the facade beneath a second floor balcony supported by brick piers with a wood railing. The entrance is accessed by a brick and concrete porch with a wood railing. West of the entrance are three vinyl hung windows, set beneath matching windows on the second floor. First floor windows are trimmed with brick arches infilled with decorative cast stone, featuring keystones and springers painted white. Windows have cast stone sills that have been painted white. Similar windows appear on other elevations. A concrete driveway runs along the east of the house to the rear. There is no garage.
970	4349 Waverly Street			1924	Prairie	1/garage	C	Unknown	Unknown	The duplex at 4349 Waverly Street is two-stories and topped with a hipped asphalt shingle roof intersected by a segmented arch roof dormer clad in wood siding with two multi-paned wood windows with arched tops centered above the facade. A brick chimney is located at the eave on the west facade, and another brick chimney is near the rear of the house. The facade is clad in light brown brick laid in a running bond pattern with some decorative brickwork, other facades are composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the east corner of the facade beneath an aluminum metal awning and is accessed by a concrete stoop with metal railings. The entrance is trimmed with a decorative door surround. West of the entrance is a set of three casement windows set beneath a matching set on the second story. At the west corner of the facade is a two-story porch supported by brick piers with a brick kneewall on the first floor, while the second floor balcony is covered with an aluminum metal awning and has metal railings. Windows have cast stone sills with aluminum storms. Similar windows appear on other elevations. A concrete driveway runs along the east of the house to the rear where there is a front gabled garage.

ID	Address	Historic Name	Other Name	Date Built	Architectural Style	Number/Type Outbuildings	C/NC	Architect	Builder	Narrative Architectural Description
971	4350 Waverly Street			1924	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4350 Waverly Street is one-and-a-half-stories and topped with an asphalt shingle jerkinhead roof. A brick chimney is located near the center of the house. The façade is clad with stucco. The entrance is located near the west corner facing the west façade beneath an overhang that extends from the principal roofline. Centered on the façade is a single square window opening, set beneath another window opening on the second story. A sidewalk runs along the east side of the house. There is no garage.
972	4357 Waverly Street			1926	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4357 Waverly Street is two-stories and topped with an asphalt shingle side gabled roof intersected by three front gables and another front gable towards the rear. A brick chimney is located near the center of the house. The façade is clad in brown and red face brick laid in a running bond pattern with decorative brickwork false half-timbering beneath the two outermost front gables, and the side gables are clad with wood shingles. There is an arched entrance with decorative cast stone surround on either corner of the front façade, accessed by a concrete and brick full-width porch with metal railing. Centered between the entrances is a large multipaned wood casement window with fixed transom and fixed sidelights, beneath a matching window on the second floor. Windows have cast stone sills. Similar windows appear on other elevations. A driveway runs along the east of the house. There is no garage.
973	4358 Waverly Street			1926	Prairie	n/a	C	Unknown	Unknown	The duplex at 4358 Waverly Street is two-stories and topped with a hipped asphalt shingle roof intersected by a hipped roof dormer clad in wood shingles with two multi-paned wood windows centered above the façade, and a shed dormer facing the east façade. A brick chimney is located near the center of the house. The façade is clad in red face brick laid in a running bond pattern with cast stone accents, other facades are composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the east corner of the facade and is accessed by a brick and concrete stoop with metal railing. The entrance is trimmed with a decorative wood door surround including pedimented crown and pilasters. West of the entrance is a vinyl slider window set beneath picture window with simulated divided lights on the second story. At the west corner of the façade is a two-story denticulated porch supported by brick piers with a wood railings. Windows have cast stone sills. Similar windows appear on other elevations. A concrete ribbon driveway runs along the east of the house to the rear. There is no garage.
974	4364 Waverly Street			1926	Tudor Revival	n/a	C	Unknown	Unknown	The house at 4364 Waverly Street is two-stories and topped with an asphalt shingle hipped roof intersected by a front gable. A brick chimney is located near the center of the house. The façade is clad in light brown face brick laid in a running bond pattern, other facades are composed of red common brick laid in a running bond pattern. The entrance is near the east corner of the facade, there is presently no porch. West of the entrance are three window openings that have been boarded, with arched brick surrounds and cast stone accents, beneath a large boarded window opening on the second floor. There are gaps in the façade brick at the second floor indicating where a balcony has since been removed and a former balcony entrance that has been boarded. Windows have cast stone sills. Similar boarded window openings appear on other elevations. A ribbon driveway runs along the east of the house. There is no garage.
975	4365 Waverly Street			1926	Prairie	n/a	C	Unknown	Unknown	The duplex at 4365 Waverly Street is two-stories and topped with a hipped asphalt shingle roof intersected by a hipped roof dormer clad in wood shingles with two small windows with leaded-glass detailing centered above the façade. A brick chimney is located near the center of the house. The façade is clad in blonde face brick laid in a running bond pattern with some decorative brickwork and cast stone accents, other facades are composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the east corner of the façade, accessed by a brick and concrete stoop with a metal handrail, beneath a second floor balcony which is supported by brick piers with a metal railing and covered with an aluminum metal awning. West of the entrance, three wood windows with leaded-glass detailing on the upper sashes are covered by an aluminum metal awning, set beneath matching windows on the second floor. Windows have cast stone sills. Similar windows appear on other elevations. A concrete driveway runs along the east of the house to the rear. There is no garage.
976	4370 Waverly Street			1924	Prairie	n/a	C	Unknown	Unknown	The duplex at 4370 Waverly Street is two-stories and topped with a hipped asphalt shingle roof intersected by a front gabled roof dormer clad in wood shingles with three small wood windows centered above the front façade. A brick chimney is located at the eave on the west façade and another brick chimney is located near the center of the house. The façade is clad in red and brown brick laid in a running bond pattern, with other facades composed of red common brick laid in a running bond pattern. The primary entrance to each flat is near the east corner of the facade beneath a second floor balcony supported by brick piers. The entrance is accessed by a brick and concrete full-width porch with a metal railing. West of the entrance are three six-over-one hung wood windows, set beneath matching windows on the second floor. First floor windows are topped with brick arches. Windows have cast stone sills. Similar windows appear on other elevations. There is no driveway or garage.